

22/03/2009

ASS. REC. BY:

REF: CS/CT/19013182/TIVF312

Special Instruction:

Surveyor: Taufiqh

ASSIGNMENT (Office)

From (Person): Chary Boon Sen of CTI Date/Time: 25/7/19 @ 4:28pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SKH 2829R Insured: GBB 5266H

at Workshop m/s performance Tel: 6319 0174

of 303 Alexandra Road

Policy No: Claim No: SNM19D203452

Sum Insured: Excess:

Make of Veh: D.O.A. 21/07/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 9:16am @ 26/7/19 Person Contacted: Caroline Vehicle: IN / OUT

| Date/Time | Action/Instruction |
|-----------|--|
| | Estimated (/) |
| | SKH 2829R X |
| | GBB 5266H X |
| 16/9/19 | Final fig \$17,002.65 confirmed by email (Ref 2636, 139) |

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 25 July 2019 4:28 PM
To: PBSP
Cc: assignments
Subject: RE: OUR REF: SNM19D203452/CHONGBS - FW: REQUEST FOR DIRECT SETTLEMENT - SKH2829R & GBB5266H ON 21/07/2019

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Thursday, 25 July, 2019 3:36 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D203452/CHONGBS - FW: REQUEST FOR DIRECT SETTLEMENT - SKH2829R & GBB5266H ON 21/07/2019

Dear Boon Sen

We are agreeable to use a common surveyor below as the SJE.

| |
|----------------|
| XING QUO QIANG |
| KENNETH KONG |

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint

303, Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 25 July 2019 3:32:21 PM
To: PBSP <pml-pbsp@simedarby.com.sg>
Subject: RE: OUR REF: SNM19D203452/CHONGBS - FW: REQUEST FOR DIRECT SETTLEMENT - SKH2829R & GBB5266H ON 21/07/2019

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

| |
|-------------------------|
| ADRIAN LING |
| Kelvin Ang |
| SEE CHEW SENG |
| MOHD FADHILAH BIN OSMAN |
| XING QUO QIANG |
| KENNETH KONG |
| SIMON HO |
| CHUA WEIJIE |
| MARCUS CHUA |
| HENRY NG |

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.
You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Thursday, 25 July, 2019 2:53 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; pml-pbsp@simedarby.com.sg

Subject: OUR REF: SNM19D203452/CHONGBS - FW: REQUEST FOR DIRECT SETTLEMENT - SKH2829R & GBB5266H ON 21/07/2019

Dear Boon Sen,

Please conduct PRS for SKH2829R.

Note: Office in charge is Boon Sen, 63896171.

Thanks,
shumin

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Thursday, July 25, 2019 10:50 AM
To: Claims Dept of CTI
Subject: REQUEST FOR DIRECT SETTLEMENT - SKH2829R & GBB5266H ON 21/07/2019

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

“This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's.”

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|---------------------------------------|
| Date Of Report | 22/07/2019 15:32 |
| Date Of Accident | 21/07/2019 15:00 |
| Exact Location Of Accident | J2 CARPARK LOT 20 (JURONG EAST ST 13) |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SKH2829R |
| Insured/Policyholder | |
| Name Of Registered Owner | CHUA CHAI THIAN |
| NRIC No | S1635489I |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-96825703 |
| Alternative Phone No | OTHERS-96825703 |

Vehicle Particulars

| | |
|--|--------------|
| Manufacturer | BMW |
| Model | 740LI |
| Exact Purpose for which vehicle was being used at time of accident | NORMAL USAGE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|---|
| Name of Insurance Company | GREAT EASTERN GENERAL INSURANCE LIMITED |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 2018-V0099185-VDP-R002 |
| Cover Note Number | |

Driver

| | |
|----------------------|----------------------|
| Name of Driver | LEE XIN YAN |
| NRIC No | S9241769G |
| Date Of Birth | 06/11/1992 |
| Occupation | INDOOR |
| Date Of Driving Pass | 01/04/2011 |
| Driving Experience | 8 YEARS AND 3 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-82335444 |
| Fax Number | |
| Contact Number | |
| Email Address | XINYAN1379@GMAIL.COM |

| | |
|---|--------------------------------------|
| Address | BLK 833 JURONG WEST STREET 81 #13-03 |
| Postcode | 640833 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | RELATIVE |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|------------------------------|
| Type Of Accident | COLLIDED INTO PARKED VEHICLE |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 0 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|---|
| Vehicle Registration Number | GBB5266H |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | COMMERCIAL VEHICLE |
| Name of Driver | LIM ZHEN JIE TERRY |
| NRIC/Passport Number | |
| Contact Number | 96986523 |
| Address | |
| Postcode | |
| Insurance Company Name | CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


21/07/19
1452

Reporting Centre Personnel's Signature


Name: Inthiran A.L. Thiruganay
NRIC/FIN No. Performance Motors Limited
503 Alexandra Road
Sime Darby Performance Centre
Singapore 15914



Sketch Plan Pg. 2

SKETCH PLAN

open carpark at J2 (Jurong East St 13)



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21st July 2019, 1500 hours, my car (SKH 2829 R) was parked in lot 20 at open carpark J2 (Jurong East St 13). I was at a unit in BLK 109 and I heard a loud bang. I looked out of the window, to see a van parked in front of my vehicle. Thus, I went down to check.

Upon discussion with the driver of the van (G B B 5266 H), he admitted he had reversed carelessly into SKH 2829 R. Particulars of driver of van as follows:

Name: LIM ZHEN JIE, TERRY
 Licence number: T 0023151C

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

22/07/19 1452

Reporting Centre Personnel's Signature
 Name: Inthara P. P. P.
 NRIC/FIN No.: Performance Motor Limited
 203 Aljunied Road
 Sime Darby Performance Centre
 Singapore 155941

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
 Toll-Free Number (1800-2255269)

303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

0/08

*Survey & repair
 ← 31/07 @ 10am
 survey before 12pm*



GST REG. NO : M2 - 0020081 - X

25 JUL 2019

E S T I M A T E

| | |
|--------------------------------------|-------------------|
| Estimate No. : b1 52106 | Page No. : 1 of 5 |
| Date Estimated : 25/07/2019 | |
| Prepared By : Inthiran A/L Thurasamy | |

| | |
|---|--|
| - ESTIMATE REPAIR FOR - Chua Chai Thian 34 Jalan Kelulut Singapore 809051 | - ACCOUNT - 135 China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 |
|---|--|

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------|------------|--------|---------|
| SKH2829R | DD87068 | 23/11/2012 | 740LiA | 0 |

| DESCRIPTION | VALUE |
|---|---|
| To replace front bumper, fender left, support left, attachments and repair bonnet. | 2550-5,100.00 <i>- with support = 3825</i> |
| Painting front bumper, fender left and bonnet. | ✓ 3164 3,516.00 |
| To replace left headlight. | ✓ 408 481.00 |
| To check electrical wiring systems at the front section for proper function including adjustments of headlights. | ✓ 150 177.00 |
| To carry out body cavity preservation. (Per panel). | 100 200- 236.00 |
| To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function. | ✓ 150 177.00 |
| Sundries. | ✓ / 150.00 |

Total Labour 1: **9,837.00**

| DESCRIPTION | QTY | PRIC | VALUE |
|--------------------------------------|-----|----------|----------------|
| FRT LH FENDER | 1 | 1,236.65 | bt 1,236.65 ✓ |
| LH SIDE PANEL HEADLIGHT HOLDER | 1 | 34.25 | de ? 34.25 ✓ |
| LH RUBBER STRIP | 1 | 54.00 | at ? 54.00 ✓ |
| FRT BUMPER TRIM PRIMED (PDC/SIDIEVIE | 1 | 1,540.90 | de 1,540.90 ✓ |
| BMW EMBLEM | 1 | 71.25 | dis ? 71.25 ✓ |
| LH SUPPORT | 1 | 260.35 | dis ? 260.35 ✓ |
| FRT LH COVER WHEELHOUSING FRT | 1 | 139.85 | de ? 139.85 ✓ |
| LH HEADLIGHT WITH LED TECHNOLOGY | 1 | 5,062.80 | cu 5,062.80 ✓ |
| PDC sensor | 2 | 373.00 | 47 746.00 ✓ |
| DECOUPLING RING PDC TORQUE CONVERTE | 4 | 5.05 | rel 20.20 ✓ |

Total Parts : **9,166.25**

Performance Motors Limited



A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
 Toll-Free Number (1800-2255269)

303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax: 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax: 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax: 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

| | |
|---|--------------------------|
| Estimate No. : b1 52106 | Page No. : 2 of 5 |
| Date Estimated : 25/07/2019 | |
| Prepared By : Inthiran A/L Thurasamy | |

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------|------------|--------|---------|
| SKH2829R | DD87068 | 23/11/2012 | 740LiA | 0 |

[Handwritten Signature]
 2/8/19

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time: 1/8/19 Excess S\$ _____

Surveyor Name: Tanpin Sign: [Signature]

Sum Insured: 974,574.9 A. Insured Yes / No _____

Approved: wp Date: _____

Estimate No. _____ P.M.L. Yes / No _____

Surveyor's Name: Tanpin @ Uluantown

Remarks: 6-7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

19,638.65

| | | |
|--------------------|---|------------------|
| Labour 1 | : | 9,837.00 |
| Parts | : | 9,166.25 |
| Labour 2 | : | 0.00 |
| Excess | : | 0.00 |
| Total GST @ 7% | : | 1,330.23 |
| Grand Total | : | 20,333.48 |

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
 ** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 52106**
Date Estimated : **25/07/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Chua Chai Tian
34 Jalan Kelulut

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 809051

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------------|----------------|-------------------|---------------|----------|
| SKH2829R | DD87068 | 23/11/2012 | 740LiA | 0 |

| DESCRIPTION | ACCOUNT: ORIGINAL PRICE | DISC. % | NETT |
|--|----------------------------|---------|----------|
| To replace front bumper and attachments, front left fender, front left wheel housing cover and left support etc including to make good front bonnet and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job. | 3,825.00 | 0 | 3,825.00 |
| To respray front bumper, front bonnet and front left fender. | 3,164.00 | 0 | 3,164.00 |
| To replace left Technology LED headlight and left fog lamp | 408.00 | 0 | 408.00 |
| To check electrical wiring systems at the front section for proper function including adjustments of headlights. | 150.00 | 0 | 150.00 |
| To carry out body cavity preservation. | 100.00 | 0 | 100.00 |
| To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function. | 150.00 | 0 | 150.00 |
| Sundries. | 150.00 | 0 | 150.00 |

| DESCRIPTION | UNIT PRICE | QTY | DISC. % | NETT |
|--------------------------------------|------------|------|---------|----------|
| # FRT LH FENDER | 1,236.65 | 1.00 | 0 | 1,236.65 |
| LH SIDE PANEL HEADLIGHT HOLDER | 34.25 | 1.00 | 0 | 34.25 |
| LH RUBBER STRIP | 54.00 | 1.00 | 0 | 54.00 |
| FRT BUMPER TRIM PRIMED (PDC/SIDIEVIE | 1,540.90 | 1.00 | 0 | 1,540.90 |
| # EMBLEM GROMMET (A) | 0.80 | 2.00 | 0 | 1.60 |
| BMW EMBLEM | 71.25 | 1.00 | 0 | 71.25 |
| # LH SPACER (A) | 8.05 | 1.00 | 0 | 8.05 |
| LH SUPPORT | 260.35 | 1.00 | 0 | 260.35 |
| FRT LH COVER WHEELHOUSING FRT | 139.85 | 1.00 | 0 | 139.85 |
| # LH HIGH PRESSURE NOZZLE (A) | 183.80 | 1.00 | 0 | 183.80 |
| LH HEADLIGHT WITH LED TECHNOLOGY | 5,062.80 | 1.00 | 0 | 5,062.80 |
| # LH LED FOGLAMP (A) | 441.95 | 1.00 | 0 | 441.95 |
| DECOUPLING RING PDC TORQUE CONVERTE | 5.05 | 4.00 | 0 | 20.20 |

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

#

SUPPLEMENTARY ITEMS

| | |
|---------------------------------|------------------|
| Total Labour : | 7,947.00 |
| Total Parts : | 9,055.65 |
| Total Labour & Parts : | 17,002.65 |
| Deduction for Excess : | |
| Total Repair Costs less Excess: | 17,002.65 |
| GST @7%: | 1,190.19 |
| Grand Total : | 18,192.84 |

| | OD | REMARKS | DATE | WORKING DAYS |
|------------------|----|---------------|---------|--------------|
| FAX TO FAX NO | | ianAth LKK | 13/9/19 | 7 |
| FAX TO FAX NO | | | | |
| FAX TO FAX NO | | | | |
| CONFIRMED DATE | | | | |
| PLEASE INCLUDE B | | | | |

LOSS OF USE = \$120 X 9 DAYS
GIA SEARCH FEE - \$2.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 52106**
Date Estimated : **25/07/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Chua Chai Thian
34 Jalan Kelulut

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 809051

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------------|----------------|-------------------|---------------|----------|
| SKH2829R | DD87068 | 23/11/2012 | 740LiA | 0 |

| DESCRIPTION | ACCOUNT: | | |
|-------------|----------------|---------|------|
| | ORIGINAL PRICE | DISC. % | NETT |

| DESCRIPTION | UNIT PRICE | QTY | DISC. % | NETT |
|---------------------------|------------|------|---------|----------------------|
| # | | | | |
| # EMBLEM GROMMET | 0.80 | 2.00 | 0 | 1.60 <i>all ✓</i> |
| # LH SPACER | 8.05 | 1.00 | 0 | 8.05 <i>de ✓</i> |
| # LH HIGH PRESSURE NOZZLE | 183.80 | 1.00 | 0 | 183.80 <i>cash ✓</i> |
| # LH LED FOGLAMP | 441.95 | 1.00 | 0 | 441.95 <i>cash ✓</i> |
| # | | | | |
| # | | | | |
| # | | | | |
| # | | | | |

SUPPLEMENTARY ITEMS

| | |
|------------------------|--------|
| Total Labour : | |
| Total Parts : | 635.40 |
| Total Labour & Parts : | 635.40 |

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 16 September 2019 9:54 AM
To: Sharon Heng L K; Taufikh (LKKAuto); SUR
Subject: RE: DIRECT SETTLEMENT FINAL REPORT - SKH2829R

Dear Sharon,

WITHOUT PREJUDICE

Confirm Total \$17002.65 before GST @ 7 working days.

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Sharon Heng L K <sharon.heng.leekun@simedarby.com.sg>
Sent: Friday, 13 September 2019 6:19 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: DIRECT SETTLEMENT FINAL REPORT - SKH2829R

Dear Taufikh

For your perusal :

Labour\$ 7947.00
Parts\$ 9055.65
Total\$17002.65

Owner is claimingLOSS OF USE = \$120 X 9 DAYS GIA SEARCH FEE - \$2.00

Note : 7 working days.

Please reply me directly.

Best Regards

Sharon Heng
PML – Body and Paint
DID : 63190123
Fax : 64743229

-----Original Message-----

From: service.pml@simedarby.com.sg [mailto:service.pml@simedarby.com.sg]

Sent: Friday, 13 September, 2019 4:07 PM

To: Sharon Heng L K

Subject: Message from KM_C458

“This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's.”

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|---|---|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 02 Aug 2019 | | 02 Aug 2019 13:52 Edit Adj Rpt | S\$17,002.65 Edit Estimates | S\$17,002.65 View Rpt | | Pending for Survey Report Cancel Case |

| | | | | |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

| CLAIM SUBFOLDER DETAILS | | [Created by insurer] | |
|----------------------------------|--|---------------------------------|--|
| Insured: | -, Co. Reg. No.: - | | |
| Main Claimant: | CHUA CHAI THIAN , ID: S16354891 | | |
| Vehicle Reg. No.: | SKH2829R | Date of Loss: | 21/07/2019 15:00 - :59 [79 Months and 28 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / SNM19D203452C02 | Policy/Cover Note No.: | DMCVSN19206319000 |
| Vehicle Reg. No. (Insured): | GBB5266H | Policy No. (Claimant): | 2018-V0099185-VDP-R002 |
| | | Excess: | S\$0.00 |
| Repairer: | Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174 | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen] | | |
| Claimant's Insurer: | Great Eastern General Insurance Limited (HQ) - Tel: +65 248 2888 | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 15/08/2019] | | |
| ASSOCIATED MAIL RECEIVED | | View All | Compose Case Mail |
| There are no mail for this case. | | | |
| ALL ASSOCIATED TASKS | | View All | Search Tasks |
| | | Create New Task | Complete |
| Due Date | Priority | Type | Task Group |
| | | | Subject |
| | | | Handler |
| | | | Assigned By |
| | | | Completed On |
| | | | Created On |
| | | | Done? |
| No results. | | | |

Claim Documents

*SKH2829R (SNM19D203452C02)
[GBB5266H]
TP
CHUA CHAI THIAN
Jul 21 2019 3:00PM
[-]
Performance Motors Limited

| Upload Documents | | Upload Photos | Compose New Letter | View View in Browser <input type="button" value="v"/> |
|----------------------------------|----------------|---|------------------------------------|--|
| Assessment Reports | | | | 1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/> |
| No | Finalized On | Performance Motors Limited (Alexandra) | Thumbnail | Print |
| 1 | 22/07/19 16:37 | Accident Statement | Load HTM | <input type="checkbox"/> |
| Photos/Images | | | | 3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/> |
| No | Finalized On | Performance Motors Limited (Alexandra) | Thumbnail | Print |
| 1 | 22/07/19 16:32 | Accident Photo [Linked Accident Report Documents] | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 22/07/19 16:32 | Accident Photo [Linked Accident Report Documents] | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 22/07/19 16:32 | Accident Photo [Linked Accident Report Documents] | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 22/07/19 16:32 | Accident Photo [Linked Accident Report Documents] | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 22/07/19 16:32 | Accident Photo [Linked Accident Report Documents] | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 22/07/19 16:32 | Accident Photo [Linked Accident Report Documents] | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 22/07/19 16:32 | Accident Photo [Linked Accident Report Documents] | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 22/07/19 16:32 | Accident Photo [Linked Accident Report Documents] | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 22/07/19 16:32 | Accident Photo [Linked Accident Report Documents] | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 22/07/19 16:32 | Accident Photo [Linked Accident Report Documents] | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 22/07/19 16:32 | Accident Photo [Linked Accident Report Documents] | Load JPG | <input checked="" type="checkbox"/> |
| 12 | 22/07/19 16:32 | Accident Photo [Linked Accident Report Documents] | Load JPG | <input checked="" type="checkbox"/> |
| 13 | 22/07/19 16:32 | Accident Photo [Linked Accident Report Documents] | Load JPG | <input checked="" type="checkbox"/> |
| Relabel/Reorder | | | | Thumbnail Print |
| 1 | 16/09/19 09:56 | General View | Load PDF | <input type="checkbox"/> |
| 2 | 16/09/19 09:56 | Reinspection Photo | Load PDF | <input type="checkbox"/> |
| Documentation | | | | 1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/> |
| No | Finalized On | Performance Motors Limited (Alexandra) | Thumbnail | Print |
| 1 | 22/07/19 15:36 | Sketch Plan [Linked Accident Report Documents] | Load TIF | <input type="checkbox"/> |
| Relabel/Reorder | | | | Thumbnail Print |
| 1 | 04/10/19 10:27 | Supplementary | Load PDF | <input type="checkbox"/> |

Linked Accident Report Documents

| | | | | View View in Browser <input type="button" value="v"/> |
|---------------------------|----------------|--|-----------|--|
| Assessment Reports | | | | 1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/> |
| No | Finalized On | Performance Motors Limited (Alexandra) | Thumbnail | Print |
| 1 | 22/07/19 16:37 | Accident Statement | Load HTM | <input type="checkbox"/> |
| Photos/Images | | | | 3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/> |
| No | Finalized On | Performance Motors Limited (Alexandra) | Thumbnail | Print |
| 1 | 22/07/19 16:32 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 22/07/19 16:32 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 22/07/19 16:32 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 22/07/19 16:32 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 22/07/19 16:32 | Accident Photo | Load JPG | <input type="checkbox"/> |

| Assessment Reports | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|--|------------|-------------------------------------|
| No | Finalized On | Performance Motors Limited (Alexandra) | Thumbnail | Print |
| | | | | <input checked="" type="checkbox"/> |
| 6 | 22/07/19 16:32 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 22/07/19 16:32 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 22/07/19 16:32 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 22/07/19 16:32 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 22/07/19 16:32 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 22/07/19 16:32 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 12 | 22/07/19 16:32 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |
| 13 | 22/07/19 16:32 | Accident Photo | Load JPG | <input checked="" type="checkbox"/> |

| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
|---------------|----------------|--|------------|-------------------------------------|
| No | Finalized On | Performance Motors Limited (Alexandra) | Thumbnail | Print |
| 1 | 22/07/19 15:36 | Sketch Plan | Load TIF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119013182/T1VF3E2

Date: 04/10/2019

REFERENCE

| | | | |
|-----------------------|---|----------------------|-------------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMCVSN19206319000 |
| Claimant Vehicle No : | SKH2829R | Insured Vehicle No : | GBB5266H |
| Date of Loss: | 21/07/2019 | Nature of Claim: | TP |
| | | Claim No: | SNM19D203452C02 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SKH2829R | Engine No: | 10898248N55B30A |
| Make & Model: | BMW 740LI, 3.0 (A) | Chassis No: | WBAYE42020DD87068 |
| Reg. Date: | 23/11/2012 (Man. Year: 2012) | Odometer: | 242305 km |
| Colour: | Silver | | |
| Engine Capacity: | 2979 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 245/45 R19 | Rear Tyre Size: | 245/45 R19 |
| Front Left Side: | Goodyear 6 mm | Rear Left Side: | Goodyear 6 mm |
| Front Right Side: | Goodyear 6 mm | Rear Right Side: | Goodyear 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|------------------|------------------|-----------------|--------------|
| Parts | 9,951.65 | 9,205.65 | 746.00 | 7.50 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 9,687.00 | 7,797.00 | 1,890.00 | 19.51 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 19,638.65 | 17,002.65 | 2,636.00 | 13.42 |
| + GST 7.00/7.00% (S\$) | 1,374.71 | 1,190.19 | 184.52 | 13.42 |
| Nett Amount (S\$) | 21,013.36 | 18,192.84 | 2,820.52 | 13.42 |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 02/08/2019 | |
| Date Inspected: | 01/08/2019 Inspected At: | Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941 |
| Estimated Period of Repair: | 7.0 days | |

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | |
|---|---|
| Reference | |
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 04 Oct 2019) |
| Parts: 143 | BMW 740LI 3.0 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SKH2829R) | |
| Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount | |
|-----|-----|----------|--------------------------------------|---------------|--------------------------|-----------------|-----------------|
| 1 | 1 | | *SUNDRIES | Necessary | 150.00 FS | *150.00 FS | |
| 2 | 1 | | *FRT LH FENDER | Bent | 1,236.65 FS | *1,236.65 FS | |
| 3 | 1 | | *LH SIDE PANEL HEADLIGHT HOLDER | Deformed | 34.25 FS | *34.25 FS | |
| 4 | 1 | | *LH RUBBER STRIP | Cut | 54.00 FS | *54.00 FS | |
| 5 | 1 | | *FRT BUMPER TRIM PRIMED (PDC/SIDEVIE | Deformed | 1,540.90 FS | *1,540.90 FS | |
| 6 | 1 | | *BMW EMBLEM | Necessary | 71.25 FS | *71.25 FS | |
| 7 | 1 | | *LH SUPPORT | Distorted | 260.35 FS | *260.35 FS | |
| 8 | 1 | | *FRT LH COVER WHEELHOUSING FRT | Deformed | 139.85 FS | *139.85 FS | |
| 9 | 1 | | *LH HEADLIGHT WITH LED TECHNOLOGY | Cracked | 5,062.80 FS | *5,062.80 FS | |
| 10 | 2 | | *PDC SENSOR | Not Necessary | 746.00 FS | *- FS | |
| 11 | 4 | | *DECOUPLING RING PDC TORQUE CONVERTE | Necessary | 20.20 FS | *20.20 FS | |
| 12 | 2 | | *EMBLEM GROMMET | Necessary | 1.60 FS | *1.60 FS | |
| 13 | 1 | | *LH SPACER | Deformed | 8.05 FS | *8.05 FS | |
| 14 | 1 | | *LH HIGH PRESSURE NOZZLE | Cracked | 183.80 FS | *183.80 FS | |
| 15 | 1 | | *LH LED FOGLAMP | Cracked | 441.95 FS | *441.95 FS | |
| | | | | | Total Parts (S\$) | 9,951.65 | 9,205.65 |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REPLACE FRONT BUMPER, FENDER LEFT, SUPPORT LEFT, ATTACHMENTS AND REPAIR BONNET | New | 5,100.00 | 3,825.00 |
| 2 | PAINTING FRONT BUMPER, FENDER LEFT AND BONNET | New | 3,516.00 | 3,164.00 |
| 3 | TO REPLACE LEFT HEADLIGHT | New | 481.00 | 408.00 |
| 4 | TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS | New | 177.00 | 150.00 |
| 5 | TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION | New | 177.00 | 150.00 |
| 6 | TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL) | New | 236.00 | 100.00 |
| Gross Labour Cost (\$\$) | | | 9,687.00 | 7,797.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >