

ASS. REC. BY:

REP:

CS/CTI 19013183/TIVF3ⁿ²

Special Instructions:

Surveyor: Tan Kah

ASSIGNMENT (Office)

From (Person): Tan Kah leong

of CTI

Date/Time: 25/7/19 @ 5:41pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 1969K

Insured:

GBD 9856T

at Workshop to/s

Teamwork Garage

Tel:

6844 2475

of

53 Ubi Ave 1 # 01-24

Policy No:

DMCVSN15382718033

Claim No:

SNM19D203469

Sum Insured:

Process:

Make of Veh:

D.O.A.

24/07/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

WIP

H.O.D. Endorsement:

Date/Time:

9:29am @ 26/7/19

Person Contacted:

Darren

Vehicle IN / OUT

Date/Time	Action/Instruction
	SLD1969K NA/LIP19013090/24 OCA = 24/7/19
	GBD 9856T "
6/8/19	@ 252pm Darren said vehicle will release soon
2/10/19	LS \$10,000 confirmed by email (Recd 19, 184.80, 66%)

Tayfiki

REF: CII

ASSIGNMENT

From: Date: 26/7/19

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLD 1969K

at Workshop no/s

Teamwork

of 53 ubi Ave 1 #01-25

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$47K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

cup

Date:

Person Contacted:

Vehicle: IN / OUT
Darren

Veh No: SLD 1969K. yr Regn: 2016 June.

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi 4th gen 1143.

Colour:

Black

A/C: Insured / Std / NI / NA

Sp Reading

192561

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MMB5TA13A 14 000612.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65R15

R:

2 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

26/7/19 @ 445pm

Survey held at

Teamwork Garage.

Des. of Damages:

Fry / Rest / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Inform Owner Unit \$10,000

RECEIVED 02 OCT 2019

Date/Time, File Pass to?

☐

: Prel. Report

()

☐

: Final Report

Date/Time, File Return to?

2/10 - typist

Days Of Repair:

15

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp. C\$

☐

: Interview C\$

☐

: Tech. Insp. C\$

☐

: Wind. Insp. C\$

Survey Fee:

Transportation:

E + PS C\$

Phone:

Other:

P/T/L

220

Report Format:

Mr. Men

Lump Sum / H.R. C\$

10,000p

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jul 2019		25 Jul 2019 17:48 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	ROSET LIMOUSINE SERVICES PTE LTD, Co. Reg. No.: 2004067222		
Vehicle Reg. No.:	SLD1969K	Date of Loss:	24/07/2019 10:00 - :59
Claim Type:	TP / SNM19D203469	Policy/Cover Note No.:	DMCVSN15382718033
Vehicle Reg. No. (Insured):	GBD9856T	Policy No. (Claimant):	SD18V12322/VPZ/R00
		Excess:	S\$500.00
Reparer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/08/2019]		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Thursday, 25 July 2019 5:41 PM
To: Darren; assignments
Subject: RE: OUR REF : SNM19D203469/TANKL - FW: OUR REF : 1907-82 // YOURREF : GBD9856T ACCIDENT INVOLVING GBD9856T AND SLD1969K

WITHOUT PREJUDICE

Dear Darren,

We refer to your email of 25.07.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Darren [mailto:claims@teamworkgarage.com]
Sent: Thursday, 25 July, 2019 5:28 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: RE: OUR REF : SNM19D203469/TANKL - FW: OUR REF : 1907-82 // YOURREF : GBD9856T ACCIDENT INVOLVING GBD9856T AND SLD1969K

Hi Kah Leong,

Please appoint LKK

Darren
Teamwork Garage Pte Ltd
53 Ubi Avenue 1
#01-24 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

From: Tan Kah Leong

Sent: Thursday, 25 July 2019 5:18 PM

To: claims@teamworkgarage.com

Subject: RE: OUR REF : SNM19D203469/TANKL - FW: OUR REF : 1907-82 // YOURREF : GBD9856T ACCIDENT INVOLVING GBD9856T AND SLD1969K

Without Prejudice

Dear Shu Shan,

We refer to your email dated 25 July 2019.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
LOW SAR HUEI
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
HONG FOOK CHOY
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards

Tan Kah Leong

Assistant Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Thursday, 25 July, 2019 4:53 PM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; claims@teamworkgarage.com

Subject: OUR REF : SNM19D203469/TANKL - FW: OUR REF : 1907-82 // YOUR REF : GBD9856T ACCIDENT INVOLVING GBD9856T AND SLD1969K

Dear Kah Leong,

Please conduct PRS for SLD1969K.

Note: officer in charge – Kah Leong, 63896193.

Thanks,
shumin

From: TEAMWORK [<mailto:claims@teamworkgarage.com>]

Sent: Thursday, July 25, 2019 2:44 PM

To: Claims Dept of CTI

Cc: TEAMWORK

Subject: OUR REF : 1907-82 // YOUR REF : GBD9856T ACCIDENT INVOLVING GBD9856T AND SLD1969K

WITHOUT PREJUDICE

OUR REF : 1907-82

YOUR REF : GBD9856T

Dear Sir / Madam,
PRE-REPAIR INSPECTION FOR SLD1969K
ACCIDENT INVOLVING GBD9856T AND SLD1969K ON 24.07.2019.

We refer to the above matter and enclosed herewith our client's GIA report and notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction-Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention.

Thank you and have a nice day.

Regards,

Shu Shan

Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel: 6844 2475
Fax:6844 2474

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 2 October 2019 10:15 AM
To: Darren; Taufikh (LKKAUTO); SUR
Subject: RE: SLD1969K MITSUBISHI ATTRAGE-DOA:24/7/2019

Dear Darren,

WITHOUT PREJUDICE

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Darren <claims@teamworkgarage.com>
Sent: Wednesday, 2 October 2019 9:58 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: RE: SLD1969K MITSUBISHI ATTRAGE-DOA:24/7/2019

Hi Veron,

Finalize \$10k confirmed

Darren
Teamwork Garage Pte Ltd
53 Ubi Avenue 1
#01-24 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 1 October 2019 2:46 PM
To: Taufikh (LKKAUTO); 'Darren'
Subject: RE: SLD1969K MITSUBISHI ATTRAGE-DOA:24/7/2019

Dear Darren,

Can confirm?

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Sent: Thursday, 19 September 2019 1:13 PM
To: 'Darren' <claims@teamworkgarage.com>
Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: SLD1969K MITSUBISHI ATTRAGE

Hi Darren,

This car got repair limit \$10,000, have inform you previously thru whatsapp.

COR l/s \$10,000 , 15 days.

Regards
Taufikh
Lkk Auto

From: Darren [<mailto:claims@teamworkgarage.com>]
Sent: Saturday, 7 September 2019 9:26 AM
To: taufikh@lkkauto.com
Subject: SLD1969K MITSUBISHI ATTRAGE

Hi Taufikh,

FYNA

Based on estimate calculation:

COR @ \$20600
DOR @ 16 Days

Please revise and get back to us so that we can close the case

Darren
Teamwork Garage Pte Ltd
53 Ubi Avenue 1
#01-24 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474



This email has been checked for viruses by AVG antivirus software.
www.avg.com

VISIT THE LEXUS SHOWCASE @ SUNTEC FROM NOW TO THIS SUNDAY
SIGN UP NOW FOR COMPLIMENTARY GIFTS AT OUR BOOTH.





Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

BMW 3 Series 325i Convertible (COE Till Aug/2028).



Low Mileage (95k Km) New Xenon Lamps. Price Of A Jap Car!
Direct Owner [View](#)

ABWIN
ONE STOP
AUTOMOTIVE SOLUTIONS

[View All Vehicles](#)

Browse by Category

Sort by Date Posted 20 results/page

6 vehicles

Mitsubishi Attrage

Advanced Search ☒ Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mitsubishi Attrage		Any	Any	2016	Any	Any	Any	Available
	Mitsubishi	Attrage 1.2A	\$48,800	\$7,170 /yr	07-Jan-2016	1,193 cc	-	Sedan	Available
Well Maintained, Immaculate Condition, View To Believe, High Loan Available, Trade In Welcome, Price Negotiable, Call Or Visit Our Showroom For Viewing Now!									
Posted: 26-Jul-2019 Tags: 2016 Mitsubishi Attrage, 2016 mitsubishi attrage, Mitsubishi Attrage, mitsubishi attrage, Mitsubishi Attrage, attrage, Used Mitsubishi									
	Mitsubishi	Attrage 1.2A	\$48,800	\$6,300 /yr	30-Nov-2016	1,193 cc	-	Sedan	Available
Agent Serviced And Maintained. Vehicle With 5 Years Unlimited Mileage Warranty. Well Maintained By 1 Owner. High Loan Available! Excellent Condition! Buy With A Peace Of Mind From Award Accredited Company! Attractive Loan Interest Rate And Competitive Tr...									
Autolink Holdings Pte Ltd									
Posted: 22-Jul-2019 Tags: 2016 Mitsubishi Attrage, 2016 mitsubishi attrage, Mitsubishi Attrage, mitsubishi attrage, Mitsubishi Attrage, attrage, Used Mitsubishi									
	Mitsubishi	Attrage 1.2A	\$50,800	\$7,310 /yr	03-Mar-2016	1,193 cc	48,027 km	Sedan	Available
Know More About The Car Through Vicom Evaluation Report, All Our Cars Are Vicom Evaluated! Free 6 Months Maintenance And 1 Grooming At In-House Workshop.									
Yong Lee Seng Motor									
Posted: 20-Jul-2019 Tags: 2016 Mitsubishi Attrage, 2016 mitsubishi attrage, Mitsubishi Attrage, mitsubishi attrage, Mitsubishi Attrage, attrage, Used Mitsubishi									
	Mitsubishi	Attrage 1.2A	\$47,988	\$6,530 /yr	14-Jul-2016	1,193 cc	38,000 km	Sedan	Available
One-Owner. Agent Serviced And Maintained. Vehicle With 5 Years Unlimited Mileage Warranty From The Date Of Purchase And 10 Years Engine Warranty By C&C, Well Maintained. Eligible For Up To 70% Loan Of The Car Price With Authorized Banks. Call/SMS/Wh...									
Cycle & Carriage,Fulco Motor Dealer									
Posted: 17-Jul-2019 Tags: 2016 Mitsubishi Attrage, 2016 mitsubishi attrage, Mitsubishi Attrage, mitsubishi attrage, Mitsubishi Attrage, attrage, Used Mitsubishi									
	PTT Performa Synthetic 5W40 Vehicle Servicing KIA : PTT 5W40 Performa: MAJOR Service Package @ \$428 Nett Find out more!								
	Mitsubishi	Attrage 1.2A	\$55,800	\$7,480 /yr	08-Sep-2016	1,193 cc	16,000 km	Sedan	Available
Sports Edition With Body Kit. Agent Servicing With Low Mileage. Non-Private Hire Car. Flexible Loan/High Trade In. Please Call For Viewing Now.									
Posted: 02-Jul-2019 Tags: 2016 Mitsubishi Attrage, 2016 mitsubishi attrage, Mitsubishi Attrage, mitsubishi attrage, Mitsubishi Attrage, attrage, Used Mitsubishi									
	Mitsubishi	Attrage 1.2A	\$47,800	\$6,160 /yr	30-Nov-2016	1,193 cc	66,811 km	Sedan	Available
Agent Serviced And Maintained. Vehicle With 5 Years Unlimited Mileage Warranty From The Date Of Purchase And 10 Years Engine Warranty By C&C, Well Maintained By 1 Owner. Eligible For Up To 70% Loan Of The Car Price With Authorized Banks. Call/SMS/Wha...									

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	722Z
Vehicle Details	
Vehicle No.:	SLD1969K
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jul 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	ATTRAGE 1.2 CVT
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	3A92UDD7491
Chassis No.:	MMBSTA13AHH000612
Maximum Power Output:	57.0 kW (76 bhp)
Open Market Value:	\$13,930.00
Original Registration Date:	07 Jun 2016
First Registration Date:	07 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Jun 2026
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	06 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,889.00
COE Rebate Amount:	\$32,868.00
Total Rebate Amount:	\$36,618.00

The information contained herein is correct as at 26 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/07/2019 17:24
Date Of Accident	24/07/2019 10:00
Exact Location Of Accident	JUNC HOLLAND RD & BELMOUNT RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD1969K
Insured/Policyholder	
Name Of Registered Owner	ROSET LIMOUSINE SERVICES PTE LTD
Co Reg No	200406722Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	ATTRAGE 1.2 CVT
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V12322/VPZ/R00
Cover Note Number	

Driver

Name of Driver	HO WEE HUA, DELIA
NRIC No	S7540822F
Date Of Birth	27/08/1975
Occupation	OUTDOOR
Date Of Driving Pass	15/12/2005
Driving Experience	13 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93632139
Fax Number	
Contact Number	OFFICE-93632139
Email Address	NOEMAIL

Address	BLK 656 SENJA ROAD #05-266
Postcode	670656
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD9856T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GZ3234C
-----------------------------	---------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be completed by the **Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The legal and economic use of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) My Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulations, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Insured Party's
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Person's Signature
Name
NRIC/IN No.

Accident Sketch Plan

SKETCH PLAN

1. 6071892
2. 6079567
3. 6079567



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Milland Road, slowing down before red lights at Belmont Junction. I was not aware of a lorry and hit it from behind and hit the van in front.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
(Name & Title)

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/PTN No.

CHINA TAIPING INSURANCE

Vehicle number	SLD1969K
Make / Model	MITSUBISHI ATTRAGE
Chassis number	MMBSTA13AHH000612
Accident date	24 July 2019
Reference	1907-82

Qty Particulars

Unit Price - SGD \$

<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER	849.60 <i>do ✓</i>
2	REAR BUMPER RETAINER	60.00 <i>nee ✓</i>
2	REAR BUMPER REFLECTOR	68.00 <i>Rny ✓</i>
1	END PANEL	582.00 <i>bl ✓</i>
1	END PANEL KEYLESS SENSOR	114.00 <i>cur ✓</i>
1	END PANEL TOP GARNISH	178.00 <i>?dl ✓</i>
1	END PANEL OUTER GARNISH	165.00 <i>?dis ✓</i>
2	REAR TAILLAMP	662.50 <i>cur ✓</i>
2	REAR TAILLAMP PANEL	390.10 <i>bl ✓</i>
2	REAR TAILLAMP SEALER	50.00 <i>nee ✓</i>
1	REAR EXHAUST SILENCER	685.00 <i>Ry ✓</i>
2	REAR EXHAUST MOUNTING	67.20 <i>X 7 X ✓</i>
1	REAR EXHAUST HEAT SHIELD	85.00 <i>X 7 ✓</i>
2	FENDER INNER TRIM	379.30 <i>X 7 ✓</i>
1	BOOTLID	993.60 <i>bt ✓</i>
1	BOOTLID WEATHERSTRIP	177.60 <i>hri ✓</i>
1	BOOTLID EMBLEM	49.20 <i>nee ✓</i>
1	BOOTLID EMBLEM - ATTRAGE	26.40 <i>nee ✓</i>
1	BOOTLID EMBLEM - ICON	54.00 <i>nee ✓</i>
1	BOOTLID CHROME OUTER GARNISH	219.40 <i>cut ✓</i>
1	BOOTLID LOCK	247.20 <i>bl ✓</i>
1	BOOTLID STRIKER	48.00 <i>bt ✓</i>
2	BOOTLID HINGE	192.00 <i>bt ✓</i>
2	BOOTLID ABSORBER	360.00 <i>X 47 ✓</i>
1	BOOTLID SPOILER	614.40 <i>de ✓</i>
1	SPARE TYRE TOP BOARD	222.00 <i>?Cur ✓</i>
1	REAR FLOOR PANEL	1087.20 <i>Rx ✓</i>
2	REAR FENDER	1716.00 <i>hri ✓</i>
2	REAR FENDER AIR VENT	90.00 <i>X 47 ✓</i>
1	BOOTLID INNER TRIM	230.50 <i>X 47 ✓</i>
1	REAR WINDSCREEN MOULDING	48.00 <i>wa ✓</i>
1	REAR AIR DUCT	40.50 <i>wa ✓</i>
1	REAR AIR DUCT COVER	54.00 <i>?Cur ✓</i>
1	THIRD BRAKE LIGHT	252.00 <i>cut ✓</i>
2	MUD FLAP	117.00 <i>X 47 ✓</i>

111747

1	FRONT BUMPER	818.80	de
2	FRONT BUMPER RETAINER	43.20	re
1	FRONT BUMPER LOWER GRILLE	151.30	de
1	FRONT BUMPER REINFORCEMENT	350.50	?ht
2	FRONT BUMPER REINFORCEMENT BRACKET	312.00	?bt
1	FRONT TOW COVER	18.00	at
1	FRONT GRILLE	410.55	as
1	FRONT GRILLE EMBLEM	48.00	at
2	FRONT FOG LAMP	609.50	Xun
2	FRONT FOG LAMP COVER	288.00	? LH X, RH - at
2	FRONT HEADLAMP	1978.00	ay
1	FRONT SUPPORT PANEL	1147.70	Key X un
1	FRONT SUPPORT PANEL TOP GARNISH	130.00	Xun
1	AIRCON CONDENSER	899.30	?ht
1	AIRCON FAN COWLING	237.60	X
1	AIRCON FAN MOTOR	198.00	X
1	RADIATOR	967.15	X
1	RADIATOR FAN COWLING	237.60	X
1	RADIATOR FAN MOTOR	319.70	X
1	BONNET	1200.30	bt
1	BONNET INSULATOR	101.50	de
1	BONNET HINGE	98.00	Rx
1	BONNET CABLE	59.00	X un
2	FRONT FENDER	1988.00	bt
		23786.40	16468.75
Less 10%		2203.05	14822.05
Subtotal		19827.45	
Balance C/F		19827.45	
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>			
Balance B/F		19827.45	
1	REAR NUMBER PLATE	50.00	45 bt
1 SET	REVERSE SENSOR	400.00	200 un
1 SET	REAR FENDER INNER TRIM CLIP	80.00	40 un
1	FLOOR INSULATOR	150.00	Xun
1 SET	END PANEL TOP GARNISH CLIP	60.00	20 at
1 SET	REAR BUMPER CLIP	60.00	30 at
1	WINDSCREEN SEALANT	150.00	60 at
1	JOINT SEALANT	150.00	50 at
1 SET	FRONT BUMPER CLIP	60.00	30 at
1 SET	SUPPORT PANEL TOP GARNISH CLIP	60.00	X un
1	FRONT NUMBER PLATE	50.00	45 bt
1	COOLANT	150.00	Run
Subtotal		1420.00	480
Balance C/F		21247.45	

S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	21247.45
1	CHECK FRONT & REAR WIRING AND LIGHTING SYSTEM	200.00 ✓ 60.
2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	200.00 60.
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 30.
4	REMOVE AND RENEW REAR EXHAUSY ASSY	150.00 60.
5	REMOVE AND REFIT FUEL TANK	150.00 80.
6	REMOVE AND REFIT REAR WINDSCREEN	150.00 120.
7	REMOVE AND RENEW FLOOR INSUALTOR	150.00 60.
8	TRANSFER PARTS, ATTACHEMENT FROM OLD BOOTLID TO NEW	150.00 60.
9	REMOVE AND RENEW RADIATOR AND TOP UP COOLANT	200.00 100.
10	REMOVE AND RENEW CONDENSER AND TOP UP GAS	200.00 100.
11	PANEL BEATING ON AFFECTED AREAS	3000.00 2000.
12	SPRAY PAINTING ON AFFECTED AREAS	3000.00 2400.
13	APPLY ANTI-RUST ON AFFECTED AREAS	200.00 100.
	Subtotal	7720.00
	Grand total	28967.45
	29,184.80	30945.11

5230

[Signature]

Tarjileh 97495744, 'WP'

30/1/2010

Lumpsum

205320
20% 16425.6

Resurvey after repair 45910,000

14-16 days

20/7/19 @ 445

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 Register number : 201015366H

CHINA TAIPING INSURANCE

REPAIR PERFORMA INVOICE

Vehicle number	SLD1969K
Make / Model	MITSUBISHI ATTRAGE
Chassis number	MMBSTA13AHH000612
Accident date	24 July 2019
Reference	1907-82

Qty	Particulars	Unit Price - SGD \$
	<u>PARTS REPLACEMENT - LIST ITEMS</u>	
1	KEYLESS SENSOR SPEAKER	241.50 <i>QW</i>
		241.50
	Less 10%	24.15
	Subtotal	217.35
	Balance C/F	217.35

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19013183/T1VF3N2

Date: 08/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN15382718033
Claimant Vehicle No :	SLD1969K	Insured Vehicle No :	GBD9856T
Date of Loss:	24/07/2019	Nature of Claim:	TP
		Claim No:	SNM19D203469

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD1969K	Engine No:	3A92UDD7491
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AHH000612
Reg. Date:	07/06/2016 (Man. Year: 2016)	Odometer:	192561 km
Colour:	Black		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	23,045.11	15,519.40	7,525.71	32.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,900.00	5,230.00	2,670.00	33.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,945.11	20,749.40	10,195.71	32.95
Approved Total (Overridden) (S\$)		10,000.00		
(S\$)	30,945.11	10,000.00	20,945.11	67.68
+ GST 7.00/7.00% (S\$)	2,166.16	700.00	1,466.16	67.68
Nett Amount (S\$)	33,111.27	10,700.00	22,411.27	67.68

INSPECTION

Date of Assignment:	25/07/2019	
Date Inspected:	26/07/2019	Inspected At:
		Teamwork Garage Pte Ltd (HQ)
		53 Ubi Ave 1 #01-24, Paya Ubi
		Industrial Park
		Singapore 408934

Estimated Period of Repair: 15.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Oct 2019)	
Parts:	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD1969K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	849.60 FL	*849.60 FL
2	2		*REAR BUMPER RETAINER	Necessary	60.00 FL	*60.00 FL
3	2		*REAR BUMPER REFLECTOR	Not Necessary	68.00 FL	*- FL
4	1		*END PANEL	Bent	582.00 FL	*582.00 FL
5	1		*END PANEL KEYLESS SENSOR	Cracked	114.00 FL	*114.00 FL
6	1		*END PANEL TOP GARNISH	Deformed	178.00 FL	*178.00 FL
7	1		*END PANEL OUTER GARNISH	Distorted	165.00 FL	*165.00 FL
8	2		*REAR TAILLAMP	Cracked	662.50 FL	*662.50 FL
9	2		*REAR TAILLAMP PANEL	Bent	390.10 FL	*390.10 FL
10	2		*REAR TAILLAMP SEALER	Necessary	50.00 FL	*50.00 FL
11	1		*REAR EXHAUST SILENCER	Repair	685.00 FL	*- FL
12	2		*REAR EXHAUST MOUNTING	Not Necessary	67.20 FL	*- FL
13	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	85.00 FL	*- FL
14	2		*FENDER INNER TRIM	Not Necessary	379.30 FL	*- FL
15	1		*BOOTLID	Bent	993.60 FL	*993.60 FL
16	1		*BOOTLID WEATHERSTRIP	Twisted	177.60 FL	*177.60 FL
17	1		*BOOTLID EMBLEM	Necessary	49.20 FL	*49.20 FL
18	1		*BOOTLID EMBLEM-ATTRAGE	Necessary	26.40 FL	*26.40 FL
19	1		*BOOTLID EMBLEM-ICON	Necessary	54.00 FL	*54.00 FL
20	1		*BOOTLID CHROME OUTER GARNISH	Cut	219.40 FL	*219.40 FL
21	1		*BOOTLID LOCK	Bent	247.20 FL	*247.20 FL
22	1		*BOOTLID STRIKER	Bent	48.00 FL	*48.00 FL
23	2		*BOOTLID HINGE	Bent	192.00 FL	*192.00 FL
24	2		*BOOTLID ABSORBER	Not Necessary	360.00 FL	*- FL
25	1		*BOOTLID SPOILER	Deformed	614.40 FL	*614.40 FL
26	1		*SPARE TYRE TOP BOARD	Cracked	222.00 FL	*222.00 FL
27	1		*REAR FLOOR PANEL	Repair	1,087.20 FL	*- FL
28	2		*REAR FENDER	Buckled	1,716.00 FL	*1,716.00 FL
29	2		*REAR FENDER AIR VENT	Not Necessary	90.00 FL	*- FL
30	1		*BOOTLID INNER TRIM	Not Necessary	230.50 FL	*- FL
31	1		*REAR WINDSCREEN MOULDING	Necessary	48.00 FL	*48.00 FL
32	1		*REAR AIR DUCT	Cracked	40.50 FL	*40.50 FL
33	1		*REAR AIR DUCT COVER	Cracked	54.00 FL	*54.00 FL
34	1		*THIRD BRAKE LIGHT	Cut	252.00 FL	*252.00 FL
35	2		*MUD FLAP	Not Necessary	117.00 FL	*- FL
36	1		*FRONT BUMPER	Deformed	818.80 FL	*818.80 FL
37	2		*FRONT BUMPER RETAINER	Necessary	43.20 FL	*43.20 FL
38	1		*FRONT BUMPER LOWER GRILLE	Deformed	151.30 FL	*151.30 FL
39	1		*FRONT BUMPER REINFORCEMENT	Bent	350.50 FL	*350.50 FL
40	2		*FRONT BUMPER REINFORCEMENT BRACKET	Bent	312.00 FL	*312.00 FL
41	1		*FRONT TOW COVER	Cut	18.00 FL	*18.00 FL
42	1		*FRONT GRILLE	Cracked	410.55 FL	*410.55 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT GRILLE EMBLEM	Necessary	48.00 FL	*48.00 FL
44	2		*FRONT FOG LAMP	Not Necessary	609.50 FL	*- FL
45	1		*FRONT FOG LAMP COVER	O/s Cut/N/s Not Necessary	288.00 FL	*144.00 FL
46	2		*FRONT HEADLAMP	Cracked	1,978.00 FL	*1,978.00 FL
47	1		*FRONT SUPPORT PANEL	Not Necessary	1,147.70 FL	*- FL
48	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	130.00 FL	*- FL
49	1		*AIRCON CONDENSER	Bent	899.30 FL	*899.30 FL
50	1		*AIRCON FAN COWLING	Not Necessary	237.60 FL	*- FL
51	1		*AIRCON FAN MOTOR	Not Necessary	198.00 FL	*- FL
52	1		*RADIATOR	Not Necessary	967.15 FL	*- FL
53	1		*RADIATOR FAN COWLING	Not Necessary	237.60 FL	*- FL
54	1		*RADIATOR FAN MOTOR	Not Necessary	319.70 FL	*- FL
55	1		*BONNET	Bent	1,200.30 FL	*1,200.30 FL
56	1		*BONNET INSULATOR	Deformed	101.50 FL	*101.50 FL
57	1		*BONNET HINGE	Repair	98.00 FL	*- FL
58	1		*BONNET CABLE	Not Necessary	59.00 FL	*- FL
59	2		*FRONT FENDER	Bent	1,988.00 FL	*1,988.00 FL
60	1		*KEYLESS SENSOR SPEAKER	Cracked	241.50 FL	*241.50 FL
61	1		*REAR NUMBER PLATE	Bent	50.00 FS	*45.00 FS
62	1		*SET REVERSE SENSOR	Not Working	400.00 FS	*200.00 FS
63	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
64	1		*FLOOR INSULATOR	Not Necessary	150.00 FS	*- FS
65	1		*SET END PANEL TOP GARNISH CLIP	Necessary	60.00 FS	*20.00 FS
66	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
67	1		*WINDSCREEN SEALANT	Necessary	150.00 FS	*60.00 FS
68	1		*JOINT SEALANT	Necessary	150.00 FS	*50.00 FS
69	1		*SET FRONT BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
70	1		*SET SUPPORT PANEL TOP GARNISH CLIP	Not Necessary	60.00 FS	*- FS
71	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*45.00 FS
72	1		*COOLANT	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 25,447.90 17,190.45
 - List Item Discount on L Items 10.00/10.00% (\$\$) 2,402.79 1,671.05

Total Parts (\$\$) 23,045.11 15,519.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK FRONT & REAR WIRING AND LIGHTING SYSTEM	New	200.00	60.00
2	REMOVE AND REFIT RAER LINING,TRIM AND GARNISH	New	200.00	60.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	30.00
4	REMOVE AND RENEW REAR EXHAUST ASSY	New	150.00	60.00
5	REMOVE AND REFIT FUEL TANK	New	150.00	80.00
6	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
7	REMOVE AND RENEW FLOOR INSULATOR	New	150.00	60.00
8	TRANSFER PARTS,ATTACHMENT FROM OLD BOOTLID TO NEW	New	150.00	60.00
9	REMOVE AND RENEW RADIATOR AND TOP UP COOLANT	New	200.00	100.00
10	REMOVE AND RENEW CONDENSER AND TOP UP GAS	New	200.00	100.00
11	PANEL BEATING ON AFFECTED AREAS	New	3,000.00	2,000.00
12	SPRAY PAINTING ON AFFECTED AREAS	New	3,000.00	2,400.00
13	APPLY ANTI-RUST ON AFFECTED AREAS	New	200.00	100.00
Gross Labour Cost (S\$)			7,900.00	5,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >