

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Jul 2019 Edit Reg		25 Jul 2019 00:00 Edit Adj Rpt	S\$2,064.12 Edit Estimates	S\$2,064.12 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: BMS Marble & Granite Specialist , Co. Reg. No.: 41695300W									
Main Claimant: SMRT TAXIS PTE LTD , Co. Reg. No.: 198905369K									
Vehicle Reg. No.:	SHF185Z	Date of Loss:	24/07/2019 08:00 - :59 [19 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1654294983SG	Policy/Cover Note No.:	2100484718-02 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	GBA6260Y	Policy No. (Claimant):	D-19093197MFSH						
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 06/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (06/03/2020): Alert - Adj Mandate Approved (S\$2925.67) - SHF185Z - Claim Handler: Tan, Bennie-... - AIG_SG_EXPRESS (16/01/2020): Alert - Adj Mandate Maintained - SHF185Z - Claim Handler: Tan, Bennie-WZ - AIG_SG (29/07/2019): Re: No Policy Found - AIG_SG (29/07/2019): No OI GIA Report - AIG_SG (29/07/2019): No Policy Found									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHF185Z (1654294983SG)**
[GBA6260Y]
TP
SMRT TAXIS PTE LTD
Jul 24 2019 8:30AM
[BMS Marble & Granite Specialist]
SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Video			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/08/19 16:04	TP VIDEO	Load MP4	
2	13/08/19 16:04	Video - Accident TP VIDEO	Load MP4	
Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit	
Assessment Reports			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/11/19 16:22	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/08/19 19:31	General View	Load JPG	✓
2	05/08/19 19:31	General View	Load JPG	✓
3	05/08/19 19:31	General View	Load JPG	✓
4	05/08/19 19:31	Odometer Reading	Load JPG	✓
5	05/08/19 19:31	Chassis Number	Load JPG	✓
6	05/08/19 19:31	General View	Load JPG	✓
7	05/08/19 19:31	General View	Load JPG	✓
8	05/08/19 19:31	General View	Load JPG	✓
9	05/08/19 19:31	General View	Load JPG	✓
10	05/08/19 19:31	General View	Load JPG	✓
11	05/08/19 19:31	General View	Load JPG	✓
12	05/08/19 19:31	General View	Load JPG	✓
13	05/08/19 19:31	General View	Load JPG	✓
14	05/08/19 19:31	General View	Load JPG	✓
15	05/08/19 19:31	General View	Load JPG	✓
16	05/08/19 19:31	General View	Load JPG	✓
17	05/08/19 19:31	General View	Load JPG	✓
18	05/08/19 19:31	General View	Load JPG	✓
19	05/08/19 19:31	General View	Load JPG	✓
20	05/08/19 19:31	General View	Load JPG	✓
21	05/08/19 19:31	General View	Load JPG	✓
22	05/08/19 19:31	General View	Load JPG	✓
23	05/08/19 19:31	General View	Load JPG	✓
24	05/08/19 19:31	Reinspection Photo	Load JPG	✓
25	05/08/19 19:31	Reinspection Photo	Load JPG	✓
26	05/08/19 19:31	Reinspection Photo	Load JPG	✓
27	05/08/19 19:31	Reinspection Photo	Load JPG	✓
28	05/08/19 19:31	Reinspection Photo	Load JPG	✓
29	05/08/19 19:31	Reinspection Photo	Load JPG	✓

Video			1 per page ▼	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page ▼	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/07/19 17:33	TP ESTIMATE- MARKED	Load PDF	
2	26/07/19 17:33	TP GIA REPORT.	Load PDF	
3	30/07/19 10:53	Non reporting letter.	Load PDF	
4	13/08/19 10:52	EMAIL TO OI	Load PDF	
5	12/11/19 16:08	TP ESTIMATE MARKED (FINAL)	Load PDF	
6	12/11/19 16:20	LOD	Load PDF	
7	12/11/19 16:21	FINAL REPAIR TAX INVOICE, RENTAL SUPPORTING DOCS, LTA SEARCH	Load PDF	
8	23/01/20 10:06	LTA SEARCH	Load PDF	
9	23/01/20 10:06	RENTAL MILEAGE	Load PDF	
10	23/01/20 10:06	RENTAL RECEIPT	Load PDF	
11	30/04/20 10:53	Authorisation to Act	Load PDF	
12	30/04/20 10:53	Release Voucher	Load PDF	
13	30/04/20 10:53	WORKSHOP INVOICE	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	06/08/19 14:42	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBA6260Y (Insd veh)	Model:	TOYOTA PRIUS TAXI 1.8 (A)
	SHF185Z (TP veh)		
Date of Accident:	24/07/2019		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:\$	9,427.10	
Final Repair Cost	:\$	2,900.00	
Loss of Use	:\$	5.00 days at \$50.00 per day	
Rental (if any)	:\$	5 days	
LTA / GIA Search Fee	:\$		
Others:	:\$		
	:\$		
Final Settlement Sum (GLOBAL SUM)	:\$	2,900.00	
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	SMRT TAXIS PTE LTD	:\$	2,900.00
2)		:\$	
3)		:\$	
4)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

30 Apr
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG19013184/EKA3S2**Date:** 30/04/2020**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100484718-02
Claimant Vehicle No :	SHF185Z	Insured Vehicle No :	GBA6260Y
Date of Loss:	24/07/2019	Nature of Claim:	TP
		Claim No:	1654294983SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHF185Z	Engine No:	2ZR8281124
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKB3FU903578997
Reg. Date:	19/12/2017 (Man. Year: 2017)	Odometer:	214368 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,035.10	1,184.12	5,850.98	83.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,392.00	880.00	1,512.00	63.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	9,427.10	2,064.12	7,362.98	78.10
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$120.91/day) (S\$)		604.55		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		2,925.67		
Global Sum Settlement (S\$)		2,900.00		

INSPECTION

Date of Assignment:	25/07/2019	
Date Inspected:	25/07/2019	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Khanchna Pothuraj*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER, FR BUMPER (DISC 25%)	Broken	495.50 F	*371.63 F
2	1		*CLIPS PIECE, FRT & RR (DISC 25%) 10pcs	Necessary	15.00 F	*11.25 F
3	1		*SUPPORT, FR BUMPER LH (DISC 25%)	Broken	82.30 F	*61.73 F
4	1		*FENDER SUB-ASSY, FR, LH (DISC 25%)	Dented	933.10 F	*699.83 F
5	1		*EMBLEM, SIDE PANEL (HYBRID) (DISC 25%)	Necessary	52.90 F	*39.68 F
6	1		*COVER ASSY, ENGINE	Not Necessary	180.10 F	*- F
7	1		*LAMP ASSY, FOG, LH	Not Necessary	910.20 F	*- F
8	1		*UNIT HEADLAMP, LH	Not Necessary	2,558.90 F	*- F
9	1		*LINER, FR FENDER, LH	Not Necessary	194.30 F	*- F
10	1		*PAD, FR WHEEL LH	Not Necessary	57.70 F	*- F
11	1		*WHEEL, DISC FRONT	Not Necessary	1,555.10 F	*- F
					Total Parts (\$\$)	7,035.10 1,184.12

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK.	New	676.00	400.00
2	SPRAY PAINT.	New	936.00	400.00
3	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	20.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA.	New	100.00	20.00
5	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	New	120.00	0.00
6	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).	New	120.00	0.00
7	TO REMOVE AND REFIT WIRE HARDESS.	New	200.00	20.00
8	TO REPLACE SUNDRY PARTS.	New	100.00	20.00
9	TO WASH AND VACUUM.	New	60.00	0.00
Gross Labour Cost (S\$)			2,392.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >