

Case Details

Case Reference Number : TAX/07/19/2091

Type of Repair : Accident Repair

Vehicle Registration Number : SHF185Z

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-7791-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd

Accident Date and Time : 24/07/2019 01:00 AM

Vehicle Age(In Months) : 19

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace ▾	
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace ▾	
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	1	61.72	Replace ▾	
One Time Key In	Main			COVER ASSY, ENGINE	1	180.10	180.10	25.00	135.07	Replace	0	0	Not Given ▾	
One Time Key In	Main			LAMP ASSY, FOG, LH	1	910.20	910.20	10.00	819.18	Replace	0	0	Check ▾	
One Time Key In	Main			UNIT, HEADLAMP , LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Check ▾	
One Time Key In	Main			FENDER SUB-ASSY, FR , LH	1	933.10	933.10	25.00	699.83	Replace	1	699.83	Replace ▾	
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67	Replace ▾	
One Time Key In	Main			LINER, FR FENDER, LH	1	194.30	194.30	25.00	145.73	Replace	0	0	Not Given ▾	
One Time Key In	Main			PAD, FR WHEEL LH	1	57.70	57.70	25.00	43.28	Replace	0	0	Not Given ▾	
One Time Key In	Main			WHEEL, DISC FRONT	1	1,555.10	1,555.10	25.00	1,166.32	Replace	0	0	Not Given ▾	
Total Spare Part Cost									5,796.69	Surveyor Total			1,184.10	
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)			0	
Final Spare Part Cost									5,796.69	Final Sur Total			1,184.10	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
-------	--------------	-----------	-------------------------	-------------------------	---------

			Recommendation(\$)	Adjustment(\$)	
1	Main	TO REPAIR FRONT LH PORTION	676.00	400	
Total:			676.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
3	Main	TO RESPRAY RIM	180.00	0	
Total:			936.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
4	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0	
5	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	20	
6	Main	TO REPLACE SUNDRY PARTS	100.00	20	
7	Main	TO WASH AND VACUUM	60.00	0	
Total:			780.00	80.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	5,796.69	1,184.10
Total Labour Cost	676.00	400.00
Total Spray Painting	936.00	400.00
Other	780.00	80.00
Overall Total	8,188.69	2,064.10
Lump Sum Repair Option		☐
Lump Sum Total	0.00	2,064.10
Surveyor Approved Amount		2,064.10
No of Repair Days*	5	4
Remarks	-	P/P repair, take before spray. Finalize sent to stevechen@lkkauto.com

Surveyor Name

STEVE CHEN

Signature



Save

Clear

Survey Date

25/07/2019

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: