

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

MCQUEEN RENTALS PTE LTD

c/o 46 Lentor Plain
Singapore 786548

Not Authorised
1/1 Sep 87
Pharmy After Repair
4-5 days

Date: 25/7/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: MAZDA 3 / SLJ 9029 P	
1 pc	rear boot lid	<i>Per</i> 1,018.30 ✓
1 pc	rear boot emblem logo	<i>Per</i> 82.60 ✓
1 pc	rear boot emblem " MAZDA 3 "	<i>Per</i> 63.80 ✓
1 pc	rear boot emblem "SKYACTIVE TECHNOLOGY"	<i>Per</i> 75.60 ✓
1 pc	rear boot lock	<i>Per</i> 291.30 X
1 pc	rear boot weatherstrip	<i>Per</i> 326.80 X
2 pcs	rear boot lamp @ 296.80	<i>Per</i> 593.60 X
1 pc	rear bumper reinforcement	583.60 7
1 pc	rear bumper	<i>Per</i> 1,178.60 ✓
1 pc	end panel garnish	328.60 7
1 pc	end panel	369.20 7
	Sub-total	4,912.00
	Less 15%	736.80
	Sub-total	4,175.20
1 set	reverse sensor s.nett	<i>Per</i> 220.00 X
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	600.00 ?
	To install reversensor.	<i>500</i> 80.00
	To check wiring system.	<i>150</i> 50.00
	To apply putty and spray painting on affected areas.	<i>500</i> 600.00
	To apply waterproof sealant on affected areas.	<i>200</i> 80.00
	To apply rust proofing on affected areas.	<i>?</i> 80.00
	Total	5,885.20

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: