

Date: 25.07.2019
Vehicle No: SFZ9595H
Model: MERCEDES BENZ E250 A
Chassis: WDD2120362A867588 - 2013
Reg.Year: 2014

Third Party Insurer: EQ
Third Party Veh No: GV8690G
Date of Accident: 24.07.2019

ESTIMATE

Not Notarized
61 Pm 25400 Vdc
4 day
Repair After Paint

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1		<i>Pr</i> \$1,276.50
2	FRONT BUMPER PARKING SENSOR LH	1		<i>Pr</i> \$194.25
3	FRONT BUMPER SIDE BRACKET LH	1		<i>Pr</i> \$52.20
4	FRONT BUMPER SIDE RETAINER LH	1		<i>Pr</i> \$74.00
5	FRONT BUMPER CLIP	12	<i>Pr</i> \$6.50	\$78.00
6	FRONT HEAD LAMP ASST LH <i>3815</i>	1		<i>Pr</i> \$4,070.00
7	FRONT FENDER LH	1		<i>Pr</i> \$906.50
8	FRONT FENDER INNER LINER LH	1		<i>Pr</i> \$170.20
9	FRONT FENDER INNER LINER CLIP LH	10	\$6.80	<i>Pr</i> \$68.00
10	FRONT FENDER LOWER CHROME MOULDING LH <i>Pr?</i>	1	<i>43.00</i>	<i>Pr</i> \$412.65
SUB TOTAL				\$7,302.30
LESS 10%				-\$730.23
PARTS TOTAL				\$6,572.07

7,005.80
- 700.50
6,305.30

LABOUR CHARGES:

LABOUR CHARGES FOR KNOCKING, REPAIR, REPLACE, READJUST FRONT ACCIDENT AREAS & ETC

\$400.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER LH & ETC

\$600.00

TO CHECK ELECTRICAL WIRING & TO DIAGNOSIS FRONT PARKING SENSOR & ETC

\$120.00

LABOUR TOTAL \$1,120.00

ONG

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

TOTAL \$7,692.07

P - \$6,305.30
L - \$1,050.00

\$7,355.30 - 20%

415 \$5,850

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 Fax: (+65) 6452 9223

