

Date: 25.07.2019
Vehicle No: SFZ9595H
Model: MERCEDES BENZ E250 A
Chassis: WDD2120362A867588 - 2013
Reg.Year: 2014

Third Party Insurer: EQ
Third Party Veh No: GV8690G
Date of Accident: 24.07.2019

Not Notarised

LI Pump & ?

4 day recovery After Paint

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1		<i>Br</i> \$1,276.50
2	FRONT BUMPER PARKING SENSOR LH	1		<i>Br</i> \$194.25
3	FRONT BUMPER SIDE BRACKET LH	1		\$52.20
4	FRONT BUMPER SIDE RETAINER LH	1		\$74.00
5	FRONT BUMPER CLIP	12	<i>Br</i> \$6.50	\$78.00
6	FRONT HEAD LAMP ASST LH	1		<i>Br</i> \$4,070.00
7	FRONT FENDER LH	1		<i>Br</i> \$906.50
8	FRONT FENDER INNER LINER LH	1		\$170.20
9	FRONT FENDER INNER LINER CLIP LH	10	\$6.80	<i>Br</i> \$68.00
10	FRONT FENDER LOWER CHROME MOULDING LH <i>Pr?</i>	1		<i>Br</i> \$412.65
SUB TOTAL				\$7,302.30
LESS 10%				-\$730.23
PARTS TOTAL				\$6,572.07

LABOUR CHARGES:

LABOUR CHARGES FOR KNOCKING, REPAIR, REPLACE, READJUST FRONT ACCIDENT AREAS & ETC

\$400.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER LH & ETC

\$600.00

TO CHECK ELECTRICAL WIRING & TO DIAGNOSIS FRONT PARKING SENSOR & ETC

\$120.00

LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:		LABOUR TOTAL	\$1,120.00
ONG		TOTAL	\$7,692.07