

22002002

ASS. REC. BY
Envelope: Rasul

REF: CS/CT119013200/Rlyf30r Special Instruction:

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTI Date/Time: 26/7/19 @ 1.46pm

Estimated Cost: _____ Bill to: _____

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SF U 7737E Insured: PC 6429C

at Workshop m/s Koh Motor Tel: 8288 6309

of No. 255 Alexandra Road

Policy No: _____ Claim No: SNM19D203483

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 25/7/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____

Date/Time: 2:10pm @ 26/7/19 Person Contacted: Jack Vehicle IN / ~~OUT~~

Date/Time	Action/Instruction
	<u>Estimate ✓</u>
	<u>SFR 7737E X</u>
	<u>PC 6429C NBA/CT119013172/4 DOA = 25/7/19</u>
<u>13/9/19</u>	<u>Confirmed amt \$ 7,401.12 / 6 days (Red = \$5649-23,43%)</u>

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Monday, September 16, 2019 3:45 PM
To: Jack Ng; Rasul (LKKAuto)
Cc: SUR
Subject: FINALIZATION FOR SFU 7737 E

Hi Jack

WITHOUT PREJUDICE

Confirm Total \$7,401.12 before GST @ 6 working days.

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jack Ng [mailto:jackng@honda.com.sg]
Sent: Monday, September 16, 2019 1:14 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Subject: RE: FINALIZATION FOR SFU 7737 E
Importance: High

REMINDER. WILL BE CLOSING BY NEXT WEEK.

If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank you and have a great days ahead

Cheers !!!

Best Regards,

Jack Ng

Hp: 8288 6309

Email: Jackng@honda.com.sg

BODY REPAIR AND PAINT CENTRE

Yvonne Wong (LKK Auto)

From: Jack Ng <jackng@honda.com.sg>
Sent: Wednesday, September 04, 2019 9:20 AM
To: Rasul (LKKAuto)
Cc: Shiau Chan (LKKAuto); Asher Sng (LKKAuto)
Subject: FINALIZATION FOR SFU 7737 E
Attachments: 4489_001.pdf; Resurvey B4 Paint _ SFU 7737 E

Importance: High

Dear Rasul,

We enclosed the total final repair costs for,

Vehicle No.	SFU 7737 E
Final Repair Costs (exclude GST)	S\$7,401.12
Repair Period* (Days)	6 WORKING DAYS

***Note: Repair period does NOT include Sunday and Public Holiday.**

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

In addition, I have attached photos of before paint, '?' items and supplementary parts (if any) for your records.

Thank you and have a great days ahead

Cheers !!!

Best Regards,

Jack Ng

Hp: 8288 6309

Email: Jackng@honda.com.sg

BODY REPAIR AND PAINT CENTRE

255 Alexandra Road Singapore 159937

DID : +65 6514 5481 FAX : +65 6362 5015

Kah Motor Co. Sdn. Bhd.

(A MEMBER OF ORIENTAL HOLDING BERHAD)

Website: www.honda.com.sg



Visit our
Facebook page

 **Please consider the environment before printing this email**

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 26 July 2019 1:46 PM
To: Jack Ng
Cc: assignments
Subject: RE: OUR REF: SNM19D203483-PC6429C-TAYHP -& YR REF: SFR7737E - ACCIDENT BETWEEN SFU 7737 E AND PC 6429 C ON 25.07.19

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Jack Ng [mailto:jackng@honda.com.sg]
Sent: Friday, 26 July, 2019 11:26 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D203483-PC6429C-TAYHP -& YR REF: SFR7737E - ACCIDENT BETWEEN SFU 7737 E AND PC 6429 C ON 25.07.19

Dear Boon Sen,

Kindly arrange LKK for this case.

Thank you and have a great days ahead

Cheers !!!

Best Regards,
Jack Ng
Hp: 8288 6309
Email: Jackng@honda.com.sg

BODY REPAIR AND PAINT CENTRE
255 Alexandra Road Singapore 159937
DID : +65 6514 5481 FAX : +65 6362 5015
Kah Motor Co. Sdn. Bhd.
(A MEMBER OF ORIENTAL HOLDING BERHAD)
Website: www.honda.com.sg



Visit our
Facebook page

 Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 26 July 2019 11:25 AM
To: Jack Ng <jackng@honda.com.sg>
Subject: RE: OUR REF: SNM19D203483-PC6429C-TAYHP -& YR REF: SFR7737E - ACCIDENT BETWEEN SFU 7737 E AND PC 6429 C ON 25.07.19

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen
Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Angie Foo

Sent: Friday, 26 July, 2019 11:19 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>;
jackng@honda.com.sg

Cc: Lim Shu Min <shumin.lim@sg.cntaiping.com>

Subject: OUR REF: SNM19D203483-PC6429C-TAYHP -& YR REF: SFR7737E - ACCIDENT BETWEEN SFU 7737 E AND PC 6429 C ON 25.07.19

Dear Boon Sen

Please assist Irene Tay to conduct PRS- SFU7737E & revert liability. Our Insured had not filed SAS Report.

File with Boon Sen for assignment.

Officer In Charge –Irene Tay -6389 6192

Regards

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
TEL: (65) 63896116 - F: (65) 6224 7478

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Jack Ng [<mailto:jackng@honda.com.sg>]

Sent: Thursday, 25 July, 2019 7:14 PM

To: DL-CLAIMS

Cc: Alfred Toh; Chong Boon Sen; Irene Tay

Subject: ACCIDENT BETWEEN SFU 7737 E AND YOUR INSURED PC 6429 C

Dear all,

Kindly assist to register for direct settlement, attached is the GIA report.

Thank you and have a great days ahead

Cheers !!!

Best Regards,

Jack Ng

Hp: 8288 6309

Email: Jackng@honda.com.sg

BODY REPAIR AND PAINT CENTRE

255 Alexandra Road Singapore 159937

DID : +65 6514 5481 FAX : +65 6362 5015

Kah Motor Co. Sdn. Bhd.

(A MEMBER OF ORIENTAL HOLDING BERHAD)

Website: www.honda.com.sg



Visit our
Facebook page

 Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/07/2019 19:00
Date Of Accident	25/07/2019 10:50
Exact Location Of Accident	ORCHARD ROAD AT PLAZA SINGPURA BUS STOP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFU7737E
Insured/Policyholder	
Name Of Registered Owner	NG WHEE CHENG
NRIC No	S1726235A
Email Address	JOREEN_DEW@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96692072
Alternative Phone No	OFFICE-96692072

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO

Policy Number

Cover Note Number

Driver

Name of Driver	ANG SWEE HENG
NRIC No	S9319649Z
Date Of Birth	07/06/1993
Occupation	INDOOR
Date Of Driving Pass	21/08/2013
Driving Experience	5 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91820798
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 234 BUKIT PANJANG RING ROAD
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC6429C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Vehicle Number: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 25/7/19 at 13:47, my vehicle SFU7737 E was stopping at the red light junction ~~at~~ at Plaza Singapura bus stop. Bus number PC 6429 C was behind my vehicle and did not stop completely, making contact with the rear of my vehicle.

No injured in this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SFU7737E
Chassis No : JHMGK3850JX222813
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : NG WHEE CHENG
Ins Policy No. :
Date of Accident : 25/7/2019

Document No. : SQT19003356 **Page** 1
Date : 31. Jul 2019
Customer No. : WZC008
Svc Advisor : JACK NG
Engine No : L13B11030786
Date | Time : 31. Jul 2019 8:47:16 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:NG WHEE CHENG OWNER INSURER:TOKIO MARINE ACC DATE:25/07/2019 SURVEYED BY: DATE: REF NO: TP INSURER:CHINA TAIPING TP VEH:PC 6429 C						
04715-T5A-J50ZZ	FACE,RR.BUMPER <i>de</i>	1	492.70 ✓	5	468.06	32.76	500.82
71505-T5A-J50	GARNISH,RR.BUMPER <i>X</i>	1	38.30	5	36.38	2.55	38.93
71502-T5A-J60	COVER,R.RR.BUMPER <i>X</i> <i>src</i>	1	20.70	5	19.66	1.38	21.04
71507-T5A-J60	COVER,L.RR.BUMPER <i>X</i>	1	20.70	5	19.66	1.38	21.04
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE <i>new</i>	1	16.90 ✓	5	16.05	1.12	17.17
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE <i>new</i>	1	16.90 ✓	5	16.05	1.12	17.17
91505-TM8-003	CLIP,BUMPER <i>new</i>	7	2.30 ✓	5	15.29	1.07	16.36
66100-TAR-T00ZZ	PANEL COMPR. <i>new</i> <i>X repair</i>	1	320.40	5	304.38	21.31	325.69
68100-T5A-U10ZZ	TAIL GATE COMP <i>bd</i>	1	730.60 ✓	5	694.07	48.58	742.65
74440-T5A-003	WEATHERSTRIPTAILGATE <i>X src</i>	1	92.30	5	87.68	6.14	93.82
73127-TY0-000	RUBBER CWINDSHIELD DAMPER <i>new</i>	1	11.40 ✓	5	10.83	0.76	11.59
73214-T5A-013	RUBBERWINDSHIELD DAMPER <i>new</i>	2	6.50 ✓	5	12.35	0.86	13.21
73226-SZW-000	DAMPERSTD 5X5 <i>new</i>	1	8.50 ✓	5	8.07	0.56	8.63
	Sum Item				1708.53	119.59	1,828.12
BOSUN	SUNDRIES	1	100.00 <i>50</i>		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	150.00 <i>120</i>		150.00	10.50	160.50
BOJSE	BODY JOINT SEALANT.	1	150.00 <i>X N</i>		150.00	10.50	160.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	380.00 <i>280</i>		380.00	26.60	406.60

Printed on 31/7/2019 8:57:34 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SFU7737E
Chassis No : JHMGK3850JX222813
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : NG WHEEL CHENG
Ins Policy No. :
Date of Accident : 25/7/2019

Document No. : SQT19003356
Date : 31. Jul 2019
Customer No. : WZC008
Svc Advisor : JACK NG
Engine No : L13B11030786
Date | Time : 31. Jul 2019 8:47:16 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BA02R	REMOVE & REINSTALL REVERSE SENSORS-4 PCS (N)	1	380.00		380.00	26.60	406.60
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA (N)	1	450.00		450.00	31.50	481.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM(N)	1	450.00		450.00	31.50	481.50
BODAMKIT	WINDSCREEN DAM KIT.	1	200.00	150	200.00	14.00	214.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	800.00	280	800.00	56.00	856.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00	280	800.00	56.00	856.00
BKRP02M	CUT OFF & RENEW RR PANEL. NEW ALL DAMAGE PARTS	1	5000.00	1680	5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3500.00	1350	3500.00	245.00	3745.00
Sum Labor					12920.00	904.40	13,824.40

Survey By

RASUL - Hp 90010068

Date & Time

05/08/19 @ 1355

Excess

Status

Signature

[Signature]

5-6 days

Resurvey before paint

Total Amount 14,628.53 1,023.99 15,652.52
Total (Inclusive of GST) 15,652.52

114798.88

Printed on 31/7/2019 8:57:34 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0052626 / NG WHEE CHENG
Chassis No: JHMGK3850JX222813
License No: SFU7737E
Mileage: 11946
Engine No: L13B11030786

Document No: SVO19050254
Printed By: JACKNG
Order Date: 5. August 2019
Order Time: 1:59:55 PM
Service Advisor: JACK NG

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incl GST
75722-T5L-T01	EMBLEMRR. <i>NA</i>	1	10.90	<i>25</i>	<i>8.1705</i>	0.57	8.74
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>NA</i>	2	60.00		120.00	8.40	128.40
SUM PARTS:					128.17	8.97	137.14
TOTAL SGD					<i>128.17</i>	8.97	137.14
Total Payable (SGD)					<i>130.95</i>		137.14

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0052626 / CHINA TAIPING
 Chassis No: JHMGK3850JX222813
 License No: SFU7737E
 Mileage: 11946
 Engine No: L13B11030786

Document No: SVO19050254
 Printed By: JACKNG
 Order Date: 5. August 2019
 Order Time: 1:59:55 PM
 Service Advisor: JACK NG

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:NG WHEE CHENG OWNER INSURER:TOKIO MARINE ACC DATE:25/07/2019 SURVEYED BY: DATE: REF NO: TP INSURER:CHINA TAIPING TP VEH:PC 6429 C SUPPLEMENTARY PART						
04715-T5A-J50ZZ	FACE,RR.BUMPER	1	492.70 ✓	5	468.06	32.76	500.82
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	16.90 ✓	5	16.05	1.12	17.17
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	16.90 ✓	5	16.05	1.12	17.17
91505-TM8-003	CLIP,BUMPER	7	2.30 ✓	5	15.29	1.07	16.36
68100-T5A-U10ZZ	TAIL GATE COMP	1	730.60 ✓	5	694.07	48.58	742.65
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.40 ✓	5	10.83	0.76	11.59
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.50 ✓	5	12.35	0.86	13.21
73226-SZW-000	DAMPERSTD 5X5	1	8.50 ✓	5	8.07	0.56	8.63
75722-T5L-T01	EMBLEMRR.	1	10.90 (5) ✓	5	10.35	0.72	11.07
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00 (5) ✓		120.00	8.40	128.40
	SUM PARTS:				1,371.12	95.95	1,467.07
BOSUN	1438 SUNDRIES	1	50.00 ✓		50.00	3.50	53.50
BOJSE	1438 BODY JOINT SEALANT FOR TAILGATE	1	120.00 ✓		120.00	8.40	128.40
BML02I	1438 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	280.00 ✓		280.00	19.60	299.60
BA02R	1466 REMOVE & REINSTALL REVERSE SENSORS-4 PCS (N)	1	380.00 ✓		380.00	26.60	406.60
BC011R	1466 REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA(N)	1	450.00 ✓		450.00	31.50	481.50
BC012R	1438 RESET VEHICLE SMART ENTRY SYSTEM (N)	1	450.00 ✓		450.00	31.50	481.50
BODAMKIT	1438 WINDSCREEN DAM KIT.	1	150.00 ✓		150.00	10.50	160.50
BG02R	1438 REPLACE RR. WINDSCREEN.(N)	1	560.00 ✓		560.00	39.20	599.20
BKTG02R	1466 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	280.00 ✓		280.00	19.60	299.60
BMI03D	1438 REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	280.00 ✓		280.00	19.60	299.60

**HONDA****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICEGST Reg No.: M200050223
Company Ref. No.: S60FC1380G**Customer:** CU0052626 / CHINA TAIPING
Chassis No: JHMGK3850JX222813
License No: SFU7737E
Mileage: 11946
Engine No: L13B11030786**Document No:** SVO19050254
Printed By: JACKNG
Order Date: 5. August 2019
Order Time: 1:59:55 PM
Service Advisor: JACK NG

BKRP02M	1466 CUT OFF & RENEW RR PANEL. NEW ALL DAMAGE PARTS FLOOR PANEL INCLUDING FITTINGS ON ATTACHMENT ITEM	1	1,680.00 /	1,680.00	117.60	1,797.60
BP06R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	1,350.00 /	1,350.00	94.50	1,444.50
SUM LABOUR:				6,030.00	422.10	6,452.10
TOTAL SGD				7,401.12	518.05	7,919.17
Total Payable (SGD)						7,919.17

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Aug 2019		13 Aug 2019 11:07 Edit Adj Rpt	S\$7,401.12 Edit Estimates	S\$7,401.12 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	-, Co. Reg. No.: -		
Main Claimant:	NG WHEE CHENG, ID: S1726235A		
Vehicle Reg. No.:	SFU7737E	Date of Loss:	25/07/2019 10:00 - :59 [13 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D203483C02	Policy/Cover Note No.:	DMB1SN18259318000
Vehicle Reg. No. (Insured):	PC6429C	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 22/08/2019]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

*SFU7737E (SNM19D203483C02)
 [PC6429C]
 TP
 NG WHEE CHENG
 Jul 25 2019 10:00AM
 [-]
 Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser	
Video										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)					Thumbnail		Print		
1	25/07/19 19:11	Video - Accident [Linked Accident Report Documents]						Load AVI			
2	25/07/19 19:11	Video - Accident [Linked Accident Report Documents]						Load AVI			
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)					Thumbnail		Print		
1	25/07/19 19:11	Accident Statement						Load HTM			
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)					Thumbnail		Print		
1	25/07/19 19:10	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
2	25/07/19 19:10	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
3	25/07/19 19:10	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
4	25/07/19 19:10	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
5	25/07/19 19:10	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
6	25/07/19 19:10	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
7	25/07/19 19:10	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
8	25/07/19 19:10	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
9	25/07/19 19:10	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
10	25/07/19 19:10	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
11	25/07/19 19:10	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
12	25/07/19 19:10	Accident Photo [Linked Accident Report Documents]						Load JPG	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print		
1	16/09/19 18:01	General View						Load JPG	<input checked="" type="checkbox"/>		
2	16/09/19 18:01	General View						Load JPG	<input checked="" type="checkbox"/>		
3	16/09/19 18:01	General View						Load JPG	<input checked="" type="checkbox"/>		
4	16/09/19 18:01	General View						Load JPG	<input checked="" type="checkbox"/>		
5	16/09/19 18:01	General View						Load JPG	<input checked="" type="checkbox"/>		
6	16/09/19 18:01	General View						Load JPG	<input checked="" type="checkbox"/>		
7	16/09/19 18:01	General View						Load JPG	<input checked="" type="checkbox"/>		
8	16/09/19 18:01	General View						Load JPG	<input checked="" type="checkbox"/>		
9	16/09/19 18:01	General View						Load JPG	<input checked="" type="checkbox"/>		
10	16/09/19 18:01	General View						Load JPG	<input checked="" type="checkbox"/>		
11	16/09/19 18:01	General View						Load JPG	<input checked="" type="checkbox"/>		
12	16/09/19 18:01	General View						Load JPG	<input checked="" type="checkbox"/>		
13	16/09/19 18:01	General View						Load JPG	<input checked="" type="checkbox"/>		
14	16/09/19 18:01	General View						Load JPG	<input checked="" type="checkbox"/>		
15	16/09/19 18:01	General View						Load JPG	<input checked="" type="checkbox"/>		
16	16/09/19 18:01	General View						Load JPG	<input checked="" type="checkbox"/>		
17	16/09/19 18:01	General View						Load JPG	<input checked="" type="checkbox"/>		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
18	16/09/19 18:01	General View		Load JPG <input checked="" type="checkbox"/>
19	16/09/19 18:01	General View		Load JPG <input checked="" type="checkbox"/>
20	16/09/19 18:01	General View		Load JPG <input checked="" type="checkbox"/>
21	16/09/19 18:01	General View		Load JPG <input checked="" type="checkbox"/>
22	16/09/19 18:02	General View		Load JPG <input checked="" type="checkbox"/>
23	16/09/19 18:02	General View		Load JPG <input checked="" type="checkbox"/>
24	16/09/19 18:02	General View		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	25/07/19 19:10	Sketch Plan <small>[Linked Accident Report Documents]</small>		Load TIF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/10/19 10:52	Supplementary		Load PDF

Linked Accident Report Documents

			View	View in Browser
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	25/07/19 19:11	Video - Accident		Load AVI
2	25/07/19 19:11	Video - Accident		Load AVI
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	25/07/19 19:11	Accident Statement		Load HTM
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	25/07/19 19:10	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	25/07/19 19:10	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	25/07/19 19:10	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	25/07/19 19:10	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	25/07/19 19:10	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	25/07/19 19:10	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	25/07/19 19:10	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	25/07/19 19:10	Accident Photo		Load JPG <input checked="" type="checkbox"/>
9	25/07/19 19:10	Accident Photo		Load JPG <input checked="" type="checkbox"/>
10	25/07/19 19:10	Accident Photo		Load JPG <input checked="" type="checkbox"/>
11	25/07/19 19:10	Accident Photo		Load JPG <input checked="" type="checkbox"/>
12	25/07/19 19:10	Accident Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	25/07/19 19:10	Sketch Plan		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19013200/R1YF3E2

Date: 04/10/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMB1SN18259318000	
Claimant Vehicle No : SFU7737E	Insured Vehicle No : PC6429C	
Date of Loss: 25/07/2019	Nature of Claim: TP	Claim No: SNM19D203483C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFU7737E	
Make & Model: HONDA JAZZ, 1.3 LX (GE6) (A)	Engine No: L13B11030786
Reg. Date: 08/06/2018 (Man. Year: 2018)	Chassis No: JHMGK3850JX222813
Colour: Blue	Odometer: 13075 km
Engine Capacity: 1318 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/65 R15	Rear Tyre Size: 175/65 R15
Front Left Side: Yokohama 6 mm	Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm	Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,938.88	1,421.12	517.76	26.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,820.00	5,980.00	6,840.00	53.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,758.88	7,401.12	7,357.76	49.85
+ GST 7.00/7.00% (S\$)	1,033.12	518.08	515.04	49.85
Nett Amount (S\$)	15,792.00	7,919.20	7,872.80	49.85

INSPECTION

Date of Assignment: 13/08/2019		
Date Inspected: 05/08/2019	Inspected At:	Kah Motor Co Sdn Bhd (Ubi) NO. 255 ALEXANDRA ROAD SINGAPORE 159937
Estimated Period of Repair: 6.0 days		

Adjuster: MOHD RASUL

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2019)
Parts: 144	HONDA JAZZ 1.3 LX (GE6) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SFU7737E)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE,RR.BUMPER	Deformed	468.06 FS	*468.06 FS
2	1		*GARNISH,RR.BUMPER	Serviceable	36.38 FS	*- FS
3	1		*COVER,R.RR.BUMPER	Serviceable	19.66 FS	*- FS
4	1		*COVER,L.RR.BUMPER	Serviceable	19.66 FS	*- FS
5	1		*SPACER,R.RR.BUMPER SIDE	Necessary	16.05 FS	*16.05 FS
6	1		*SPACER,L.RR.BUMPER SIDE	Necessary	16.05 FS	*16.05 FS
7	1		*CLIP,BUMPER (7PCS)	Necessary	15.29 FS	*15.29 FS
8	1		*PANEL COMPRR.	Repair	304.38 FS	*- FS
9	1		*TAIL GATE COMP	Bent	694.07 FS	*694.07 FS
10	1		*WEATHERSTRIPTAILGATE	Serviceable	87.68 FS	*- FS
11	1		*RUBBER CWINDSHIELD DAMPER	Necessary	10.83 FS	*10.83 FS
12	1		*RUBBERWINDSHIELD DAMPER (2PCS)	Necessary	12.35 FS	*12.35 FS
13	1		*DAMPERSTD 5X5	Necessary	8.07 FS	*8.07 FS
14	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
15	1		*EMBLEMRR.	Necessary	10.35 FS	*10.35 FS
16	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 1,938.88 1,421.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	BODY JOINT SEALANT	New	150.00	120.00
2	BODY JOINT SEALANT	New	150.00	0.00
3	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	New	380.00	280.00
4	REMOVE & REINSTALL REVERSE SENSORS-4 PCS	New	380.00	380.00
5	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	450.00	450.00
6	RESET VEHICLE SMART ENTRY SYSTEM	New	450.00	450.00
7	WINDSCREEN DAM KIT	New	200.00	150.00
8	REPLACE RR.WINDSCREEN	New	560.00	560.00
9	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	New	800.00	280.00
10	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	800.00	280.00
11	CUT OFF & RENEW RR PANEL. NEW ALL DAMAGE PARTS	New	5,000.00	1,680.00
12	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	New	3,500.00	1,350.00
Gross Labour Cost (\$\$)			12,820.00	5,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >