

Envelope: RCU

CWS

ASSIGNMENT (Office)

From (Person): Henry Kao

of FCI

Date/Time: 12:18pm @ 26/7/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLM 5941R

Insured: SHB 2457Y

at Workshop m/s: performance

Tel: 6319 0174

of 303 Alex and re Road

Policy No:

Claim No: D19004806MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 19/07/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

CDS

H.O.D. Endorsement:

Date/Time: 12:56pm @ 26/7/19

Person Contacted: Caroline

Vehicle-IN: OUT

Date/Time	Action/Instruction
	Estimated (✓)
	SLM 5941R X
	SHB 2457Y CC3/FCI13017012/Kgu2 OA = 4/7/13
31/7/19 @ 11:02am	Vehicle used to Henry Kao by email.
	Part by part \$4246.75 (Red: 1894.44; 30%)

ASS. REC. BY:

REF: FCI

676c

ASSIGNMENT

From: Date: 30/7/2019

Estimated Cost:

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLM 5941R
at Workshop m/s Performance Motor
of 303 Alexandria Road

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Before 12 noon
Inthiran

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{rup}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLM 5941R Yr Regn: 2017 / JAN

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 116 D C.C. 1496

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 61108 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDA 1V72050V725329

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 1"

☒ SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 19/07/19 D.O.I. 30/07/19

Survey held at PERFORMANCE

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 02 SEP 2019

Date/Time, File Pass to?

1) 219 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B. (\$) 4246.75

TP

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

145

50

50

35

280



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004806MFSH

Date: 31 July 2019

Our Ref: CS/FCI19013202/R1tf3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLM 5941R

Please be informed that we had conducted the inspection of the abovementioned vehicle on 30/07/2019 at the premises of M/s PERFORMANCE MOTORS LIMITED, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,224.20</u>
Revised Estimate Amount	: S\$ <u>3,461.05</u>
"Check" Items Amount	: S\$ <u>2,140.15</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	23-07-2019	Our Ref No. D19004806MFSH
Accident Date	19-07-2019	Claim Type. Third Party
Insured Vehicle	SHB2457Y	Third Party Vehicle. SLM5941R
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
Contact Person.	CAROLINE	
Contact No.	63190174/ 0	Fax No. 64794601
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 31 July 2019 11:02 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Henry Kao'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004806MFSH/1
Attachments: CSFCI19013202R1tf3.pdf

Dear Henry,

Enclosed herewith preliminary advice of SLM 5941R.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 26 July 2019 3:40 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004806MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer arrange on 30/07/2019.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 26 July 2019 12:18 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004806MFSH/1

Dear Sir/Mdm,

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



Survey & repair
30.7.2019
Survey before 12pm

GST REG. NO : M2 - 0020081 - X

25 JUL 2019

ESTIMATE

Estimate No. : b1 52111
Date Estimated : 25/07/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Roselle Mont-Clair Furnishing Pte Ltd
NO. 1 COMMONWEALTH LANE
#04-22/23

Singapore 149544

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLM5941R	V725329	24/01/2017	116d	0

DESCRIPTION

To replace rear bumper and attachments.

VALUE
850 ~~1,275.00~~

Painting rear bumper.

934 ~~1,038.00~~

To check electrical wiring systems and lightings at the rear section for proper function.

150 ~~177.00~~

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 ~~177.00~~

To remove and install front rear view cameras including program and conduct checks for proper function.

226 ~~266.00~~

Sundries.

net ? 80.00

No. plate \$83 ~~4~~

Total Labour 1: 3,013.00

DESCRIPTION

REAR BUMPER CARRIER ? X su
REAR BUMPER CENTRE GUIDE (M) ? X su
REAR BUMPER PRIMED (RFC) de
REAR PDC HOLDER SET ? su
HEAT INSULATOR REAR SILENCER ? X su
NUMBER PLATE LIGHT LED ? X su
DECOUPLING RING PDC TORQUE CONVERTE ? X su
RR PDC SENSOR ALPINWEISS (300) ? X su
REVERSING CAMERA ? su
(DG/SL) ADHESIVE SET K6 su

QTY	PRIC	VALUE
1	416.45	416.45
1	67.05	67.05
1	1,015.00	1,015.00
1	24.60	24.60
1	63.15	63.15
2	25.00	50.00
4	5.05	20.20
2	368.80	737.60
1	681.10	681.10
1	53.05	53.05

Total Parts : 3,128.20

6224.20

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T EEstimate No. : b1 52111
Date Estimated : 25/07/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLM5941R	V725329	24/01/2017	116d	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 30/07/19 @ 1115 Excess \$S _____

Surveyor's Name RASUL Sign _____

Surveyor's Tel 9000068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 3 days

[Signature]
31/7/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from the Insurer Company

Acknowledged by Repairer:
Signature: _____
Date: _____

641.20

Labour 1	:	3,013.00
Parts	:	3,128.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	429.88
Grand Total	:	6,571.08

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X

denise



Final Report

Estimate No. : **b1 52111**
Date Estimated : **25/07/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Roselle Mont-Clair Furnishing Pte Ltd
NO. 1 COMMONWEALTH LANE
#04-22/23

Singapore 149544

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLM5941R	V725329	24/01/2017	116d	0

DESCRIPTION	ACCOUNT:		
	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper panel including to remove and install body parts in order to carry out painting job	850.00	0	850.00
To respray rear bumper	934.00	0	934.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00	0	150.00
To remove and replace rear view cameras including program and conduct checks for proper function.	226.00	0	226.00
Sundries.	80.00	0	80.00
# To supply rear emboss number plate <i>bt</i>	83.00	0	83.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PRIMED (RFC)	1,015.00	1.00	0	1,015.00
REAR PDC HOLDER SET	24.60	1.00	0	24.60
REVERSING CAMERA	681.10	1.00	0	681.10
(DG/SL) ADHESIVE SET K6	53.05	1.00	0	53.05

DD	ADD. SENTRY	DATE	WORKING DAYS
	Rasul LKK	7/8/19	3
CONFIRM DATE			
PLEASE FIN			

Total Labour :	2,473.00
Total Parts :	1,773.75
Total Repair Costs less Excess:	4,246.75
GST @7%:	297.27
Grand Total :	4,544.02

CAR RENTAL - \$224.70
LTA SEARCH FEE - \$7.45



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19013202/R1tf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 04-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2457Y	Veh. Inspected	SLM 5941R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004806MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	26/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 116D	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBA1V72050V725329	Colour	WHITE	
Odometer	61108	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/07/2019	Inspection Date	30/07/2019	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 5941R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER CARRIER (SN)	SERVICEABLE	416.45	-
1	REAR BUMPER CENTRE GUIDE (M)(SN)	SERVICEABLE	67.05	-
1	REAR BUMPER PRIMED (RFC)(SN)	DEFORMED	1,015.00	1,015.00
1	REAR PDC HOLDER SET (SN)	NECESSARY	24.60	24.60
1	HEAT INSULATOR REAR SILENCER (SN)	SERVICEABLE	63.15	-
2	NUMBER PLATE LIGHT LED (SN)	SERVICEABLE	50.00	-
4	DECOUPLING RING PDC TORQUE CONVERTE (SN)	SERVICEABLE	20.20	-
2	RR PDC SENSOR ALPINWEISS (300)(SN)	SERVICEABLE	737.60	-
1	REVERSING CAMERA (SN)	SCRATCHED	681.10	681.10
1	(DG/SL) ADHESIVE SET K6 (SN)	NECESSARY	53.05	53.05
1	REAR EMBOSS NUMBER PLATE (ADDITIONAL)(SN)	BENT	83.00	83.00
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
			3,291.20	1,936.75
LABOUR				
	TO REPLACE REAR BUMPER AND ATTACHMENTS.		1,275.00	850.00
	PAINTING REAR BUMPER.		1,038.00	934.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.		177.00	150.00
	TO REMOVE AND INSTALL FRONT REAR VIEW CAMERAS INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION.		266.00	226.00
			2,933.00	2,310.00
GRAND TOTAL			6,224.20	4,246.75
RECOMMENDED COST OF REPAIRS				4,246.75

Report Ref No. CS/FCI19013202/R1tf3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.