

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X

denise



Final Report

Estimate No. : **b1 52111**
Date Estimated : **25/07/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -

Roselle Mont-Clair Furnishing Pte Ltd
NO. 1 COMMONWEALTH LANE
#04-22/23

Singapore 149544

- ACCOUNT -

303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLM5941R	V725329	24/01/2017	116d	0
DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper panel including to remove and install body parts in order to carry out painting job	850.00	0	850.00	
To respray rear bumper	934.00	0	934.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00	
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00	0	150.00	
To remove and replace rear view cameras including program and conduct checks for proper function.	226.00	0	226.00	
Sundries.	80.00	0	80.00	
# To supply rear emboss number plate <i>bt</i>	83.00	0	83.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PRIMED (RFC)	1,015.00	1.00	0	1,015.00
REAR PDC HOLDER SET	24.60	1.00	0	24.60
REVERSING CAMERA	681.10	1.00	0	681.10
(DG/SL) ADHESIVE SET K6	53.05	1.00	0	53.05

OD	ADD PARTY	DATE	WORKING DAYS
	Rasul LKK	7/8/19	3
CONFIRMED DATE			
PLEASE FINISH			

Total Labour : 2,473.00
Total Parts : 1,773.75
Total Repair Costs less Excess: 4,246.75
GST @7%: 297.27
Grand Total : 4,544.02

CAR RENTAL - \$224.70
LTA SEARCH FEE - \$7.45