



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

YEO BROTHER PACKING ENTERPRISE

30/07/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPChim

Jia le

Accident date: 24/07/2019

Estimated repair cost for vehicle no: YP2070D MITSUBISHI FUSO CANTER 3.0 M '16

CHASSIS: FEB50542898

S/n	Qty	Items	U/price	Amount
1	1	Front Bumper <i>Bent.</i>		\$1,218.30 ✓
2	2	Front Bumper Side Pad <i>Deformed</i>	\$457.60	\$915.20 ✓
3	2	Front Bumper Lamp <i>new</i>	\$289.40	\$578.80 +
4	2	Front Bumper Bracket <i>Bent</i>	\$143.00	\$286.00 ✓
5	1	Front Bumper Number Plate <i>new</i>		\$50.00 +
6	1	Front Grille <i>cracked</i>		\$698.50 ✓
7	8	Front Grille Clip <i>new</i>	\$6.50	\$52.00 20 ✓
8	1	Front Grille Emblem Logo <i>new</i>		\$85.00 ✓
9	2	Front Head Lamp <i>cracked</i>	\$897.00	\$1,794.00 ✓
10	2	Front Signal Lamp <i>cracked</i>	\$286.35	\$572.70 ✓
11	2	Front Side Reflector <i>Not Nec</i>	\$86.50	\$173.00 ✓
12	2	Front Corner Panel <i>cracked</i>	\$498.50	\$997.00 ✓
13	1	Front Wiper Panel Garnish <i>cracked</i>		\$398.40 ✓
14	1	Front Wiper Panel Garnish Clip <i>new</i>	\$6.50	\$6.50 ✓
15	1	Front Panel <i>Dented</i>		\$1,223.00 ✓
16	1	Front Panel Fuso Logo <i>new</i>		\$180.20 ✓
17	1	Front Dashboard <i>new</i>		\$1,450.10 ✓
18	1	Front Dashboard Cover <i>new</i>		\$248.20 +
19	1	Front Air-Con Blower <i>cracked</i>		\$1,358.80 ✓
20	1	Front Air Cleaner <i>cracked</i>		\$249.80 ✓
21	1	Front Air Duct <i>cracked</i>		\$384.90 ✓
22	1	Front Windscreen Seal <i>new</i>		\$85.00 ✓
23	1	Front Windscreen Moulding <i>new</i>		\$493.50 ✓
24	1	Front Cabin Rear Panel <i>new</i>		\$1,655.00 +
25	1	Front Cabin Rear Windscreen Moulding <i>new</i>		\$289.90 ✓
26	1	Front Cabin Lock Lever <i>new</i>		\$288.40 ✓
27	1	Front Intake Manifold Pipe <i>Dented</i>		\$1,427.60 ✓

28	1	Front Egr Pipe Cover <i>cancel</i>		\$315.60	✓
29	1	Front Turbo Valve Wire Cover <i>cancel</i>		\$3,220.40	✓
30	2	Rear Taillamp <i>HN</i>	\$295.40	\$590.80	X
31	10	U Bolt <i>Bent</i>	\$100.00	\$1,000.00	400
			16908.70		
			12681.52		
			Subtotal :-	\$22,286.60	

S/n	Qty	Items / Special Nett	U/price	Amount	
32	1	Rear Tailgate <i>cancel</i>		\$1,800.00	1300
33	2	Rear Tailgate Center Bracket <i>Bent</i>	\$250.00	\$500.00	360
34	2	Rear Tailgate Side Bracket <i>Bent</i>	\$280.00	\$560.00	380
35	1	Rear Tailgate Lower Panel <i>Rpr</i>		\$850.00	X
36	4	Rear Tailgate Hinge <i>HN</i>	\$150.00	\$600.00	+
37	2	Rear Tailgate Side Lock Pin <i>HN</i>	\$100.00	\$200.00	+
38	1	Rear Tailgate Advertisement <i>NCU</i>		\$280.00	260
39	1	Rear Tailgate 60km/H Sticker <i>NCU</i>		\$25.00	10
40	1	Rear Tailgate Lower Horizontal Wooden Plank <i>HN</i>		\$850.00	X
41	1	Rear Tailgate Lower Step Wooden Panel <i>cancel</i>		\$350.00	300
42	2	Rear Vertical Wooden Chassis Member <i>cancel</i>	\$1,350.00	\$2,700.00	2000
43	5	Rear Deck Horizontal Wooden Member <i>4 pieces</i>	\$550.00	\$2,750.00	1800
44	1	Rear Number Plate <i>3mm</i>		\$50.00	+
45	1	Rear Number Plate Bracket		\$100.00	+
46	2	Rear Side Gate <i>2 nos</i>	\$2,500.00	\$5,000.00	+
47	1	Rear Side Gate Advertisement	\$350.00	\$350.00	+
			6400		
			Subtotal :-	\$17,065.00	

Labour charges

To remove & refit front windscreen

~~\$250.00~~ 120

Gum

\$60.00 ✓

To remove & refit rear windscreen

~~\$150.00~~ 100

Gum

\$60.00 ✓

To remove & refit dashboard

~~\$450.00~~ 220

To remove & refit air-con blower

~~\$380.00~~ 250

To remove rear wooden deck

~~\$1,600.00~~ 800

To repair & straighten rear chassis frame

~~\$2,500.00~~ 1000

To varnish rear wooden deck

~~\$800.00~~ 400

To check wiring

~~\$150.00~~ 60

Tuff kote

5370 ~~\$200.00~~ 100

Panel beating

~~\$4,500.00~~ 1000

Spray painting

~~\$2,000.00~~ 1200

Subtotal :- \$13,100.00

Total:- \$52,451.60

total = 445152

4/5 : 19.5K

14 Days

19.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date: