



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV No. AC2005677  
INV Date 18/08/2020  
Reference CC6/CTI19013206/Ada3n2  
Code CTI



### PROFESSIONAL SERVICE FEE

Vehicle No. SKW 789G  
Insured Veh. GBH 6356T  
Claim No. SNM19D203384C02/6  
Policy No. DMCVSN1824491800  
Accident Date 17/07/2019  
Inspection Date 14/08/2019

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19013206/Ada3n2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 18-08-2020



Code : CTI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 6356T	Veh. Inspected	SKW 789G
Policy No.	DMCVSN1824491800	Coverage (\$)	0.00
Claim No.	SNM19D203384C02/6	Excess (\$)	0.00
Assign From		Assign Date	14/08/2019

### 2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C200 COUPE	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WDD2053422F484549	Colour	BLACK
Odometer	50450	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/45 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/45 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/45 R18	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	17/07/2019	Inspection Date	14/08/2019
Survey held at	F-1 AUTOCLINIC PTE LTD 25 KAKI BUKIT ROAD 4 #05-26 SYNERGY @ KB SINGAPORE 417800		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 789G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BOOT LID (N)	TO REPAIR SEE LABOUR	2,150.00	-
1	REAR BOOT LID C200 LOGO (N)	NECESSARY	41.00	41.00
1	REAR BOOT LID CNC LOGO (N)	NECESSARY	55.00	55.00
1	REAR BOOT LID EMBLE LOGO (N)	NECESSARY	80.00	80.00
1	REAR BOOT LID INNER RUBBER (N)	NOT NECESSARY	144.00	-
1	REAR BOOT LID INNER LOCK (N)	NOT NECESSARY	352.00	-
1	REAR BOOT LID NUMBER PLATE (N)	NOT NECESSARY	50.00	-
2	REAR BOOT LID NUMBER PLATE LAMP @\$155.00 (N)	NOT NECESSARY	310.00	-
2	REAR TAIL LAMP @\$950.00 (N)	NOT NECESSARY	1,900.00	-
1	REAR BUMPER (N)	TO REPAIR SEE LABOUR	1,650.00	-
2	REAR BUMPER BRACKET @\$115.00 (N)	NOT NECESSARY	230.00	-
1	SET REAR BUMPER REVERSE SENSOR (N)	NOT NECESSARY	550.00	-
10	REAR BUMPER CLIPS @\$5.00 (N)	NOT NECESSARY	50.00	-
2	REAR BUMPER SIDE REFLECTOR @\$85.00 (N)	NOT NECESSARY	170.00	-
1	REAR BUMPER TOWING COVER (N)	NOT NECESSARY	88.00	-
1	REAR BUMPER REINFORCEMENT (N)	NOT NECESSARY	885.00	-
1	REAR BUMPER LOWER COVER (N)	NOT NECESSARY	525.00	-
1	END PANEL (N)	NOT NECESSARY	950.00	-
1	END PANEL TOP GARNISH (N)	NOT NECESSARY	275.00	-
1	REAR EXHAUST (N)	NOT NECESSARY	2,250.00	-
1	REAR EXHAUST CHROME PIPE (N)	NOT NECESSARY	325.00	-
	LESS 10% DISCOUNT		-	-17.60
			13,030.00	158.40
<b><u>LABOUR</u></b>				
	TO REMOVE & RE-FIX CUSHION.	NOT NECESSARY	150.00	-
	TO REMOVE & RE-FIX REVERSE SENSOR.		120.00	60.00
	TO REMOVE & RE-FIX REAR EXHAUST.	NOT NECESSARY	180.00	-
	TO CHECK WIRING SYSTEM.		100.00	40.00
	TUFF KOTE.	NOT NECESSARY	150.00	-

Report Ref No. CC6/CTI19013206/Ada3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BOOT LID AND REAR BUMPER. SPRAY PAINTING.		800.00	300.00
			800.00	500.00
			2,300.00	900.00
GRAND TOTAL			15,330.00	1,058.40
RECOMMENDED COST OF REPAIRS				1,058.40

Report Ref No. CC6/CTI19013206/Ada3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKW 789G

RE-INSPECTION

