

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0370/2019
DATE : 25-JUL-2019

ECICS LIMITED
7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
S(038987)
TEL : 63374779
FAX : 63389267
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MR KOI WEI TER (CAI WEIDE)
ADDRESS : 966 DUNEARN ROAD
#07-03
S(589488)
TELEPHONE NO : 97321462

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP - SLJ754M
VEHICLE NO : SLL5142K
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2327066A
CHASSIS NO : SJNFEAJ11U1757251
MILEAGE : 1 KM
DATE IN : 25/07/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 09/07/2019

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

~~CAR AT WORKSHOP~~ / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

25.07.2019

EMAIL : zuhri@tanchong.com

OFFICE : 67038916 FAX : 64697472

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLL5142K

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	
2 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	
3 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	
4 ZZ/001	CHECK LIGHTING	48.00	
5 ZZ/002	REPAIR REAR TAILGATE & REAR END PANEL RENEW RR BUMPER	1170.00	
6 ZZ/003	S/PAINT RR BUMPER (2 TONE),RR END PANEL & TAILGATE RR FENDER RH & LH SIDE	1350.00	
TOTAL LABOUR CHARGES		2898.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLL5142K

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	SUNDRIES	NPN			40.00
2	ORNAMENT-BACK D	90892-4EA0A	87.00		
3	EMBLEM-REAR	90890-4EA0A	59.70		
4	BRACKET-BUMPER LH	85221-4EA0A	35.90		
5	BRACKET-BUMPER RH	85220-4EA0A	35.90		
6	STAY ASSY-RH	H5210-4EAMA	126.00		
7	REINF-BUMPER RR	H5030-4EAMA	619.20		
8	ENERGY ABSORBER	85090-4EA0A	126.40		
9	FINISHER-REAR B	85071-4EA0A	16.80		
10	CLIP(7.4X3)	85284-JD00A	22.20		
11	CROMMET(2.5X2)	63846-5V000	5.00		
12	FASCIA-RR BUMP	85022-4EA0H	717.00		
13	REVERSE SENSOR(J11)	SENSOR-TE5140			180.00
SUB TOTAL			1851.10	0.00	220.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			370.22	0.00	0.00
GRAND TOTAL			1480.88	0.00	220.00
OVERALL TOTAL			1700.88		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLL5142K

TOTAL LABOUR CHARGES	2898.00
TOTAL SPARE PARTS CHARGES	1700.88

GRAND TOTAL	4598.88 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.