



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS3/AWA19013213/R1tf3e2

(SINGAPORE BRANCH)  
60 ANSON ROAD #08-01 (8th FLOOR)  
MAPLETREE ANSON  
SINGAPORE 079914

Date : 11-12-2019



Code : AWA

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBG 474E	<b>Veh. Inspected</b>	SKN 5811P
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	NSV1900378/KW	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	STELLA GOH	<b>Assign Date</b>	26/07/2019

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	SUBARU XV 1.6I	<b>c.c</b>	1600
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2014
<b>Chassis No.</b>	JF1GP3KC5CG008303	<b>Colour</b>	BLACK
<b>Odometer</b>	99974	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	225/55 R17	GOODYEAR	6 mm
<b>L/H Front Tyre</b>	225/55 R17	GOODYEAR	6 mm
<b>R/H Rear Tyre</b>	225/55 R17	GOODYEAR	6 mm
<b>L/H Rear Tyre</b>	225/55 R17	GOODYEAR	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	24/07/2019	<b>Inspection Date</b>	26/07/2019
<b>Survey held at</b>	40 TOH GUAN ROAD EAST #01-67		
<b>Repairer</b>	MASTER CAR SPRAY SERVICE		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**