



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
INDIA INTERNATIONAL INSURANCE SINGA 64 CECIL STREET #04-05 IOU BUILDING SINGAPORE 049711 Contact No	Cust No/Name	/Ms Cheong Chui Chui Hilary
	Reg No/Reg Date	SLF1954S / 17/08/2016
	Date In/Mileage	23/07/2019/ 49842
	Chassis No	KNAHU815VG7163609
	Engine No	D4FDGH112722
	Make/Model	KIA/CARENS 1.7 A D SX SUNROOF GP8
	Colour/Trim	K7N / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000036	Credit	24/07/2019/ 17:04	DS	218 / MarsLer	29044			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S	MIPNT88088	DIAGNOSTIC / SCANNING						✓ 250.00
S	MIPNT88088	TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS						80 100.00
S	MIPNT88088	TO REMOVE AND REPLACE LH GLASS & MOULDING ASSY TO GIVE WAY FACILATATE ACCESS RENEWEL LHF FENDER						450) ? 300.00
M	SUNDRY	SEALANT KIT ON LH GLASS						? 100.00
S	MIPNT88088	TO INSTALL RIKE COOL SOLAR FILM ON LH GLASS						? 150.00
S	MIPNT88088	TO REPLACE FRONT BODY KIT -INCLUDE APPLY SEALANT & SPRAY PAINTING						✓ 800.00
S	MIPNT88088	TO REPLACE LHF FENDER, FRT BUMPER, ETC -TO REPLACE FRONT END MODULE CARRIER ASSY -REPAIR LHF BODY WHEEL HOUSE AFFECTED AREAS STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS	600					1200 3600.00
S	MIPNT88088	TO REPLACE UNDERCARRIAGE PARTS						? 600.00
S	MIPNT88088	TO APPLY SEALANT KIT	420					100 200.00
S	MIPNT98088	SPRAY PAINTING ON LHS ACCIDENT AFFECTED AREAS						1050 1680.00
M	KS 66311 A4 000	LH FENDER PANEL / Blue			1.00	405.00	0.00	405.00
M	KS 84141 A4 000	INSULATOR-FENDER LH			1.00	48.00	0.00	48.00
M	KS 64101 A4 000	CARRIER ASSY - FRONT			1.00	628.00	0.00	628.00
P	JJMZ313950	COOLANT			4.00	26.00	0.00	104.00
P	KS 92101 A4 160	LH HEADLAMP ASSY			1.00	1558.00	0.00	1558.00
M	KS 86511 A4 010	COVER - FRONT BUMPER			1.00	695.00	0.00	695.00
M	KS 86561 A4 000	MESH - FRONT BUMPER,			1.00	183.00	0.00	183.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
INDIA INTERNATIONAL INSURANCE SINGA 64 CECIL STREET #04-05 IOU BUILDING SINGAPORE 049711	Cust No/Name /Ms Cheong Chui Chui Hilary
Contact No	Reg No/Reg Date SLF1954S / 17/08/2016
	Date In/Mileage 23/07/2019/ 49842
	Chassis No KNAHU815VG7163609
	Engine No D4FDGH112722
	Make/Model KIA/CARENS 1.7 A D SX SUNROOF GP8
	Colour/Trim K7N / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000036	Credit	24/07/2019/ 17:04	DS	218 / MarsLer	29044			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	KS	86513 A4 000	LH BRACKET - FRONT B	✓ RR	1.00	12.00	0.00	12.00
M	KS	86514 A4 000	RH BRACKET - FRONT B	X NN	1.00	12.00	0.00	12.00
M	KS	86520 A4 000	ABSORBER - FRONT BUM	?	1.00	78.00	0.00	78.00
M	KS	92201 A4 020	LH FOG LAMP ASSY - F	?	1.00	206.00	0.00	206.00
M	KS	95720 A4 001K 7N	ULTRASONIC SENSOR AS	?	2.00	162.00	0.00	324.00
M	KS	86584 A4 000	HOLDER-PARKING ASSIS	✓	1.00	17.00	0.00	17.00
M	KS	86582 A4 000	HOLDER-PARKING ASSIS	✓	1.00	17.00	0.00	17.00
M	KS	86581 A4 000	HOLDER-PARKING ASSIS	✓	1.00	17.00	0.00	17.00
M	KS	86583 A4 000	HOLDER-PARKING ASSIS	✓	1.00	17.00	0.00	17.00
M	KS	86320 A4 000	EMBLEM - KIA	✓	1.00	76.00	0.00	76.00
M	SUK	91010107	CARENS BODY KIT	✓	1.00	1688.00	0.00	1688.00
M	KS	52910 A4 200	WHEEL ASSY - ALUMINI	✓ Est	1.00	1680.00	0.00	1680.00
M	KS	54650 A4 850	LH STRUT ASSY-FR	?	1.00	335.00	0.00	335.00
M	KS	54610 A4 000	INSULATOR ASSY-STRUT	?	1.00	104.00	0.00	104.00
M	KS	86180 A4 100	LH GLASS & MOULDING	?	1.00	189.00	0.00	189.00
P	WYK	2254517-ES32	YOKOHAMA 225/45/17 E	?	2.00	184.00	0.00	368.00
Z	NOTES							
ACCIDENT ON 22/06/2019 ALONG REPUBLIC BOULEVARD OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP # SHA7915P TP INS : I.I.I								

5 Days.
before paint photos.
Gmo @iay - 82880282
29/7/19.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Confirm & accepted by

Authorized signatory and company stamp

Parts	8,761.00
Labour	0.00
Standard Menu	0.00
Specialist Job	7,680.00
Others(Lub,etc)	0.00
Sundry	100.00
Total(w/o GST)	16,541.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.