, 1552018 DIS CASE ORDERED	CC 4, MG 190 13220,	U GOR SUN IDAC
INS. CASE OWNER:	MARIM ASSIGNMENT	761410
Surveyor:	DOI: DOI:	Registered in Merimen:
Pre-assign / CCU /	FTE	
Insured Vehicle No.	Som Sup Claim No.	
Name of Insured	Chern Su min Bernard Policy No.	:
D U		
Insured Tel No.	HP: Make / Mode	
Excess Sec II :SS	D.O.A : 18/01/19/9 Place of Acci	dent :
Is driver the owner?		^
If NO, Driver Nam Driver Tel N		ORT (YES / NO ; TP GIA REPORT: (YES / NO lity: % Final ? Yes / No
PC 8116 S	- $ -$	
INSRS:	INSRS: INSRS:	INSRS:
Tel: Thank	WSP: WSP: Tel: Tel:	WSP: Tel:
Liability:	Liability: Liability:	Linbility:
RMKS:	RMKS: RMKS:	RMKS:
Date/Time		
	9081165-X; 500 509-X	STAGE DATE/PIC
	repairs and Nava Paller at	Non-Reporting ltr (1st): Non-Reporting ltr (2nd):
9/2/9	- To Reject JP claim.	Non-Reporting ltr (Final):
Chanche	- File pass to mei know to cluse	Notification ltr (if non-pickup): Call OI:
	the bear to met to we to close	After call ltr to Ol:
		Documentation Check List: Handler Typist
		Notification ltr (if non-pickup)
	Khanehan	After call itr to Oi:
	Francisco III Van	Authorisation To Act: Release Voucher:
	69-12-19	Final Repair Bill:
		Car Rental Invoice:
		Towing Invoice
		LTA / GIA : Medical Bill:
		PIR:
		Mandate/Reject Instruction:
		LOD
		Payment Breakdown Form:
PRELIMINARY ADVICE	Date/Time: Sent By:	Post-Repair Photos: Others:
FINALIZATION	Date/Time: Confirm with:	Confirm by:
Repair Cost: US	ss 4/100 (3 days) Reduction: 5 %	Email Call
FINAL SETTLEMENT	Date/Time: Confirm with	Email Call
Final Liability:	% (Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia:
Repair Cost: Loss of Rental (LOR):	S\$ S\$ (days)	* REJECT CLAIM+
Loss of Use (LOU):	S\$ (\$ x days)	- 181 - 1100 II Chossicil All o
Loss of Income (LOI):	S\$ (\$ x days)	
LOR only LOU only	LOR + LOU LOR + LOI [Tick only one]	
GIA/LTA Search Medical:	S\$ S\$	1) Claim status: Normal/Reject/Private Settle
Disbursement:	S\$ (e.g. Tow/ Independent)	2) Report Format:
Legal Cost	\$\$	3) Survey fee: 250 320
Total:	S\$ Global Sum SS:	
FINAL PAYMENT	Date/Time: Confirm with:	Email Call
Payee 1:	S\$ Name 1:	
Fayee 2. (Strike if N.A.) Payee 3: (Strike if N.A.)	S5 Point 2: S5 No.242.3:	CORN, SENST
7		(D) WIN 191

ASSIGNMENT

From . Date 29/3/19	Veh No. PC 8116	S Yr Rego 4/19
Estimpled Cost:	Type: M.Car J M.Cycle Bus I Van	Lorry / Taxi / Prime Mover /
OD (TP) WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or (A)	
To Inspect Vehicle No. PC 81165	Make Toyota he	ace commuter 6.4 278
at Workshop mis Think one Autocare		A/C: Insured / Std / NI / NA
No.18 Defu Avenue 2	Sp.Reading 239 00	T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:	
Policy No.	C/No: GDH	2232001437
Claims No.	Gen. Cond: Good / Fair / Poor / Bu	rnt /
Sum Insured: Excess:	Steering: Interest / Jammed / Leak	ed / Burnt or
(Client's Record)	Brake: Worder / Jammed / Leak	ed / Burnt or
Make of Veh: Pm @ withing	Modi: NIL S/Rim / STD A/Rim	or
Michael 5	Tyre Size: F: /95	-1BR15
(Policy Condition)	R:	
Remark: The veh had commenced its N/S O/S	ESTOUN / EXNOVA / GY / FS / LE	ZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	Τογο / γοκο α	
Bat or Market Value:	Eront /	Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. omm	R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm	L/Bal 6 mm
Est Repairs:	DOA 1817/19	0.01. 29/7/18
Lum Sum: Zv % 3 Val. Yes or No	Survey held at	
CA / REV / REP. / 24 HRS (UP) LA 2018/	Des. of Damages/ Frt / Rear / O	IS I N/S I U/C I Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / Of	or MSM.	NIS 12/
Date: Person Contacled:	The U/C / Chassis frame / B	ody Structure affected due to collision
Date / Time Action / Instruction	41.	
17/18 Carful MS \$4(00)	wil Medil 1\$6,702.35157.	
Cha	1 dr 200 161 600	
(ka	136/102.33136/)
Automorphism The Sale	or our v	
Date/Time: File Pens to/ : Prell. Report	Days Of Repair:	
i) : Final Report	Resurvey No. of Trip:	Survey Fee:
DotaTime: File Paisson (e) Acticl F	oor Suntan A	Transpodator:
3 A00 F		3488_9
Proceed Processes	Interview (\$	Hein
Expert Formst:	Tech inve G) (She)
Lung Sum / USE 1	:Westissol til	
		SOUR.

Think One Autocare Pte Ltd No.18 Defu Avenue 2 Singapore 539522

No	Qty	TOYOTA HIACE GDH223-2001437 PARTICULAR		AMOUNT S\$	
1	1	FRONT BONNET		R 988.00 X	-
2	1	CORNER PANEL LH		752.30	
3	1	CORNER PANEL INNER SUPPORT LH		1 3 252.00 ×	<
2 3 4 5 7	1	FRONT BUMPER		g mad 693.00 -	_
5	1	FRONT BUMPER SIDE RETAINER LH		71 120.10 %	€
7	1	HEADLAMP BRACKET LH		44 421.00 X	1
8	1	DOOR PILLAR LH		1,422.00 ×	1
9	1	DOOR RH		DD/32 1,752.00	_
				\$ 6,000.40	
			LESS 25%	\$ 1,500.10	
				\$ 1,500.10 \$ 4,425.30	
				\$ 4,500.30	
No	Qty	PARTICULAR NETT ITEM		AMOUNT S\$	
1	1	HEADLAMP ASSY LH 2450		cm1 2.539.50 =	-
2	1	FENDER MIRROR LH		11 985.00 N	-
				\$ 3,524,50	
			LESS 10%	25 \$ 352.45	
			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	\$ 3,172.05 /	
				X	rue
					3
		LABOUR & MISCELLANEOUS:			200
1		LABOUR & MISCELLANEOUS: To remove damaged body parts with all necessary con	mponents/attach-	480 1,000.00	393
1		To remove damaged body parts with all necessary cor	7	480 1,000.00	393
1		To remove damaged body parts with all necessary comments apply hot-works where necessary repair, reshape	e body dented	480 1,000.00	393
1		To remove damaged body parts with all necessary comments apply hot-works where necessary repair, reshap panels in accordance with factory specifications replace	e body dented ce new parts refit	480 1,000.00	393
1		To remove damaged body parts with all necessary comments apply hot-works where necessary repair, reshape	e body dented ce new parts refit	480 1,000.00	393
1		To remove damaged body parts with all necessary comments apply hot-works where necessary repair, reshap panels in accordance with factory specifications replace	e body dented ce new parts refit attachments	480 1,000.00 3	393
2		To remove damaged body parts with all necessary cor- ments apply hot-works where necessary repair, reshape panels in accordance with factory specifications replac- and align into position refit all necessary components/ To spray paint replaced/repaired body parts inclusive	e body dented ce new parts refit attachments		393
		To remove damaged body parts with all necessary comments apply hot-works where necessary repair, reshap panels in accordance with factory specifications replace and align into position refit all necessary components. To spray paint replaced/repaired body parts inclusive works and painting materials	e body dented ce new parts refit attachments of preparatory	6 fo 1,000.00	393
2		To remove damaged body parts with all necessary cor- ments apply hot-works where necessary repair, reshape panels in accordance with factory specifications replac- and align into position refit all necessary components/ To spray paint replaced/repaired body parts inclusive	e body dented ce new parts refit attachments of preparatory		393
		To remove damaged body parts with all necessary comments apply hot-works where necessary repair, reshap panels in accordance with factory specifications replace and align into position refit all necessary components. To spray paint replaced/repaired body parts inclusive works and painting materials	e body dented ce new parts refit attachments of preparatory	6 fo 1,000.00	383
3		To remove damaged body parts with all necessary corments apply hot-works where necessary repair, reshape panels in accordance with factory specifications replace and align into position refit all necessary components. To spray paint replaced/repaired body parts inclusive works and painting materials To transfer front door components with all necessary and conduct headlamp alignment	e body dented ce new parts refit attachments of preparatory	6 fo 1,000.00 60 100.00	379
3		To remove damaged body parts with all necessary comments apply hot-works where necessary repair, reshape panels in accordance with factory specifications replace and align into position refit all necessary components. To spray paint replaced/repaired body parts inclusive works and painting materials. To transfer front door components with all necessary and conduct headlamp alignment.	e body dented ce new parts refit attachments of preparatory	6 fo 1,000.00 6 0 100.00 20 30.00 8 2,130.00	399
3		To remove damaged body parts with all necessary comments apply hot-works where necessary repair, reshape panels in accordance with factory specifications replace and align into position refit all necessary components. To spray paint replaced/repaired body parts inclusive works and painting materials. To transfer front door components with all necessary in the conduct headlamp alignment.	e body dented ce new parts refit attachments of preparatory	6 fo 1,000.00 6 0 100.00 20 30.00 8 2,130.00	383 174
3		To remove damaged body parts with all necessary comments apply hot-works where necessary repair, reshape panels in accordance with factory specifications replaced and align into position refit all necessary components. To spray paint replaced/repaired body parts inclusive works and painting materials. To transfer front door components with all necessary. To conduct headlamp alignment LKK Auto Consultants hence notify the Repairer of the following: * To mesuremy before/after spray paintings.	e body dented ce new parts refit attachments of preparatory attachments	6 fo 1,000.00 6 0 100.00 20 30.00 8 2,130.00	174
3		To remove damaged body parts with all necessary comments apply hot-works where necessary repair, reshape panels in accordance with factory specifications replaced and align into position refit all necessary components. To spray paint replaced/repaired body parts inclusive works and painting materials. To transfer front door components with all necessary. To conduct headlamp alignment LKK Auto Consultants hence notify the Repairer of the following: To mesurely before/after spray painting To display damaged partial during research.	e body dented ce new parts refit attachments of preparatory attachments	6 fo 1,000.00 6 0 100.00 20 30.00 8 2,130.00	383
3		To remove damaged body parts with all necessary comments apply hot-works where necessary repair, reshape panels in accordance with factory specifications replaced and align into position refit all necessary components. To spray paint replaced/repaired body parts inclusive works and painting materials. To transfer front door components with all necessary. To conduct headlamp alignment LKK Auto Consultants hence notify the Repairer of the following: To mesurely before/after spray painting To dispiny damaged part(s) during resurvey. Parts prices are subject to confirmation.	e body dented ce new parts refit attachments of preparatory	6 fo 1,000.00 6 0 100.00 20 30.00 8 2,130.00	379
3		To remove damaged body parts with all necessary comments apply hot-works where necessary repair, reshape panels in accordance with factory specifications replaced and align into position refit all necessary components. To spray paint replaced/repaired body parts inclusive works and painting materials. To transfer front door components with all necessary. To conduct headlamp alignment LKK Auto Consultants hence notify the Repairer of the following: To insurvey before/after spray painting To display damaged part(s) during resurvey. Parts prices are subject to confirmation. Third party survey is on a "Without Prejudice" basis.	e body dented ce new parts refit attachments of preparatory attachments	6 fo 1,000.00 6 0 100.00 20 30.00 8 2,130.00	175
3		To remove damaged body parts with all necessary comments apply hot-works where necessary repair, reshape panels in accordance with factory specifications replaced and align into position refit all necessary components. To spray paint replaced/repaired body parts inclusive works and painting materials. To transfer front door components with all necessary. To conduct headlamp alignment LKK Auto Consultants hence notify the Repairer of the following: To mesurely before/after spray painting. To display damaged part(s) during resurvey. Parts prices are subject to confirmation. Third party survey is on a "Without Prejudice" basis. Supplementary decembers in allowed.	e body dented ce new parts refit attachments of preparatory attachments	6 PU 1,000.00 6 0 100.00 20 30.00 8 2,130.00	175
3		To remove damaged body parts with all necessary comments apply hot-works where necessary repair, reshape panels in accordance with factory specifications replaced and align into position refit all necessary components. To spray paint replaced/repaired body parts inclusive works and painting materials. To transfer front door components with all necessary. To conduct headlamp alignment LKK Auto Consultants hence notify the Repairer of the following: To mesurely before/after spray painting. To display damaged part(s) during resurvey. Parts prices are subject to confirmation. Third party survey is on a "Without Prejudice" basis. Supplementary decembers in allowed.	e body dented ce new parts refit attachments of preparatory attachments	6 PU 1,000.00 6 0 100.00 20 30.00 8 2,130.00	38
3		To remove damaged body parts with all necessary comments apply hot-works where necessary repair, reshape panels in accordance with factory specifications replaced and align into position refit all necessary components. To spray paint replaced/repaired body parts inclusive works and painting materials. To transfer front door components with all necessary and transfer front door components with all necessary. To conduct headlamp alignment. LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting. To display damaged part(s) during resurvey. Parts prices are subject to confirmation. Third party survey is on a "Without Prejudice" basis. No dilegal modification(s) is allowed. Supplementary item(s) must be resurveyed and in subject to final approval from irraurance Company.	e body dented ce new parts refit attachments of preparatory attachments	6 PU 1,000.00 6 0 100.00 20 30.00 8 2,130.00	375
3		To remove damaged body parts with all necessary comments apply hot-works where necessary repair, reshape panels in accordance with factory specifications replaced and align into position refit all necessary components. To spray paint replaced/repaired body parts inclusive works and painting materials. To transfer front door components with all necessary. To conduct headlamp alignment LKK Auto Consultants hence notify the Repairer of the following: To mesurely before/after spray painting. To display damaged part(s) during resurvey. Parts prices are subject to confirmation. Third party survey is on a "Without Prejudice" basis. Supplementary decembers in allowed.	e body dented ce new parts refit attachments of preparatory attachments	6 PU 1,000.00 6 0 100.00 20 30.00 8 2,130.00	174

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

0 10.7	Comment
Owner ID Type:	Company
Owner ID:	609M
Vehicle Details	0001115
Vehicle No.:	PC8116S
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER 2.8 GL AUTO
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	1GD8385389
Chassis No.:	GDH2232001437
Maximum Power Output:	æ
Open Market Value:	\$44,133.00
Original Registration Date:	08 Apr 2019
First Registration Date:	08 Apr 2019
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$2,207.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	07 Apr 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$27,021.00
COE Rebate Amount:	\$26,187.00
Total Rebate Amount:	\$26,187.00

The information contained herein is correct as at 29 Jul 2019

OK

PRE-REPAIR INSPECTION REQUEST - PC8116S vs SDM50P [OI] on D.O.A.: 18/07/2019

From: Hor, Yinnui

'assignments@Rkauto.com', Ammo A (admiri-a@Roautil.com) To:

Fong, Andy-SY, Chin, Lee-Ying, John Kassim, Noor Mannes, Actor Lazerdon, Chin, Yoke Shi, Sheng Yang, Mithocoungh, Asshweeneetkaur, Subramaniam, Divyashni, Tong, Wahxin Cc ·

7/26/2019 3:24:30 PM

Hi.

Please refer to the enclosed request from Think One Autocare Pte List.

Claim no

±8265069074SG003

Case Owner Wan Nur Saliha Binte Syed Yosoff

If you have any queries/concerns, please let us know.

Kindly assist to assign Marcus Chus as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rut (Viviane)

AIG-

FNOL Adjuster 1

Singapore FNOL | Clams Operations - Auto

Young Hondbarg.com i www.aig.sg

From: michaelng@thinkone.com.sg [mailto:michaelng@thinkone.com.sg]

Sent: Friday, July 26, 2019 3:12 PM

Tot Hor, Yinrul

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDM50P AND PC81165 ON 18/07/2019

We prefer Mr Marcus Chua from LKK consultancy to take the job

Thank you

Michael Ng

From: Hor, Yinrul

Sent: Fri, 26 Jul 2019 02:36:00 +0000 To: michaelng@thinkone.com.sg

Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kaasim, Noor Mariem, Azlan, Syuzairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur,

Subramaniam, Divyashni, Tong, Wahxin

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VIHICLE SDM50P AND PC8116S ON 18/07/2019

Without Prejudice

Your Reference

1 PC8116S

Our Reference

: 82650690745G003

Dear Sir/Madam:

We refer to your Notice of Accident of even date.

We intend to conduct a pre-regair survey of the damage to your claims your customer's vehicle monthy with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair access as a single joint expert

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Lad
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Loui	Automobile Inspection Services Pro Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Ptc Ltif.
Ng You Han	Formteam Adjusters Pt= Ltd
Soon HanXin (Gary)	Formfelim Adjusters Ptc Ltd
Chow Bo Xiong	Fremteum Adjustera Pt- Ltd
Chua Soo Teek (Benjamin)	Formteum Adjusters Ptv Ltd.
Kalvin Ang	LKK Auto Consultants Pie Lid
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consiliants Ptg Ltd
Mohamad Taufikh	LKK Auto Consultante Pre Ltd
Adrian Ling	LKK Aute Consultants Ptc Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd

3.42 pmg 28/7/19 VAI person@Michael. Amorge on 29/7/19

Kenneth Kong

LKK Auto Consultants Pto Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor-surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rut (Vistane) AIG FNOL Adjuster t Simpapore FNOL | Claims Operations - /

Yoru PortBala com I www.aig.au

From: michaelng@thinkone.com.sg [mailto:michaelng@thinkone.com.sg]

Sent: Friday, July 26, 2019 10:05 AM

To: ClaimsDocManagement

Subject: [EXTERNAL] RE:PCB116S & SDMS0P DOA.18.7.2019

Importance: High

This message is from an external sender; be cautious with links and attachments.

Dear Sir.

Accident along Rangoon Road on 18.7.2019

We would like to arrange to survey our client senior con 1165

Thank You

Michael Ng

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defice that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group. Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intunted recipient, you must not use or disseminate the information, if you have received this email in error, please immediately notify me by "Repty" communical and permanently detect the original and any causes are printed as above. Although this email and any attachments are believed to be free of any virus or other defect that night affect any computer system into which it is received and appended by the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Khanchna (LKK Auto)

From:

Sved-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>

Sent:

Friday, 23 August 2019 11:58 AM

To:

Khanchna (LKK Auto)

Cc:

Admin A

Subject:

RE: YOUR REF: TP / 8265069074SG - Seeking approval to reject TP claim

Dear Khanchna,

Please proceed with rejection based on the VF.

Kind Regards, Saliha

Saliha Syed Yusoff

AIG

Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building,78 Shenton Way #08-16, Singapore 079120 Tel +(65) 6419 1917 | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Khanchna (LKK Auto) [mailto:khanchna@lkkauto.com]

Sent: Thursday, August 22, 2019 5:23 PM

To: Syed-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: [EXTERNAL] YOUR REF: TP / 8265069074SG - Seeking approval to reject TP claim

This message is from an external sender; be cautious with links and attachments.

OUR REF: CC4/AIG19013220/Uka3 YOUR REF: TP / 8265069074SG Dear Ms. Saliha,

ACCIDENT INVOLVING PC 8116S & SDM 50P [OI-AIG] ON 18/07/2019


The above matter refers.

The Third party said that Insured driver had encroached into his lane and collision ensued. The third party's statement is below for your easy reference:



Whereas our Insured driver said that Third party had encroached into his lane and collided into his vehicle. The Insured driver's

statement is below for your easy reference:



Sketch Plan #4

I was driving along forgen food at 8/7/19, 1555 hr

I storms of the terffic light protuce of singura &

The storms and protects

As I more drove off when the triffic light turn of the yelvel of PC21165 continue light believed and right, drive who my lare and hit the light side wants.

I was drived in my car, Idamaging my light side wants.

I was stormed by P Rampon food just pair of the fraffic light store and assess dismages driver perficulars and assess dismages.

Drive full cular of PC81165 Is food for field light IC 315841012.

Based on the Insured's video footage on Merimen, we opine the liability is down against Third party as the video shows Insured vehicle is still on his lane and Third party had collided into Insured vehicle.

As such, we suggest to reject the Third party claim.

Appreciate your approval/instructions please.

Thank you.

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: <u>Khanchna@lkkauto.com</u> Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Khanchna (LKK Auto)

From:

michaelng@thinkone.com.sg

Sent:

Monday, 9 December 2019 2:42 PM

To:

Khanchna (LKK Auto)

Subject:

RE: Reject claim - Accident involving PC 8116S (TP) & SDM 50P (OI-

AIG:CC4/AIG19013220/Uka3) on 18/07/2019

Importance:

High

Hi Khanchna,

Ok thank you

From: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Sent: Monday, 9 December, 2019 1:20 PM

To: michaelng@thinkone.com.sg Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Reject claim - Accident involving PC 8116S (TP) & SDM 50P (OI-AIG:CC4/AIG19013220/Uka3) on 18/07/2019

WITHOUT PREJUDICE

Dear Sir/Madam,

The above matter and your e-mail below refers.

Please refer to the accident video(as attached), we maintain our opinion that the liability is down against Third party as the video shows

Insured vehicle is still on his lane and Third party had collided into Insured vehicle.

As such, we have our principal's instruction to reject the claim and we are unable to look into your client's claim.

We will now close the matter in our end.

Thank you.

Note: This video footage is solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com| Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: michaelng@thinkone.com.sg <michaelng@thinkone.com.sg>

Sent: Tuesday, 22 October 2019 11:06 AM

To: Khanchna (LKK Auto) < khanchna@lkkauto.com>

Subject: RE: Reject claim - Accident involving PC 8116S (TP) & SDM 50P (OI-AIG:CC4/AIG19013220/Uka3) on 18/07/2019

Importance: High

Dear Khanchna,

Your total rejected the claim is un exceptionable your insure enter the merge lane and my client going straight is on the correct lane.

If you put on 50 / 50 bases may be look into matter.

Looking forward to hear from you soon.

Thank you

Michael Ng

From: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Sent: Thursday, 17 October, 2019 4:30 PM

To: michaelng@thinkone.com.sg
Cc: Admin A <admin-a@lkkauto.com>

Subject: Reject claim - Accident involving PC 81165 (TP) & SDM 50P (OI-AIG:CC4/AIG19013220/Uka3) on 18/07/2019

WITHOUT PREJUDICE

Dear Sir/Madam,

The above matter and your e-mail below refers.

Please be informed that our principal has reviewed the claim.

Based on all documents at hand and video footage, we opine the liability is down against Third party as the video shows Insured vehicle is still on his lane and Third party had collided into Insured vehicle.

We append below screenshots of the Insured's accident video:





As such, we have our principal's instruction to reject the claim and we are unable to look into your client's claim.

We will now close the matter in our end.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this regotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards, Khanchna | Case Handler LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: <u>Khanchna@lkkauto.com</u> Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report) Revoked / No settlement

LAIM SUE	BFOLDER TRA	CKING								
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj Sul	bmitted	Ins Auth'ed	Status	
Main	24 Jul 2019 Edit Reg		26 Jul 2019 00:00 Edit Ad) Rpt	5\$4,100.0 Edit Estim	And the same of the same of	\$\$4,10 View	00.00 Pat		Pending for Report Cancel Case	ilaci
	Main	R	eference	CIA	im Deta	ils		Documents		Show All
CLAIM S	UBFOLDER D	ETAILS					[Created	by adjuster]		
Insured:	CHERN S	U MIN BERNARD	, ID: S1612359E					17 - 67		
Main Claimant:	THINK O	NE LEASING PTE	LTD, Co. Reg. No	0.1 20111560	9M					
Vehicle Re No.:	PC8116	is			Date of L			9 00:00 - :59 and 10 Days Fron	n LTA Reg Date (Man Yr)]
Claim Typ	e: TP / 826	55069074SG			Palicy/Co Nate No.:		2100396417 (Comprehensive)			
Vehicle Re No. (Insured):	SDMSOP				Policy No. (Claimant		51077824	31		
	10				Excess:					
Repairer:			td (HQ) No. 18 De							
Handling Insurer:	AIG Asia Yusoff@a		e Pte. Ltd. (Expre	ss) - Tel: 65-	6419-30	00	[Handled b	y Syed-Yusoff, S	ialiha) Salina.Sy	ed-
Claimant's Insurer:	NTUC In		Co-operative Ltd (The same of the sa						
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	256-3561 [Handled	by MA	RCUS CH	UA] [Final R	pt due 06/08/	2019]
ASSOCIA	ATED MAIL RI	ECEIVED						Vie	w All Compo	se Case Mail
AIG_SO	G (29/07/2019)	: Request To Up	load TP GIA Repor	rt						
ALL ASS	OCIATED TA	sks=				- vs	ew All	Searth Tasks (Create New Task	Complete
Due Da No results	THE RELEGION	Type Task	Group Subje	ct Handle	r As	signe	d By	Completed On	Created O	n Done

Claim Documents

*PC8116S (82650690745G) [SDM50P] TP THINK ONE LEASING PTE LTD Jul 18 2019 12:00AM [CHERN SU MIN BERNARD] Think One Autocare Pte Ltd

Vide	eo		1 per	page 🔽	V
Na	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnall	Print
1	31/07/19 13:43	Video - Accident From:SC - Reg. No: SOMSOP, Claimant: CHERN SU MIN BERNARD	0	Load MP4	
Pho	tos/Images		3 per	page 🔻	120
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	_
1	29/07/19 18:42	Odometer Reading	0	Load JPG	N
2	29/07/19 18:42	Chassis Number	0	Load JPG	Ø
3	29/07/19 18:43	Chassis Number	6	Load JPG	N
4	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
5	29/07/19 18:43	Chassis Number	0	Load JPG	M
6	29/07/19 18:43	Chassis Number	0	Load JPG	M
7	29/07/19 18:43	Chassis Number	0	Load JPG	M
8	29/07/19 18:43	Chassis Number	0	Load JPG	V
9	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
10	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
11	29/07/19 18:43	Chassis Number	0	Load JPG	E.
12	29/07/19 18:43	Chassis Number	0	Load JPG	N
13	29/07/19 18:43	Chassis Number	0	Load JPG	M
14	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
15	29/07/19 18:43	Chassis Number	0	Load JPG	
16	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
17	29/07/19 18:43	Chassis Number	0	Load JPG	2
18	29/07/19 18:43	Chassis Number	0	Load JPG	M
19	29/07/19 18:43	Chassis Number	0	Load JPG	V
20	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
21	29/07/19 18:43	Chassis Number	0	Load JPG	82
22	29/07/19 18:43	Chassis Number	0	Load JPG	12
23	29/07/19 18:43	Chassis Number	0	Load JPG	M
24	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
25	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
26	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
27	29/07/19 18:43	Chassis Number	0	Load JPG	80
28	29/07/19 18:43	Chassis Number	0	Load JPG	V
29	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
30	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
31	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
32	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
33	29/07/19 18:43	Chassis Number	0	Load JPG	V
34	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
35	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
36	29/07/19 18:43	Chassis Number	0	Load JPG	120
37	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
38	29/07/19 18:43	Chassis Number	0	Load JPG	N
30	29/07/19 18:43	Chassis Number	0	Load JPG	Ø

Vid	00		1 per	page 🗸	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
40	29/07/19 18:43	Chassis Number	0	Load JPG	N
41	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
42	29/07/19 18:43	Chassis Number	0	Load 3PG	
43	29/07/19 18:43	Chassis Number	0	Load JPG	
44	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
45	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
46	29/07/19 18:43	Chassis Number	0	Load JPG	821
47	29/07/19 18:43	Chassis Number	0	Load JPG	
48	29/07/19 18:43	Chassis Number	0	Load JPG	2
		Chassis Number	0	Load JPG	Ø
49	29/07/19 18:43		0	Load JPG	12
50	29/07/19 18:43	Chassis Number	0	Load JPG	2
51	29/07/19 18:43	Chassis Number		110 150 50 100 50	-
52	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
53	29/07/19 18:43	Chassis Number	0	Load JPG	82
54	29/07/19 18:43	Chassis Number	0	Load JPG	82
55	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
56	29/07/19 18:43	Chassis Number	0	Load 3PG	2
57	29/07/19 18:43	Chassis Number	0	Load JPG	
58	29/07/19 18:43	Chassis Number	0	Load JPG	
59	29/07/19 18:43	Chassis Number	0	Load JPG	N
60	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
61	29/07/19 18:43	Chassis Number	0	Load JPG	2
62	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
63	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
64	29/07/19 18:43	Chassis Number	0	Load JPG	₩.
65	29/07/19 18:43	Chassis Number	0	Load JPG	Ø
66	29/07/19 18:43	Chassis Number	O	Load JPG	82
-		10 0002 100	0	Load 3PG	8
67	08/08/19 08:45	Photo After Spray	0	Load JPG	8
68	08/08/19 08:45	Photo After Spray	0	Load 3PG	₩.
69	06/08/19 08:45	Photo After Spray		1090 350	BET
Do	umentation		1 per	page 🔻	Ø
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/07/19 17:41	ACKNOWLEDGEMENT EMAIL TO AIG DD 26.07.2019	0	Load PDF	
2	26/07/19 17:41	EMAIL FROM AIG DD 26.07.2019	0	Load PDF	
3	30/07/19 21:59	TP ESTIMATE - MARKED	0	Load PDF	
4	30/07/19 21:59	TP GIA REPORT	0	Load PDF	
5	10/12/19 11:14	EMAIL FROM AIG APPROVAL TO REJECT.	0	Load PDF	
6	10/12/19 11:14	EMAIL TO TP WKSHOP REJECT CLAIM	0	Load PDF	
Na	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	29/07/19 10:12	OI GIA REPORT	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			,
Show Remarks To: Handling Insurer Nate: Remarks are private unless you show it to other porties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No:199607198R)

51 Ubi Ave 1 #01-25. Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG19013220/UKA3Q2

Date:

19/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100396417

Claimant Vehicle No:

PC8116S

Insured Vehicle No: SDM50P

Date of Loss:

18/07/2019

Nature of Claim:

TP

Claim No: 8265069074SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

PC8116S

Make & Model:

TOYOTA HIACE, 3.0 COMMUTER GL (A)

Engine No: Chassis No:

Odometer:

1GD8385389 GDH2232001437

23900 km

Reg. Date: Colour

08/04/2019 (Man. Year: 2019)

Engine Capacity: Market Value/New Car Price: N/A

2754 cc

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

195/80 R15

Rear Tyre Size:

195/80 R15

Front Left Side:

Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side:

Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,672.35	3,935.47	3,736.88	48.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	1,240.00	890.00	41.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,802.35	5,175.47	4,626.88	47.20
Approved Total (Overridden) (S\$)		4,100.00	5,702.35 399.16	
(S\$)	9,802.35	4,100.00		58.17
+ GST 7.00/7.00% (S\$)	686.16	287.00		58.17
Nett Amount (S\$)	10,488.51	4,387.00	6,101.51	58.17
Global Sum S	settlement (S\$)	0.00		

INSPECTION

Date of Assignment:

26/07/2019

Date Inspected:

29/07/2019 Inspected At:

Think One Autocare Pte Ltd (HQ)

No. 18 Defu Avenue 2 Singapore 539522

Estimated Period of Repair:

3.0 days

Manager: Khanchna Pothuraj Adjuster: MARCUS CHUA

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liebility under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommend	led	Parts
-----------	-----	-------

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	988.00 FL	*-FL
2	1		*CORNER PANEL LH	Dented	352.30 FL	*352.30 FL
3	1		*CORNER PANEL INNER SUPPORT LH	Not Necessary	252.00 FL	*-FL
4	1		*FRONT BUMPER	Grazed	693.00 FL	*693.00 FL
5	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	120.10 FL	*-FL
6	1		*HEADLAMP BRACKET LH	Not Necessary	421.00 FL	*-FL
7	1		*DOOR PILLAR LH	Repair	1,422.00 FL	*-FL
В	1		*DOOR RH	Dented / Bent	1,752.00 FL	*1,752.00 FL
9	1		*HEADLAMP ASSY LH	Cracked	2,539.50 FN	*2,450.00 FN
10	1		*FENDER MIRROR LH	Not Necessary	985.00 FN	*- FN
F=Fn	nchise	part. L=ListIt	emDisc. N=NettItemDisc.	Sub Total (S\$)	9,524.90	5,247.30
			- List Item Discount on L Item	s 25.00/25.00% (S\$)	1,500.10	699.33
			- Nett Item Discount on N Item	ns 10.00/25.00% (S\$)	352.45	612.50
				Total Parts (S\$)	7,672.35	3,935.47

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
TO REMOVE DAMAGED BODY PARTS WITH ALL NECESSARY COMPONENTS /ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY REPAIR ,RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS /ATTACHMENTS	New	1,000.00	480.00
TO SPRAY PAINT REPLACED /REPAIRED BODY PARTS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	1,000.00	680.00
TO TRANSFER FRONT DOOR COMPONENTS WITH ALL NECESSARY ATTACHMENTS	New	100.00	60.00
TO CONDUCT HEADLAMP ALIGNMENT	New	30.00	20.00
Gross Labour Cost (S\$)		2,130.00	1,240.00
	TO REMOVE DAMAGED BODY PARTS WITH ALL NECESSARY COMPONENTS /ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY REPAIR ,RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS /ATTACHMENTS TO SPRAY PAINT REPLACED /REPAIRED BODY PARTS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS TO TRANSFER FRONT DOOR COMPONENTS WITH ALL NECESSARY ATTACHMENTS TO CONDUCT HEADLAMP ALIGNMENT	TO REMOVE DAMAGED BODY PARTS WITH ALL NECESSARY COMPONENTS /ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY REPAIR ,RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS /ATTACHMENTS TO SPRAY PAINT REPLACED /REPAIRED BODY PARTS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS TO TRANSFER FRONT DOOR COMPONENTS WITH ALL NEW NECESSARY ATTACHMENTS TO CONDUCT HEADLAMP ALIGNMENT New	TO REMOVE DAMAGED BODY PARTS WITH ALL New 1,000.00 NECESSARY COMPONENTS /ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY REPAIR ,RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS /ATTACHMENTS TO SPRAY PAINT REPLACED /REPAIRED BODY PARTS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS TO TRANSFER FRONT DOOR COMPONENTS WITH ALL NEW 100.00 NECESSARY ATTACHMENTS TO CONDUCT HEADLAMP ALIGNMENT New 30.00

< END OF ESTIMATES >