来發(明記)摩哆有限公司

LAI HUAT (MENG KEE) MOTOR PTE

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267 GST No: M2-0128609-3 UEN: 199407592C

ESTIMATE

EST. No: EST0022829

The Salvation Army

Page 1 of 2

Your ref. TP-SLP 9693P India

Job No. 70732

Payment

Attn

Vehicle No ...: PC 2320H Vehicle Model: Nissan NV350 Accident on ::: 22/7/2019

Not Nothairs

Ully 8?

Risony Afre Pain

Eday

Unit price Disc. pct. Amount Description Quantity Unit Supply of Parts - Nett item:

1.00	Pc I	Rear tailgate		1,742.00	10.00	120	,567.80	_
1.00		Rear tailgate chrome moulding		511.40	10.00	Sen	460.26	X
+ 1.00		Rear bumper		600.20	10.00		540.18	
4.00		Rear bumper lower clips		12.00	10.00	na	43.20	
1.00		Rear logo emblem		59.70	10.00	ne	53.73	
> 1.00		Rear NV350 emblem		101.30	10.00	M	91.17	
1.00		Rear URVAN emblem		59.70	10.00	Me	53.73	
1.00		Rear tail lamp LH	NZ	209.80	10.00((Py)	188.82	X

1.00 Pc Rear Emergency & Pull to Open sticker 1.00 Pc Rear 70km sticker	15.00
---	-------

Ma 20.00 va 15.00 C

Labour & Misc.

Special nett item:

1.00

140.00

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

除外,还有先进的 SAICO Deluxe 喷漆烘炉。

本公司拥有最先进的 CAROLINER MARK IV 机械,可提供给感感或的底扇及给于快速与准确的测量方式和大铁修理 Signature:

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICC Deluxe oven heater for re-spraying all motor vehicles."