

Rame

ASSIGNMENT

Form: _____ Date: _____
 Estimated Cost: _____
 () / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SCM 9545G**
 at Workshop n/s: **PREMIUM**
 of: **281, Alexander Rd**
 Insured: **AKH**
 Policy No: _____
 Claims No: _____
 Sum Insured: _____
 (Client's Record)
 Make of Vels: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

341K

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res: Yes or No

Lien Sett:

% 3 Val: Yes or No

CA / **REV** / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: **SCM 9545G** Yr Reg: **2019 / MAR**
 Type: **C** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: **Audi A7 3.0** cc **2995**

Colour: **Red** A/C: Insured / Std / Nil / NA

Sp Reading: **6750** T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No: **WAUZZZF2XKN063880**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: **C** / Jammed / Leaked / Burnt or

Drain: **C** / Jammed / Leaked / Burnt or

Modi: Nil / 2 Rim / STD / Rim or

Tyre Size F: **225/55R21**

R:

BS / DUN / EXNOVA / GY / S / LIZA / MIC / OHTSU / **C** / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: **6** mm

R/Bal: **6** mm

L/Bal: **6** mm

L/Bal: **6** mm

D.O.A: **22/07/19**

D.O.I: **26/07/19**

Survey held at: **PREMIUM**

Des. of Damages: **C** / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SCM 9545G - X

29/07/19 @ 12:04 pm revised IA to AIG via memo.

29/07/19 @ 14:37 pm mandee request authorize repair to Victor via memo.

29/07/19 @ 16:24 pm mandee approved by Victor Koh.

29/07/19 @ 17:23 pm inform CIA to George via email.

03/08/19 Confirmed P/P \$ 24,451.20 @ 5 days with Result.
 (\$ 31,897.80 Red - 61%)

Date/Time, File Pass (s)

19/02/20

Typist

Date/Time, File Return (s)

2)

Report Format:

Lump Sum / I.B. (\$) **24,451.20 P/P**

Days Of Repair: **5**

Resurvey No. of Trip: **1**

Add Fee:

☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

Photos

Others

TOTAL

200

11

211

6/12/2019

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	316F
Vehicle Details	
Vehicle No.:	SCM9545G
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jul 2019
Vehicle Make:	AUDI
Vehicle Model:	A7 5B 3.0 TFSI QU S TRONIC (SR, 21")
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	DLZ023139
Chassis No.:	WAUZZZF2XKN063880
Maximum Power Output:	250.0 kW (335 bhp)
Open Market Value:	\$73,088.00
Original Registration Date:	05 Mar 2019
First Registration Date:	05 Mar 2019
Transfer Count:	0
Actual ARF Paid:	\$103,559.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Mar 2029
PARF Rebate Amount:	\$77,669.00
Intended COE Rebate Details	
COE Expiry Date:	04 Mar 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$34,509.00
COE Rebate Amount:	\$33,108.00
Total Rebate Amount:	\$110,777.00

The information contained herein is correct as at 29 Jul 2019

OK

341,000
110,777
230,223

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Wednesday, 4 December 2019 11:02 am
To: jiajee.yap@premiumauto.com.sg; Adrian Ling (LKKAuto)
Cc: 'Boo seng yak'; 'Carrine Leong'; 'Chang Chee Sing'; CS A Team; Admin A; SUR; Rasul (LKKAuto)
Subject: RE: FINAL REVISION - SCM9545G - OD AIG - SURVEYED 26 JUL 19

Dear Jia Yee,

Confirmed final fig \$24,451.20 @ 5 days of repairs before excess \$ 1,000/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jiajee.yap@premiumauto.com.sg <jiajee.yap@premiumauto.com.sg>
Sent: Monday, 30 September 2019 10:42 am
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: 'Boo seng yak' <boojohnny@gmail.com>; 'Carrine Leong' <carrine.leong@premiumauto.com.sg>; 'Chang Chee Sing' <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SCM9545G - OD AIG - SURVEYED 26 JUL 19

Hi Adrian, Rasul and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$24,451.20 @ 5 days of repair.

Your early closure is well appreciated.

Thanks & Best Regard
JiaYee Yap
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 189902273W)
55 Ubi Road 1 Road Singapore 408699

Re: Supplementary list and check item list for SCM 9545 G

Shirley Hiew (LKK Auto)

Mon 9/9/2019 5:21 PM

To: glory.tan@premiumauto.com.sg <glory.tan@premiumauto.com.sg>; SUR <sur@lkkauto.com>

Cc: 'Claims' <claims@premiumauto.com.sg>; allan.wu@premiumauto.com.sg <allan.wu@premiumauto.com.sg>

1 attachments (864 KB)

SUPP & CHECK ITEMS MARKED.pdf;

Hi Glory,

Supplementary approved by AIG.

Check items has been marked by Rasul. Please refer attached.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte LtdPhone: 6256-3561 | email: [Sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: glory.tan@premiumauto.com.sg <glory.tan@premiumauto.com.sg>**Sent:** Friday, 6 September 2019 9:39 AM**To:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; SUR <sur@lkkauto.com>**Cc:** 'Claims' <claims@premiumauto.com.sg>; allan.wu@premiumauto.com.sg
<allan.wu@premiumauto.com.sg>**Subject:** Supplementary list and check item list for SCM 9545 G

Dear Shirley,

Please refer to the attached for supplementary list and check item marked estimate list for SCM 9545.

The blue circles in marked estimate are the check items.

We are still waiting for the supplementary items approval so that we only can proceed repairing. Please revise and get back to us.

Thank you.

Best Regard,

Glory Tan

Bodyworks Department

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 f. +65 6841 1183

e. glory.tan@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

From: glory.tan@premiumauto.com.sg <glory.tan@premiumauto.com.sg>
Sent: Tuesday, 3 September 2019 4:49 PM
To: 'taufikh@lkkauto.com' <taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'allan.wu@premiumauto.com.sg' <allan.wu@premiumauto.com.sg>; 'Claims' <claims@premiumauto.com.sg>
Subject: Supplementary list and check item list for SCM 9545 G

Dear Taufikh,

Please refer to the attached for supplementary list and check item list for SCM 9545 G.

Thank you.

Best Regard,
Glory Tan
Bodyworks Department

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 f. +65 6841 1183

e. glory.tan@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 29 July 2019 5:23 PM
To: claims@premiumauto.com.sg
Cc: SUR; assignments
Subject: RE: OD CLAIMS FOR SCM 9545 G
Attachments: ESTIMATE.pdf

Dear George,

As instructed by our client, please proceed to repair the insured vehicle **SCM 9545G (Excess \$ 1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Monday, 29 July 2019 2:27 PM
To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>
Cc: 'SUR' <sur@lkkauto.com>; 'assignments' <assignments@lkkauto.com>; claims@premiumauto.com.sg
Subject: RE: OD CLAIMS FOR SCM 9545 G

Hi Shirley,

Please find attached for the CI and Driving license

Thank you.

Best Regards,
Ezuwan Huzaini
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 **d.** +65 6768 9911 **f.** +65 6841 1183
e. claims@premiumauto.com.sg **w.** www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 **p.** +65 6836 2223

View Received Message

This mail is associated with :

***SCM9545G (7527576363SG)**

OD

Jul 22 2019 7:00PM

[TANG KOK PENG]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 02/12/2019 10:42 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$24451.20) - SCM9545G - Claim Handler: Nadaraja, Deeban

Approved:24451.20:

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SCM9545G (7527576363SG)**

OD

Jul 22 2019 7:00PM

[TANG KOK PENG]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 09/09/2019 16:57 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$15665.00) - SCM9545G - Claim Handler: Nadaraja, Deeban

Approved:15665.00:Re-inspection to be done for damage check and supplementary items / labour,

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SCM9545G (7527576363SG)**

OO

Jul 22 2019 7:00PM

[TANG KOK PENG]

Premium Automobiles Pte Ltd - Alexandra

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 29/07/2019 16:24 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$14652.00) - SCM9545G - Claim Handler: Nadaraja, Deeban

Approved:14652.00;Re-inspection to be done for damage check and supplementary items / labour,

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nadaraja, Deeban

Date: 05 Sep 2019

Preliminary Advice

Vehicle No	: SCM9545G	Accident Date	: 22/07/2019
Make	: AUDI A7	Policy No.	: 1900023012
Assignment Date	: 29/07/2019	Excess	: S\$1,000.00
Date of Inspection	: 26/07/2019	Est. Duration of Repair	: 5 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	62,349.00 (inclusive supp)
Revised Amount	:S\$	15,665.00 (inclusive supp)
Check Items (Estimated)	:S\$	36,014.00
Total	:S\$	51,679.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	341,000.00
COE / PARF Rebate	:S\$	110,777.00
Salvage Value	:S\$	
Margin for Repair	:S\$	230,223.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplementary amount is \$ 1,013.00.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 29 Jul 2019

Preliminary Advice

Vehicle No	: SCM9545G	Accident Date	: 22/07/2019
Make	: AUDI A7	Policy No.	: 1900023012
Assignment Date	: 29/07/2019	Excess	: S\$0.00
Date of Inspection	: 26/07/2019	Est. Duration of Repair	: 5 days
Inspection At	: Premium Automobiles Pte Ltd - Alexandra (HQ) 281 Alexandra Pte Ltd, Level B2 Singapore 159938		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	61,336.00
Revised Amount	:S\$	14,652.00
Check Items (Estimated)	:S\$	36,014.00
Total	:S\$	50,666.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	341,000.00
COE / PARF Rebate	:S\$	110,777.00
Salvage Value	:S\$	
Margin for Repair	:S\$	230,223.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/07/2019 14:14
Date Of Accident	22/07/2019 19:20
Exact Location Of Accident	UPPER BUKIT TIMAH ROAD IN FRONT OF SHELL STATION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCM9545G
Insured/Policyholder	
Name Of Registered Owner	TANG KOK PENG
NRIC No	S1758316F
Email Address	DTKP2002@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96759600
Alternative Phone No	OFFICE-96759600

Vehicle Particulars

Manufacturer	AUDI
Model	A7 SB 3.0 TFSI QU
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900023012
Cover Note Number	

Driver

Name of Driver	TANG KOK PENG
NRIC No	S1758316F
Date Of Birth	28/03/1966
Occupation	INDOOR
Date Of Driving Pass	10/01/1989
Driving Experience	30 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96759600
Fax Number	
Contact Number	OFFICE-96759600
Email Address	DTKP2002@YAHOO.COM

Address	64 ENG KONG TERRACE
Postcode	599018
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG UPPER BUKIT TIMAH ROAD IN THE DIRECTION OF BUKIT PANJANG. TRAFFIC WAS HEAVY. WHEN I WAS IN FRONT OF THE SHELL STATION (NEXT TO BUKIT TIMAH HAWKER CENTRE) , THE CAR (SLH 1266 J) IN FRONT OF ME BRAKE SUDDENLY. I WAS JUST GOING TO MOVE MY CAR AND COULD NOT STOP IN TIME. HITTING SLH 1266 J AT THE BACK. I THEN REALIZED THAT IT WAS A CHAIN ACCIDENT BECAUSE THE CAR I HIT HAS ALSO HIT THE CAR IN FRONT (SMG 6533 Z).

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH1266J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMG6533Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name: S. BHARATHI
NRIC/IN No: G2947434

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along ~~the~~ Upper Bukit Timah Road in the direction of Bukit Panjang. Traffic was heavy. When I was in front of the shell station (next to Bukit Timah Hawker centre), the car ~~to~~ (SLH1266J) in front of me brake suddenly. I was just going to move my car and could not stop in time, hitting SLH1266J at the back. I then realised that it was a chain accident because the car I hit has also hit the car in front (SMH6533Z).

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Concern Personnel's Signature
Name: Willy Kenneth S. Bandy, Group
NRIC/PA No: G29871436



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : TANG KOK PENG
Period of Insurance : 05 Mar 2019 To 04 Mar 2020
Engine No. : DL2023139
Chassis No. : WAUZZZF2XKN063880

Vehicle No. : SCM9545G
Policy No. : 1900023012
Endorsement No. :
Issued Date : 06 Mar 2019

ABOUT THE COVER

Make/Model	: AUDI A7 (PI) SPORTBACK 3.0 TFSI QU		
Engine Capacity/Tonnage	: 2,995.00 CC	Sum Insured	: Market Value
Driver Restriction	: Age/DE Condition	Off Peak Car	: No
Person or Classes of Persons Entitled to Drive*			First Year of Registration : 2019
			Insuring with COE/PAF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition

Any driver who is below 25 years old is not covered under this Policy.
You have to pay an additional sum of \$35,000 as "Elderly, Young and/or Inexperienced Driver Excess" ("EYIDR") if You are or Your Authorized Driver (named or unnamed) is above the age of 85 or under the age of 25 and/or has less than 2 years' driving experience.

Age Condition : Driver Restriction applies-Refer to T&C
Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1967 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$2000 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - 10

Wintergreen: \$100

Named Driver and Excess (where applicable)
--

TANG KOK PENG - \$2000 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

† Audi Customer Service Center, Add: 55, Ubi Road 1 Singapore 408699 83662327

For other Approved Reporting Centres/AIG Authorised Repairs, please contact our 24-hour accident emergency hotline at +65 6338 6300. Alternatively, you may refer to AIG website www.aig.com.sg or AIG 24 Mobile App. Simply search and download "AIG 50" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

(We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 188), Part IV of the Road Transport Act, 1967 (Akta Laluan dan Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125216

PREMIUM LEASING - CW

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Five

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Will/Summons/Correspondence from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within 5 working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the original insurance policy and schedule issued by AIG, a copy of the Accident Report from Audi Customer Service Centre must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc.)

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0902/2019/GW
Date	:	25-Jul-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Tang Kok Peng
Address	:	64 Eng Kong Terrance Singapore 599018
Telephone	:	HP +65 96759600
Type of Claim	:	Own Damage Claims
Policy No.	:	1900023012
Vehicle No	:	SCM 9545 G
Model Code	:	Audi A7 3.0 TFSI Qu
Model / Year	:	Mar-19
Engine No	:	DLZ 023139
Chassis No	:	WAUZZZF2XKN063880
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	22-Jul-19
Place of Accident	:	Upper Bukit Timah Rd In Front of Shell Station

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SCM 9545 G

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓
2	To remove and renew aircond condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,400.00 ? ✓ 1400.00 Xan
3	To dismantle and renew front bumper, bonnet and both headlights. To renew front lock carrier and align to position. Reinstall all parts removed.	\$ 6,300.00 1000 1250
4	To respray front bumper, bonnet and both front fenders.	\$ 4,500.00 1100
5	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u>\$ 12,872.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCM 9545 G

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>de</i>	S 3,289.00	2631.20
2	FRONT BUMPER FIXING PARTS <i>? X SUC</i>	S 589.00	X
3	FRONT BUMPER CLOSING ELEMENT -CENTER <i>? cm</i>	S 202.00	161.60
4	FRONT BUMPER ADAPTER-LH/RH <i>? cm</i>	2 S 72.00	56.32
5	FRONT BUMPER CATCH-LH/RH <i>? X SUC</i>	2 S 80.00	
6	FRONT BUMPER GRILLE-LOWER CENTRE <i>X SUC</i>	S 175.00	
7	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>X SUC</i>	S 265.00	
8	FRONT BUMPER SPOILER <i>X SUC</i>	S 229.00	
9	FRONT BUMPER REINFORCEMENT-LH/RH <i>? X SUC</i>	2 S 152.00	
10	FRONT BUMPER AIR GUIDE GRILLE-LH/RH <i>? X RH-ut/LH-X SUC</i>	2 S 904.00	452 361.20
11	FRONT BUMPER AIR GUDIE-LH/RH <i>? X SUC</i>	2 S 118.00	
12	FRONT BUMPER REAR AIR GUDIE-LH/RH <i>X SUC</i>	2 S 118.00	
13	RADIATOR GRILLE <i>cm</i>	S 2,031.00	1624.80
14	RADIATOR GRILLE INSCRIPTION ' QUATTRO ' <i>cm</i>	S 87.00	69.28
15	RADIATOR GRILLE INSCRIPTION ' QUATTRO ' BRACKET <i>X SUC</i>	S 11.00	X
16	RADIATOR GRILLE COVER <i>? cm X SUC</i>	S 49.00	
17	RADIATOR GRILLE BRACKET <i>X SUC</i>	S 85.00	X
18	RADIATOR COVER CAP <i>? X SUC</i>	S 33.00	X
19	CONNECTOR HOUSING BRACKET-LH <i>? X SUC</i>	S 25.00	X
20	FRONT FOAM FILLER PIECE <i>int</i>	S 205.00	164
SUB-TOTAL SPARE PARTS		S 8,719.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCM 9545 G

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT BUMPER RENFORCEMENT BEAM ? x su	\$	887.00 X
22	FRONT BUMPER SUPPORT ? x su	2 \$	53.00 X
23	FRONT BUMPER COVER ? cu	\$	131.00 104.80
24	FRONT BUMPER GUIDE SECTION-LH/RH ? x su	2 \$	80.00 X
25	SIGN 'CAUTION' ? x su	\$	13.00 X
26	AIR CONDITIONER STICKER ? x su	\$	7.00 X
27	FRONT SENSOR ? x su	2 \$	462.00 X
28	FRONT SENSOR SEAL RING ? x su	4 \$	12.00 X
29	FRONT FAN FARE -LH LOW TONE ? x su	\$	198.00 X
30	FRONT FAN FARE -RH HIGH TONE ? x su	\$	198.00 X
31	SPRING SHACKLE-LH/RH ? x su	2 \$	86.00 X
32	BONNET 34	\$	5,605.00 44.84
33	BONNET IMPACT PROTECTION-LH/RH cu	2 \$	35.00 27.44
34	BONNET IMPACT PROTECTION-CENTER cu	\$	40.00 31.84
35	BONNET STRIKER-LH/RH ? x su	2 \$	200.00 X
36	SOUND ABSORBER FOR FLAP x su	\$	289.00
37	BONNET RELEASE ELEMENT ? x su		TBC X
38	BONNET BOWDEN CABLE-CENTER ? x su	\$	53.00 X
39	BONNET BOWDEN CABLE COVER ? x su	\$	9.00 X
40	BONNET RELEASE LEVER ? x su	\$	12.00 X
SUB- TOTAL SPARE PARTS		\$	8,370.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCM 9545 G

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	HEADLIGHT MOUNTING-LH/RH ? cm /	2 \$ 107.00	85.60
42	LED HEADLIGHT WITH MATRIX BEAM -LH/RH ? cm /	2 \$ 23,716.00	11858 9426.40
43	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM-LH/RH ? X sm	2 \$ 362.00	
44	HOSE ON ROLLER 5M FOR LIFT CYLINDER X sm	2 \$ 80.00	
45	LOCK CARRIER WITH MOUNTING FOR RADIATOR ? X sm	\$ 1,127.00	
46	A/C CONDENSER ? bt /	\$ 568.00	454
47	RADIATOR ? X sm	\$ 1,029.00	X
48	READY MIX COOLANT ? X sm	4 \$ 165.00	X
49	ADDITIONAL RADIATOR ? X sm	\$ 724.00	X
50	RADIATOR FAN RING ? X sm	\$ 242.00	X
51	RADIATOR FAN WITH CONTROL UNIT ? X sm	\$ 2,107.00	X
52	RADIATOR AIR GUIDE-LH/RH ? X sm	2 \$ 68.00	✓ 53.76
53	RADIATOR UPPER AIR GUIDE-LH ?	\$ 27.00	X
54	RADIATOR LOWER AIR GUIDE-RH ?	\$ 29.00	X
55	AIR INTAKE AIR DUCT ?	\$ 42.00	X
56	AIR INTAKE INNER AIR DUCT ?	\$ 76.00	X
57	AIR FILTER FOR AIR INTAKE ?	\$ 266.00	X
58	AIR INTAKE HOSE ?	\$ 100.00	X
59	FRONT NO. PLATE X bt /	S/N \$ 40.00	✓
60	SUNDRIES ?	\$ 500.00	64.88
TOTAL SPARE PARTS		: \$ 48,464.00	
TOTAL LABOUR CHARGES		: \$ 12,872.00	
GRAND TOTAL		: \$ 61,336.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved. Remarks (X) = Not approved
Spare parts are Special Nett.

62349

62316 08

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: RASUL - 4p 90010068

: 26/07/19 @ 1540

: 5 days

: EXCESS: TBA

REVERT

Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Tel : (65) 6366 2323 Fax : (65) 6841 1183

GST Reg No. 19-9902271-W

For Premium Automobiles Pte Ltd

Date:

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Norakhai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0902/2019/GW
Date	:	25-Jul-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Tang Kok Peng
Address	:	64 Eng Kong Terrace Singapore 599018
Telephone	:	HP +65 96759600
Type of Claim	:	Own Damage Claims
Policy No.	:	1900023012
Vehicle No	:	SCM 9545 G
Model Code	:	Audi A7 3.0 TFSI Qu
Model / Year	:	Mar-19
Engine No	:	DLZ 023139
Chassis No	:	WAUZZZF2XKN063880
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	22-Jul-19
Place of Accident	:	Upper Bukit Timah Rd In Front of Shell Station

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SCM 9545 G

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 /
2	To remove and renew aircond condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,400.00 ? X 111
3	To dismantle and renew front bumper, bonnet and both headlights. To renew front lock carrier and align to position. Reinstall all parts removed.	\$ 6,300.00 1000
4	To respray front bumper, bonnet and both front fenders.	\$ 4,500.00 1100
5	To carry out diagnostic check.	S/N \$ 192.00 /
TOTAL LABOUR CHARGES		: \$ <u>12,872.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCM 9545 G

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
1	FRONT BUMPER <i>de-</i>	S	3,289.00
2	FRONT BUMPER FIXING PARTS <i>? XSVL</i>	S	589.00
3	FRONT BUMPER CLOSING ELEMENT - CENTER <i>? crn -</i>	S	202.00
4	FRONT BUMPER ADAPTER <i>(H/RH) ? ca</i>	2 S	72.00
5	FRONT BUMPER CATCH-LH/RH <i>? XSVL</i>	2 S	80.00
6	FRONT BUMPER GRILLE-LOWER CENTRE <i>XSVL</i>	S	175.00
7	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>XSVL</i>	S	265.00
8	FRONT BUMPER SPOILER <i>XSVL</i>	S	229.00
9	FRONT BUMPER REINFORCEMENT-LH/RH <i>? XSVL</i>	2 S	152.00
10	FRONT BUMPER AIR GUIDE GRILLE-LH/RH <i>? XSVL</i>	2 S	904.00 452
11	FRONT BUMPER AIR GUDIE-LH/RH <i>? XSVL</i>	2 S	118.00
12	FRONT BUMPER REAR AIR GUDIE-LH/RH <i>XSVL</i>	2 S	118.00
13	RADIATOR GRILLE <i>crn -</i>	S	2,031.00
14	RADIATOR GRILLE INSCRIPTION 'QUATTRO' <i>crn -</i>	S	87.00
15	RADIATOR GRILLE INSCRIPTION 'QUATTRO' BRACKET <i>crn -</i>	S	11.00
16	RADIATOR GRILLE COVER <i>? XSVL</i>	S	49.00
17	RADIATOR GRILLE BRACKET <i>crn -</i>	S	85.00
18	RADIATOR COVER CAP <i>? MIS -</i>	S	33.00
19	CONNECTOR HOUSING BRACKET-LH <i>? XSVL</i>	S	25.00
20	FRONT FOAM FILLER PIECE <i>crn -</i>	S	205.00
SUB-TOTAL SPARE PARTS		S	8,719.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

OK
6/8.
AIR SK 6/8.
AIR GER

AIR SK -

AIR SK -

AIR GER -

AIR GER -

AIR GER -

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCM 9545 G

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
SK MR.	21 FRONT BUMPER REINFORCEMENT BEAM ? x suc	S	887.00
SK MR.	22 FRONT BUMPER SUPPORT ? x suc	2 S	53.00
SK MR.	23 FRONT BUMPER COVER ? crn	S	131.00
SK MR.	24 FRONT BUMPER GUIDE SECTION-LH/RH ? x suc	2 S	80.00
25	SIGN 'CAUTION' ? n	S	13.00
26	AIR CONDITIONER STICKER ? n	S	7.00
27	FRONT SENSOR ? x suc	2 S	462.00
28	FRONT SENSOR SEAL RING ? x suc	4 S	12.00
29	FRONT FAN FARE-LH LOW TONE ? x suc	S	198.00
30	FRONT FAN FARE-RH HIGH TONE ? x suc	S	198.00
31	SPRING SHACKLE-LH/RH ? x suc	2 S	86.00
SK MR.	32 BONNET St	S	5,605.00
SK MR.	33 BONNET IMPACT PROTECTION-LH/RH n	2 S	35.00
SK MR.	34 BONNET IMPACT PROTECTION-CENTER n	S	40.00
SK MR.	35 BONNET STRIKER-LH/RH ? x suc	2 S	200.00
36	SOUND ABSORBER FOR FLAP x suc	S	289.00
37	BONNET RELEASE ELEMENT ? St		TBC
38	BONNET BOWDEN CABLE-CENTER ? x suc	S	53.00
39	BONNET BOWDEN CABLE COVER ? x suc	S	9.00
40	BONNET RELEASE LEVER ? x suc	S	12.00
SUB-TOTAL SPARE PARTS		\$	8,370.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCM 9545 G

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
SC MK - (41)	HEADLIGHT MOUNTING-LH/RH ? ca /	2 S	107.00
GER MK - (42)	LED HEADLIGHT WITH MATRIX BEAM-LH/RH ? ca /	2 S	23,716.00 11858
43	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM-LH/RH ? X su	2 S	362.00
44	HOSE ON ROLLER 5M FOR LIFT CYLINDER X su	2 S	80.00
45	LOCK CARRIER WITH MOUNTING FOR RADIATOR ? X su	S	1,127.00
(46)	A/C CONDENSER ? bt /	S	568.00
47	RADIATOR ? X su	S	1,029.00
48	READY MIX COOLANT ? X su	S	165.00
49	ADDITIONAL RADIATOR ? Charge with Cooler X su	S	724.00
50	RADIATOR FAN RING ? X su	S	242.00
51	RADIATOR FAN WITH CONTROL UNIT ? X su	S	2,107.00
(52)	RADIATOR AIR GUIDE ? ca /	2 S	68.00
53	RADIATOR UPPER AIR GUIDE-LH ? X su	S	27.00
54	RADIATOR LOWER AIR GUIDE-RH ? X su	S	29.00
55	AIR INTAKE AIR DUCT ? X su	S	42.00
56	AIR INTAKE INNER AIR DUCT ? X su	S	76.00
57	AIR FILTER FOR AIR INTAKE ? X su	S	266.00
58	AIR INTAKE HOSE ? X su	S	100.00
59	FRONT NO. PLATE X bt /	S/N S	40.00
60	SUNDRIES ?	S	500.00
TOTAL SPARE PARTS		:	\$ 48,464.00
TOTAL LABOUR CHARGES		:	\$ 12,872.00
GRAND TOTAL		:	\$ 61,336.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: RASUL - Hp 90010068

: 26/07/19 @ 1540

:

: 5 days

:

: EXCESS: TBA

:

Revert

Recovery before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0902/2019/GW
Date : 25-Jul-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Rasul,
5 days - ok - Jy - 30 Sep 2019

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tang Kok Peng
Address : 64 Eng Kong Terrance
Singapore 599018
Telephone : HP +65 96759600
Type of Claim : Own Damage Claims
Policy No. : 1900023012
Vehicle No : **SCM 9545 G**
Model Code : Audi A7 3.0 TFSI Qu
Model / Year : Mar-19
Engine No : DLZ 023139
Chassis No : WAUZZZF2XKN063880
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Jul-19
Place of Accident : Upper Bukit Timah Rd In Front of Shell Station

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SCM 9545 G

S/N	Nature of Jobs	Estimated Charges			
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00	\$	480.00
2	To remove and renew aircond condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N	\$ 1,400.00	\$	1,400.00
3	To dismantle and renew front bumper, bonnet and both headlights. To renew front lock carrier and align to position. Reinstall all parts removed.		\$ 6,300.00	\$	1,250.00
4	To respray front bumper, bonnet and both front fenders.		\$ 4,500.00	\$	1,100.00
5	To carry out diagnostic check.	S/N	\$ 192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 12,872.00	\$	4,422.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCM 9545 G

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 3,289.00	\$ 2,631.20
2	FRONT BUMPER FIXING PARTS	\$ 589.00	
3	FRONT BUMPER CLOSING ELEMENT -CENTER	\$ 202.00	\$ 161.60
4	FRONT BUMPER ADAPTER-LH/RH	2 \$ 72.00	\$ 56.32
5	FRONT BUMPER CATCH-LH/RH	2 \$ 80.00	
6	FRONT BUMPER GRILLE-LOWER CENTRE	\$ 175.00	
7	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 265.00	
8	FRONT BUMPER SPOILER	\$ 229.00	
9	FRONT BUMPER REINFORCEMENT-LH/RH	2 \$ 152.00	
10	FRONT BUMPER AIR GUIDE GRILLE-LH/RH	2 \$ 904.00	\$ 361.20
11	FRONT BUMPER AIR GUDIE-LH/RH	2 \$ 118.00	
12	FRONT BUMPER REAR AIR GUDIE-LH/RH	2 \$ 118.00	
13	RADIATOR GRILLE	\$ 2,031.00	\$ 1,624.80
14	RADIATOR GRILLE INSCRIPTION ' QUATTRO '	\$ 87.00	\$ 69.28
15	RADIATOR GRILLE INSCRIPTION ' QUATTRO ' BRACKET	\$ 11.00	
16	RADIATOR GRILLE COVER	\$ 49.00	
17	RADIATOR GRILLE BRACKET	\$ 85.00	
18	RADIATOR COVER CAP	\$ 33.00	
19	CONNECTOR HOUSING BRACKET-LH	\$ 25.00	
20	FRONT FOAM FILLER PIECE	\$ 205.00	\$ 164.00
SUB-TOTAL SPARE PARTS		\$ 8,719.00	\$ 5,068.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCM 9545 G

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		<i>c/f</i>	\$	5,068.40
21	FRONT BUMPER RENFORCEMENT BEAM	\$	887.00	
22	FRONT BUMPER SUPPORT	2 \$	53.00	
23	FRONT BUMPER COVER	\$	131.00	\$ 104.80
24	FRONT BUMPER GUIDE SECTION-LH/RH	2 \$	80.00	
25	SIGN 'CAUTION'	\$	13.00	
26	AIR CONDITIONER STICKER	\$	7.00	
27	FRONT SENSOR	2 \$	462.00	
28	FRONT SENSOR SEAL RING	4 \$	12.00	
29	FRONT FAN FARE -LH LOW TONE	\$	198.00	
30	FRONT FAN FARE -RH HIGH TONE	\$	198.00	
31	SPRING SHACKLE-LH/RH	2 \$	86.00	
32	BONNET	\$	5,605.00	\$ 4,484.00
33	BONNET IMPACT PROTECTION-LH/RH	2 \$	35.00	\$ 27.44
34	BONNET IMPACT PROTECTION-CENTER	\$	40.00	\$ 31.84
35	BONNET STRIKER-LH/RH	2 \$	200.00	
36	SOUND ABSORBER FOR FLAP	\$	289.00	
37	BONNET RELEASE ELEMENT	\$	52.10	
38	BONNET BOWDEN CABLE-CENTER	\$	53.00	
39	BONNET BOWDEN CABLE COVER	\$	9.00	
40	BONNET RELEASE LEVER	\$	12.00	
SUB- TOTAL SPARE PARTS		:	\$ 8,422.10	\$ 9,716.48

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCM 9545 G

S/N	Parts Description		Damage Pa S/NETT
		<i>c/f</i>	
41	HEADLIGHT MOUNTING-LH/RH	2 \$	107.00
42	LED HEADLIGHT WITH MATRIX BEAM -LH/RH	2 \$	23,716.00
43	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM-LH/RH	2 \$	362.00
44	HOSE ON ROLLER 5M FOR LIFT CYLINDER	2 \$	80.00
45	LOCK CARRIER WITH MOUNTING FOR RADIATOR	\$	1,127.00
46	A/C CONDENSER	\$	568.00
47	RADIATOR	\$	1,029.00
48	READY MIX COOLANT	4 \$	165.00
49	ADDITIONAL RADIATOR	\$	724.00
50	RADIATOR FAN RING	\$	242.00
51	RADIATOR FAN WITH CONTROL UNIT	\$	2,107.00
52	RADIATOR AIR GUIDE-LH/RH	2 \$	68.00
53	RADIATOR UPPER AIR GUIDE-LH	\$	27.00
54	RADIATOR LOWER AIR GUIDE-RH	\$	29.00
55	AIR INTAKE AIR DUCT	\$	42.00
56	AIR INTAKE INNER AIR DUCT	\$	76.00
57	AIR FILTER FOR AIR INTAKE	\$	266.00
58	AIR INTAKE HOSE	\$	100.00
59	FRONT NO. PLATE	S/N \$	40.00
60	SUPPLEMENTARY	\$	1,013.00
61	SUNDRIES	\$	500.00
	TOTAL SPARE PARTS	:	\$ 49,529.10
	TOTAL LABOUR CHARGES	:	\$ 12,872.00
	GRAND TOTAL	:	\$ 62,401.10

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

rates & Prices

REMARKS

\$	9,716.48
\$	85.60
\$	9,486.40

\$	454.00
----	--------

\$	53.76
----	-------

\$	40.00
----	-------

\$	128.08
----	--------

\$	64.88
----	-------

\$	20,029.20
----	-----------

\$	4,422.00
----	----------

\$	24,451.20
----	-----------

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0902/2019/GW 3-Sep-19 Glory Tan 1 of 1 SCM 9545 G Audi A7 3.0 TFSI Qu	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	Radiator grille camera <i>XSVL</i>	\$ 852.00		
2	Bracket for camera <i>cm</i>	\$ 85.00	\$	67.52
3	Securing plate for camera <i>SCA</i>	\$ 76.00	\$	60.56
		\$ 1,013.00		
	TOTAL	\$ 1,013.00	\$	128.08

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SCM 9545 G

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0902/2019/NH

17th February 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SCM 9545 G, Audi A7 SB 3.0 TFSI QU.

With reference to the above-mentioned vehicle, no. **SCM 9545 G**, claimant, **Mr. Tang Kok Peng**, please find the related document per attached.

1. A copy of the Original invoice no. 85014842 – S\$ 25,092.78.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SCM 9545 G

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 15:44

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014842 Date: 14/02/2020 Order: SCM9545G Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SCM9545G (V 41318) Regn Date: 05/03/2019 Mileage: 15699 WIP No.: 62011

Model: A7 SB 3.0 TFSI qu 4KA02Y Chassis: WAUZZZF2KXN063880 Engine: DLZ 023139 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	40.00	1.00	40.00
Q	EXC	M: 8888 Insurance Excess/Liability	-1000.00	1.00	-1,000.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO REMOVE AND RENEW AIRCON CONDENSER. REMOVE AND REINSTALL RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM.	1400.00	1.00	1,400.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. TO REALIGN FRONT LOCK CARRIER TO POSITION. REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND BONNET	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A4K8807065E GRU	COVER(LAST)	1.00	3289.00	2,631.20
X	A4K8807233	(A) (SK) PLATE 6/8/19	Less 020%	1.00	202.00
X	A4K8807077	(A) (SK) ADAPTER 2/9/1	Less 020%	1.00	35.20
X	A4K8807078	007409/(V) (GER) ADAPT	Less 020%	1.00	35.20
X	A4K8807648C RU6	(A) (SK) GRILL 2/9/19	Less 020%	1.00	451.50
X	A4K8853651 RN4	(A) (SK) GRILLE 6/8/19	Less 020%	1.00	2031.00
X	A4G0853737 222	INSCRIPTION "QUATTRO	Less 020%	1.00	86.60
X	A4K8853231	007407/(V) (GER) BRACK	Less 020%	1.00	84.40
X	A4K8853140 9B9	(A) (GER) CAP 6/8/19 A	Less 020%	1.00	32.10
X	A4K8807550D	(A) (GER) FOAM INSER 6	Less 020%	1.00	205.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Teletax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Teletax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Teletax 6841 1183

Customer Service
Service Appointment 6386 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 15:44

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014842 Date : 14/02/2020 Order : SCM9545G Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SCM9545G (V 41318)	Regn Date: 05/03/2019	Mileage: 15699	WIP No.: 62011
Model: A7 SB 3.0 TFSI qu 4KA02Y	Chassis: WAUZZZF2XKN063880	Engine: DLZ 023139	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details		Qty	Unit Price	Amount
X	A4K8807081B	(A) (SK) COVER 6/8/19	Less 020%	1.00	131.00	104.80
X	A8K0010520C	PLATE AP	Less 020%	1.00	12.20	9.76
X	A8W0010515A	STICKER AP	Less 020%	1.00	6.40	5.12
X	A4K8823029B	(A) (SK) HOOD 6/8/19	Less 020%	1.00	5605.00	4,484.00
X	A4K8823124	(A) (SK) PROTECTION 6/	Less 020%	1.00	16.50	13.20
X	A4K8823126	(A) (SK) PROTECTION 6/	Less 020%	1.00	17.80	14.24
X	A4K8823125A	(A) (SK) PROTECTION 6/	Less 020%	1.00	39.80	31.84
X	A4K0805608	(A) (SK) MOUNTING 6/8/	Less 020%	1.00	107.00	85.60
X	A4K8941036A	(A) (GER) HEADLIGHT 6/	Less 020%	1.00	11858.00	9,486.40
X	A8W0816421J	CONDENSER (LAST)	Less 020%	1.00	567.50	454.00
X	A4K0121283AC	(A) (SK) AIR DUCT 2/9/	Less 020%	1.00	33.60	26.88
X	A4K0121284AC	(A) (SK) AIR DUCT 2/9/	Less 020%	1.00	33.60	26.88
X	A3D0260749C	WASHER	Less 020%	2.00	8.00	12.80
X	A4E0260749A	WASHER	Less 020%	2.00	7.20	11.52
X	A4K8853795	(A) (SK) PLATE 2/9/19	Less 020%	1.00	75.70	60.56

Parts 19,989.20
Labour 0.00
Sublet 4,462.00
Menus 0.00
Lubricant 0.00

Sub-Total 23,451.20

7% GST 1,641.58

Grand Total 25,092.78



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SCM 9545 G

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0902/2019/EH
6 September 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A7 3.0 TFSI QU
Vehicle Chassis No. : WAUZZZF2XKN063880
Vehicle Regn No. : **SCM 9545 G**
Vehicle Mileage : 8419 KM
Vehicle Owner : Mr. Tang Kok Peng
Certificate No : 1900023012
Own Damage Excess : \$ 1070.00 (Inclusive GST)
Accident Date : 22 July 2019
Place : Upper Bukit Timah Rd in front of Shell Station
Repair Cost : S\$ 25092.78
WIP No. : 62011
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 1930 hrs
Date : 6/9/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jul 2019		29 Jul 2019 10:25 Edit Adj Rpt	S\$24,451.20 Edit Estimates	S\$24,451.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TANG KOK PENG, ID: S1758316F, Tel: +6596759600, Email: DTKP2002@YAHOO.COM								
Vehicle Reg. No.:	SCM9545G	Date of Loss:	22/07/2019 19:00 - :59 [4 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 7527576363SG	Policy/Cover Note No.:	1900023012 (Comprehensive)						
		Excess:	S\$1,000.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Nadaraja, Deeban] Deeban@nadaraja.Nadaraja@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Hiew May Fung] ... [Final Rpt due 07/08/2019]								
Driver/Custodian:	TANG KOK PENG (53 / Male) , NRIC: S1758316F, Tel: +6596759600 Email: DTKP2002@YAHOO.COM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (02/12/2019): Alert - Adj Mandate Approved (S\$24451.20) - SCM9545G - Claim Handler: Nadaraja, ... - AIG_SG (09/09/2019): Alert - Adj Mandate Approved (S\$15665.00) - SCM9545G - Claim Handler: Nadaraja, ... - AIG_SG (29/07/2019): Alert - Adj Mandate Approved (S\$14652.00) - SCM9545G - Claim Handler: Nadaraja, ... - AIG_SG (29/07/2019): SCM9545G / OD / 22/07/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SCM9545G (7527576363SG)
OD
Jul 22 2019 7:00PM
[TANG KOK PENG]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser v		
Video														1 per page v		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	29/07/19 11:21	Video - Other										1	Load MP4				
														1 per page v		☒	
Assessment Reports														1 per page v		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	29/07/19 12:04	Adjuster Immediate Advice										1	Load HTM				
2	05/09/19 12:04	Adjuster Immediate Advice										1	Load HTM				
														3 per page v		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	29/07/19 11:26	General View										1	Load JPG	☒			
2	29/07/19 11:26	General View										1	Load JPG	☒			
3	29/07/19 11:26	General View										1	Load JPG	☒			
4	29/07/19 11:26	General View										1	Load JPG	☒			
5	29/07/19 11:26	General View										1	Load JPG	☒			
6	29/07/19 11:26	General View										1	Load JPG	☒			
7	29/07/19 11:26	General View										1	Load JPG	☒			
8	29/07/19 11:26	General View										1	Load JPG	☒			
9	29/07/19 11:26	General View										1	Load JPG	☒			
10	29/07/19 11:26	General View										1	Load JPG	☒			
11	29/07/19 11:26	General View										1	Load JPG	☒			
12	29/07/19 11:26	General View										1	Load JPG	☒			
13	29/07/19 11:26	General View										1	Load JPG	☒			
14	29/07/19 11:26	General View										1	Load JPG	☒			
15	29/07/19 11:26	General View										1	Load JPG	☒			
16	29/07/19 11:26	General View										1	Load JPG	☒			
17	29/07/19 11:26	General View										1	Load JPG	☒			
18	29/07/19 11:26	General View										1	Load JPG	☒			
19	29/07/19 11:26	General View										1	Load JPG	☒			
20	29/07/19 11:26	General View										1	Load JPG	☒			
21	29/07/19 11:26	General View										1	Load JPG	☒			
22	29/07/19 11:26	General View										1	Load JPG	☒			
23	29/07/19 11:26	General View										1	Load JPG	☒			
24	29/07/19 11:26	General View										1	Load JPG	☒			
25	29/07/19 11:26	General View										1	Load JPG	☒			
26	29/07/19 11:26	General View										1	Load JPG	☒			
27	29/07/19 11:26	General View										1	Load JPG	☒			
28	29/07/19 11:26	General View										1	Load JPG	☒			
29	29/07/19 11:26	General View										1	Load JPG	☒			
30	29/07/19 11:26	General View										1	Load JPG	☒			
31	29/07/19 11:26	General View										1	Load JPG	☒			

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
32	29/07/19 11:26	General View	 Load JPG	☒
33	29/07/19 11:26	General View	 Load JPG	☒
34	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
35	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
36	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
37	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
38	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
39	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
40	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
41	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
42	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
43	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
44	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
45	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
46	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
47	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
48	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
49	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
50	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
51	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
52	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
53	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
54	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
55	05/09/19 11:58	Reinspection Photo	 Load JPG	☒
56	03/10/19 10:54	Reinspection Photo	 Load JPG	☒
57	03/10/19 10:54	Reinspection Photo	 Load JPG	☒
58	03/10/19 10:54	Reinspection Photo	 Load JPG	☒
59	03/10/19 10:54	Reinspection Photo	 Load JPG	☒
60	03/10/19 10:54	Reinspection Photo	 Load JPG	☒
61	03/10/19 10:54	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/07/19 11:24	SCM 9545G GIA.pdf	 Load PDF	
2	29/07/19 11:24	ESTIMATE.pdf	 Load PDF	
3	29/07/19 14:36	SCM 9545 G CI.pdf	 Load PDF	
4	29/07/19 14:36	SCM 9545 G IC and Driving License.pdf	 Load PDF	
5	05/09/19 11:58	SUPP.pdf	 Load PDF	
6	03/10/19 10:55	ESTIMATE & SUPP MARKED.pdf	 Load PDF	
7	19/02/20 14:11	Workshop Invoice	 Load PDF	
8	19/02/20 14:11	Discharge Voucher	 Load PDF	

Linked Accident Report Documents

			View	View in Browser
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	04/09/19 02:00	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	23/07/19 14:43	Accident Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
2	23/07/19 14:43	Accident Photo	 Load JPG	☒
3	23/07/19 14:43	Accident Photo	 Load JPG	☒
4	23/07/19 14:43	Accident Photo	 Load JPG	☒
5	23/07/19 14:43	Accident Photo	 Load JPG	☒
6	23/07/19 14:43	Accident Photo	 Load JPG	☒
7	23/07/19 14:43	Accident Photo	 Load JPG	☒
8	23/07/19 14:43	Accident Photo	 Load JPG	☒
9	23/07/19 14:43	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	23/07/19 14:27	Sketch Plan	 Load JPG	☒
2	23/07/19 14:27	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19013250/R1SF3E2

Date: 19/02/2020

REFERENCE

Insured/Claimant: TANG KOK PENG Policy No: 1900023012
Date of Loss: 22/07/2019 Nature of Claim: OD Claim No: 7527576363SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCM9545G**
Make & Model: AUDI A7, 3.0 (A) Engine No: DLZ023139
Reg. Date: 05/03/2019 (Man. Year: 2018) Chassis No: WAUZZZF2XKN063880
Colour: Red Odometer: 6750 km
Engine Capacity: 2995 cc
Market Value/New Car Price: S\$341,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R21 Rear Tyre Size: 225/55 R21
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	49,444.08	20,029.20	29,414.88	59.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,872.00	4,422.00	8,450.00	65.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	62,316.08	24,451.20	37,864.88	60.76
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	61,316.08	23,451.20	37,864.88	61.75
+ GST 7.00/7.00% (S\$)	4,292.13	1,641.58	2,650.55	61.75
Nett Amount (S\$)	65,608.21	25,092.78	40,515.43	61.75

INSPECTION

Date of Assignment: 29/07/2019
Date Inspected: 26/07/2019 Inspected At: 281 Alexandra Road
Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair: 5.0 days

Adjuster: Hiew May Fung

Manager: MOHD RASUL

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	3,289.00 FS	*2,631.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Serviceable	589.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - CENTER	Cracked	202.00 FS	*161.60 FS
4	2		*FRONT BUMPER ADAPTER - LH / RH	Cracked	72.00 FS	*56.32 FS
5	2		*FRONT BUMPER CATCH - LH / RH	Serviceable	80.00 FS	*- FS
6	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Serviceable	175.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Serviceable	265.00 FS	*- FS
8	1		*FRONT BUMPER SPOILER	Serviceable	229.00 FS	*- FS
9	2		*FRONT BUMPER REINFORCEMENT - LH / RH	Serviceable	152.00 FS	*- FS
10	1		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	O/S Cut / N/S Serviceable	904.00 FS	*361.20 FS
11	2		*FRONT BUMPER AIR GUIDE - LH / RH	Serviceable	118.00 FS	*- FS
12	2		*FRONT BUMPER REAR AIR GUIDE - LH / RH	Serviceable	118.00 FS	*- FS
13	1		*RADIATOR GRILLE	Cracked	2,031.00 FS	*1,624.80 FS
14	1		*RADIATOR GRILLE INSCRIPTION QUATTRO	Necessary	87.00 FS	*69.28 FS
15	1		*RADIATOR GRILLE INSCRIPTION QUATTRO BRACKET	Not Necessary	11.00 FS	*- FS
16	1		*RADIATOR GRILLE COVER	Serviceable	49.00 FS	*- FS
17	1		*RADIATOR GRILLE BRACKET	Serviceable	85.00 FS	*- FS
18	1		*RADIATOR COVER CAP	Serviceable	33.00 FS	*- FS
19	1		*CONNECTOR HOUSING BRACKET - LH	Serviceable	25.00 FS	*- FS
20	1		*FRONT FOAM FILLER PIECE	Cut	205.00 FS	*164.00 FS
21	1		*FRONT BUMPER REINFORCEMENT BEAM	Serviceable	887.00 FS	*- FS
22	2		*FRONT BUMPER SUPPORT	Serviceable	53.00 FS	*- FS
23	1		*FRONT BUMPER COVER	Cracked	131.00 FS	*104.80 FS
24	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Serviceable	80.00 FS	*- FS
25	1		*SIGN CAUTION	Not Necessary	13.00 FS	*- FS
26	1		*AIR CONDITIONER STICKER	Not Necessary	7.00 FS	*- FS
27	2		*FRONT SENSOR	Serviceable	462.00 FS	*- FS
28	4		*FRONT SENSOR SEAL RING	Serviceable	12.00 FS	*- FS
29	1		*FRONT FAN FARE - LH LOW TONE	Serviceable	198.00 FS	*- FS
30	1		*FRONT FAN FARE - RH HIGH TONE	Serviceable	198.00 FS	*- FS
31	2		*SPRING SHACKLE - LH / RH	Serviceable	86.00 FS	*- FS
32	1		*BONNET	Bent	5,605.00 FS	*4,484.00 FS
33	2		*BONNET IMPACT PROTECTION - LH / RH	Necessary	35.00 FS	*27.44 FS
34	1		*BONNET IMPACT PROTECTION - CENTER	Necessary	40.00 FS	*31.84 FS
35	2		*BONNET STRIKER - LH / RH	Serviceable	200.00 FS	*- FS
36	1		*SOUND ABSORBER FOR FLAP	Serviceable	289.00 FS	*- FS
37	1		*BONNET RELEASE ELEMENT (NPA)	Serviceable	0.00 FS	*- FS
38	1		*BONNET BOWDEN CABLE - CENTER	Serviceable	53.00 FS	*- FS
39	1		*BONNET BOWDEN CABLE COVER	Serviceable	9.00 FS	*- FS
40	1		*BONNET RELEASE LEVER	Serviceable	12.00 FS	*- FS
41	2		*HEADLIGHT MOUNTING - LH / RH	Cracked	107.00 FS	*85.60 FS
42	2		*LED HEADLIGHT WITH MATRIX BEAM - LH / RH	Cracked	23,716.00 FS	*9,486.40 FS
43	2		*LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM - LH / RH	Serviceable	362.00 FS	*- FS
44	2		*HOSE ON ROLLER 5M FOR LIFT CYLINDER	Serviceable	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*LOCK CARRIER WITH MOUNTING FOR RADIATOR	Serviceable	1,127.00 FS	*- FS
46	1		*A/C CONDENSER	Bent	568.00 FS	*454.00 FS
47	1		*RADIATOR	Serviceable	1,029.00 FS	*- FS
48	4		*READY MIX COOLANT	Serviceable	165.00 FS	*- FS
49	1		*ADDITIONAL RADIATOR	Serviceable	724.00 FS	*- FS
50	1		*RADIATOR FAN RING	Serviceable	242.00 FS	*- FS
51	1		*RADIATOR FAN WITH CONTROL UNIT	Serviceable	2,107.00 FS	*- FS
52	2		*RADIATOR AIR GUIDE - LH / RH	Cracked	68.00 FS	*53.76 FS
53	1		*RADIATOR UPPER AIR GUIDE - LH	Serviceable	27.00 FS	*- FS
54	1		*RADIATOR LOWER AIR GUIDE - RH	Serviceable	29.00 FS	*- FS
55	1		*AIR INTAKE AIR DUCT	Serviceable	42.00 FS	*- FS
56	1		*AIR INTAKE INNER AIR DUCT	Serviceable	76.00 FS	*- FS
57	1		*AIR FILTER FOR AIR INTAKE	Serviceable	266.00 FS	*- FS
58	1		*AIR INTAKE HOSE	Serviceable	100.00 FS	*- FS
59	1		*FRONT NO. PLATE	Bent	40.00 FS	*40.00 FS
60	1		*SUNDRIES	Necessary	500.00 FS	*64.88 FS
61	1		*RADIATOR GRILLE CAMERA	Serviceable	852.00 FS	*- FS
62	1		*BRACKET FOR CAMERA	Cracked	67.52 FS	*67.52 FS
63	1		*SECURING PLATE FOR CAMERA	Scratched	60.56 FS	*60.56 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 49,444.08 20,029.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND RENEW AIRCOND CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,400.00	1,400.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED	New	6,300.00	1,250.00
4	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT FENDERS	New	4,500.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			12,872.00	4,422.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >