



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : ERGO Insurance Pte Ltd
5 Temasek Boulevard Pte Ltd
#04-01 Suntec Tower Five
Singapore 038985

Estimate No: ES1900038

Date: 29 Jul 2019

Policy No:

Veh Reg No: GBE7529X

Make/Model: TOYOTA TOYOTA
HIACE VAN TURBO 5
DR MANUAL

Chassis No: JTFHT02P600192083

Engine No: 1KD2597862

Reg. Date: 18/03/2016

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 25/07/2019
TP Veh Reg No: YP3556M

*Not within
1 Day & ?
Running After Claim
5 days*

Estimate Repair Cost to Vehicle No : GBE7529X

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 DOOR STICKER (TOPFLIGHT GROUP PTE LTD)	50.00	1 PC	<i>na</i> 50.00	<i>25.00</i>
2 WINDSCREEN GLASS SEALANT RH	60.00	1 PC	<i>na</i> 60.00	<i>40.00</i>
3 FRONT WINDSCREEN IU STICKER	30.00	1 PC	<i>na</i> 30.00	<i>20.00</i>
			140.00	140.00
Spare Parts				
4 FRONT BUMPER	572.80	1 PC	<i>na</i> 572.80	<i>X</i>
5 FRONT BUMPER CLIPS	50.00	1 SET	<i>na</i> 50.00	<i>X</i>
6 FRONT BUMPER SIDE RETAINER - LH	137.20	1 PC	<i>na</i> 137.20	<i>X</i>
7 FRONT BUMPER SIDE RETAINER - RH	137.20	1 PC	<i>na</i> 137.20	<i>X</i>
8 FRONT DOOR - RH	1,268.50	1 PC	<i>na</i> 1,268.50	<i>✓</i>
9 FRONT DOOR WEATHERSTRIP - RH	125.60	1 PC	<i>na</i> 125.60	<i>750.00 (26.00)</i>
10 FRONT DOOR PILLAR - RH	520.10	1 PC	<i>na</i> 520.10	<i>✓</i>
11 FRONT HEADLAMP - RH	858.40	1 PC	<i>na</i> 858.40	<i>X</i>
12 FRONT DOOR PILLAR INNER COVER - RH	225.90	1 PC	<i>na</i> 225.90	<i>✓</i>
13 ANTENNA (RADIO)	185.10	1 PC	<i>na</i> 185.10	<i>X</i>
14 FRONT WINDSCREEN GLASS	1,382.06	1 PC	<i>na</i> 1,382.06	<i>✓</i>
15 FRONT WINDSCREEN GLASS MOUNTING	108.50	1 PC	<i>na</i> 108.50	<i>✓</i>
16 FRONT SIDE MIRROR - RH	365.10	1 PC	<i>na</i> 365.10	<i>X</i>
			5,936.46	5,936.46
Labour				
17 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,000.00	1 JOB	1,000.00	<i>600</i>
18 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,000.00	1 JOB	1,000.00	<i>400</i>
19 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	150.00	1 JOB	150.00	<i>60</i>
20 TO REMOVE/TRANSFER FRONT DOOR COMPONENTS.	200.00	1 JOB	200.00	<i>80</i>
21 TO CHECK WIRING FUNCTIONS.	60.00	1 JOB	60.00	<i>20</i>
			2,410.00	2,410.00



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : ERGO Insurance Pte Ltd
5 Temasek Boulevard Pte Ltd
#04-01 Suntec Tower Five
Singapore 038985

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 25/07/2019
TP Veh Reg No: YP3556M

Estimate No: **ES1900038**
Date: 29 Jul 2019
Policy No:
Veh Reg No: **GBE7529X**
Make/Model: TOYOTA TOYOTA
HIACE VAN TURBO 5
DR MANUAL
Chassis No: JTFHT02P600192083
Engine No: 1KD2597862
Reg. Date: 18/03/2016

Estimate Repair Cost to Vehicle No :GBE7529X

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	S\$ 8,486.46
			Add GST @ 7%	594.05
			Total Amount Payable	S\$ 9,080.51

TOTAL: SINGAPORE DOLLAR NINE THOUSAND EIGHTY AND CENTS FIFTY ONE ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: