

22/07/2012

ASS. REC. BY:

REF:

CS/AGI19013271/Eqd302

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person):

Ivy Ruffin

of

AGI

Date/Time:

29/7/19 @ 11:45am

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 4342B

Insured:

SKJ 92ISE

at Workshop m/s

SMRT

Tel:

6866 267

of

Woodlands SMRT Depot

Policy No:

Claim No:

C10003589/JM

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/07/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:19pm @ 29/7/19

Person Contacted:

shanti

Vehicle IN / OUT

Date/Time

Action/Instruction

Estimated ☒

SHC 4342B - CC3/AGI 30232010/Riv193w2

DOA: 8/12/13

SKJ 92ISE - X

30/7/19 @ 12:00pm revised to Ivy by email.

Star

REF: Auto & General Ins (AGI)

ASSIGNMENT

From _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

N/S	O/S

Veh No: SHC 4342B Yr Bgn: 22/11/13
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota Plus C.C. 1798
Colour: Meron A/C Insured / Std / NI
Sp. Reading: 522453 T/Radio: Insured / Std / NI
Eng/No: _____
C/No: JTO KAI 364 305705576
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/50R15 R: 1
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Wotake
Front _____ Rear _____
R/Bal. 5 mm R/Bal. 5
L/Bal. 5 mm L/Bal. 5
D.O.A. 25/7/19 D.O.I. 29/7/19
Survey held at SMRT
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
The UIC / Chassis frame / Body Structure affected due to col

Date / Time | Action / Instruction
13/8/19 Finalize confirm \$1150. 3 repair. day.
check \$ 6582.80, 85%

07/19/2019
SKJ 9215E

RECEIVED 14 AUG 2019

Date/Time, File Pass to? ☐ : Prel. Report
11/4/8 ☐ : Final Report
Date/Time, File Return to?

Days Of Repair: 3
Resurvey No. of Trip: 1

Report Format : TP
Lump Sum / I.B.F. (\$) 1150

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee: 250
Transportation
S + RS \$1
Photos
Other
TOTAL 250

Nivitha (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Monday, 29 July 2019 11:45 AM
To: Admin-D (LKKAuto)
Cc: sur@lkkauto.com; Julie Mangubat
Subject: FW: TPPD Survey: Claim ref:C10003589/JM || OI- SKJ9215E (White) TP- SHC4342B || Est:0.00 || SMRT
Attachments: TP GIA Report SHC4342B.pdf

Hi team,

Good morning.
TP Survey for SHC4342B please.

Kindly confirm.

Regards,

Ivy Ratilla
Executive, Claims Admin

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg



Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: Shanti B Thaiyal Nayagi (Auto Svcs/Claims & IA/Claims & IA/Taxis) <BThaiyalN@smrt.com.sg>

Sent: Saturday, 27 July 2019 8:51 AM

To: 'claims@budgetdirect.com.sg'

Cc: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>; Kok Tuck Foo (Auto Svcs/ARC/AR & SC/Taxis) <TuckFoo@smrt.com.sg>; Koo Yew Chung (Auto Svcs/ARC/AR & SC) <YewChung@smrt.com.sg>; Phua Zhi Yang (Auto Svcs/ARC/AR & SC/Taxis) <ZhiYang.Phua@smrt.com.sg>; Grace Ng Siu Ching (Auto Svcs/ARC/AR & SC/Taxis) <ngsiuching@smrt.com.sg>; Chin Kim Ming (Auto Svcs/ARC/AR & SC/Taxis) <kimming.chin@smrt.com.sg>

Subject: RE: SHC4342B - SURVEY (AUTO & GENERAL INSURANCE)

Dear Sir /Mdm

Kindly arrange to survey the vehicle **SHC4342B** within 48 hours according to GIA guide line, involving your insured **SKJ9215E**

Vehicle in Woodlands SMRT Depot

Regards

Shanti

SMRT Automotive Services PTE LTD

Accident Reporting Center (Claims Dept)

6866 2671/2 | bthaiyaln@smrt.com.sg



This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 30 July 2019 12:02 PM
To: 'Ivy Ratilla'; assignments
Cc: SUR; 'Julie Mangubat'
Subject: RE: TPPD Survey: Claim ref:C10003589/JM || OI- SKJ9215E (White) TP- SHC4342B || Est:0.00 || SMRT
Attachments: CSAGI19013271Eqd3.pdf

Dear Ivy,

Enclosed herewith preliminary advice of SHC 4342B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 29 July 2019 12:25 PM
To: 'Ivy Ratilla' <ivy.r@budgetdirect.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; 'Julie Mangubat' <julie.m@budgetdirect.com.sg>
Subject: RE: TPPD Survey: Claim ref:C10003589/JM || OI- SKJ9215E (White) TP- SHC4342B || Est:0.00 || SMRT

Dear Ivy,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ivy Ratilla [<mailto:ivy.r@budgetdirect.com.sg>]
Sent: Monday, 29 July 2019 11:45 AM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: sur@lkkauto.com; Julie Mangubat <julie.m@budgetdirect.com.sg>
Subject: FW: TPPD Survey: Claim ref:C10003589/JM || OI- SKJ9215E (White) TP- SHC4342B || Est:0.00 || SMRT

Hi team,

Good morning.

TP Survey for SHC4342B please.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: C10003589/JM

Date: 30th July 2019

Our Ref: CS/AGI19013271/Eqd3

The Motor Claims Department
Auto & General Insurance Budget Direct Insurance)

Attn: Ivy

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SHC 4342B


We thank you for the instruction on 29/07/2019.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 29/07/2019 at the premises of M/s SMRT and have the following to report:-

Workshop Estimate Amount	: S\$	<u>7,732.80</u>	.
Revised Estimate Amount	: S\$	<u>1,237.13</u>	.
"Check" Items Amount	: S\$	<u>334.27</u>	.
Market Value	: S\$	<u>-</u>	.
LTA Rebate Amount	: S\$	<u>-</u>	.
Nett Value	: S\$	<u>-</u>	.

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 3 days.

We have NOT authorise repair.

Yours faithfully

TAUFIKH
Automotive Assessor

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

369K

Vehicle Details

Vehicle No.:

SHC4342B

Vehicle to be Exported:

No

Intended Deregistration Date:

29 Jul 2019

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS TAXI (SMRT)

Primary Colour:

Maroon

Manufacturing Year:

2013

Engine No.:

2ZR5904994

Chassis No.:

JTDKN36U305705576

Maximum Power Output:

100.0 kW (134 bhp)

Open Market Value:

\$33,120.00

Original Registration Date:

22 Nov 2013

First Registration Date:

22 Nov 2013

Transfer Count:

0

Actual ARF Paid:

\$8,368.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

21 Nov 2021

PARF Rebate Amount:

\$5,857.00

Intended COE Rebate Details

COE Expiry Date:

21 Nov 2021

COE Category:

A - Car (1600cc & below)

COE Period(Years):

8

PQP Paid:

\$63,297.00

COE Rebate Amount:

\$18,306.00

Total Rebate Amount:

\$24,163.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 29 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/07/2019 10:57
Date Of Accident	25/07/2019 15:55
Exact Location Of Accident	JERVOIS ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4342B
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	LECK KIN THONG
NRIC No	S1611011F
Date Of Birth	02/12/1963
Occupation	OUTDOOR
Date Of Driving Pass	22/01/1981
Driving Experience	38 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	160
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS STATIONARY ALONG JERVOIS ROAD WAITING TO TURN RIGHT INTO SPC STATION. A MOMENT LATER, SUDDENLY I FELT AN IMPACT FROM BEHIND, THE VEHICLE SKJ9215E FROM BEHIND HAD COLLIDED ONTO THE REAR PORTION OF MY TAXI. WHEN I ALIGHTED AND CHECKED, I THEN REALISED THAT THERE WAS ANOTHER VEHICLE SFQ1638T WHICH WAS BEHIND THE VEHICLE SKJ9215E ALSO INVOLVED IN THE ACCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SKJ9215E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ANJALI PASKER
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SFQ1638T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HUSSEIN PAPAR
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

26/3/19

Case Details

Case Reference Number :
TAX/07/19/2099
Type of Repair : Accident Repair
Vehicle Registration Number :
SHC4342B

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-7804-ID
Assigned By : Taxi Claims Manager
Team

Insurance Company Name : Auto & General Insurance (Singapore) Pte Ltd
Accident Date and Time : 25/07/2019 07:57 AM
Vehicle Age(In Months) : 68

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	/ N/A
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	/ N/A
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BUMPER, RR SPRING LH/RH	1	79.30	79.30	25.00	59.47	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	/ BR
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	/ BR
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	X N/A
Total Spare Part Cost									3,917.46	Surveyor Total				547.13
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)				20
Final Spare Part Cost									3,133.97	Final Sur Total				437.70

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give	X NMI
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	X NMI
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check	X NMI
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0	Not Give	X NMI
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	X NMI
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	X NMI
One Time Key In	Main			ANTENNA,ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Not Give	X NMI
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give	X NMI
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	0	0	Not Give	X NMI
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give	X NMI
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	1	0	Repair	X R
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give	X NMI
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	0	0	Not Give	X NMI
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	25.00	27.75	Replace	0	0	Not Give	X NMI
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0	Not Give	X NMI
Total Spare Part Cost									3,917.46	Surveyor Total		547.13		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									3,133.97	Final Sur Total		437.70		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	845.00	350	
Total:			845.00	350.00	/

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	/
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
3	Main	TO RESPRAY REAR PANEL	180.00	80	/
4	Main	TO RESPRAY TAIL GATE	378.00	0	
Total:			1,116.00	280.00	/

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/ N/C
2	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
3	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0	
4	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	20	/ N/C
5	Main	TO REPLACE SUNDRY PARTS	100.00	20	/ N/C
6	Main	TO WASH AND VACUUM	60.00	0	
Total:			680.00	60.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,133.97	437.70
Total Labour Cost	845.00	350.00
Total Spray Painting	1,116.00	280.00
Other	680.00	60.00
Overall Total	5,774.97	1,127.70
Lump Sum Repair Option		/

Estimator Assesment(\$)

Lump Sum Total

0.00

Surveyor Approved Amount

No of Repair Days*

6

Remarks

Surveyor Name

Signature

Survey Date

29/07/2019

Surveyor Assesment(\$)

1,150.00

1,150.00

3

L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com.

STEVE CHEN

Save Clear

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer



Signature:

Date:

7732-80



Section A - Accident Details

Registration Number	SHC4342B
Case Reference Number	TAX/07/19/2099
Registration Date	22/11/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	LECK KIN THONG
Type of Accident	Head to Rear
Accident Date and Time	25/7/2019 3:57 PM
Accident Reported Date and Time	26/7/2019 11:00 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24102566
Special Instruction to ARC, if any	DROVE IN
Prepared Date and Time	26/7/2019 3:48 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$350.00
Total Spray Cost	\$1,116.00	\$280.00
Total Spare Part Cost	\$3,133.97	\$437.70
Total Other Cost	\$680.00	\$60.00
TOTAL COST	\$5,774.97	\$1,127.70
Lump Sum Total	\$0.00	\$1,150.00 (L/S)
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Ang Bang Kien	STEVE CHEN (LKK) / AUTO & GENERAL
ARC / Surveyor Sign Off Date	29/07/2019 3:07 PM	29/07/2019 2:08 PM
Signature		
Remarks	L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com.	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662633
Accident Reporting Number : 68662672

Date Generated : 18/08/2019

User ID : PohSuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0087	Invoice Number	
Quotation Date	07.08.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$845.00	\$350.00
Total Labour	\$845.00	\$350.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$80.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$1,116.00	\$280.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$680.00	\$60.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given X
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace ✓
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given X
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given X
		48341-75010	BUMPER, RR SPRING LH/RH	0.00	\$79.30	0.00	\$0.00	Replace	Not Given X
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given X
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace ✓
		52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace ✓
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given X
		76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given X
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check X

		SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check	X
	67881-47022	TAILGATE DOOR WEATHER STRIP	0.00	\$353.40	0.00	\$0.00	Replace	Not Given	X
	52016-47030	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X
	52015-47050	ARM SUB-ASSY. RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X
	89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Not Given	X
	58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given	X
	67005-47241	TAILGATE ASY	0.00	\$1,007.90	0.00	\$0.00	Replace	Not Given	X
	75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X
	58307-47060	END PANEL	1.00	\$602.10	100.00	\$0.00	Replace	Repair	✓
	64718-47031B0	END PANEL COVER, DECK TRIM HOLE	0.00	\$46.10	0.00	\$0.00	Replace	Not Given	X
	64716-47031B0	END PANEL COVER, DECK TRIM, RR	0.00	\$121.10	0.00	\$0.00	Replace	Not Given	X
		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
	52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Not Given	X
Total				\$5,017.31		\$547.13			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

547.13
 - 202
 437.70
 + 350.00
 + 340.00

 1127.70
 US \$1150/-
 7732.80



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL			Ref : CS/AGI19013271/Eqd3e2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date : 16-08-2019	
			Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKJ 9215E	Veh. Inspected	SHC 4342B	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10003589/JM	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	29/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	JTDKN36U305705576	Colour	MAROON	
Odometer	522453	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R15	WEST LAKE	5 mm	
L/H Front Tyre	195/50 R15	WEST LAKE	5 mm	
R/H Rear Tyre	195/50 R15	WEST LAKE	5 mm	
L/H Rear Tyre	195/50 R15	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/07/2019	Inspection Date	29/07/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4342B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER REAR (DISC 25%)	BROKEN	458.60	343.95
1	BUMPER SIDE RETAINER RR/RH (DISC 25%)	BROKEN	94.80	71.10
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	ARM SUB-ASSY, RR BUMPER RH	NOT NECESSARY	139.60	-
1	BUMPER SEAL, RR LH	NOT NECESSARY	88.90	-
1	BUMPER SEAL, RR RH	NOT NECESSARY	65.70	-
1	BUMPER, RR SPRING LH/RH	NOT NECESSARY	79.30	-
1	BUMPER LIP COVER RR/RH	NOT NECESSARY	118.10	-
1	BUMPER SIDE RETAINER RR/LH	NOT NECESSARY	94.80	-
1	BUMPER LIP REAR	NOT NECESSARY	228.90	-
1	BUMPER REINFORCEMENT REAR	NOT NECESSARY	205.70	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	TAILGATE DOOR WEATHER STRIP	NOT NECESSARY	353.40	-
1	ARM SUB-ASSY. RR BUMPER RH	NOT NECESSARY	139.60	-
1	ARM SUB-ASSY. RR BUMPER LH	NOT NECESSARY	139.60	-
1	ANTENNA, ELECTRICAL LOWER REAR	NOT NECESSARY	157.40	-
1	UNDER COVER SUB-ASSY, RR FLOOR	NOT NECESSARY	514.50	-
1	TAILGATE ASY	NOT NECESSARY	1,007.90	-
1	NAME PLATE (HYBRID)	NOT NECESSARY	51.90	-
1	END PANEL COVER, DECK TRIM HOLE	NOT NECESSARY	46.10	-
1	END PANEL COVER, DECK TRIM, RR	NOT NECESSARY	121.10	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	TAIL LAMP BRACKET, RH	NOT NECESSARY	30.70	-
1	END PANEL	TO REPAIR SEE LABOUR	602.10	-
			5,091.80	547.13
LABOUR				
PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF END PANEL.			845.00	350.00
SPRAY PAINT.			1,116.00	280.00
TO CHECK WIRING AND SYSTEM FUNCTION.			80.00	20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM.		NOT NECESSARY	120.00	-
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT T		NOT NECESSARY	120.00	-

Report Ref No. CS/AGI19013271/Eqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT WIRE HARDESS.	NOT NECESSARY	200.00	20.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.		60.00	-
			2,641.00	690.00
GRAND TOTAL			7,732.80	1,237.13

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,150.00
---	--	--	----------

Report Ref No. CS/AGI19013271/Eqd3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.