



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 Register number : 201015366H

India International Insurance

REPAIR PERFORMA INVOICE

Vehicle number	SLN8705G
Make / Model	HONDA/CIVIC 1.6
Chassis number	MRHFC5650GT001046
Accident date	24 July 2019
Reference	1907-81

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER <i>- dismount photo.</i>	709.78 <i>de</i>
1	REAR BUMPER REFLECTOR WITH COVER	66.00 <i>ant</i>
1	REAR BUMPER LH RETAINER	33.60 <i>rec</i>
1	REAR BUMPER LH BRACKET	45.60 <i>?</i>
1	REAR BUMPER LOWER GARNISH	136.00 X
1	TAILLAMP	564.00 X
1	TAILLAMP PANAL	165.60 X
1	END PANEL	488.00 X
1	END PANEL TOP GARNISH	180.00 X
		2388.58
		477.72
		1910.86
		1910.86
		1910.86
		1910.86
1 SET	REAR BUMPER CLIP	40.00 <i>30.</i>
1	JOINT SEALANT	150.00 X
1 SET	REAR REVERSE SENSOR	400.00 X
		590.00
		2500.86
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
		2500.86
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 <i>30.</i>
2	REMOVE, REFIT REAR LINING TRIM AND GARNISH	150.00 <i>40.</i>
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 <i>30.</i>
4	PANEL BEATING ON AFFECTED AREAS	800.00 <i>250.</i>
5	SPRAY PAINTING ON AFFECTED AREAS	800.00 <i>200.</i>
6	APPLY ANTI RUST ON AFFECTED AREAS	150.00 X
		2110.00
		4610.86

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Less 20%
 Subtotal
 Balance C/F
 Signature:
 Date: PARTS REPLACEMENT SPECIAL NETT ITEMS
 Balance B/F

Tan Jiah 97495749
WP 20/7/19 @ Spore
2 days
Resurvey after repair
 Grand total
sub @ 11 months com.