

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111  
 Tel No. : 6287 6666 Fax No. : 6257 1330  
 CO./GST Reg. No. 201019626G  
**SHD 216D**

**AAD1907-235**

*Not Authored  
 V. Long &*

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model: *26 JUL 2019*  
 Date of Accident :  
 Third Party Insurer :  
 Date of Registration:

**SHD 216D**  
 VF1ABL15AUC281592  
 RENAULT  
 LATITUDE  
 25.7.19  
**AXA**  
 2/10/2015

PART		LIST	
1	1 BUMPER COVER REAR	\$ <i>Bumper</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$ <i>bumper</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$ <i>DI</i> 113.47	✓
4	1 BUMPER BRACKET SIDE RH REAR	\$ <i>SL</i> 135.97	X
5	1 BUMPER RETAINER RH REAR	\$ <i>SL</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$ <i>SL</i> 43.61	X
7	1 BUMPER BRACKET SIDE LH REAR	\$ <i>SL</i> 135.97	X
8	1 BUMPER RETAINER LH REAR	\$ <i>SL</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$ <i>CM</i> 43.61	✓
10	1 BUMPER BEAM REAR	\$ <i>B</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$ <i>DI</i> 225.95	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$ <i>R</i> 225.95	X
13	1 BOOT REAR	\$ <i>Boo</i> 2,872.68	✓
14	1 BOOT FINISHER	\$ <i>Pen</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$ <i>SL</i> 323.05	X
16	1 BOOT REFLECTOR LAMP LH	\$ <i>SL</i> 493.35	X
17	1 BOOT REFLECTOR LAMP RH	\$ <i>DI</i> 493.35	✓
18	1 BOOT BADGE 'RENAULT'	\$ <i>SL</i> 225.36	✓
19	1 BOOT BADGE	\$ <i>SL</i> 225.36	✓
20	1 BOOT STRUT LH	\$ <i>SL</i> 276.08	} X
21	1 BOOT STRUT RH	\$ <i>SL</i> 276.08	
22	1 BOOT HINGE LH	\$ <i>R</i> 367.84	
23	1 BOOT HINGE RH	\$ <i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$ <i>SL</i> 586.45	
25	1 BOOT SWITCH	\$ <i>SL</i> 168.13	
26	1 BOOT LOCK	\$ <i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$ <i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$ <i>SL</i> 50.52	
29	2 BOOT RUBBER PLUG	\$ <i>SL</i> 221.81	

# Trans-cab Auto Services Pte Ltd

AAD1907-235

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

## SHD 216D

30	1	FENDER PANEL INNER TRIM REAR RH	\$	Pr	671.45	}
31	1	FENDER PANEL REAR RH	\$	N	3,299.13	
32	1	WHEELARCH REAR RH	\$	Pr	543.47	
33	1	FENDER PANEL REAR LH	\$	N	3,299.13	
34	1	FENDER PANEL INNER TRIM REAR LH	\$	Pr	671.45	
35	1	WHEELARCH REAR LH	\$	Pr	543.47	
36	1	TAILLAMP RH	\$	Pr	552.55	
37	1	TAILLAMP PANEL RH	\$	N	986.70	
38	1	TAILLAMP LH	\$	Pr	552.55	
39	1	TAILLAMP PANEL LH	\$	N	986.70	
40	1	OUTER PANEL REAR (End Panel)	\$	Pr	1,471.77	✓
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	N	404.56	✓
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	N	2,189.88	X
43	1	SPARE WHEEL PANEL TRIM	\$	Pr	612.21	X
44	1	EXHAUST REAR	\$	N	7,489.05	X
45	1	EXHAUST CAP REAR	\$	N	230.49	X
46	1	FUEL FLAP	\$	N	343.57	X
<b>TOTAL</b>			<b>\$</b>		<b>36,212.51</b>	
<b>10%</b>			<b>\$</b>		<b>3,621.25</b>	
			<b>\$</b>		<b>32,591.26</b>	

## Special Nett

1	1SET	PARKING AID	\$	Pr	700.00	X
2	1SET	REAR BUMPER CLIP	\$	N	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	N	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	N	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	N	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	N	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	N	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	N	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	N	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	N	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	N	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	N	30.00	✓
13	1	BOOT STICKER "6555-3333"	\$	N	30.00	✓
14	1	BOOT INNER TRIM CLIP	\$	N	45.00	X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	N	35.00	X
16	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Pr	385.00	X

**Trans-cab Auto Services Pte Ltd**

AAD1907-235

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 216D**

17	1	SPARE TYRE	\$	Sp	330.00	}
18	1	FENDER INNER TRIM CLIP RH	\$	nn	28.00	
19	1	TAILLAMP CLIP RH	\$	nn	5.00	
20	2	REAR WINDSCREEN SEALANT	\$	nn	80.00	
21	1	WINDSCREEN MOULDING	\$	nn	100.00	
22	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
23	1	TAILLAMP CLIP LH	\$	nn	5.00	
24	1	FENDER INNER TRIM CLIP LH	\$	nn	28.00	
25	1SET	FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	
26	1	Rear left tyre	\$	Sp	330.00	
27	1	Rear left tyre rim	\$	Sp	380.00	
28	1	Rear right tyre	\$	Sp	330.00	
29	1	Rear right tyre rim	\$	Sp	380.00	
<b>TOTAL</b>			<b>\$</b>		<b>3,645.02</b>	
<b>TOTAL PARTS</b>			<b>\$</b>		<b>36,236.28</b>	

**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	6601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	6001
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X

**Trans-cab Auto Services Pte Ltd**

AAD1907-235

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 216D

To check steering geometry and computer wheel alignment	\$	<i>na</i>	220.00	X
To Rust-Proofing Of The Affected Areas.	\$		170.00	<i>601</i>
To repair and realign rear exhaust pipe.	\$		170.00	X
To transfer of tire, rim and on wheel balancing.	\$		170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	<i>602</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i>	380.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>na</i>	170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>na</i>	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i>	380.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	<i>na</i>	380.00	X
To Check Electrical Lighting Concerned.	\$		170.00	<i>201</i>
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	<i>na</i>	380.00	X
<b>TOTAL</b>	<b>\$</b>		<b>19,200.00</b>	

**Over All Total \$ 55,436.28****(LUMP SUM) Repair Days****25 DAYS***5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: