

INS. CASE OWNER:

Ho minnie

CC 4, ASM 190 13280, A ga3sr

LKK: 128948
IDAC: 128948

Surveyor:

UMP

DOI:

ASSIGNMENT

29/7/2019

Date / Time :

29/07/2019

Registered in Merimen:

Pre-assign / CCU / FTE

XE3848R

Claim No. :

sq m01V8T



Insured Vehicle No. :

Name of Insured :

PINA SIONG INTERNATIONAL P/L & OR
1BT 16A mm plc

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II :SS

1,000.00

D.O.A: 28/7/2019

Place of Accident :

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident :

OI GIA REPORT: YES NO ; TP GIA REPORT: YES NO

If NO, Driver Name / Age :

Driver Tel No. :

(V/L YES / NO)

Insured Liability : % Final ? Yes / No

6809410 X



INRS: WSP: Tel: Liability: RMKS:

Chew motor



INRS: WSP: Tel: Liability: RMKS:



INRS: WSP: Tel: Liability: RMKS:



INRS: WSP: Tel: Liability: RMKS:

Date/Time	STAGE	DATE / PIC
20/7	Non-Reporting ltr (1st):	
20/7	Non-Reporting ltr (2nd):	
20/7	Non-Reporting ltr (Final):	
20/7	Notification ltr (if non-pickup):	
20/7	Call OI:	
20/7	After call ltr to OI:	23/9/19
23/10	Documentation Check List:	Handler Typist
23/10	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
23/10	After call ltr to OI:	<input type="checkbox"/>
23/10	Authorisation To Act:	<input checked="" type="checkbox"/>
23/10	Release Voucher:	<input checked="" type="checkbox"/>
23/10	Final Repair Bill:	<input checked="" type="checkbox"/>
23/10	Car Rental Invoice:	<input checked="" type="checkbox"/>
23/10	Towing Invoice:	<input checked="" type="checkbox"/>
23/10	LTA / GIA :	<input checked="" type="checkbox"/>
23/10	Medical Bill:	<input checked="" type="checkbox"/>
23/10	PIR:	<input checked="" type="checkbox"/>
23/10	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
23/10	LOD:	<input checked="" type="checkbox"/>
23/10	Payment Breakdown Form:	<input type="checkbox"/>
23/10	Post-Repair Photos:	<input checked="" type="checkbox"/>
23/10	Others:	<input checked="" type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By: Confirm with: Confirm by: Adrain

FINALIZATION Date/Time: Confirm with: Confirm by: Email Call

Repair Cost: 45 S\$ 10,500.00 (8 days) Reduction: 15744.30 % 60

FINAL SETTLEMENT Date/Time: 20/10/19 Confirm with: SUEY Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: Nil

Repair Cost: (w/LOI) S\$ 11,275.00

Loss of Rental (LOR): S\$ (days)

Loss of Use (LOU): S\$ 600.00 (\$ 60 x 10 days)

Loss of Income (LOI): S\$ (\$ x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search S\$ 7.45

Medical: S\$ (e.g. Tow/ Independent)

Disbursement: S\$

Legal Cost S\$

Total: S\$ 11,842.45 Global Sum SS: Email Call

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: S\$ 11,842.45 Name 1: Chew motor Pte Ltd

COPY SENT 11/11/19

13280/AG

ASSIGNMENT

Action

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Chew Motor

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBD9410X Yr Regn: 2015 August

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Nissan NV200 c.c 1461

Colour Silver A/C: Insured / Std / NI / NA

Sp. Reading 153145 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VSKYBAM2020098778

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 175/70R14

R: 175/70R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxtrex

Front R/Bal. 06 mm Rear R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 29/07/19

Survey held at Chew Motor

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Front O/S, w/c.

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP AXA.</u>

US \$10,500 - (Red = \$15,744.30/60%)

MV: 38K

PV: 27K

Nett: 11K

007E

* 8 repair days + 1 Sunday + 1 Saturday + 2 PRS = 12 days.

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:		Survey Fee:	Date:					
1)	2)	IN	OUT	Basic & Add.	<table border="1"> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> </table>					
3)	4)			<u> </u> S + RS, <u> </u> SI						
5)	6)			Photos						
Prel. Report				Others						
Final Report				TOTAL						

cc4(ASM)90137807 Agaz



CHEW MOTOR PTE. LTD. Cecilia

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883
Tel: 6509 5545 Fax: 6509 5567
Website: www.chewmotor.com
Registration No.: 201718369R GST Reg No.: 201718369R

04/06/2019

BUDGET MARKET MARKETING

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

TPAYA VSKYBAM20Z0098778
Cecilia

Accident date: 03/06/2019

Estimated repair cost for vehicle no: GBD9410X NISSAN NV200 1.5 M '15

CHASSIS: VSKYBAM20Z0098778

S/n	Qty	Items / Nett	U/price	Amount
				\$1,157.90 +
1	1	Front Bonnet <i>Ryng</i>		\$115.40 +
2	2	Front Bonnet Hinge <i>Neu</i>	\$57.70	\$78.70 +
3	1	Front Bonnet Lock <i>Neu</i>		\$892.80 ✓
4	2	Front Head Lamp <i>cracked</i>	\$446.40	\$151.40 +
5	2	Front Head Lamp Lower Bracket <i>Neu</i>	\$75.70	\$589.70 ✓
6	1	Front Bumper <i>Distorted</i>		\$70.40 ✓
7	2	Front Bumper Side Retainer <i>Neu</i>	\$35.20	\$65.00 30
8	10	Front Bumper Clip <i>Neu</i>	\$6.50	\$724.40 ✓
9	2	Front Bumper Side Cover <i>MISSING</i>	\$362.20	\$231.00 ✓
10	1	Front Bumper Centre Garnish <i>cracked</i>		\$614.90 5918
11	1	Front Bumper Reinforcement <i>Bent</i>		\$183.40 X
12	2	Front Bumper Reinforcement Bracket <i>Neu</i>	\$91.70	\$338.00 ✓
13	1	Front Grille <i>cracked</i>		\$52.00 20
14	8	Front Grille Clip <i>Neu</i>	\$6.50	\$73.50 ✓
15	1	Front Grille Emblem Logo <i>Neu</i>		\$205.50 ✓
16	1	Front Grille Lower Moulding <i>cracked</i>		\$1,057.00 507
17	1	Front Support Panel <i>Buckled</i>		\$145.30 ✓
18	1	Front Support Panel Top Cover <i>cracked</i>		\$129.20 ✓
19	1	Front Support Panel Air Duct Cover <i>cracked</i>		\$94.60 X
20	1	Front Radiator Tank <i>Neu</i>		\$504.70 ✓
21	1	Front R/H Fender <i>Buckled</i>		\$285.60 142.80
22	2	Front Fender Cowling <i>RH torn</i>	\$142.80	\$104.00 30
23	16	Front Fender Cowling Clip <i>Neu</i>	\$6.50	\$66.60 X
24	1	Front R/H Fender Signal Lamp <i>Neu</i>		\$162.60 +
25	1	Front R/H Fender Quarter Glass Garnish <i>Neu</i>		\$275.90 +
26	1	Front R/H Fender Quarter Glass Assy <i>Neu</i>		\$197.60 +
27	2	Front Horn <i>Neu</i>	\$98.80	

28	1	Front Air Cleaner Box Assy <i>credited</i>		\$566.40 ✓
29	1	Front Engine Lower Cover <i>ton</i>		\$272.30 ✓
30	1	Front R/H Lower Arm <i>Best</i>	\$192.50	\$192.50 ✓

Subtotal :- \$9,598.30

S/n	Qty	Items / Special Nett	U/price	Amount
31	1	Front Wiper Tank <i>Detached</i>		\$247.90 ✓
32	1	Front Radiator <i>Best</i>		\$687.40 ✓
33	1	Front Radiator Fan Motor <i>credited</i>		\$685.90 ✓ 452
34	1	Front Air-Con Condenser <i>Best</i>		\$653.00 ✓
35	1	Front Air-Con Air Duct Blower Assy <i>3 NY</i>		\$508.40 ✓
36	1	Front Air-Con Coolant Coil Blower Assy <i>new</i>		\$1,101.40 ✓
37	1	Front Alternator <i>Damaged</i>		\$1,889.80 ✓
38	1	Front Air-Con Compressor <i>Damaged</i>		\$1,121.10 ✓
39	1	Front Air-Con Compressor Pipe <i>Best</i>		\$251.30 ✓
40	2	Front Air-Con Compressor Bracket <i>new</i>		\$108.80 ✓
41	1	Front Intercooler <i>Dented</i>		\$2,121.60 ✓ 1100
42	1	Front R/H Tyre <i>new</i>		\$380.00 ✓
43	1	Front R/H Hub Cap <i>new</i>		\$166.10 ✓ 600/w
44	1	Front R/H Knuckle Arm <i>Damaged</i>		\$583.20 ✓
45	1	Front R/H Knuckle Arm Bearing <i>damaged</i>		\$329.70 ✓
46	1	Front R/H Shock Absorber <i>Best</i>		\$252.80 ✓
47	1	Front Steering Rack <i>new</i>		\$1,117.60 ✓

Subtotal :- \$12,206.00

11597.80
10488.02 S.V.U:60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer
Signature:
Date:

Labour charges

To remove & refit air-con blower, coolant coil, air duct blower & top up gas	\$280.00	X	
To remove & refit air-con condenser, radiator, fan motor & top up gas	\$280.00	120	
To remove & refit front undercarriage, drive shaft & steering rack	\$480.00	200	
To check wiring	\$100.00	30	
To check wheel alignment	\$150.00	80	
Towing Fee	2650	\$150.00	60
Panel beating	\$1,600.00	1200	
Spray painting	\$1,400.00	1000	

Subtotal :- \$4,440.00


Total:- \$26,244.30

total: 138802.
H/s: 10.5K.
08 Days.
10.5K


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



PEOPLES AUTO TRADING
 BLK 3007 UBI ROAD 1 #01-400
 TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER	CHEW MOTOR	DATE	Jul 30, 2019 9:29:22 AM
LICENSE NO.	GBD 9410 X		
MILEAGE	153150		
REFERENCE	CUSTOM	MODEL	NISSAN NV200

Front Wheel	SPECS				DIAGNOSIS				ADJUSTMEN			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	-1.00	0.00	1.00			6.90				6.90		
PARTIAL TOE	-0.50	0.00	0.50		2.30		4.60		2.60		4.20	
SET BACK	---	---	---			-0°24"				-0°24"		
CAMBER	-1°12"	-0°12"	0°48"		-0°56"		-2°14" 1°18"		-0°56"		-2°14" 1°18"	
CASTER	3°30"	4°30"	5°30"		4°12"		4°24" 0°12"		4°12"		4°24" 0°12"	
KING-PIN	---	---	---		10°10"		9°46" 0°24"		10°10"		9°46" 0°24"	
INCL ANGLE	---	---	---		9°12"		7°30"		9°12"		7°30"	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel	SPECS				DIAGNOSIS				ADJUSTMEN			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	---	---	---			4.30				4.30		
PARTIAL TOE	---	---	---		3.40		0.80		3.40		0.80	
SET BACK	---	---	---			0°00'				0°00'		
CAMBER	---	---	---		-1°28"		-2°00" 0°32"		-1°28"		-2°00" 0°32"	
THRUST ANGLE	-0°08"	0.00	0°08'			0°12"				0°12"		

Assignment

To: Chew Motor Pte Ltd (Workshop)

In consideration for your agreement to repair my motor vehicle registration no. GBD9410X and to defer demanding for payment of the cost of repair, I/we the undersigned do hereby irrevocably assign absolutely to you all the proceeds of my/our claim(s) including damages, interest, costs and expenses (including legal costs / disbursements payable on a party and party basis which are to be paid to the parties so entitled including solicitors, vehicle appraisers and other experts / consultants).

I/We further confirm that payment to you only or to any person authorised by you to receive payment shall constitute a good and effectual discharge of the obligations by any party of the aforesaid proceeds of my/our claim(s).

I/We authorise you expressly to give notice of this assignment to the party concerned.

I/We confirm that by this assignment, I/we shall not be entitled in law to receive any payment. If a cheque is sent to me/us, I/we shall return same to the sender as I/we am/are precluded from accepting any payment.

Dated this 24 day of 07 20 19.

Signature : [Signature]
Name : Budgetmarket
ID No. : Wavteti4
Address : 53125007E

Witness Signature : [Signature]
Witness Name : **CHEW MOTOR PTE. LTD.**
Witness ID : 1 Kaki Bukit Avenue 6 Blk C #01-41
Witness Address : Autobay@Kaki Bukit Singapore 417883
Tel: 6509 5545 Fax: 6509 5567
Email: claims@chewmotor.com
UEN: 201718369R



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	007E
Vehicle Details	
Vehicle No.:	GBD9410X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Jul 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5L MT ABS AIRBAG 2WD 6DR EURO 5
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	K9KC400D054520
Chassis No.:	VSKYBAM20Z0098778
Maximum Power Output:	-
Open Market Value:	\$20,122.00
Original Registration Date:	05 Aug 2015
First Registration Date:	05 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$1,007.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 Aug 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$44,870.00
COE Rebate Amount:	\$26,994.00
Total Rebate Amount:	\$26,994.00

The information contained herein is correct as at 29 Jul 2019

OK

CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

SEARCH

Price Range

Depreciation

2015

Vehicle Type

Advanced Search

Used Car Comparison

— Comparing 4 Vehicles —

Nissan NV200 1.5M	Nissan NV200 1.5M	Nissan NV200 1.5M	Nissan NV200 1.6A
<input type="button" value="Add all to Shortlist"/>	<input type="button" value="Add to Shortlist"/>	<input type="button" value="Add to Shortlist"/>	<input type="button" value="Add to Shortlist"/>

CAR DETAILS				
Price	\$39,980	\$38,800	\$42,000	\$43,800
Instalment	N.A.	N.A.	N.A.	N.A.
Registration Date	30-Apr-2015	29-May-2015	31-Jul-2015	19-Aug-2015
Manufactured	2014	2015	2015	2015
Mileage	34,000 km	-	-	-
Transmission	Manual	Manual	Manual	Auto
Engine Cap	1,461 cc	1,461 cc	1,461 cc	1,597 cc
Road Tax	-	-	-	-
Power	-	-	-	-
Curb Weight	1,320 kg	1,320 kg	1,320 kg	1,220 kg
Features	-	-	Owner Consignment Well Taken Care By One Owner Only No Repair Needed.	-
Accessories	-	-	Front Recording Camera, Plywood Back Compartment, Premium PU Leather Seating	-
Description	Low Mileage 34k Km, 1 Owner And Road Tax Till Oct 19. Accident-Free, Excellent Condition! Flexible In House 100% Loan No Problem. View Now To Believe. No Plate For Sale 6999 = Forever Blessed, Excellent Condition, Viewing By Appointment, Call Now.	Agent Unit! FREE Front Recording Cam! New Paintwork! New Leather Upholstery Fitted! Engine And Gearbox In Pristine Condition! Well Maintained By Previous Owner! Ideal For Personal/Work Usage! Comes With Reverse Sensors! Insurance And Up To 100% Loan Available For Your One Stop Convenience! Attractive Loan Packages And High Trade In! Call Now To Inquiry Further! All Price Inquires Are Welcome!	Excellent Condition Vehicle Direct With Only One Owner. Comes With Front Recording Camera, Plywood Back Compartment, Premium PU Leather Seating. Large Cargo Capacity. Strong And Fuel Efficient Diesel Engine. Come View And Make Us An Offer.	1 Owner Only! Well Excellent Condition Loan Available. Call
COE	\$59,999	\$50,098	\$50,502	\$37,215
OMV	\$20,544	\$20,122	\$20,050	\$14,436
ARF	\$1,028	\$1,007	\$1,003	\$722
Depreciation	\$6,950 /yr	\$6,650 /yr	\$6,990 /yr	\$7,230 /yr
No. of Owners	1	2	1	1
Type of Vehicle	Van	Van	Van	Van
Category	-	Premium Ad Car	-	-
Availability	Available	Available	Available	Available
Remarks	Fuel type Diesel	Fuel type Diesel	Fuel type Diesel	Fuel type Petrol

◀ Service Request Details

Claim

S9M01V8T

Reference

None 

Loss Date

July 25, 2019

Report Date

Jul 26, 2019 12:00:00 AM

Request Date

July 29, 2019

Due Date

August 5, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

P: Sukyi

T: 10:29a.m

v:lh

E. ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

GBD9410X

Model

NISSAN NV200

Service Address

Primary Contact/Insured

PING SIONG INTERNATIONAL PTE LTD &/OR IRIT LEASING PTE LTD
3 PIONEER ROAD NORTH, #01-13, 628457, Singapore
65674755

Claim Handler

HO Winnie
6568804833
winnie.ho@axa.com.sg

Additional Instructions
NON-REPORTED

Messages Invoices History Documents2 Assessment Metrics Notes

New Message

Catherine Chong (LKK Auto)

From: Chew Motor Pte. Ltd. <claims@chewmotor.com>
Sent: Friday, 26 July, 2019 2:06 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: GBD9410X CLAIMING AGAINST XE3848R DOA:25.07.19
Attachments: GBD9410X PRI.pdf

Categories: Shailendra

Without Prejudice

Hi Motor Claim Dept

Please send us your surveyor list,thanks.

*****Please take note this claim under Chew Motor Pte Ltd*****

Please kindly take note that we have a mutual agreement on the selection of appointed surveyor from your panel surveyor's list. We hope that there will not be any further changes to the finalised repair cost after confirmation with your appointed surveyor or at the stage of LOD.

Please kindly take note that CHEW MOTOR PTE LTD is GST-registered.

Regards,

Sukyi Chong

Chew Motor Pte Ltd
(GST Registration No.: 201718369R)
1 Kaki Bukit Ave 6
Blk A #01-11 Autobay
Singapore 417883
T : 6747 9241
F : 6741 7276



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

29 July, 2019

PING SIONG INTERNATIONAL PTE LTD &/OR IRIT LEASING PTE LTD
3 PIONEER ROAD NORTH
#01-13
SINGAPORE 628457

Dear Sir,

OUR REF : S9M01V8T // CC4/ASM19013280/Aga3
YOUR REF : XE 3848R
ACCIDENT INVOLVING XE 3848R & GBD 9410X ALONG/ AT 8 BENOI SECTOR ON
25/07/2019

We write to inform you that we are the appointed loss adjuster by your motor insurer, AXA insurance Singapore Pte Ltd to deal with the third party claim against your motor policy.

We have received a third party claim(s) from **Chew Motor Pte Ltd** acting on behalf of the owner of **GBD 9410X** against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We highlight that this accident has not been reported to your insurer. Under the Motor Claims Framework (MCF), you are required to report any accident with the accident vehicle (whether damaged or not) within 24 hours or by the next working day after the accident. The primary purpose of this reporting is to provide your version of the accident to AXA. Omission to report the accident will result in a loss of your No Claim Discount (NCD) upon renewal of your policy, and will prejudice any claim(s) by or against you. We would appreciate it if you could urgently file a report at our approved reporting centre.

The report has to be lodged at any of AXA Premium Workshops or reporting centres (subject to your policy). For the list of AXA Premium Workshops conveniently located throughout Singapore, please refer to the back of your Certificate of Insurance or the accompanying folder, or visit <https://www.axa.com.sg/customer-care/personal/motor/motor-claims>

Your full co-operation in the handling of the claim is required and kindly submit the following to <<YOUR EMAIL ADDRESS>> within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)



PING SIONG INTERNATIONAL PTE LTD

NO: 1 TUAS SOUTH STREET 13 Singapore 637084
Tel: (65) 62657826 Fax: (65) 62665874
E-mail: kpsmotor@singnet.com.sg
Business Reg No: 200909894M GST Reg No: 200909894M

23/10/19

TO: WHOM IT MAY CONCERN

Dear Sirs / Mdm,

**RE: ACCIDENT INVOLVING VEHICLE NO: XE3848R AND GBD9410X
D/D 25/07/2019 @1650 AT NO: 8 BENOI SECTOR**

Please be informed that we are the owner of the Vehicle No: XE3848R, we hereby Authorized MR. SAINI BIN RAHMAN holder of driving license No: S0436902E to drive this Prime Mover to deliver the cargo.

Thank you,

Yours faithfully,


Tan Lian Huay / Director



Immediate Advice

To : AXA Insurance Pte Ltd

Date: 26/10/2019

Survey Details:

Date of loss	25-Jul-19
Date of appointment	29-Jul-19
Date of survey	29-Jul-19
Location of survey	CHEW MOTOR PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	GBD9410X
Make and Model	NISSAN NV200 1.5L MT ABS AIRBAG
Date of registration	5-Aug-15
Parf Rebate	
Market Value	\$ 38,000.00
Parf Rebate	\$ 26,994.00
Nett Loss	\$ 11,006.00

Repair details:

Initial Estimate	26,244.30
------------------	-----------

Proposed/Revised repair cost:

Parts	\$ 12,503.04
Check items (estimate)	\$ -
Labour	\$ 2,690.00
Total	\$ 15,193.04
Lump Sum(if applicable)	\$ 10,500.00

Number of days for repair	8.0
---------------------------	-----



Remarks:

08 RECOMMENDED REPAIR DAYS + 1 SATURDAY + 1 SUNDAY +
2PRS = 12 DAYS

Mandate:

Liability(TP)		100%	
Proposed repair cost	\$	11,235.00	W/GST
Loss of use	\$	1,200.00	12days x \$100
Loss of rental	\$	-	
Loss of income	\$	-	
LTA search fees	\$	7.45	
Others	\$	-	
Proposed Total	\$	12,442.45	

 <MANDATE IA> - S9M01V8T {ACCIDENT INVOLVING XE 3848R (OI) & GBD 9410X (TP) ON 25/07/2019}

Type

 Question

Message

LIABILITY: 100%, OI OVERTOOK TP ON THE 2ND LANE AND MAKE A LEFT TURN WHEN TP AT 1ST LANE. : INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$12,442.45 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL

[Reply](#)



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

GST Reg No.: 201718369R

TAX INVOICE

AXA Insurance Pte Ltd
8 Shenton Way,
#B1-01,
Singapore 068811

Client: BUDGETMARKET MARKETING

Invoice No : CPI1909-0127

Date : 18-Sep-19

Date of Accident : 25-Jul-19

Vehicle No. : GBD9410X

Model Type : Nissan NV200

Descriptions	Amount
Lump Sum Repair Cost	10,500.00
GST 7% :	735.00
Total :	11,235.00

(SGD) Dollars: ELEVEN THOUSAND TWO HUNDRED AND THIRTY-FIVE ONLY



Our Reference : CM1909-0127 / GBD9410X
Your Reference : XE3848R



CHEW MOTOR PTE. LTD

18 September 2019

AXA Insurance Singapore Pte Ltd
8 Shenton Way,
#B1-01,
Singapore 068811

WITHOUT PREJUDICE

Dear Sir/Madam

ACCIDENT INVOLVING GBD9410X & XE3848R ON 25.07.2019 ALONG 8 BENOI SECTOR AT 16:45HRS

We are instructed by **BUDGETMARKET MARKETING** to claim damages and losses against you in connection with the above-captioned road traffic accident which our client's vehicle **GBD9410X** damaged by vehicle **XE3848R** driven by your insured at the material time.

We are informed that the said accident was caused by your insured's negligence. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows: -

➤ Repair Costs (7% GST)	\$ 11,235.00
➤ Loss of Use for 12 days (10 + 2 Weekend)	\$ 1,200.00
➤ LTA Search Fees	\$ 7.45
➤ Total	<u>\$ 12,442.45</u>

A copy of each supporting documents are enclosed for your perusal.

- GIA Report
- Invoice
- LTA Search Receipt

Please let us have your cheque for the sum of **\$12,442.45** made payable to us, **CHEW MOTOR PTE. LTD.** within the next 14 days.

Yours Sincerely,



CHEW MOTOR PTE. LTD.



 **<MANDATE IA> - S9M01V8T {ACCIDENT INVOLVING
XE 3848R (OI) & GBD 9410X (TP) ON 25/07/2019}**

Type

 Question

Message

Hi Cecila, COR - proceed. LOU - \$60 per day X 10 days max. LTA - proceed. Tks

[Reply](#)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19013280/Aga3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: WINNIE HO

Date : 05-11-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 3848R	Veh. Inspected	GBD 9410X
Policy No.	VFX/P1979987	Coverage (\$)	0.00
Claim No.	S9M01V8T	Excess (\$)	0.00
Assign From	WINNIE HO	Assign Date	29/07/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV200	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	VSKYBAM20Z0098778	Colour	SILVER
Odometer	153145	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R14	MAXTREX	6 mm
L/H Front Tyre	175/70 R14	MAXTREX	6 mm
R/H Rear Tyre	175/70 R14	MAXTREX	6 mm
L/H Rear Tyre	175/70 R14	MAXTREX	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND UNDERCARRIAGE.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/07/2019	Inspection Date	29/07/2019
Survey held at	CHEW MOTOR PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 9410X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET (N) (CONSISTENT)	TO REPAIR SEE LABOUR	1,157.90	-
2	FRONT BONNET HINGE @ \$57.70 (N) (CONSISTENT)	NOT NECESSARY	115.40	-
1	FRONT BONNET LOCK (N) (CONSISTENT)	NOT NECESSARY	78.70	-
2	FRONT HEAD LAMP @ \$446.40 (N) (CONSISTENT)	CRACKED	892.80	892.80
2	FRONT HEAD LAMP LOWER BRACKET @ \$75.70 (N) (CONSISTENT)	NOT NECESSARY	151.40	-
1	FRONT BUMPER (N) (CONSISTENT)	DISTORTED	589.70	589.70
2	FRONT BUMPER SIDE RETAINER @ \$35.20 (N) (CONSISTENT)	NECESSARY	70.40	70.40
10	FRONT BUMPER CLIP @ \$6.50 (N) (CONSISTENT)	NECESSARY	65.00	30.00
2	FRONT BUMPER SIDE COVER @ \$362.20 (N) (CONSISTENT)	MISSING	724.40	724.40
1	FRONT BUMPER CENTRE GARNISH (N) (CONSISTENT)	CRACKED	231.00	231.00
1	FRONT BUMPER REINFORCEMENT (N) (CONSISTENT)	BENT	614.90	591.90
2	FRONT BUMPER REINFORCEMENT BRACKET @ \$91.70 (N) (CONSISTENT)	NOT NECESSARY	183.40	-
1	FRONT GRILLE (N) (CONSISTENT)	CRACKED	338.00	338.00
8	FRONT GRILLE CLIP @ \$6.50 (N) (CONSISTENT)	NECESSARY	52.00	20.00
1	FRONT GRILLE EMBLEM LOGO (N) (CONSISTENT)	NECESSARY	73.50	73.50
1	FRONT GRILLE LOWER MOULDING (N) (CONSISTENT)	CRACKED	205.50	205.50
1	FRONT SUPPORT PANEL (N) (CONSISTENT)	BUCKLED	1,057.00	507.00
1	FRONT SUPPORT PANEL TOP COVER (N) (CONSISTENT)	CRACKED	145.30	145.30
1	FRONT SUPPORT PANEL AIR DUCT COVER (N) (CONSISTENT)	CRACKED	129.20	129.20
1	FRONT RADIATOR TANK (N) (CONSISTENT)	NOT NECESSARY	94.60	-
1	FRONT R/H FENDER (N) (CONSISTENT)	BUCKLED	504.70	504.70
2	FRONT FENDER COWLING @ \$142.80 (N) (CONSISTENT)	O/S TORN	285.60	142.80
16	FRONT FENDER COWLING CLIP @ \$6.50 (N) (CONSISTENT)	NECESSARY	104.00	30.00
1	FRONT R/H FENDER SIGNAL LAMP (N) (CONSISTENT)	NOT NECESSARY	66.60	-
1	FRONT R/H FENDER QUARTER GLASS GARNISH (N) (CONSISTENT)	NOT NECESSARY	162.60	-

Report Ref No. CC4/ASM19013280/Aga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT R/H FENDER QUARTER GLASS ASSY (N) (CONSISTENT)	NOT NECESSARY	275.90	-
2	FRONT HORN @ \$98.80 (N) (CONSISTENT)	NOT NECESSARY	197.60	-
1	FRONT AIR CLEANER BOX ASSY (N) (CONSISTENT)	CRACKED	566.40	566.40
1	FRONT ENGINE LOWER COVER (N) (CONSISTENT)	TORN	272.30	272.30
1	FRONT R/H LOWER ARM (N) (CONSISTENT)	BENT	192.50	192.50
1	FRONT WIPER TANK (N) (CONSISTENT)	DEFORMED	247.90	247.90
1	FRONT RADIATOR (N) (CONSISTENT)	BENT	687.40	687.40
1	FRONT RADIATOR FAN MOTOR (N) (CONSISTENT)	CRACKED	685.90	452.00
1	FRONT AIR-CON CONDENSER (N) (CONSISTENT)	BENT	653.00	653.00
1	FRONT AIR-CON AIR DUCT BLOWER ASSY (N) (CONSISTENT)	NOT NECESSARY	508.40	-
1	FRONT AIR-CON COOLANT COIL BLOWER ASSY (N) (CONSISTENT)	NOT NECESSARY	1,101.40	-
1	FRONT ALTERNATOR (N) (CONSISTENT)	DAMAGED	1,889.80	1,889.80
1	FRONT AIR-CON COMPRESSOR (N) (CONSISTENT)	DAMAGED	1,121.10	1,121.10
1	FRONT AIR-CON COMPRESSOR PIPE (N) (CONSISTENT)	BENT	251.30	251.30
2	FRONT AIR-CON COMPRESSOR BRACKET (N) (CONSISTENT)	NOT NECESSARY	108.80	-
1	FRONT INTERCOOLER (N) (CONSISTENT)	DENTED	2,121.60	1,100.00
1	FRONT R/H TYRE (N) (CONSISTENT)	NOT NECESSARY	380.00	-
1	FRONT R/H KNUCKLE ARM (N) (CONSISTENT)	DAMAGED	583.20	583.20
1	FRONT R/H KNUCKLE ARM BEARING (N) (CONSISTENT)	DAMAGED	329.70	329.70
1	FRONT R/H SHOCK ABSORBER (N) (CONSISTENT)	BENT	252.80	252.80
1	FRONT STEERING RACK (N) (CONSISTENT)	NOT NECESSARY	1,117.60	-
	LESS 10% DISCOUNT		-	-1,382.56
			21,638.20	12,443.04
	SPECIAL NETT ITEMS			
1	FRONT R/H HUB CAP (SN) (CONSISTENT)	CRACKED	166.10	60.00
			166.10	60.00
	LABOUR			
	TO REMOVE & REFIT AIR-CON BLOWER, COOLANT COIL, AIR DUCT BLOWER & TOP UP GAS.	NOT NECESSARY	280.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT AIR-CON CONDENSER, RADIATOR, FAN MOTOR & TOP UP GAS.		280.00	120.00
	TO REMOVE & REFIT FRONT UNDERCARRIAGE, DRIVE SHAFT & STEERING RACK.		480.00	200.00
	TO CHECK WIRING.		100.00	30.00
	TO CHECK WHEEL ALIGNMENT.		150.00	80.00
	TOWING FEE.		150.00	60.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT BONNET.		1,600.00	1,200.00
	SPRAY PAINTING.		1,400.00	1,000.00
			4,440.00	2,690.00
	GRAND TOTAL		26,244.30	15,193.04
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			10,500.00

Report Ref No. CC4/ASM19013280/Aga3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.