



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

GST Reg No.: 201718369R

BUDGET MARKET MARKETING

04/06/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TRAYA. VSKYBAM20Z0098778
Cecilia.

Accident date: 03/06/2019

Estimated repair cost for vehicle no: GBD9410X NISSAN NV200 1.5 M '15

CHASSIS: VSKYBAM20Z0098778

S/n	Qty	Items / Nett	U/price	Amount
1	1	Front Bonnet <i>Rynt</i>		\$1,157.90 ✓
2	2	Front Bonnet Hinge <i>Not new</i>	\$57.70	\$115.40 +
3	1	Front Bonnet Lock <i>Not new</i>		\$78.70 +
4	2	Front Head Lamp <i>cracked</i>	\$446.40	\$892.80 ✓
5	2	Front Head Lamp Lower Bracket <i>Not new</i>	\$75.70	\$151.40 +
6	1	Front Bumper <i>Distorted</i>		\$589.70 ✓
7	2	Front Bumper Side Retainer <i>new</i>	\$35.20	\$70.40 ✓
8	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 30
9	2	Front Bumper Side Cover <i>Not new</i>	\$362.20	\$724.40 ✓
10	1	Front Bumper Centre Garnish <i>cracked</i>		\$231.00 ✓
11	1	Front Bumper Reinforcement <i>Bent</i>		\$614.90 5918
12	2	Front Bumper Reinforcement Bracket <i>Not new</i>	\$91.70	\$183.40 X
13	1	Front Grille <i>cracked</i>		\$338.00 ✓
14	8	Front Grille Clip <i>new</i>	\$6.50	\$52.00 20
15	1	Front Grille Emblem Logo <i>new</i>		\$73.50 ✓
16	1	Front Grille Lower Moulding <i>cracked</i>		\$205.50 ✓
17	1	Front Support Panel <i>Buckled</i>		\$1,057.00 309
18	1	Front Support Panel Top Cover <i>cracked</i>		\$145.30 ✓
19	1	Front Support Panel Air Duct Cover <i>cracked</i>		\$129.20 ✓
20	1	Front Radiator Tank <i>Not new</i>		\$94.60 +
21	1	Front R/H Fender <i>Buckled</i>		\$504.70 ✓
22	2	Front Fender Cowling <i>RH torn</i>	\$142.80	\$285.60 142.80
23	16	Front Fender Cowling Clip <i>new</i>	\$6.50	\$104.00 30
24	1	Front R/H Fender Signal Lamp <i>Not new</i>		\$66.60 +
25	1	Front R/H Fender Quarter Glass Garnish <i>Not new</i>		\$162.60 +
26	1	Front R/H Fender Quarter Glass Assy <i>Not new</i>		\$275.90 +
27	2	Front Horn <i>Not new</i>	\$98.80	\$197.60 +

28	1	Front Air Cleaner Box Assy <i>needed</i>		\$566.40 ✓
29	1	Front Engine Lower Cover <i>for</i>		\$272.30 ✓
30	1	Front R/H Lower Arm <i>Best</i>	\$192.50	\$192.50 ✓
			Subtotal :-	\$9,598.30

S/n	Qty	Items / Special Nett	U/price	Amount
31	1	Front Wiper Tank <i>needed</i>		\$247.90 ✓
32	1	Front Radiator <i>Best</i>		\$687.40 ✓
33	1	Front Radiator Fan Motor <i>needed</i>		\$685.90 ✓ 450
34	1	Front Air-Con Condenser <i>Best</i>		\$653.00 ✓
35	1	Front Air-Con Air Duct Blower Assy <i>3 NY</i>		\$508.40 ✓
36	1	Front Air-Con Coolant Coil Blower Assy <i>new</i>		\$1,101.40 ✓
37	1	Front Alternator <i>Damaged</i>		\$1,889.80 ✓
38	1	Front Air-Con Compressor <i>Damaged</i>		\$1,121.10 ✓
39	1	Front Air-Con Compressor Pipe <i>Best</i>		\$251.30 ✓
40	2	Front Air-Con Compressor Bracket <i>new</i>		\$108.80 ✓
41	1	Front Intercooler <i>needed</i>		\$2,121.60 ✓ 1100
42	1	Front R/H Tyre <i>new</i>		\$380.00 ✓
43	1	Front R/H Hub Cap <i>new</i>		\$166.10 ✓ 600
44	1	Front R/H Knuckle Arm <i>Damaged</i>		\$583.20 ✓
45	1	Front R/H Knuckle Arm Bearing <i>needed</i>		\$329.70 ✓
46	1	Front R/H Shock Absorber <i>Best</i>		\$252.80 ✓
47	1	Front Steering Rack <i>new</i>		\$1,117.60 ✓
			Subtotal :-	\$12,206.00

11597.80
104802 \$20.60

Labour charges

To remove & refit air-con blower, coolant coil, air duct blower & top up gas		\$280.00 X
To remove & refit air-con condenser, radiator, fan motor & top up gas		\$280.00 120
To remove & refit front undercarriage, drive shaft & steering rack		\$480.00 200
To check wiring		\$100.00 30
To check wheel alignment		\$150.00 80
Towing Fee	2650	\$150.00 60
Panel beating		\$1,600.00 1200
Spray painting		\$1,400.00 1000

Subtotal :- \$4,440.00

Total:- \$26,244.30

total 138802.
 1/5 10.5K
 08 Days.
 10.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



PEOPLES AUTO TRADING
 BLK 3007 UBI ROAD 1 #01-400
 TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER	CHEW MOTOR	DATE	Jul 30, 2019 9:29:22 AM
LICENSE NO.	GBD 9410 X		
MILEAGE	153150		
REFERENCE	CUSTOM	MODEL	NISSAN NV200

Front Wheel	SPECS				DIAGNOSIS				ADJUSTMEN			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	-1.00	0.00	1.00			6.90				6.90		
PARTIAL TOE	-0.50	0.00	0.50		2.30		4.60		2.60		4.20	
SET BACK	---	---	---				-0°24"				-0°24"	
CAMBER	-1°12"	-0°12"	0°48"		-0°56"		-2°14" 1°18"		-0°56"		-2°14" 1°18"	
CASTER	3°30"	4°30"	5°30"		4°12"		4°24" 0°12"		4°12"		4°24" 0°12"	
KING-PIN	---	---	---		10°10"		9°46" 0°24"		10°10"		9°46" 0°24"	
INCL ANGLE	---	---	---		9°12"		7°30"		9°12"		7°30"	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel	SPECS				DIAGNOSIS				ADJUSTMEN			
	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	---	---	---			4.30				4.30		
PARTIAL TOE	---	---	---		3.40		0.80		3.40		0.80	
SET BACK	---	---	---				0°00'				0°00'	
CAMBER	---	---	---		-1°28"		-2°00" 0°32"		-1°28"		-2°00" 0°32"	
THRUST ANGLE	-0°08"	0.00	0°08'				0°12"				0°12"	