



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Repair Estimates

SLK 7407 P

Not Authorized  
Mercury Repair

Parts	(a) Cost / List Price Items	\$ 1626.37	3,449.17
	Plus/Less 25%	\$ 406.59	862.29
	Total of Cost / List	\$ 1219.78	2,586.88
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
Total Parts Cost		\$	2,786.88
Labour		\$ 580.00	3,140.00
Total		\$ 1799.78	5,926.88

The above total will be subjected to 7% G.S.T.

Name of Surveyor

:

Kennerth

Company

:

HLK

Survey conducted on

:

30/7/11 P

at

### Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 02-7 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor

:

Le

Date:

30/7/11 P



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : SLK 7407 P  
Make & Model : TOYOTA PRIUS  
Chassis No : JTDKB3FU903540525

Submit By : JENNY  
Year Manufacture : 2016  
Engine No. :                       
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>Sn</i>	1	\$200.00	S.N	X
2	Rear bumper <i>Bu</i>	1	\$497.50		✓
3	Rear bumper clip <i>Un</i>	10	\$40.00		✓
4	Rear bumper side retainer LH <i>Sn</i>	1	\$112.70		X
5	Rear bumper side retainer RH <i>Sn</i>	1	\$112.70		X
6	Rear bumper reinforcement <i>Rt</i>	1	\$398.90		✓
7	Rear bumper lower centre garnish <i>nt/lt</i>	1	\$582.60		✓
8	Rear bumper tow cover <i>Sn</i>	1	\$31.70		X
9	Wording "PRIUS" <i>Un</i>	1	\$51.90		✓
10	Wording "HYBRID" <i>Un</i>	1	\$55.47		✓
11	Tail door plate garnish <i>Sn</i>	1	\$782.50		X
12	Tail end panel <i>R</i>	1	\$596.60		X
13	Tail end panel garnish <i>Sn</i>	1	\$151.60		X
14	Tail end panel garnish clip <i>Un</i>	10	\$35.00		X
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829  
Company Reg No. 200005485N / GST No. 20-0005485-N

166.37



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Labour

Vehicle No. : SLK 7407 P Submit By : Carmen Lim  
Make & Model : TOYOTA PRIUS Year of Manufacture : 2016

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, TAIL DOOR PLATE GARNISH, END PANEL, SPARE TYRE COMPARTMENT)	\$1,200.00	2000
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, TAIL DOOR PLATE GARNISH, END PANEL, SPARE TYRE COMPARTMENT)	\$1,200.00	3200
3	To check Wiring	\$50.00	100
4	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	X
5	To tuff coat	\$150.00	X
6	To conduct water leakage tests to ensure proper air and sealing	\$120.00	X
7	To transfer boot mechanism to new boot	\$120.00	X
8	To remove & refit reverse sensor	\$150.00	500

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.