ESTIMATED ACCIDENT REPAIR COST



CCIDENT TIME EPORTED	13:40	BUS REGISTRATION NUMBER	SMB3532Y
CCIDENT DATE	23-Jul-19	BUS TYPE (SD/DD)	DD
US CAPTAIN NAME	CHANDRASEKHARAM S/O V RATNAM	BUS ROUTE NUMBER	
MPLOYEE NUMBER		BUS ADVERTS (Y/N)	N

SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

Part No.	Part or Item Description	Quantity	Total Cost
77200172	O/S/F CORNER BUMPER repuir	1	\$395.58
		7% GST	\$27.69
		FINAL TOTAL COST	\$423.27

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)		TOTA	L COST
TO REMOVE & REPLACE THE DAMAGED PARTS			\$650.00
SPRAY PAINTING		500	\$650.00
	7% GST		\$91.00
	FINAL TOTAL COST		\$1,391.00

PAGE 1

ESTIMATED ACCIDENT REPAIR COST



SECTION 3: REPAIRS	TO BUS	ADVERTISMENT	VINYLS/PANELS	(ADVERTISEMENT CO	ST)

TOTAL	ADVERTISEMENT	REPAIR	COST

LOSS OF USE COST

SECTION 4: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST

SECTION 5: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

Date In For Repairs	
Date Out From Repairs	
Number of Days Under Repair	2
	\$800.00

SUMMARY COST \$423.27 \$1,391.00

BUS TYPE (SD / DD)

SECTION NO. 1 2 3 4 5 \$800.00 **ESTIMATED ACCIDENT** REPAIR COST \$2,614.27 (1+2+3+4+5)

Rasul
Ap 90010088

2 days
29/07/12 @1650

Resun after
repair

PAGE 2

LKK Auto Consultants hence notify

- the Pepairer of the following:
- * To resurvey before/after spray painting
- o display damaged part(s) during resurvey
- Paris prices are subject to confirmation
- ATTEM I party survey is on a "Without Prejudice" basis lanal modification(s) is allowed
- · Ementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowled- Id by Repairer