

ESTIMATED ACCIDENT REPAIR COST

ACCIDENT TIME REPORTED	13:40
ACCIDENT DATE	23-Jul-19
BUS CAPTAIN NAME	CHANDRASEKHARAM S/O V RATNAM
EMPLOYEE NUMBER	

BUS REGISTRATION NUMBER	SMB3532Y
BUS TYPE (SD/DD)	DD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

	Part No.	Part or Item Description	Quantity	Total Cost
	77200172	O/S/F CORNER BUMPER <i>repair</i>	1	\$395.58
			7% GST	\$27.69
			FINAL TOTAL COST	\$423.27

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

[illegible]

ESTIMATED ACCIDENT REPAIR COST



SECTION 3: REPAIRS TO BUS ADVERTISEMENT VINYL/PANELS (ADVERTISEMENT COST)

TOTAL ADVERTISEMENT REPAIR COST	-
---------------------------------	---

SECTION 4: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

SECTION 5: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

		Date In For Repairs	
		Date Out From Repairs	
		Number of Days Under Repair	2
BUS TYPE (SD / DD)		LOSS OF USE COST	
		\$800.00	

SUMMARY	
SECTION NO.	COST
1	\$423.27
2	\$1,391.00
3	-
4	-
5	\$800.00
ESTIMATED ACCIDENT REPAIR COST (1+2+3+4+5)	\$2,614.27

Rasul
Hp 900/0068
2 days
29/07/19 @ 1650
Resurvey after repair

If the vehicle is damaged, hence notify
 of the following:
 before/after spray painting
 damaged part(s) during resurvey
 are subject to confirmation
 on a "Without Prejudice" basis
 is allowed
 must be resurveyed and
 from Insurance Co.