

Mon 05/08 @ 10am SMD911X
P&K Wed 14/08 @ 10am

How Dealer

Performance Motors Limited

A Sime Darby Motors Company
 103, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159944
 Toll-Free Number: 1800 2255269

103, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159944
 Fax: 64796770

280, Kampong Atang Road
 East Coast Centre
 Singapore 438180
 Fax: 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax: 64796601 (AfterSales)
 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

29 JUL 2019

ESTIMATE

Estimate No. : b1 52131		Page No. : 1 of 5
Date Estimated : 29/07/2019		
Prepared By : Han Kwan Yong		

- ESTIMATE REPAIR FOR - Goh Yiu Ngee (Wu Youyi) 54 Sengkang Square #09-11 Singapore 544832	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD911X	LC94178	27/07/2018	X3 sDrive20i	0

DESCRIPTION	VALUE
To replace rear bumper & attachments including to knock out dented area caused by the accident	850 1,275.00
To respray rear bumper top and bottom trim panel	1357 1,486.00
To check electrical wiring systems and lightings at the rear section for proper function	150 177.00
Sundries -	80.00
FOR CASH JOB REPAIR ONLY. NOT FOR INSURANCE CLAIM PURPOSE.	
- DURATION OF THE JOB TAKES 2-3 WORKING DAYS.	
Total Labour 1:	3,018.00

DESCRIPTION	QTY	PRIC	VALUE
EXPANDING RIVET	10	2.50	25.00
LH SIDE GUIDE FOR BUMPER	1	61.50	61.50
LH BUMPER GUIDE	1	70.30	70.30
REAR UNDERRIDE GUARD (X LINE)	1	227.90	227.90
REAR BUMPER PANEL PRIMED (X LINE PM)	1	1,555.40	1,555.40
REAR BUMPER CLADDING (PDC)	1	581.90	581.90
EXPANDING RIVET BLACK	30	1.35	40.50
LH REFLECTOR	1	37.90	37.90
\$ ULTRASONIC SENSOR BLACK	1	248.70	248.70
DECOUPING RING PDC TORQUE CONVERTER	2	5.05	10.10
# ULTRASONIC SENSOR GLACIERSIL	1	368.80	368.80
Total Parts :			3,228.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X
Toll Free Number: 1800 2154249

303, Alexandria Road
Sime Darby Performance Centre
Singapore 159944
Fax: 64796624

290, Kampong Arang Road
East Coast Centre
Singapore 438186
Fax: 63449773

315, Alexandria Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 52131

Page No. : 2 of 5

Date Estimated : 29/07/2019

Prepared By : Han Kwan Yong

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD911X	LC94178	27/07/2018	X3 sDrive20i	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts provided subject to confirmation
- Third party involvement - "Without Prejudice" basis
- No legal action is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims: 0D / 3rd Party / Uninsured losses / Direct Settlement

Ref: 14/8/14c1110 Claim No: _____

Excess S\$: _____

Sign: _____

Authorised: Yes / No

Time: _____

EX-SURVEYOR Yes / No PML Yes / No

Signature: _____

Recommendation: 3 days

Labour 1	:	3,018.00
Parts	:	3,228.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	437.22
Grand Total	:	6,683.22

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE **



Estimate No. : **b1 52131**
Date Estimated : **29/07/2019**
Prepared By : **Han Kwan Yong**

Goh Yiu Ngee (Wu Youyi)
54 Sengkang Square
#09-11

- ACCOUNT - 121
AIG ASIA PACIFIC INSURANCE
78 SHENTON WAY
#08-16 CHARTIS BUILDING
SINGAPORE 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD911X	LC94178	27/07/2018	X3 sDrive20i	0

		ACCOUNT:		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments including to remove and install body parts in order to carry out painting job.	850.00	0	850.00	
To respray rear bumper top and bottom trim panel	1,337.00	0	1,337.00	
To check electrical wiring systems and lightings at the rear section for proper function	150.00	0	150.00	
Sundries. -	80.00	0	80.00	
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
LH SIDE GUIDE FOR BUMPER	61.50	1.00	0	61.50
REAR BUMPER PANEL PRIMED (X LINE PM	1,555.40	1.00	0	1,555.40
REAR BUMPER CLADDING (PDC)	581.90	1.00	0	581.90
EXPANDING RIVET BLACK	1.35	30.00	0	40.50
LH REFLECTOR	37.90	1.00	0	37.90

FAX TO FAX NO					
FAX TO FAX NO					

70011K1
LKK 23/5/19 3

Total Labour :	2,417.00
Total Parts :	2,277.20
Total Repair Costs less Excess:	4,694.20
GST @7%:	328.59
Grand Total :	5,022.79

LOSS OF USE = \$120 X 3 DAYS
GIA SEARCH FEE - \$2.00