Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19013291/AGA3Q2

Date: 02/11/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00003601

Claimant Insured Vehicle No: SLL2494P

GBC8512Y Vehicle No:

Date of Loss: 25/07/2019 Nature of Claim: ΤP Claim No: 1201900021811

DESCRIPTION & IDENTIFICATION OF VEHICLE

GBC8512Y Reg No:

Engine No: Make & Model: NISSAN NV350, 2.5 D Panel Van (M) YD25340036A

Reg. Date: 20/01/2014 (Man. Year: 2013) Chassis No: JN1MC2E26Z0001488

Colour: Odometer: 178653 km Silver

Engine Capacity: 2488 cc Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C Dunlop 6 mm Front Left Side: Rear Left Side: Dunlop 6 mm Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,066.30	1,228.35	1,837.95	59.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	830.00	670.00	44.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,566.30	2,058.35	2,507.95	54.92
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	4,566.30	1,650.00	2,916.30	63.87
+ GST 7.00/7.00% (S\$)	319.64	115.50	204.14	63.87
Nett Amount (S\$)	4,885.94	1,765.50	3,120.44	63.87
Global Sum S	Settlement (S\$)	0.00		

INSPECTION

Date of Assignment: 29/07/2019

03/10/2019 Inspected At: Date Inspected: New Hock Teck Motor Pte Ltd (HQ)

1 Kaki Bukit Ave 6. Blk C #01-43

Autobay@Kaki Bukit Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING Manager: Chong Pui Lin Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference				
Part Source:		(Last Synchronised: 02 Nov 2020)		
Parts:	N/A	NISSAN NV350 2.5 D Panel Van (M) (Model not available in database)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for GBC8512Y)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *				

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	578.90 F	*578.90 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	1		*FRONT BUMPER SIDE HOLDER LH	Not Necessary	146.00 F	*-FL
4	1		*FRONT BUMPER FOG LAMP LH	Not Necessary	225.00 F	*-FL
5	1		*FRONT BUMPER FOG LAMP GARNISH LH	Not Necessary	115.80 F	*-FL
6	1		*HEADLAMP LH	Cut	481.40 F	*481.40 FL
7	1		*FRONT LH DOOR	Repair	1,218.00 F	*-FL
8	1		*FRONT LH DOOR COMPANY ADDRESS STICKER	Necessary	30.00 FS	*30.00 FS
9	1		*FRONT LH STEP PANEL GARNISH	Cut	241.20 F	*241.20 FL
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc.					
				Sub Total (S\$)	3,066.30	1,361.50
- List Item Discount on L Items 0.00/10.00% (S\$)			0.00	133.15		
				Total Parts (S\$)	3,066.30	1,228.35

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	700.00	400.00
2	SPRAY PAINTING	New	600.00	400.00
3	WIRING	New	50.00	30.00
4	TO TRANSFER FRONT DOOR FITTINGS	New	150.00	0.00
		Gross Labour Cost (S\$)	1,500.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >