

2200000

ASS. REC. BY:

REF: CS/SMO19013295/ Ksf3n2

Special Instruction:

Surveyor: Konreth

ASSIGNMENT (Office)

From (Person): Agnes Chan Shu Hui of SMO

Date/Time: 29.7.19 12.05p.m.

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 5323A

Insured: SKB 4660C

at Workshop m/s Trans-cab

Tel: 62130998

of No 2 Ant street 63

Policy No: D18MPV01014425

Claim No: (MTD) 1902622

Sum Insured:

Excess:

Make of Veh:

D.O.A. 2.7.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 29.7.19 5.22p.m.

Person Contacted: Amanda

Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 5323A - CC3 / B Mod 4499 / K463 D.O.A - 06/10/2019
	SKB 4660C - X
31/07/19	@ 17:04 pm revised ZA to Agnes Chan V.S me:im.

ASSIGNMENT

03 19

12 08

From: Date: 30.7.2019

Estimated Cost:

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHC 5323A

at Workshop mla Trans cab

of MD 2 Amk Street 63

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR. Seen: Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

rup

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHC 5323A

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prima Mover /

Truck / Trailer or

Make: Renault Latitude cc 1995

Colour: M. White / R/A/C Insured / Std / NI / NA

Sp. Reading: 330528 T/Ratio: Insured / Std / NI / NA

Eng/No:

C/No: VF1ABL15AUC 27868

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: X/Rim / STD A/Rim or

Tyre Size: F: Giti 215/60R16

Roadstone

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 8 mm R/Bal: 9 mm

L/Bal: 8 mm L/Bal: 9 mm

D.O.A. 26/7/19 D.O.I. 30/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

C/S M

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

L1Ry 8/18502

C\$ 27,191.82 Res - 94% ?

RECEIVED 02 SEP 2019

Cater/Time, File Pass to?

02/09/19

1) Typ: 4

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + P.S. S

Photos

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) 1,850/- H/S

TOTAL

450
11

461

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 31 Jul 2019

Preliminary Advice

Insured Vehicle No	: SKB4660C	Accident Date	: 26/07/2019
TP Vehicle No	: SHC5323A	Assignment Date	: 29/07/2019
Make	: RENAULT LATITUDE	Est. Duration of Repair	: 2 days
Date of Inspection	: 30/07/2019		
Inspection At	: Trans-cab Services Pte Ltd- Ang Mo Kio (HQ) No. 2 Ang Mo Kio Street 63 Singapore 569111		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,041.82
Revised Amount	:S\$	2,334.57
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,334.57

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jul 2019		29 Jul 2019 17:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	WONG KIN HOONG, ID: 514025168								
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHC5323A	Date of Loss:	26/07/2019 04:00 - :59						
Claim Type:	TP / CMTD1903622	Policy/Cover Note No.:	D18MTPVD1014425 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKB4660C	Policy No. (Claimant):							
	Excess:								
Repairer:	Trans-cab Services Pte Ltd- Ang Mo Kio (HQ) No. 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/08/2019]								
Driver/Custodian (Insured):	RICTUS WONG JOON SENG (), NRIC: 59235385, Tel: +6592347836 Email:								
Adj Asg. Remarks:	WS: AMANDA TAY 62130998 PLS ARR SUV ON TUE 30/07/19								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

FW: TCS REF: AAD1907-241--Accident involving SHC 5323A & SKB 4660C on 26/07/2019

Ng Wai Yin <waiyin.ng@transcab.com.sg>

Fri 30/8/2019 3:25 PM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

📎 5 attachments (12 MB)

image001.wmz; ESTIMATE MARKED .pdf; DSCF2925.JPG; DSCF2926.JPG; DSCF2927.JPG;

Hi Shirley

Amount confirmed \$ 1,850 (before GST).

Thank You

Best Regards,

Ng Wai Yin

Finance Department

TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: www.transcab.com.sg



This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]

Sent: Friday, 30 August, 2019 12:06 PM

To: Ng Wai Yin <waiyin.ng@transcab.com.sg>

Cc: SUR <sur@lkkauto.com>

Subject: TCS REF: AAD1907-241--Accident involving SHC 5323A & SKB 4660C on 26/07/2019

Dear Wai Yin,

Please confirm final fig \$ 1,850.00 (lump sum) @ 2 days of repairs before GST.

Kindly provide us after paint photo.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHC5323A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Jul 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000916
Chassis No.:	VF1ABL15AUC276868
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	21 Mar 2014
First Registration Date:	21 Mar 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Mar 2022
PARF Rebate Amount:	\$8,748.00

Intended COE Rebate Details

COE Expiry Date:	20 Mar 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$58,745.00
COE Rebate Amount:	\$19,408.00
Total Rebate Amount:	\$28,156.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 26 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	26/07/2019 10:30
Date Of Accident	26/07/2019 04:30
Exact Location Of Accident	BENCOOLEN STREET TOWARDS ORCHARD ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHC5323A
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
Vehicle Particulars	
Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
Driver	
Name of Driver	KUAN KHENG YONG
NRIC No	S7239231J
Date Of Birth	20/10/1972
Occupation	OUTDOOR
Date Of Driving Pass	29/01/1993
Driving Experience	26 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93871626
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 143 POTONG PASIR AVE 2 #07-14
Postcode	350143
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 26.07.2019 at about 0430 hours, I was travelling on the centre lane along Bencoolen Street. When the traffic light was green on my favour, I made a right turn towards Orchard Road. Suddenly, I felt an impact. Vehicle B (SKB4660C) which was travelling on my right, was heading straight instead of making a right turn and hence hit onto my taxi right side rear portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKB4660C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	RICTUS WONG JOON SENG
NRIC/Passport Number	S9235385J
Contact Number	92347836
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

please see the attach GLA report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Kew
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Aminda
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Submit sketch plan to the relevant authority

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5323A**AAD1907-241***Not Authored
11 Sep @ 1850h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model: 30 JUL 2019

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5323A

VF1ABL15AUC276868

RENAULT

LATITUDE

26.7.19

SOMPO

21/3/2014

PART		LIST	
1	DOOR PANEL REAR RH	\$	<i>n</i> 2,844.66
1	ROCKER PANEL INNER GARNISH RH	\$	<i>sn</i> 466.51
1	ROCKER PANEL INNER RH	\$	<i>n</i> 1,024.79
1	ROCKER PANEL OUTER RH	\$	<i>n</i> 1,184.99
1	ROCKER PANEL CENTER RH	\$	<i>n</i> 990.25
1	BOOT REFLECTOR LAMP RH	\$	<i>sn</i> 493.35
1	FENDER PANEL REAR RH	\$	<i>n</i> 3,299.13
1	FENDER PANEL INNER TRIM REAR RH	\$	<i>sn</i> 671.45
1	WHEELARCH REAR RH	\$	<i>sn</i> 543.47
1	BUMPER COVER REAR	\$	<i>Buckler</i> 1,108.46
1	BUMPER LOWER REAR	\$	<i>sn</i> 768.84
1	BUMPER BRACKET CTR REAR	\$	<i>sn</i> 113.47
1	BUMPER BRACKET SIDE RH REAR	\$	<i>sn</i> 135.97
1	BUMPER RETAINER RH REAR	\$	<i>sn</i> 44.99
1	BUMPER REFLECTOR RH	\$	<i>sn</i> 43.61
1	BUMPER BEAM REAR	\$	<i>n</i> 777.52
1	BUMPER BEAM BRACKET RH REAR	\$	<i>n</i> 225.95
1	TAILLAMP RH	\$	<i>sn</i> 552.55
1	TAILLAMP PANEL RH	\$	<i>n</i> 986.70
TOTAL		\$	16,276.66
10%		\$	1,627.67
		\$	14,649.00

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	<i>nn</i> 80.00 X
1	FENDER INNER TRIM CLIP RH	\$	<i>nn</i> 28.00 X
1	TAILLAMP CLIP RH	\$	<i>nn</i> 5.00 X
1SET	FENDER WHEELARCH REAR RH CLIP	\$	<i>nn</i> 35.00 X
2	REAR WINDSCREEN SEALANT	\$	<i>nn</i> 80.00 X

Trans-cab Auto Services Pte Ltd

AAD1907-241

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5323A

1	WINDSCREEN MOULDING	\$	na	100.00	X
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	X
1	REAR RIGHT TYRE	\$	Sh	300.00	X
1	REAR RIGHT TYRE RIM	\$	Sh	380.00	<
1SET	PARKING AID	\$	Sh	700.00	X
1SET	REAR BUMPER CLIP	\$	na	66.00	✓
1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	✓
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
1SET	BUMPER RETAINER CLIP RH RR	\$	na	20.00	X
1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	✓
1	EXHAUST MOUNTING REAR	\$	na	17.82	X
TOTAL		\$		2,042.82	
TOTAL PARTS		\$		16,691.82	

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2001 4,500.00
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na 380.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na 380.00 X
To check steering geometry and computer wheel alignment	\$	na 220.00 X
To rust-proofing of the affected areas.	\$	na 170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	na 170.00 X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	na 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1907-241**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5323A

To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
Putty and spray painting of the affected portion.	\$	4,500.00 <i>2201</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00 <i>X</i>
TOTAL	\$	12,350.00
Over All Total	\$	29,041.82

LUMP SUM (REPAIR DAY)***15 DAYS******2 days***

LXR Auto Consultants hereby notify the Repairer of the following:

- To survey before/after any towing
- To survey damaged part(s) during survey
- Parts prices are accurate quotation
- Third party claim must be "Without Prejudice" basis
- BOD must be approved by insurer
- Survey work must be supervised and signed off by approved firm/insurance company

Approved by Repairer:

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19013295/KSF3N2

Date: 05/09/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01014425
Claimant Vehicle No :	SHC5323A	Insured Vehicle No :	SKB4660C
Date of Loss:	26/07/2019	Nature of Claim:	TP
		Claim No:	CMTD1903622

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5323A	Engine No:	M9R8839C000916
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC276868
Reg. Date:	21/03/2014 (Man. Year: 2013)	Odometer:	330528 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Roadstone 9 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Roadstone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	16,691.81	1,854.57	14,837.24	88.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,350.00	480.00	11,870.00	96.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,041.81	2,334.57	26,707.24	91.96
Approved Total (Overridden) (S\$)		1,850.00		
(S\$)	29,041.81	1,850.00	27,191.81	93.63
+ GST 7.00/7.00% (S\$)	2,032.93	129.50	1,903.43	93.63
Nett Amount (S\$)	31,074.74	1,979.50	29,095.24	93.63

INSPECTION

Date of Assignment:	29/07/2019	
Date Inspected:	30/07/2019	Inspected At: Trans-cab Services Pte Ltd- Ang Mo Kio (HQ) No. 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Sep 2019)
Parts: 143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC5323A)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL REAR RH	Repair	2,844.66 FL	*- FL
2	1		*ROCKER PANEL INNER GARNISH RH	Serviceable	466.51 FL	*- FL
3	1		*ROCKER PANEL INNER RH	Repair	1,024.79 FL	*- FL
4	1		*ROCKER PANEL OUTER RH	Repair	1,184.99 FL	*- FL
5	1		*ROCKER PANEL CENTER RH	Repair	990.25 FL	*- FL
6	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
7	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
8	1		*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL
9	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
10	1		*BUMPER COVER REAR	Buckled/Cracked	1,108.46 FL	*1,108.46 FL
11	1		*BUMPER LOWER REAR	Cut	768.84 FL	*768.84 FL
12	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
13	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
14	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
15	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
16	1		*BUMPER BEAM REAR	Repair	777.52 FL	*- FL
17	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
18	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
19	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
20	1		*REAR DOOR STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
21	1		*FENDER INNER TRIM CLIP RH	Not Necessary	28.00 FS	*- FS
22	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
23	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
24	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
25	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
26	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
27	1		*REAR RIGHT TYRE	Serviceable	300.00 FS	*- FS
28	1		*REAR RIGHT TYRE RIM	Serviceable	380.00 FS	*- FS
29	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
30	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
31	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
32	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
33	1		*SET BUMPER RETAINER CLIP RH RR	Not Necessary	20.00 FS	*- FS
34	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
35	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
36	1		*EXHAUST MOUNTING REAR	Not Necessary	17.82 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,319.48	2,042.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,627.67	187.73
Total Parts (\$\$)	16,691.81	1,854.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,500.00	200.00
2	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
6	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
7	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
8	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	220.00
10	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
12	O TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
13	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
14	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
Gross Labour Cost (\$\$)			12,350.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >