

INS. CASE OWNER:

CC 3 / A16 190 13299, T: ea39

LKK:
IDAC:

Surveyor:

MH

DOI:

ASSIGNMENT

6/8/19

Date / Time:

29/07/19

Registered in Merimen:

29/8/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLU2310P

Claim No.:

Name of Insured:

Liu Xue Liang

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

28/07/2019

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: (YES / NO) ; TP GIA REPORT: (YES / NO)

Driver Tel No.:

(V/L: (YES / NO))

Insured Liability: %

Final ? Yes / No

SBJ 4000Y



INSRS:

WSP:

Tel:

Liability:

RMKS:

PML



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SBJ 4000Y - NAWC 09014448/P1 ; D.O.A: 28/6/04

SLU2310P. X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

PAMEK 06/08/19

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: MH

Repair Cost:

TP S\$3,655.15

(3 days)

Reduction:

45 %

Email

Call

FINAL SETTLEMENT

Date/Time: 03-10-19

Confirm with: CARPUNE

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

W/LA S\$3,911.01

DI REAR END TP

Loss of Rental (LOR):

S\$ -

(days)

Loss of Use (LOU):

S\$ 190.00

(\$ 60 x 3 days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

*330

Total:

S\$ 4,093.01

Global Sum S\$:

FINAL PAYMENT

Date/Time: 03-10-19

Confirm with: CARPUNE

Email

Call

Payee 1:

S\$ 4,093.01

Name 1:

PERFORMANCE MOTORS LIMITED

Payee 2: (Strike if N/A)

S\$

Name 2:

Payee 3: (Strike if N/A)

S\$

Name 3:

Tues 06/08 @ 10AM

SBJ4000Y

P&R

CC3/AIG/90/3299/T1ea3

Performance Motors Limited

A Gine City Motors Company
 101, Alexandra Road
 Singapore 119944
 Toll-Free Number: 1800-2265266

101, Alexandra Road
 Gine City Performance Centre
 Singapore 119944
 Fax: 64794770

290, Pasirong Asang Road
 East Coast Centre
 Singapore 438145
 Fax: 63449773

115, Alexandra Road
 Gine City Business Centre
 Singapore 119944
 Fax: 64794601 (AfterSales)
 64794624 (Motorrad)

Asher



GST REG. NO : M2 - 0020081 - X

29 JUL 2019

ESTIMATE

Estimate No. : b1 52143
 Date Estimated : 29/07/2019
 Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Tan Kim Hoon
 6 Coldstream Avenue

Singapore 459592

- ACCOUNT - 40000

Cash Sales - Service
 Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBJ4000Y	5G87148	03/11/2017	116d	0

DESCRIPTION

To replace rear bumper & attachments including to knock out tail panel and dented area caused by the accident

To respray rear bumper and tail panel

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries

VALUE
850
with help - 1700 2,125.00
434
with help - 1202 1,781.00
150 177.00
80.00

Total Labour : 4,163.00

DESCRIPTION

REAR BUMPER CARRIER
 REAR BUMPER CENTRE GUIDE (M)
 REAR BUMPER TOWING EYE COVER PRIMED
 # REAR BUMPER PRIMED (RFC)
 REAR PDC HOLDER SET
 LH REFLECTOR
 RH REFLECTOR
 NUMBER PLATE LIGHT LED
 DECOUPLING RING PDC TORQUE CONVERTE
 RR PDC SENSOR BLACK SAPPHIRE (475)
 REVERSING CAMERA
 (DG/SL) ADHESIVE SET K6

QTY	PRICE	VALUE
1	416.45	416.45
1	67.05	67.05
1	38.95	38.95
1	1,015.00	1,015.00
1	24.60	24.60
1	36.80	36.80
1	36.80	36.80
2	25.00	50.00
2	5.05	10.10
2	236.85	473.70
1	681.10	681.10
1	53.05	53.05

Total Parts : 2,903.60

Performance Motors Limited

A Lion Dairy Motors Company
Co Reg. No. 197401899K GST Reg. No. M2 0020081-X
Toll-Free Number (1800-2255263)



111, Alexandra Road
Lion Dairy Performance Centre
Singapore 119941
Fax: 64747770

110, Kembangan Road
East Coast Centre
Singapore 438139
Fax: 64447770

111, Alexandra Road
Lion Dairy Performance Centre
Singapore 119941
Fax: 64746602 (after 5pm)
64746624 (Motorised)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 52143
Date Estimated : 29/07/2019
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBJ4000Y	5G87148	03/11/2017	116d	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date/Time 6/8/19 Excess S\$ _____

Surveyor's Name Tan Kah Sign [Signature]

Surveyor's Tel 9995555 Authorised Yes / No _____

Approved/Time WP Time _____

REPAIRER'S NAME Tan Kah YES / NO _____ PNL YES / NO _____

Surveyor's Email tan.kah@lkk.com

No. of Working Days Recommended 3-4 days

Labour 1	:	4,163.00
Parts	:	2,903.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	494.66
Grand Total	:	7,561.26

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



Supplementary

Estimate No. : **b1 52143**
Date Estimated : **29/07/2019**
Prepared By : **Han Kwan Yong**

1 of 5

- ESTIMATE REPAIR FOR -
Tan Kim Hoon
6 Coldstream Avenue

Singapore 459592

- ACCOUNT - 121
AIG ASIA PACIFIC INSURANCE
78 SHENTON WAY
#08-16 CHARTIS BUILDING
SINGAPORE 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBJ4000Y	5G87148	03/11/2017	116d	0

DESCRIPTION	ACCOUNT:		DISC. %	NETT
	ORIGINAL PRICE			

# To supply rear embloss number plate	83.00	0	83.00	bt ✓
---------------------------------------	-------	---	-------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

Total Labour :	83.00
Total Parts :	
Total Repair Costs less Excess:	83.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 52143**
Date Estimated : **29/07/2019**
Prepared By : **Han Kwan Yong**

1 of 5

- ESTIMATE REPAIR FOR -
Tan Kim Hoon
6 Coldstream Avenue

- ACCOUNT - 121
AIG ASIA PACIFIC INSURANCE
78 SHENTON WAY
#08-16 CHARTIS BUILDING
SINGAPORE 079120

Singapore 459592

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBJ4000Y	5G87148	03/11/2017	116d	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments including to remove and install body parts in order to carry out painting job.	850.00	0	850.00
To respray rear bumper.	934.00	0	934.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00
Sundries.	80.00	0	80.00
# To supply rear embloss number plate	83.00	0	83.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER CARRIER	416.45	1	0	416.45
REAR BUMPER TOWING EYE COVER PRIMED	38.95	1	0	38.95
REAR BUMPER PRIMED (RFC)	1,015.00	1	0	1,015.00
REAR PDC HOLDER SET	24.60	1	0	24.60
DECOUPLING RING PDC TORQUE CONVERTE	5.05	2	0	10.10
(DG/SL) ADHESIVE SET K6	53.05	1	0	53.05

00	2019/08/01
FAX TO FAX NO	Tan Kim Hoon 22/8/19 3

Total Labour :	2,097.00
Total Parts :	1,558.15
Total Repair Costs less Excess:	3,655.15 ✓
GST @7%:	255.86
Grand Total :	3,911.01

LOSS OF USE = \$80 X 3 DAYS
GIA SEARCH FEE - \$2.00

Tues 06/08 @ 10AM
P&R

SBJ4000Y

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197422189M GST Reg. No. M2-0020081-X
Toll-Free Number: (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438100
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

29 JUL 2019

ESTIMATE

Estimate No. : b1 52143
Date Estimated : 29/07/2019
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Tan Kim Hoon
6 Coldstream Avenue

Singapore 459592

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBJ4000Y	5G87148	03/11/2017	116d	0

DESCRIPTION

To replace rear bumper & attachments including to knock out tail panel and dented area caused by the accident

To respray rear bumper and tail panel

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries.

DESCRIPTION	VALUE
Bumper - 850	
with help out - 1700	2,125.00
bumper - 934	
with help out - 1602	1,781.00
150	177.00
	80.00

Total Labour 1: 4,163.00

DESCRIPTION

REAR BUMPER CARRIER
REAR BUMPER CENTRE GUIDE (M)
REAR BUMPER TOWING EYE COVER PRIMED
REAR BUMPER PRIMED (RFC)
REAR PDC HOLDER SET
LH REFLECTOR
RH REFLECTOR
NUMBER PLATE LIGHT LED
DECOUPLING RING PDC TORQUE CONVERTE
RR PDC SENSOR BLACK SAPPHIRE (475)
REVERSING CAMERA
(DG/SL) ADHESIVE SET K6

QTY	PRIC	VALUE
1	416.45	416.45
1	67.05	67.05
1	38.95	38.95
1	1,015.00	1,015.00
1	24.60	24.60
1	36.80	36.80
1	36.80	36.80
2	25.00	50.00
2	5.05	10.10
2	236.85	473.70
1	681.10	681.10
1	53.05	53.05

Total Parts : 2,903.60

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2233269)

309, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Rempang Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796801 (AfterSales)
64796824 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 52143
Date Estimated : 29/07/2019
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBJ4000Y	5G87148	03/11/2017	116d	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 6/8/19 Excess S\$ _____

Surveyor's Name Tanpin Sign [Signature]

Surveyor's Tel 67995749 Authorised Yes / No _____

Authorised Date WP Time _____

REQUIRE PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's Email tanpin@phoenix.com

No. of Working Days Recommend 3-4 days

Labour 1	:	4,163.00
Parts	:	2,903.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	494.66
Grand Total	:	<u>7,561.26</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Thursday, 1 August 2019 2:23 PM
To: PBSP
Cc: Admin A; assignments
Subject: RE: REQUEST FOR DIRECT SETTLEMENT - SBJ4000Y & SLU2310P ON 28/07/2019 ***
LKK REF: CC3/AIG19013299/ea3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Thursday, 1 August 2019 2:21 PM
To: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: Re: REQUEST FOR DIRECT SETTLEMENT - SBJ4000Y & SLU2310P ON 28/07/2019 *** LKK REF: CC3/AIG19013299/ea3

Dear Sirs,

Kindly reply on liability.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Monday, 29 July 2019 5:55:34 PM
To: PBSP <pml-pbsp@simedarby.com.sg>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Cc: CS A Team <cs-a@lkkauto.com>; 雷琨 © <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: REQUEST FOR DIRECT SETTLEMENT - SBJ4000Y & SLU2310P ON 28/07/2019 *** LKK REF: CC3/AIG19013299/ea3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Caroline,

We refer to the above matter.

Please be informed that we are currently **pending for our principal to release OI GIA report.**

Kindly note that for liability, claim negotiation and settlement, please contact Asher at 6841 6051.

Our respective case handler will look into the matter and revert to you in due course.

Meanwhile, please arrange appointment for survey.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Monday, 29 July, 2019 4:10 PM
To: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: REQUEST FOR DIRECT SETTLEMENT - SBJ4000Y & SLU2310P ON 28/07/2019

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the Intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To : AIG Asia Pacific Insurance Pte. Ltd.
Attn : Loh, Chee-Heng

Your Ref : 3776494833SG
Our Ref : CC3/AIG19013299/T1EA3
Date : 17 Sep 2019

"WITHOUT PREJUDICE"**ACCIDENT INVOLVING SLU2310P & SBJ4000Y ON 28/07/2019**

Refer to the above accident.

The accident occurred when insured rear ended third party vehicle. We have clarified with the OI on the nature of the accident and he/she is aware that his/her NCD would be affected.

On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have **successfully / not successfully** carried out **TP Express Settlement** between your insured (vehicle no. SLU2310P) and third party claimant (vehicle no. SBJ4000Y).

Summary of offer made to workshop Performance Motors Limited is as follows :

	Claimed	Revised
Cost of Repairs w/GST	\$ 7,149.60	\$ 3,911.01
Loss of Use	\$ 240.00	\$ 180.00
LTA	\$ 2.00	\$ 2.00

Amount of claim at **Liability 100%** \$ 4,093.01

Surveyor recommended 3days repair.

Enclose herewith the relevant supporting documents for your perusal.

For your approval please.

Regards,
Asher Sng Rong Yi
LKK Auto Consultants Pte Ltd

Print Received Message

This mail is associated with :

***SBJ4000Y (3776494833SG)**
[SLU2310P]

TP

TAN KIM HOON

Jul 28 2019 3:00PM

[LIU XUELIANG]

Performance Motors Limited

From **AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS)**, sent on 18/09/2019 08:53 AM.
To **LKK_HQ**
Subject **Alert - Adj Mandate Approved (S\$4093.01) - SBJ4000Y - Claim Handler: Loh, Chee-Heng**

Approved:4093.01.

Asher Sng (LKKAUTO)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Thursday, 3 October 2019 2:08 PM
To: Asher Sng (LKKAUTO)
Subject: Re: REQUEST FOR DIRECT SETTLEMENT - SBJ4000Y & SLU2310P ON 28/07/2019 ***
LKK REF: CC3/AIG19013299/ea3

Dear Asher

We have instructions to accept your offer of settlement.

Please let us have your payment.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Sent: Friday, 20 September 2019 10:52 AM
To: PBSP <pml-pbsp@simedarby.com.sg>
Cc: Sharon Heng L K <sharon.heng.leekun@simedarby.com.sg>
Subject: RE: REQUEST FOR DIRECT SETTLEMENT - SBJ4000Y & SLU2310P ON 28/07/2019 *** LKK REF: CC3/AIG19013299/ea3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair(w/GST)	\$ 3,911.01
2. Loss of Use (3 days x \$60)	\$ 180.00
3. LTA/GIA search fee	\$ 2.00
TOTAL	<u>\$ 4,093.01</u>

Kindly let us have your acceptance.

Thank You.

Best Regards,

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____


**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SB34000Y	Model:	BMW 116D - 1496cc
Date of Accident:	28/7/2019		

Global Sum Settlement	: [] Yes	[X] No	
Repair Estimate	: \$	7561.26	
Final Repair Cost	: \$	3911.01	
Loss of Use	: \$	240.00	3 days at \$ 80 per day
Rental (if any)	: \$		days
LTA / GIA Search Fee	: \$	2.00	
Others:	: \$		
	: \$		
Final Settlement Sum	: \$	4153.01	

Is Third Party Workshop GIA Registered? [] YES [] NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks	

Payment Instruction: Payee's Breakdown		
1)	Performance Motors Ltd	: \$ 3911.01
2)	Performance Motors Ltd	: \$ 2.00
3)	Tan Kim Hoon	: \$ 240.00



Signed by appointed surveyor

4/9/19
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report/ Bill (if any))



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC3/AIG19013299/ea3

06 AUG 2019

LIU XUELIANG
679C PUNGGOL DRIVE
#12-850
SINGAPORE 823679

Dear Sir/Madam,

ACCIDENT INVOLVING SLU 2310P AND SBJ 4000Y ON 28/07/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: Ashersng@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, Ms Tan Kim Hoon (the third party claimant) of 6 Coldstream Ave, Spore 459592 (address), owner of SBT40004 (vehicle no.) hereby authorize PERFORMANCE MOTORS LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SBT40004 that was damaged pursuant to the accident which occurred on 28/07/19 (date) along PIE (along Thomson Road) (location) involving vehicle no/s SLU 2310P ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.


I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 06 (day) of 08 (month) 2019 (year)



Signed by "the third party claimant"
(with chop if applicable)

HAN KWAN YONG
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941


Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$3911.01 (Repair Cost), S\$180.00 (Loss of ~~rental~~/use), S\$ 2.00 (Disbursement), for vehicle no. SBJ4000Y that was damaged pursuant to the accident which occurred on 28/7/19 (date) along PIE (Along Thomson Road) (location) involving vehicle no/s SUW2310P. This is pursuant to the inspection conducted on 6/8/19 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Tan Kim Hoon ("the third party claimant") of vehicle no. SBJ4000Y make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SBJ4000Y (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 08 (day) of 10 (month) 20 19 (year)



MTM

Signed by appointed surveyor



Signed by "the workshop" (with chop)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190868 (AfterSales)
Fax. 63449773115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190828 (AfterSales)
63190833/330 (Motorrad)
Fax. 64796401 (AfterSales)
64796424 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1385990

Date IN : 06/08/2019

Cust. Svc. Advisor: Han Kwan Yong

Page No. : 1 of 2

Invoice Number : 2145069 / WSB

Invoice Date : 04/09/2019

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Ms Tan Kim Hoon
6 Coldstream Avenue

Singapore 459592

- INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120REGN. NO.
SBJ4000YCHASSIS NO.
5G87148REGN. DATE
03/11/2017MODEL
116DMILEAGE
18488

- - - - LABOUR 1 - - - -

To replace rear bumper and attachments including to
remove and install body parts in order to carry out painting
job.

To respray rear bumper.

To check electrical wiring systems and lightings at the
rear section for proper function.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 28.7.2019. 3RD PARTY CAR : SLU2310P.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO
CONSULTANTS PTE LTD ON 6.8.2019 AT 5.00 PM. AUTHORISED
REPAIR BY MS ASHER SNG FROM LKK ON 1.8.2019 VIA E-MAIL.
PROPOSE LOSS OF USE = \$80X3. THE AMOUNT IS SUBJECTED
TO INSURANCE COMPANY CONFIRMATION.

GIA SEARCH FEE = \$2.00.

NETT

850.00

934.00

150.00

80.00

0.00

0.00

0.00

Total Labour 1: 2,014.00

- - - - PARTS - - - -

REAR BUMPER CARRIER

DECOUPLING RING PDC TORQUE CONVERTE

(DG/SL) ADHESIVE SET K6

REAR BUMPER TOWING EYE COVER PRIMED

REAR BUMPER PRIMED (RFC)

REAR PDC HOLDER SET

Qty	Retail Price	NETT
1	416.45	416.45
2	5.05	10.10
1	53.05	53.05
1	38.95	38.95
1	1,015.00	1,015.00
1	24.60	24.60

Total Parts : 1,558.15

- - - - LABOUR 2 - - - -

To supply rear silver emboss lettering black base number
plate with bracket.

NETT

83.00

Total Labour 2: 83.00



101, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190886 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/535 (Motorrad)
Fax. 64794601 (AfterSales)
64794624 (Motorrad)

SERVICE TAX INVOICERepair Order No. : **B1 1385990**Date IN : **06/08/2019**Cust. Svc. Advisor: **Han Kwan Yong**Page No. : **2 of 2**Invoice Number : **2145069 / WSB**Invoice Date : **04/09/2019**Payment Terms : **30 Days From Invoice**Invoice By : **Sharon Heng**

Labour Charges : **2,017.00**
Parts Charges : **1,558.15**
Lubricant/Misc : **80.00**

Total Labour & Parts Charges : **S\$ 3,655.15**
Less Insurance Excess : **S\$ 0.00**
Invoice Total Amount Exclude GST : **S\$ 3,655.15**
GST @ 7% : **S\$ 255.86**
Invoice Total Amount Include GST : **S\$ 3,911.01**

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 3,911.01**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



5BJ40009



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-122202

Date of Request: 29/07/2019

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date: 29/07/2019
Enquiry By: Han Kwan Yong
TP Vehicle No: SLU2310P
Accident Date: 28/07/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLU2310P	AIG Asia Pacific Insurance Pte. Ltd.	27/11/2017-26/11/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the report or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-122202

Date of Request: 29/07/2019

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 29/07/2019
Enquiry By Han Kwan Yong
TP Vehicle No. SLU2310P
Accident Date 28/07/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1
GST Amount	0
Total Amount Due (GST Inclusive)	2

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jul 2019 Edit Reg		06 Aug 2019 00:00 Edit Adj Rpt	S\$3,655.15 Edit Estimates	S\$3,655.15 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LIU XUELIANG , ID: S8379816E								
Main Claimant:	TAN KIM HOON , ID: S1283844A								
Vehicle Reg. No.:	SBJ4000Y	Date of Loss:	28/07/2019 15:00 - :59 [20 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3776494833SG	Policy/Cover Note No.:	1700087615 (Comprehensive) Coverage: 27/11/2017 - 26/11/2019						
Vehicle Reg. No. (Insured):	SLU2310P	Policy No. (Claimant):	19-MT101488-R01						
	Excess:								
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 07/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (18/09/2019): Alert - Adj Mandate Approved (S\$4093.01) - SBJ4000Y - Claim Handler: Loh, Chee-H...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SBJ4000Y (3776494833SG)
[SLU2310P]
TP
TAN KIM HOON
Jul 28 2019 3:00PM
[LIU XUELIANG]
Performance Motors Limited


Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View <input type="button" value="View in Browser"/>
------------------	---------------	--------------------	--------------	--------------	---

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	17/09/19 14:11	Adjuster Immediate Advice		Load HTM	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print	
1	30/07/19 14:11	Accident Statement From: OD - Reg. No: SLU2310P, Claimant: LIU XUELIANG		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	17/09/19 14:07	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
2	17/09/19 14:07	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
3	17/09/19 14:07	General View		Load JPG	<input checked="" type="checkbox"/>
4	17/09/19 14:07	General View		Load JPG	<input checked="" type="checkbox"/>
5	17/09/19 14:07	General View		Load JPG	<input checked="" type="checkbox"/>
6	17/09/19 14:07	General View		Load JPG	<input checked="" type="checkbox"/>
7	17/09/19 14:07	General View		Load JPG	<input checked="" type="checkbox"/>
8	17/09/19 14:07	General View		Load JPG	<input checked="" type="checkbox"/>
9	17/09/19 14:07	General View		Load JPG	<input checked="" type="checkbox"/>
10	17/09/19 14:07	General View		Load JPG	<input checked="" type="checkbox"/>
11	17/09/19 14:07	General View		Load JPG	<input checked="" type="checkbox"/>
12	17/09/19 14:07	General View		Load JPG	<input checked="" type="checkbox"/>
13	17/09/19 14:07	General View		Load JPG	<input checked="" type="checkbox"/>
14	17/09/19 14:07	General View		Load JPG	<input checked="" type="checkbox"/>
15	17/09/19 14:07	General View		Load JPG	<input checked="" type="checkbox"/>
16	17/09/19 14:07	General View		Load JPG	<input checked="" type="checkbox"/>
17	17/09/19 14:07	General View		Load JPG	<input checked="" type="checkbox"/>
18	17/09/19 14:07	General View		Load JPG	<input checked="" type="checkbox"/>
19	17/09/19 14:07	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
20	17/09/19 14:07	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
21	17/09/19 14:07	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
22	17/09/19 14:07	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
23	17/09/19 14:07	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	29/07/19 17:53	TP ESTIMATE + DOCS		Load PDF	
2	29/07/19 17:53	TP GIA REPORT		Load PDF	
3	06/08/19 14:01	LETTER TO OI		Load PDF	
4	14/08/19 19:47	TP ESTIMATE - MARKED		Load PDF	
5	17/09/19 14:06	TP ESTIMATE - MARKED (FINAL)		Load PDF	
6	17/09/19 14:14	LOD		Load PDF	
7	10/10/19 08:23	WORKSHOP INVOICE		Load PDF	
8	10/10/19 08:23	AUTHORISATION TO ACT FORM		Load PDF	
9	10/10/19 08:23	Release Voucher		Load PDF	
10	10/10/19 08:23	GIA SEARCH		Load PDF	
11	10/10/19 08:23	LOD		Load PDF	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLU2310P (Insd veh)	Model:	BMW 116D 1.5 D 5DR LED
	SBJ4000Y (TP veh)		EU6 (A)
Date of Accident:	28/07/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	7,650.07
Final Repair Cost	:	\$	3,911.01
Loss of Use	:	\$	180.00
			3.00 days at \$60.00 per day
Rental (if any)	:	\$	0.00
			days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	4,093.01

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____(%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____

BOLA Liability: _____100____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 4,093.01
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

10 Oct
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19013299/T1EA3Q2

Date: 10/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700087615
 Claimant: SBJ4000Y Insured Vehicle No: SLU2310P
 Vehicle No: SBJ4000Y
 Date of Loss: 28/07/2019 Nature of Claim: TP Claim No: 3776494833SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SBJ4000Y
 Make & Model: BMW 116D, 1.5 D 5DR LED EU6 (A) Engine No: 31145088B37D15A
 Reg. Date: 03/11/2017 (Man. Year: 2017) Chassis No: WBA1V720305G87148
 Colour: Black Odometer: 18488 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,066.60	1,721.15	1,345.45	43.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,083.00	1,934.00	2,149.00	52.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,149.60	3,655.15	3,494.45	48.88
+ GST 7.00/7.00% (S\$)	500.47	255.86	244.61	48.88
Nett Amount (S\$)	7,650.07	3,911.01	3,739.06	48.88
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,093.01		

INSPECTION

Date of Assignment: 06/08/2019

Date Inspected: 06/08/2019 Inspected At:

Performance Motors Limited
 (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*REAR BUMPER CARRIER	Bent	416.45 FS	*416.45 FS
3	1		*REAR BUMPER CENTRE GUIDE (M)	Not Necessary	67.05 FS	*- FS
4	1		*REAR BUMPER TOWING EYE COVER PRIMED	Deformed	38.95 FS	*38.95 FS
5	1		*REAR BUMPER PRIMED (RFC)	Deformed	1,015.00 FS	*1,015.00 FS
6	1		*SET REAR PDC HOLDER	Necessary	24.60 FS	*24.60 FS
7	1		*LH REFLECTOR	Not Necessary	36.80 FS	*- FS
8	1		*RH REFLECTOR	Not Necessary	36.80 FS	*- FS
9	2		*NUMBER PLATE LIGHT LED	Not Necessary	50.00 FS	*- FS
10	2		*DECOUPLING RING PDC TORQUE CONVERTE	Necessary	10.10 FS	*10.10 FS
11	2		*RR PDC SENSOR BLACK SAPPHIRE (475)	Not Necessary	473.70 FS	*- FS
12	1		*REVERSING CAMERA	Not Necessary	681.10 FS	*- FS
13	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
14	1		*REAR EMBLOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS
Total Parts (S\$)					3,066.60	1,721.15

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER & ATTACHMENTS INCLUDING TO KNOCK OUT TAIL PANEL AND DENTED AREA CAUSED BY THE ACCIDENT	New	2,125.00	850.00
2	TO RESPRAY REAR BUMPER AND TAIL PANEL	New	1,781.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			4,083.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >