

Thes 06/08 @ 10AM
P&K

SBJ4000Y

Performance Motors Limited

A Time Saver, Motor Company
115, Alexandra Road
Singapore 115944
Toll Free Number: 1800 2155288

115, Alexandra Road
Time Saver Performance Centre
Singapore 115944
Fax: +65 434 0000

115, Raffles Avenue Road
East Coast Centre
Singapore 434115
Fax: +65 434 0000

115, Alexandra Road
Time Saver Business Centre
Singapore 115944
Fax: +65 966 0001
AfterSales
(Motorrad)



GST REG. NO : M2 - 0020081 - X

29 JUL 2019

ESTIMATE

Estimate No. : b1 52143	Page No. : 1 of 5
Date Estimated : 29/07/2019	
Prepared By : Han Kwan Yong	

- ESTIMATE REPAIR FOR - Tan Kim Hoon 6 Coldstream Avenue Singapore 459592	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBJ4000Y	5G87148	03/11/2017	116d	0

DESCRIPTION	PRICE
To replace rear bumper & attachments including to knock out tail panel and dented area caused by the accident	2,125.00
To respray rear bumper and tail panel	1,781.00
To check electrical wiring systems and lightings at the rear section for proper function.	177.00
Sundries	80.00
Total Labour :	4,163.00

DESCRIPTION	QTY	PRICE	VALUE
REAR BUMPER CARRIER	1	416.45	416.45
REAR BUMPER CENTRE GUIDE (M)	1	67.05	67.05
REAR BUMPER TOWING EYE COVER PRIMED	1	38.95	38.95
# REAR BUMPER PRIMED (RFC)	1	1,015.00	1,015.00
REAR PDC HOLDER SET	1	24.60	24.60
LH REFLECTOR	1	36.80	36.80
RH REFLECTOR	1	36.80	36.80
NUMBER PLATE LIGHT LED	2	25.00	50.00
DECOUPLING RING PDC TORQUE CONVERTE	2	5.05	10.10
RR PDC SENSOR BLACK SAPPHIRE (475)	2	236.85	473.70
REVERSING CAMERA	1	681.10	681.10
(DG/SL) ADHESIVE SET K6	1	53.05	53.05
Total Parts :			2,903.60

Performance Motors Limited

Auto Parts & Accessories Company
 CR. Reg. No. 19740159K RT Reg. No. M2 0020081 X
 T. 11 River Road, Singapore 159944

111, Alexandra Road
 Auto Parts & Accessories Centre
 Singapore 159944
 Fax: 64796101

111, Alexandra Road
 East Coast Centre
 Singapore 488167
 Fax: 64499773

111, Alexandra Road
 Singapore 159944
 Fax: 64796101
 After Sales
 Motor Ltd



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 52143
 Date Estimated : 29/07/2019
 Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBJ4000Y	5G87148	03/11/2017	116d	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims CD / 3rd Party / Uninsured losses / Direct Settlement

Ref No. 618114 Claim No.

Excess \$S

Sign [Signature]

Authorised Yes / No

Time

Yes / No Yes FML Yes / No

[Signature]

Labour 1	:	4,163.00
Parts	:	2,903.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	494.66
Grand Total	:	7,561.26

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Estimate No. : **b1 52143**
Date Estimated : **29/07/2019**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -
Tan Kim Hoon
6 Coldstream Avenue

- ACCOUNT - 121
AIG ASIA PACIFIC INSURANCE
78 SHENTON WAY
#08-16 CHARTIS BUILDING
SINGAPORE 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBJ4000Y	5G87148	03/11/2017	116d	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments including to remove and install body parts in order to carry out painting job.	850.00	0	850.00
To respray rear bumper.	934.00	0	934.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00
Sundries.	80.00	0	80.00
To supply rear embloss number plate	83.00	0	83.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER CARRIER	416.45	1	0	416.45
REAR BUMPER TOWING EYE COVER PRIMED	38.95	1	0	38.95
REAR BUMPER PRIMED (RFC)	1,015.00	1	0	1,015.00
REAR PDC HOLDER SET	24.60	1	0	24.60
DECOUPLING RING PDC TORQUE CONVERTE	5.05	2	0	10.10
(DG/SL) ADHESIVE SET K6	53.05	1	0	53.05

[illegible]

Total Labour :	2,097.00
Total Parts :	1,558.15
Total Repair Costs less Excess:	3,655.15 ✓
GST @7%:	255.86
Grand Total :	3,911.01

LOSS OF USE = \$80 X 3 DAYS
GIA SEARCH FEE - \$2.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 52143**
Date Estimated : **29/07/2019**
Prepared By : **Han Kwan Yong**

1 of 5

- ESTIMATE REPAIR FOR -
Tan Kim Hoon
6 Coldstream Avenue

- ACCOUNT - 121
AIG ASIA PACIFIC INSURANCE
78 SHENTON WAY
#08-16 CHARTIS BUILDING
SINGAPORE 079120

Singapore 459592

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBJ4000Y	5G87148	03/11/2017	116d	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
# To supply rear embloss number plate	83.00	0	83.00 <i>bt ✓</i>

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

Total Labour :	83.00
Total Parts :	
Total Repair Costs less Excess:	83.00