

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0377/2019
DATE : 29-JUL-2019

LONPAC INSURANCE BHD
300 BEACH RD
#17-04/07 THE CONCOURSE
S(199555)
TEL : 62507388
FAX : 62962706
MOTOR CLAIMS DEPT

OWNER'S NAME : MR SNG CHEE YONG
ADDRESS : 28 GARDENIA ROAD
S(578830)
TELEPHONE NO : 81221320/93882861

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP - SKQ3002E
VEHICLE NO : SMK156Y
MODEL CODE : TDWARDZE12EDAY520Z
MODEL/YEAR : NISSAN NOTE 1.2 (V) MY 2018
ENGINE NO : HR12005488K
CHASSIS NO : JN1TAAE12Z0982895
MILEAGE : 1 KM
DATE IN : 29/07/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 11/07/2019

15/05/2020

DIS

Zuhri

Penrose

#100 x 07

2# 700 + 057

2# 735

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMK156Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS		
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	120.00
3	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	55.00
4	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	100.00
5	ZZ/001	TRANSFER MACHANISM PART FOR RR BACKDOOR	60.00	60.00
6	ZZ/002	CHECK LIGHTING	48.00	48.00
7	ZZ/003	R/INSTALL RR WINDSCREEN	150.00	150.00
8	ZZ/004	REPAIR RR END PANEL,RR FENDER RH, RENEW RR BACKDOOR & RR BUMPER COVER	1560.00	975.00
9	ZZ/005	S/PAINT RR BUMPER ,BACKDOOR ,RR FENDER RH & RR END PANEL	1000.00	750.00
TOTAL LABOUR CHARGES			3093.00	2258.00

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMK156Y

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1	REAR LICENCE PLATE	RLP			60.00 X
2	STAY-RH	H5212-1HMMA	86.60		X
3	BRKT BUMPER LH	85221-3VA0C	45.40		X
4	BRKT BUMPER RH	85220-3VA0C	45.40		X
5	LAMP COMB RR,RH	26550-5WK0A	406.70		X
6	EMBLEM-BACK-SUPPLEMENTARY	90890-3VA0A	64.90	rec ✓	OK
7	ORNAMENT-BACK-SUPPLEMENTARY	90892-3VA0A	79.90	rec ✓	OK
8	A FIN BACK DOOR	90810-3VA6A	243.90		X
9	DOOR BACK	K010M-3VAMA	976.40		OK
10	CLIP(1.2X10)	01553-10501	12.00		OK
11	CROMMET(2.5X2)	63846-5V000	5.00		OK
12	SUNDRIES	NPN			20.00 OK
13	FACE-RR BUMPER	85022-5WJ0H	414.00		OK
SUB TOTAL			1552.20	0.00	20.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			310.44	0.00	0.00
GRAND TOTAL			1241.76	0.00	20.00
OVERALL TOTAL			1261.76		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SINGAPORE 589623

www.wpp.com

GRAND TOTAL	3766.14

15-May-2020

INS/IC/ZHR/0377/2019

LONPAC INSURANCE BHD
101 THOMSON RD #18-01
UNITED SQUARE
Singapore 307591

Attn : Motor Claim Manager
Claim Dept

Dear Sir

SUPPLEMENTARY CLAIM

REGN. NO. : SMK156Y
POLCY NO. : -

Further to our claim INS/IC/LAW/0999/2007 we are submitting a supplementary claim for the below mentioned items which were found damaged during the course of repairs.

Replacement of Damaged Items

1	EMBLEM NISSAN	\$64.90 NETT
2	NOTE EMBLEM	\$79.90 NETT

TOTAL \$144.80

We trust the above supplementary claim will meet with your kind approval and we will forward to you the final repair bill together with the satisfaction note on completion repairs.

Yours faithfully

TAN CHONG MOTOR SALES PTE LTD

Lawrence Teo
Insurance Claim Dept

Cc: Surveyor