

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0377/2019
DATE : 29-JUL-2019

LONPAC INSURANCE BHD
300 BEACH RD
#17-04/07 THE CONCOURSE
S(199555)
TEL : 62507388
FAX : 62962706
MOTOR CLAIMS DEPT

OWNER'S NAME : MR SNG CHEE YONG
ADDRESS : 28 GARDENIA ROAD
S(578830)
TELEPHONE NO : 81221320

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP - SKQ3002E
VEHICLE NO : SMK156Y
MODEL CODE : TDWARDZE12EDAY520Z
MODEL/YEAR : NISSAN NOTE 1.2 (V) MY 2018
ENGINE NO : HR12005488K
CHASSIS NO : JN1TAAE12Z0982895
MILEAGE : 1 KM
DATE IN : 29/07/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 11/07/2019

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

~~CAR AT WORKSHOP~~ / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : zuhri@tanchong.com

OFFICE : 67038916 FAX : 64697472

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tauhir 97495749.
'wp'

20/11/19 @ 3:45.

Resurvey before paint.

svr@lkhauto.com

25 days

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMK156Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS		
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	✓
3	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	✓
4	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	✓
5	ZZ/001	TRANSFER MACHANISM PART FOR RR BACKDOOR	60.00	✓
6	ZZ/002	CHECK LIGHTING	48.00	✓
7	ZZ/003	R/INSTALL RR WINDSCREEN	150.00	✓
8	ZZ/004	REPAIR RR END PANEL, RR FENDER RH, RENEW RR BACKDOOR & RR BUMPER COVER	1560.00	340. 975.
9	ZZ/005	S/PAINT RR BUMPER ,BACKDOOR ,RR FENDER RH & RR END PANEL ↳ photo.	1000.00	250. 750.
TOTAL LABOUR CHARGES			3093.00	

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMK156Y

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	REAR LICENCE PLATE	RLP			60.00 X nn
2	SUNDRIES	NPN			50.00 20.
3	LAMP COMB RR,RH	26550-5WK0A	406.70	X nn	
4	A FIN BACK DOOR	90810-3VA6A	243.90	X nn	
5	DOOR BACK	K010M-3VAMA	976.40	bt	
6	BRKT BUMPER LH	85221-3VA0C	45.40	X nn	
7	BRKT BUMPER RH	85220-3VA0C	45.40	X nn	
8	STAY-RH	H5212-1HMMA	86.60	X nn	
9	CLIP(1.2X10)	01553-10501	12.00	nei	
10	CROMMET(2.5X2)	63846-5V000	5.00	ue	
11	FACE-RR BUMPER	85022-5WJ0H	414.00	de	
SUB TOTAL			2235.40	0.00	110.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			447.08	0.00	0.00
GRAND TOTAL			1788.32	0.00	110.00
OVERALL TOTAL			1898.32		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMK156Y

TOTAL LABOUR CHARGES	3093.00
TOTAL SPARE PARTS CHARGES	1898.32

GRAND TOTAL	4991.32 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.