

INS. CASE OWNER:

CC 6, AG 190 13302, Hka3

LKK:  
IDAC:

Surveyor:

WMP

DOI:

ASSIGNMENT

24/12/2019

Date / Time:

24/12/19

Registered in Merimen:

24/12/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMC 5288J

Claim No.:

Name of Insured:

Seet Thian Beng Benjamin

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

18/07/2019

Place of Accident:

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLE 2590 G



INSRS:

WSP: Modern

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

SLE 2590 G. X ; SMC 5288J - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

30/12/19 Khanchan

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GLA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: US \$51850 ( 7 days) Reduction: 47 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time: 23/12/19

Confirm with: Chin

Email ☒ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost: (w/ GST) \$5 6,259.50

(OLD REAR AND TP)

Loss of Rental (LOR): \$5 400 ( 4 days) x \$100

Loss of Use (LOU): \$5 - ( 3 - x - days)

Loss of Income (LOI): \$5 - ( 3 - x - days)

LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search \$5 2.00

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/ Independent)

Legal Cost \$5 -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$320

Total: \$5 6,661.50 Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1: \$5 6,661.50

Name 1: MODERN AUTOMOTIVE PTE LTD

Payee 2: (Strike if N.A.)

Name 2:

Payee 3: (Strike if N.A.)

Name 3:



MODERN AUTOMOTIVE PTE LTD  
BLK 3023A UBI ROAD 1 # 01-61  
SINGAPORE 408717

Tel : 67484422 / 37454422 Fax : 6747- 6726 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building  
78 Shenton Way #07-15  
Singapore 079120  
Tel 6419 - 3000  
Fax 6835 - 7416

*Khoo Ching*

Quotation  
DATE : 29.07.2019  
VEH NO : SLE2590G  
MODEL : Honda Vezel  
D O A : 28.07.2019  
YR REF : SMC5288J

Attn: Motor Claim Dept (Please arrange vehicle survey & check liability)

RE: ESTIMATE FOR ACCIDENT REPAIR SLE2590G (HONDA VEZEL)

Item	Description	Qty	Am't
<b>NQ</b>	<b>LIST ITEMS</b>		
1	Rear Bumper <i>yellowed</i>	1	380.00 ✓
2	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>new</i>	2	70.40 ✓
4	Rear Bumper Reflector - LH & RH <i>new</i>	2	290.00 ✓
5	Rear Bumper Undercover <i>yellowed</i>	1	245.60 ✓
6	Rear Bumper Undercover Clips <i>new</i>	1 set	30.00 ✓
7	Rear Side Bumper - LH & RH <i>yellowed</i>	2	350.00 ✓
8	Rear End Panel <i>dent</i>	1	505.50 ✓
9	Rear End Panel Top Garnish <i>yellowed</i>	1	125.30 ✓
10	Rear End Panel Buzzer <i>damaged</i>	1	85.50 ✓
11	Rear End Panel Lock Sensor <i>new</i>	1	69.40 ✓
12	Tail Lamp - LH & RH <i>1 set</i>	2	<del>963.20</del> 481.60 ✓
13	Tailgate <i>distorted</i>	1	1,100.00 ✓
14	Tailgate Lock <i>damaged</i>	1	186.30 ✓
15	Tailgate Weatherstripe <i>at</i>	1	165.00 ✓
16	Tailgate Lamp - LH & RH <i>at</i>	2	560.20 ✓
17	Tailgate Inner Trim Board <i>yellowed</i>	1	321.70 ✓
18	Tailgate Inner Trim Board Clips <i>new</i>	1 set	30.00 ✓
19	Tailgate Glass Moulding <i>new</i>	1	158.60 ✓
20	Vezel Emblem <i>new</i>	1	56.20 ✓
21	Spare Tyre Panel Top Board <i>yellowed</i>	1	306.60 ✓
22	Tools Tray Sponge <i>new</i>	1	236.70 ✓
23	Rear Fender Inner Trim - LH & RH	2	650.60 ✓
24	Rear Fender Inner Trim Clips <i>new</i>	1 set	60.00 ✓
25	Rear Exhaust Pipe	1	688.10 ✓
26	Rear Exhaust Mounting	1	35.00 ✓

8,335.50

6064.90

4851.92

RE: ESTIMATE FOR ACCIDENT REPAIR 8LE2590G (HONDA VEZEL)

Less 20%

(1,867.72)

\$ 6,670.88

S/NETT ITEMS

1	Rear End Panel Sealant <i>new</i>	1	60.00 ✓
2	Tailgate Glass Sealant	1	60.00 ✓
3	Rear Camera <i>not new</i>	1	480.00 X
4	Reverse Sensor <i>damaged</i>	1	280.00 <i>100</i>
<i>320</i>			<u>880.00</u>

Total Parts

\$ 7,550.88

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,300.00 <i>900</i>
2	To putty & spray up paint work	\$	1,200.00 <i>800</i>
3	To check wiring	\$	50.00 <i>30</i>
4	To underseal	\$	150.00 <i>60</i>
5	To remove reverse sensor	\$	100.00 <i>50</i>
6	To remove rear camera	\$	100.00 <i>50</i>
7	To remove upholstery	\$	150.00 <i>80</i>
8	To remove tailgate glass	\$	180.00 <i>120</i>
9	To transfer tailgate fittings	\$	150.00 <i>80</i>
10	To remove exhaust pipe	\$	150.00 X
<i>2170</i>			<u>3,430.00</u>

Total Labour

\$ 3,430.00

Grand Total

\$ 10,980.88

NOTE . .

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

I hereby authorize the repair of the above vehicle by the undersigned company.  
 • To survey before repair.  
 • To display damage before repair.  
 • Parts prices are to be agreed before repair.  
 • Third party liability to be agreed before repair.  
 • No illegal modifications to be made.  
 • Supplemental work to be agreed before repair.  
 • Is subject to the terms and conditions of the company.

Acknowledged \_\_\_\_\_  
 Signed \_\_\_\_\_  
 Date \_\_\_\_\_

total 7341.92  
 f/s = 5850  
 0.7 Days

## Khanchna (LKK Auto)

---

**From:** Khanchna (LKK Auto)  
**Sent:** Monday, 30 September 2019 5:34 PM  
**To:** CAROLYNTEOSK@HOTMAIL.COM  
**Cc:** Admin A  
**Subject:** ACCIDENT INVOLVING SMC5288J & SLE2590G ON 28/07/2019 ALONG LOYANG AVENUE 8 & TAMPINES AVE 7

Tracking:	Recipient	Delivery
	CAROLYNTEOSK@HOTMAIL.COM	
	Admin A	
	olivialau@lkkauto.com	Delivered: 30/9/2019 5:34 PM
	Meikwan@lkkauto.com	Delivered: 30/9/2019 5:34 PM
	shupeil@lkkauto.com	Delivered: 30/9/2019 5:34 PM

Our Ref: CC6/AIG19013302/Aka3

**SEET THIAN BENG BENJAMIN**  
[POLICY HOLDER]

Dear Sir/Madam,

**ACCIDENT INVOLVING SMC5288J [AIG] & SLE2590G ON 28/07/2019 ALONG LOYANG AVENUE 8 & TAMPINES AVE 7**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, **AIG Asia Pacific Insurance Pte Ltd** to deal with the third party claim against your policy.

We have received a claim from SLE2590G against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,  
**Khanchna** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
DID: **6841 2360** | email: [Khanchna@lkkauto.com](mailto:Khanchna@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To : AIG Asia Pacific Insurance Pte. Ltd.  
Attn : Syed-Yusoff, Saliha

Your Ref : 6725092885SG  
Our Ref : CC6/AIG19013302/AKA3  
Date : 05 Dec 2019

**"WITHOUT PREJUDICE"****ACCIDENT INVOLVING SMC5288J & SLE2590G ON 28/07/2019**

Refer to the above accident.

The accident occurred when it is a head to rear end collision (BOLA 27- liability down against Insured). We have clarified with the OI on the nature of the accident and he/she is aware that his/her NCD would be affected.

On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have **successfully / not successfully** carried out **TP Express Settlement** between your insured (vehicle no. SMC5288J) and third party claimant (vehicle no. SLE2590G).

Summary of offer made to workshop Modern Automotive Pte Ltd is as follows :

	Claimed	Revised
Cost of Repairs (w/GST)	\$ 11,749.54	6,259.50
Loss of Rental (\$120 x 4 days)	\$ 480.00	\$ 400.00 (\$100 x 4 days)
LTA Search	\$ 2.00	\$ 2.00
Total	\$ 12,231.54	6,661.50

Amount of claim at **Liability 100%**                      \$ 6,661.50

Enclose herewith the relevant supporting documents for your perusal.

**\*\* 7 days recommendation for repair**

For your approval please.

Regards,  
Khanchna Pothuraj  
LKK Auto Consultants Pte Ltd

## Khanchna (LKK Auto)

---

**From:** Khanchna (LKK Auto)  
**Sent:** Monday, 23 December 2019 11:32 AM  
**To:** Chin  
**Cc:** Admin A  
**Subject:** OFFER - TP Settlement SLE2590G (AIG)

Without Prejudice  
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

For amicable settlement on a without prejudice basis, we propose settlement as follows:

1. Cost of Repair (w/GST)	\$ 6,259.50
2. Loss of Rental (4 days x \$100)	\$ 400.00
3. LTA Search fee	\$ 2.00
<b>TOTAL</b>	<b>\$ 6,661.50</b>

Please confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

*"Best Wishes for Merry Christmas & Happy New Year 2020"*

Best Regards,

**Khanchna** | Case Handler

**LKK Auto Consultants Pte Ltd**

DID: 6841 2360 | email: [Khanchna@lkkauto.com](mailto:Khanchna@lkkauto.com) | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Chin <[chin@modernautomotive.com.sg](mailto:chin@modernautomotive.com.sg)>  
**Sent:** Friday, 8 November 2019 11:42 AM  
**To:** Khanchna (LKK Auto) <[khanchna@lkkauto.com](mailto:khanchna@lkkauto.com)>  
**Cc:** Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>; CS A Team <[cs-a@lkkauto.com](mailto:cs-a@lkkauto.com)>  
**Subject:** Re: TP Settlement SLE2590G (AIG)

Dear Khanchna

We refer to the above matter.

## Khanchna (LKK Auto)

---

**From:** Khanchna (LKK Auto)  
**Sent:** Monday, 6 January 2020 3:58 PM  
**To:** 'Chin'  
**Cc:** Admin A  
**Subject:** RE: OFFER - TP Settlement SLE2590G (AIG)  
**Attachments:** AIG DV.pdf

Without Prejudice  
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

Thank you for the acceptance.

We attach herewith a copy of the DV for your further action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Khanchna** | Case Handler

**LKK Auto Consultants Pte Ltd**

DID: 6841 2360 | email: [Khanchna@lkkauto.com](mailto:Khanchna@lkkauto.com) | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chin <[chin@modernautomotive.com.sg](mailto:chin@modernautomotive.com.sg)>  
**Sent:** Monday, 23 December 2019 1:36 PM  
**To:** Khanchna (LKK Auto) <[khanchna@lkkauto.com](mailto:khanchna@lkkauto.com)>  
**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** RE: OFFER - TP Settlement SLE2590G (AIG)

Dear Khanchna

We accept your offer of amount \$6661.50 in settlement of this claim and forward us your DV.

Thank you



## Khanchna (LKK Auto)

---

**From:** Syed-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>  
**Sent:** Thursday, 19 December 2019 3:23 PM  
**To:** Khanchna (LKK Auto)  
**Subject:** FW: Mandate Request from LKK Auto Consultants Pte Ltd - SLE2590G

Dear Khanchna,

For cases that we have received LOD from repairer, can your side upload w/p report instead of the IA?

For this matter, I have given mandate approval via Merimen to expedite settlement.

Kind Regards,  
Saliha

Saliha Syed Yusoff  
AIG  
Senior Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16, Singapore 079120  
Tel + (65) 6419 1917 |  
[www.aig.sg](http://www.aig.sg)

### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**From:** Do-Not-Reply [mailto:do-not-reply@merimen.com]  
**Sent:** Thursday, December 5, 2019 3:20 PM  
**To:** Syed-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>  
**Subject:** [EXTERNAL] Mandate Request from LKK Auto Consultants Pte Ltd - SLE2590G

This message is from an external sender; be cautious with links and attachments.

Dear PIC,

There is a mandate request from LKK Auto Consultants Pte Ltd

Claim no.: 6725092885SG

Vehicle no.: SLE2590G

Date of Accident: 28/07/2019

Repairer: Modern Automotive Pte Ltd

## Print Received Message

This mail is associated with :

**\*SLE2590G (6725092885SG)**  
**[SMC5288J]**

TP

MOHAMAD SA'ID BIN OTHMAN

Jul 28 2019 6:00PM

[SEET THIAN BENG BENJAMIN]

Modern Automotive Pte Ltd

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 19/12/2019 15:20 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$6661.50) - SLE2590G - Claim Handler: Syed-Yusoff, Saliha

Approved:6661.50:mandate approval is subject to final repair bill & ATA

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2019 <a href="#">Edit Reg</a>		29 Jul 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$5,850.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,850.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>SEET THIAN BENG BENJAMIN</b> , ID: S1766726B								
Main Claimant:	<b>MOHAMAD SA'ID BIN OTHMAN</b> , ID: S1430238G								
Vehicle Reg. No.:	<b>SLE2590G</b>	Date of Loss:	28/07/2019 18:00 - :59 <b>36 Months and 14 Days From LTA Reg Date (Man Yr)</b>						
Claim Type:	<b>TP / 6725092885SG</b>	Policy/Cover Note No.:	1800079793 (Comprehensive) Coverage: 06/07/2019 - 05/07/2020						
Vehicle Reg. No. (Insured):	<b>SMC5288J</b>	Policy No. (Claimant):	5102220954-01						
	Excess:								
Repairer:	<b>Modern Automotive Pte Ltd (HQ)</b> Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Syed-Yusoff, Saliha</b> ] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... <b>[Final Rpt due 07/08/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• AIG_SG_EXPRESS (19/12/2019): Alert - Adj Mandate Approved (S\$6661.50) - SLE2590G - Claim Handler: Syed-Yusoff...									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLE2590G (6725092885SG)  
[SMC5288J]

TP















































MOHAMAD SA'ID BIN OTHMAN





























Jul 28 2019 6:00PM

[SEET THIAN BENG BENJAMIN]

Modern Automotive Pte Ltd

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<a href="#">Upload Video</a>	<a href="#">Upload Audio</a>	<b>View</b> <a href="#">View in Browser</a> <input type="button" value="v"/>	
<b>Letters/Correspondences</b>						1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown				Edit	
<b>Assessment Reports</b>						1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	05/12/19 15:17	Adjuster Immediate Advice				Load HTM	
<b>Photos/Images</b>						3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
2	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
3	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
4	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
5	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
6	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
7	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
8	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
9	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
10	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
11	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
12	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
13	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
14	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
15	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
16	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
17	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
18	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
19	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
20	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
21	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
22	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
23	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
24	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
25	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
26	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
27	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
28	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
29	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
30	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
31	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
32	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
33	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
34	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
35	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	
36	27/08/19 09:15	General View				Load JPG <input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
38	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
39	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
40	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
41	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
42	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
43	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
44	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
45	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
46	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
47	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
48	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
49	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
50	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
51	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
52	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
53	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
54	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
55	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
56	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
57	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
58	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
59	27/08/19 09:15	General View	 Load JPG	<input checked="" type="checkbox"/>
60	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	27/08/19 09:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
84	27/08/19 09:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
85	27/08/19 09:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
86	27/08/19 09:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
87	27/08/19 09:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
88	27/08/19 09:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
89	27/08/19 09:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
90	27/08/19 09:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
91	27/08/19 09:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
92	27/08/19 09:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
93	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	27/08/19 09:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/07/19 18:33	TP GIA REPORT	 Load PDF	
2	30/07/19 21:46	TP GIA REPORT	 Load PDF	
3	30/09/19 17:36	EMAIL TO OI	 Load PDF	
4	30/09/19 17:37	LETTER TO OI	 Load PDF	
5	05/12/19 15:11	TP ESTIMATE MARKED (FINAL)	 Load PDF	
6	05/12/19 15:11	LOD, final Repair Invoice, LTA Search, ATA, Rental Supporting docs	 Load PDF	
7	14/01/20 10:05	WORKSHOP INVOICE	 Load PDF	
8	14/01/20 10:05	AUTHORISATION TO ACT FORM	 Load PDF	
9	14/01/20 10:05	RENTAL RECEIPT	 Load PDF	
10	14/01/20 10:05	Release Voucher	 Load PDF	
11	14/01/20 10:05	LOD	 Load PDF	
12	14/01/20 10:05	GIA SEARCH	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	30/07/19 14:06	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMC5288J (Insd veh)	Model:	HONDA VEZEL 1.5 X CVT
	SLE2590G (TP veh)		(A)
Date of Accident:	28/07/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	11,749.54
Final Repair Cost	:	\$	6,259.50
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	400.00 4 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	6,661.50

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_ 100 \_\_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Modern Automotive Pte Ltd	:	\$ 6,661.50
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

14 Jan  
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;  
Medical Report/ Bill (if any))



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19013302/AKA3Q2

Date: 14/01/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800079793  
**Claimant** SLE2590G **Insured Vehicle No :** SMC5288J  
**Vehicle No :** SLE2590G  
**Date of Loss:** 28/07/2019 **Nature of Claim:** TP **Claim No:** 6725092885SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE2590G**  
 Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B4035962  
 Reg. Date: 14/07/2016 (Man. Year: 2016) Chassis No: RU11115966  
 Colour: White Odometer: 72980 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm  
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,550.88	5,171.92	2,378.96	31.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	2,170.00	1,260.00	36.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,980.88</b>	<b>7,341.92</b>	<b>3,638.96</b>	<b>33.14</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,850.00</b>		
(S\$)	10,980.88	5,850.00	5,130.88	46.73
<b>+ GST 7.00/7.00% (S\$)</b>	768.66	409.50	359.16	46.73
<b>Nett Amount (S\$)</b>	<b>11,749.54</b>	<b>6,259.50</b>	<b>5,490.04</b>	<b>46.73</b>
<b>+ Car Rental (4.0 x S\$100.00/day) (S\$)</b>		400.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>6,661.50</b>		

### INSPECTION

Date of Assignment: 29/07/2019  
 Date Inspected: 29/07/2019 Inspected At: Modern Automotive Pte Ltd (HQ)  
 Blk 3023A Ubi Road 1, #01-61 & #01-58  
 Singapore 408717

Estimated Period of Repair: 7.0 days

---

**Adjuster:** ADRIAN LING**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	880.00 FL	*880.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	2		*REAR BUMPER SIDE HOLDER -LH & RH	Necessary	70.40 FL	*70.40 FL
4	2		*REAR BUMPER REFLECTOR -LH & RH	Not Necessary	290.00 FL	*- FL
5	1		*REAR BUMPER UNDERCOVER	Deformed	245.60 FL	*245.60 FL
6	1		*SET REAR BUMPER UNDERCOVER CLIPS	Necessary	30.00 FL	*30.00 FL
7	2		*REAR SIDE BUMPER -LH & RH	Deformed	390.00 FL	*390.00 FL
8	1		*REAR END PANEL	Dented	595.60 FL	*595.60 FL
9	1		*REAR END PANEL TOP GARNISH	Deformed	125.90 FL	*125.90 FL
10	1		*REAR END PANEL BUZZER	Damaged	85.50 FL	*85.50 FL
11	1		*REAR END PANEL LOCK SENSOR	Not Necessary	69.40 FL	*- FL
12	1		*TAIL LAMP -LH & RH	N/S Cut	961.20 FL	*480.60 FL
13	1		*TAILGATE	Distorted	1,100.00 FL	*1,100.00 FL
14	1		*TAILGATE LOCK	Damaged	186.30 FL	*186.30 FL
15	1		*TAILGATE WEATHERSTRIP	Cut	165.00 FL	*165.00 FL
16	2		*TAILGATE LAMP -LH & RH	Cut	580.20 FL	*580.20 FL
17	1		*TAILGATE INNER TRIM BOARD	Deformed	321.70 FL	*321.70 FL
18	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FL	*30.00 FL
19	1		*TAILGATE GLASS MOULDING	Necessary	158.60 FL	*158.60 FL
20	1		*VEZEL EMBLEM	Necessary	56.20 FL	*56.20 FL
21	1		*SPARE TYRE PANEL TOP BOARD	Deformed	306.60 FL	*306.60 FL
22	1		*TOOLS TRAY SPONGE	Cracked	226.70 FL	*226.70 FL
23	2		*REAR FENDER INNER TRIM -LH & RH	Not Necessary	650.60 FL	*- FL
24	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 FL	*- FL
25	1		*REAR EXHAUST PIPE	Not Necessary	688.10 FL	*- FL
26	1		*REAR EXHAUST MOUNTING	Not Necessary	35.00 FL	*- FL
27	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
28	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
29	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS
30	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>9,218.60</b>	<b>6,384.90</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>1,667.72</b>	<b>1,212.98</b>
<b>Total Parts (S\$)</b>	<b>7,550.88</b>	<b>5,171.92</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,200.00	900.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,200.00	800.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	60.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE REAR CAMERA	New	100.00	50.00
7	TO REMOVE UPHOLSTERY	New	150.00	80.00
8	TO REMOVE FITTING GLASS	New	180.00	120.00
9	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
10	TO REMOVE EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (S\$)			3,430.00	2,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >