

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 #01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
78 Shenton Way #07-16
Singapore 079120
Tel : 6419 - 3000
Fax : 6835 - 7416

Khanchag

Quotation

DATE : 29.07.2019
VEH NO : SLE2590G
MODEL : Honda Vezel
D O A : 28.07.2019
YR REF : SMC5288J

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLE2590G (HONDA VEZEL)

Item	Description	Qty	Amt
<u>NO</u>	<u>LIST ITEMS</u>		
1	Rear Bumper <i>Debond</i>	1	880.00 ✓
2	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>new</i>	2	70.40 ✓
4	Rear Bumper Reflector - LH & RH <i>new</i>	2	290.00 ✗
5	Rear Bumper Undercover <i>Debond</i>	1	245.60 ✓
6	Rear Bumper Undercover Clips <i>new</i>	1 set	30.00 ✓
7	Rear Side Bumper - LH & RH <i>Debond</i>	2	390.00 ✓
8	Rear End Panel <i>Dented</i>	1	595.60 ✓
9	Rear End Panel Top Garnish <i>Debond</i>	1	125.90 ✓
10	Rear End Panel Buzzer <i>Damaged</i>	1	85.50 ✓
11	Rear End Panel Lock Sensor <i>new</i>	1	69.40 ✗
12	Tail Lamp - LH & RH <i>LH at</i>	2	961.20 <i>480.60</i>
13	Tailgate <i>Distorted</i>	1	1,100.00 ✓
14	Tailgate Lock <i>Damaged</i>	1	186.30 ✓
15	Tailgate Weatherstripe <i>at</i>	1	165.00 ✓
16	Tailgate Lamp - LH & RH <i>at</i>	2	590.20 ✓
17	Tailgate Inner Trim Board <i>Debond</i>	1	321.70 ✓
18	Tailgate Inner Trim Board Clips <i>new</i>	1 set	30.00 ✓
19	Tailgate Glass Moulding <i>new</i>	1	158.60 ✓
20	Vezel Emblem <i>new</i>	1	56.20 ✓
21	Spare Tyre Panel Top Board <i>Debond</i>	1	306.60 ✓
22	Tools Tray Sponge <i>crushed</i>	1	226.70 ✓
23	Rear Fender Inner Trim - LH & RH <i>new</i>	2	650.60 ✗
24	Rear Fender Inner Trim Clips <i>new</i>	1 set	60.00 ✗
25	Rear Exhaust Pipe <i>new</i>	1	688.10 ✗
26	Rear Exhaust Mounting <i>new</i>	1	35.00 ✗

8,338.60

6064 90

4851-92

RE : ESTIMATE FOR ACCIDENT REPAIR SLE2590G (HONDA VEZEL)

Less 20%

(1,667.72)

\$ 6,670.88

S/NETT ITEMS

1	Rear End Panel Sealant <i>Free</i>	1	60.00	/
2	Tailgate Glass Sealant	1	60.00	/
3	Rear Camera <i>Not new</i>	1	480.00	X
4	Reverse Sensor <i>Damaged</i>	1	280.00	200
			320	
			880.00	

Total Parts

\$ 7,550.88

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,200.00	900
2	To putty & spray up paint works	\$	1,200.00	800
3	To check wiring	\$	50.00	30
4	To underseal	\$	150.00	60
5	To remove reverse sensor	\$	100.00	50
6	To remove rear camera	\$	100.00	50
7	To remove upholstery	\$	150.00	80
8	To remove tailgate glass	\$	180.00	120
9	To transfer tailgate fittings	\$	150.00	80
10	To remove exhaust pipe	\$	150.00	X
			2170	

Total Labour

\$ 3,430.00

Grand Total

\$ 10,980.88

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 7341.92
C/S: 5850
07 Days