

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0924/2019/NS
Date : 30-Jul-19

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle : SME 6262 R

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MS. LIN HUI XIAN JAIME
Address : 10 WESTRIDGE WALK
Singapore 544626
Telephone : HP +65 91728108
Type of Claim : Third Party Claims
Policy No. : GA403271/1
Vehicle No : **SLS 8108 D**
Model Code : Audi A6 1.8 TFSI S TRONIC
Model / Year : Oct-17
Engine No : CYG 018348
Chassis No : WAUZZZ4G7HN079784
Mileage : 22728
Date In : 29-Jul-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Jul-19
Place of Accident : YISHUN AVE 3 AND SEMBAWANG ROAD

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 8108 D

S/n	Nature of Jobs	Estimated Charges	SURVEYOR'S RECOMMENDATION
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	
2	To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,200.00	
3	To respray rear bumper.	\$ 1,000.00	
4	To carry out diagnostic check.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: <u>\$ 2,752.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 8108 D

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	REMARKS
1	REAR BUMPER	\$ 2,676.00	
2	REAR BUMPER FIXING PARTS	\$ 247.00	
4	REAR BUMPER SPOILER	\$ 437.00	
3	REAR BUMPER SECURING STRIP	\$ 203.00	
6	REAR BUMPER CLOSING ELEMENT - LH / RH	2 \$ 146.00	
	CABLE TERMINAL	\$ 90.00	
7	EXHAUST TAIL PIPE TRIM	2 \$ 1,034.00	
8	REAR BUMPER CARRIER	\$ 887.00	
9	REAR BUMPER SEAL-LH/RH	2 \$ 26.00	
10	REAR BUMPER GUIDE SECTION - CENTRE	\$ 96.00	
11	REAR BUMPER GUDIE PROFILE-LH/RH	2 \$ 120.00	
12	REAR BUMPER GUIDE SECTION-LH/RH	2 \$ 60.00	
13	REAR BUMPER CONNECTING PIECE	2 \$ 22.00	
14	REAR BUMPER HOLDING STRAP-LH/RH	2 \$ 116.00	
15	REAR PARKING AID SENSOR	2 \$ 462.00	
17	SUNDRIES	\$ 200.00	
TOTAL SPARE PARTS CHARGES		: \$ 6,822.00	
TOTAL LABOUR CHARGES		: \$ 2,752.00	
GRAND TOTAL		: \$ 9,574.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant