

Vehicle ALICE SPIN

REF: NTUC NS/INC 19013334/ EV 1302

ASSIGNMENT

From _____ Date: _____
Estimated Cost _____
OD TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop in/ _____
at _____
Insured SJT 61513
Policy No 5109647257 (16109219- 21/10/2019)
Claims No MT/1055159-002
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No SHC 44185 13/1/14
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota Pro 1798
Colour Maroon A/C Insured / Std / N
Sp. Reading 44342 T/Rxlin: Insured / Std / N
Eng/No: _____
C/No: JTOKN364195721808
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Locked / Burnt or
Broke: Inorder / Jammed / Locked / Burnt or
Modi: Nil / S/Rim. / STD A/Rim or
Tyre Size: F: 195/50R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Achilles
Front
R/Bal. 5 mm Rear
L/Bal. 5 mm R/Bal. 5
D.O.A. 25/7/19 L/Bal. 5
Survey held at SMRT D.O.I. 29/7/19
Des. of Damages: Frl / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to co

Date / Time : Action / Instruction
SHC 44185 - NSI INC 16002809 / K10652
16/8/19 Finalize confir \$1400, 5 days (Pih Swan) ROA - 12/02/2016 07/19/2190
(Red 7687.80, 8490) SJT 61513

RECEIVED 19 AUG 2019

Date/Time, File Pass to: ☐ : Prel. Report
☐ : Final Report

Days Of Repair: 5
Resurvey No. of Trip: 1

Report Format: TP
Lump Sum / I.B. I: 1400/2

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee:
Transportation
S + R: \$
Phone
Fuel
160
160

Veron Chen (LKKAUTO)

From: MTCL@income.com.sg
Sent: Monday, 19 August 2019 1:31 PM
To: Veron Chen (LKKAUTO)
Subject: FW: REQUEST FOR CLAIM NUMBER

Hi

All claim created.

With Regards

Azlin Rani
Senior Administrator, Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Friday, 16 August 2019 9:45 AM
To: MTCL@income.com.sg
Subject: REQUEST FOR CLAIM NUMBER

Dear Sir/Madam,

Kindly provides us claim number

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle
1	MT/1055159- 002	SMRT TAXIS PTE LTD	SHC 4418S	SJT 6151J
2	MT/1055666- 002	SMRT TAXIS PTE LTD	SHF 499T	SJL 8166X

D.O.A	Time of Accident	Estimate	Tentative repair cost
25/7/2019	11:00	\$9,087.80	\$1,400.00
29/7/2019	08:15	\$3,807.90	\$700.00

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No.(For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5109647257		OPTIMUM CAR LEASING PTE LTD	201633831N	GPC	Third Party	SJT6151J	SJT6151J	16/05/2019	21/10/2019

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	369K

Vehicle Details

Vehicle No.:	SHC4418S
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2013
Engine No.:	2ZR1326243
Chassis No.:	JTDKN36U105721808
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	13 Jan 2014
First Registration Date:	13 Jan 2014
Transfer Count:	0
Actual ARF Paid:	\$8,368.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jan 2022
PARF Rebate Amount:	\$5,857.00

Intended COE Rebate Details

COE Expiry Date:	12 Jan 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$60,888.00
COE Rebate Amount:	\$18,679.00
Total Rebate Amount:	\$24,536.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 29 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/07/2019 16:13
Date Of Accident	25/07/2019 11:00
Exact Location Of Accident	CHOA CHU KANG AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4418S
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	TAN CHEK FONG
NRIC No	S1769381F
Date Of Birth	12/07/1966
Occupation	OUTDOOR
Date Of Driving Pass	14/11/1991
Driving Experience	27 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (Including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I PARKED MY TAXI ALONG CHOA CHU KANG AVE 1 ON THE EXTREME LEFT LANE WITH THE HAZARD LIGHT ON AND THE BONNET UP AS THERE WAS SOME TECHNICAL ISSUES WITH MY TAXI. I WAS STANDING ABOUT 20 METRES AWAY FROM MY TAXI TO DIRECT THE TRAFFIC WHILST WAITING FOR THE TOW TRUCK TO ARRIVE. SUDDENLY A VEHICLE SJT6151J FAILED TO SLOW DOWN AND HIT ONTO THE REAR RIGHT PORTION OF MY TAXI.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJT6151J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ABDULLAH BIN ARSHAD
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time:

西澤幸

Driver's Signature
(If driver is not the policyholder)

Date & Time:

26/7/2019

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:


26/7/2019.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Case Details

Case Reference Number :

TAX/07/19/2100

Type of Repair : Accident Repair

Vehicle Registration Number : SHC4418S

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-7818-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 25/07/2019 03:00 PM

Vehicle Age(In Months) : 66

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation					Repair/ Replace	Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace ▾ <i>MC</i>
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▾ <i>MC</i>
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check ▾ <i>X MM</i>
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give ▾ <i>X MM</i>
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check ▾ <i>X MM</i>
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace ▾ <i>/ DR</i>
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Give ▾ <i>X MM</i>
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	1	88.57 ⁸	Replace ▾ <i>CUT /</i>
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give ▾ <i>X MM</i>
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	1	0	Repair ▾ <i>X R</i>
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give ▾ <i>X MM</i>
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair ▾ <i>X R</i>

Total Spare Part Cost 4,161.34

Lump Sum Discount (%) 20.00

Final Spare Part Cost 3,329.07

Surveyor Total 717.90

Lump Sum Dis (%) 20

Final Sur Total 574.32

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			STICKER DECAL SMRT	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	/ NK
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	/ NK
One Time Key In	Main			QUARTER GLASS RR/RH	1	846.50	846.50	25.00	634.88	Replace	0	0	Not Give	X NAI
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	X NAI
One Time Key In	Main			TROUGH, BACK DOOR	1	110.90	110.90	25.00	83.18	Replace	0	0	Not Give	X NAI
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0	Not Give	X NAI
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	0	0	Not Give	X NAI
One Time Key In	Main			DUCT ASSY, QUARTER	1	70.40	70.40	25.00	52.80	Replace	1	52.80	Replace	/ BR
One Time Key In	Main			FLOOR PANEL RR/RH	1	209.90	209.90	25.00	157.43	Replace	0	0	Not Give	X NAI
One Time Key In	Main			BATTERY	1	278.00	278.00	10.00	250.20	Replace	0	0	Not Give	X NAI
One Time Key In	Main		6505648	BATTERY TRAY	1	42.80	42.80	25.00	32.10	Replace	0	0	Not Give	X NAI
Standard	Main		6505548	BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	/ BR
Total Spare Part Cost									4,161.34	Surveyor Total		717.90		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									3,329.07	Final Sur Total		574.32		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION RH	1,014.00	450	
Total:			1,014.00	450.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY REAR PANEL	180.00	80	
Total:			1,476.00	480.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
3	Main	TO RESPRAY BUMPER BEAM	180.00	0	
4	Main	TO RESPRAY FLOOR CORNER PANEL RH	180.00	0	
5	Main	TO RESPRAY REAR FENDER RH	378.00	200	
6	Main	TO RESPRAY TROUGH BACK DOOR RH	180.00	0	
Total:			1,476.00	480.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	20	N/C
2	Main	TOWING CHARGE	56.00	0	
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	N/C
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
5	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	20	N/C
6	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0	
7	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0	
8	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	N/C
9	Main	TO REPLACE SUNDRY PARTS	100.00	20	N/C
10	Main	TO WASH AND VACUUM	60.00	0	
11	Main	TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0	
Total:			1,351.00	100.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,329.07	574.32
Total Labour Cost	1,014.00	450.00
Total Spray Painting	1,476.00	480.00
Other	1,351.00	100.00

Estimator Assessment(\$)

Surveyor Assessment(\$)

Overall Total

7,170.07

1,604.32

Lump Sum Repair Option

Lump Sum Total

7,150.00

1,600.00

Surveyor Approved Amount

1,600.00

No of Repair Days*

7

5

Remarks

L/S repair, take after spray. Finalize sent to
stevecgen@lkkauto.com

Surveyor Name

STEVE CHEN

Signature


30/7/19

Save

Clear

Survey Date

29/07/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company



Acknowledged by Repairer

Signature:

Date:

Section A - Accident Details

Registration Number	SHC4418S
Case Reference Number	TAX/07/19/2100
Registration Date	13/1/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TANG CHEK FONG
Type of Accident	Head to Rear
Accident Date and Time	25/7/2019 11:00 PM
Accident Reported Date and Time	26/7/2019 3:33 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	25/7/2019 11:25 PM
Replacement Vehicle issued?	No
Job Card Number	24102568
Special Instruction to ARC, if any	TP
Prepared Date and Time	29/7/2019 9:57 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$450.00
Total Spray Cost	\$1,476.00	\$480.00
Total Spare Part Cost	\$3,329.07	\$717.91
Total Other Cost	\$1,351.00	(\$247.91)
TOTAL COST	\$7,170.07	\$1,400.00 (L/S)
Lump Sum Total	\$7,150.00	\$0.00
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	Kim Ming Chin	STEVE CHEN (LKK) / NTUC
ARC / Surveyor Sign Off Date	29/07/2019 3:09 PM	29/07/2019 2:02 PM
Signature		
Remarks	L/S repair, take after spray. Finalize sent to stevecgen@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0172	Invoice Number	
Quotation Date	14.08.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION RH	\$1,014.00	\$450.00
Total Labour	\$1,014.00	\$450.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$80.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY FLOOR CORNER PANEL RH	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,476.00	\$480.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$347.91)
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$20.00
TOWING CHARGE	\$56.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$20.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REMOVE & REFIT REAR QUARTER GLASS RH	\$120.00	\$0.00
Total Other Costs	\$1,351.00	(\$247.91)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given

NRC

NRC

NN

NN

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 63665502
Estimator Telephone Number: 68662023
Accident Reporting Number: 68662072

Date Generated: 15/08/2019

User ID: PohSuan

		SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check	X	NN
	52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace		BR
	52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given	X	NN
	76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$88.58	Replace	Replace		CH
	76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given	X	NN
	58307-47060	END PANEL	1.00	\$602.10	100.00	\$0.00	Replace	Repair		
		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X	NN
	61604-47090	FENDER RR/RH	1.00	\$766.80	100.00	\$0.00	Replace	Repair		
		STICKER DECAL SMRT	1.00	\$7.80	0.00	\$7.80	Replace	Replace		NEC
		STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace		NEC
	62710-47130	QUARTER GLASS RR/RH	0.00	\$846.50	0.00	\$0.00	Replace	Not Given	X	NN
		SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X	NN
	61621-47030	TROUGH, BACK DOOR	0.00	\$110.90	0.00	\$0.00	Replace	Not Given	X	NN
	52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Not Given	X	NN
	81551-47180	TAIL LAMP RH	0.00	\$557.80	0.00	\$0.00	Replace	Not Given	X	NN
	62940-16060	DUCT ASSY, QUARTER	1.00	\$70.40	25.00	\$52.80	Replace	Replace		BR
	58302-47030	FLOOR PANEL RR/RH	0.00	\$209.90	0.00	\$0.00	Replace	Not Given	X	NN
		BATTERY	0.00	\$278.00	0.00	\$0.00	Replace	Not Given	X	NN
6505648	74440-47030	BATTERY TRAY	0.00	\$42.80	0.00	\$0.00	Replace	Not Given	X	NN
	52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace		BR
Total				\$5,172.31		\$717.91				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

717.91
+ 450.00
+ 580.00

1747.91
- 208

1398.33
45 \$1400/-

Veron Chen (LKKAuto)

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Friday, 16 August 2019 9:12 AM
To: Steve Chen (LKK Auto)
Cc: SUR; CS A Team
Subject: RE: SHC4418S

Hi,

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Steve Chen (LKK Auto) [mailto:SteveChen@lkkauto.com]
Sent: Friday, 16 August 2019 8:36 AM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Subject: SHC4418S

Dear Poh Suan,

We confirm the finalize \$1400 (L/S, before GST). 5 repair days.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Friday, August 16, 2019 7:50 AM
To: Steve Chen (LKK Auto)
Cc: SUR; CS A Team
Subject: SHC4418S

Hi Steve,

Attached herewith the repair estimate of SHC 4418S having Case No: TAX/07/19/2100.

There is no change to the approved amount of \$1,400 @ 5 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Sent: Thursday, 15 August 2019 5:14 PM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Subject: Scan Data from FX-D421D6



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19013334/Evf3e2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 19-08-2019	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJT 6151J	Veh. Inspected	SHC 4418S	
Policy No.	5109647257	Coverage (\$)	0.00	
Claim No.	MT/1055159-002	Excess (\$)	0.00	
Assign From		Assign Date	29/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTDKN36U105721808	Colour	MAROON	
Odometer	443342	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R15	ACHILLES	5 mm	
L/H Front Tyre	195/50 R15	ACHILLES	5 mm	
R/H Rear Tyre	195/50 R15	ACHILLES	5 mm	
L/H Rear Tyre	195/50 R15	ACHILLES	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/07/2019	Inspection Date	29/07/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4418S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER SIDE RETAINER RR/RH (DISC 25%)	BROKEN	94.80	71.10
1	BUMPER LIP COVER RR/RH (DISC 25%)	CUT	118.10	88.58
1	DUCT ASSY, QUARTER (DISC 25%)	BROKEN	70.40	52.80
1	BUMPER REAR (DISC 25%)	BROKEN	458.60	343.95
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	STICKER DECAL SMRT (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	BUMPER REINFORCEMENT REAR	NOT NECESSARY	205.70	-
1	ARM SUB-ASSY, RR BUMPER RH	NOT NECESSARY	139.60	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	BUMPER SEAL, RR RH	NOT NECESSARY	65.70	-
1	BUMPER LIP REAR	NOT NECESSARY	228.90	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	QUARTER GLASS RR/RH	NOT NECESSARY	846.50	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	TROUGH, BACK DOOR	NOT NECESSARY	110.90	-
1	TAIL LAMP BRACKET, RH	NOT NECESSARY	30.70	-
1	TAIL LAMP RH	NOT NECESSARY	557.80	-
1	FLOOR PANEL RR/RH	NOT NECESSARY	209.90	-
1	BATTERY	NOT NECESSARY	278.00	-
1	BATTERY TRAY	NOT NECESSARY	42.80	-
1	END PANEL	TO REPAIR SEE LABOUR	602.10	-
1	FENDER RR/RH	TO REPAIR SEE LABOUR	766.80	-
			5,246.80	717.91
<u>LABOUR</u>				
	PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF END PANEL AND FENDER RR/RH.		1,014.00	450.00
	SPRAY PAINT.		1,476.00	480.00

Report Ref No. NS/INC19013334/Evf3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK & RESET SYSTEM FUNCTION.		350.00	20.00
	TOWING CHARGE.		56.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	NOT NECESSARY	120.00	-
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	20.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	NOT NECESSARY	120.00	-
	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM.	NOT NECESSARY	125.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	20.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REMOVE & REFIT REAR QUARTER GLASS RH.	NOT NECESSARY	120.00	-
			3,841.00	1,030.00
GRAND TOTAL			9,087.80	1,747.91
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,400.00

Report Ref No. NS/INC19013334/Evf3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.