

ASS. REC. BY:

REF: CS/CT219013340/Rsgf3

n2

Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Chang Boon Sen of CT2

Date/Time: 29.7.19 4.13p.m

Estimated Cost:

Bill to:

OD (TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: PC1876C

Insured: GBC 67845

at Workshop m/s Rydur

Tel: 67418277

of 2 Kaki Bukit Ave 2 #02-19

Policy No: DMCUSN14207819055

Claim No: SNM 19d 203514002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 26.7.2019

CA / REV / REP. / REV 24 HRS

H.O.D. endorsement:

Date/Time: 30.7.19 11.00a.m

Person Contacted: Olson

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	R1876C-7
	GBC 67845
19/8/19 @ 4.18pm	Jure will check & arrange.
	Rasul Finalised US \$1800, 4 days credit 1996.68, 55%.

Rasul

REF: CT2

105M
CUE XPRM: 2023/may

ASSIGNMENT

From: 2.9.2019

Veh No: PC 1876C W Reg: 2013 MAY

Estimate Cost:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: PC 1876C

Make: TOYOTA HIACE H/ROOF 3.0A 2582

at Workshop info: Ryder Auto

Colour: Green A/C: Insured / Std / NI / NA

of 2 Kaki Bukit Ave 2 #02-19

Sp/Reading: 503422 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No: JTFST 22P X 00016655

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or


Make of Veh: 11.00am owner waiting

Mod: NO / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 195R15C

Remarks: The veh had commenced its repair at the time of inspection.



R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or GOODRIDE

Bal. or Market Value:

Front

Rear

IDAC Accident Report: Consistent? Yes or No

R/Bal: 6 mm

R/Bal: 6 mm

GIA / PR Seen: Consistent? Yes or No

L/Bal: 6 mm

L/Bal: 6 mm

Est Repairs: 4 days Res: Yes or No

D.O.A: 26/6/19

D.O.I: 02/09/19

Lum Sum: % 3 Vol: Yes or No

Survey held at: Ryder 21/9/2019

CA / REV / REP. / 24 HRS

up

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Frt

Date: Person Contacted:

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Rasul

Pls see my remarks & check parts prices

RECEIVED 26 SEP 2019

3/9

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: 4

1) 26/9/2019

☐

: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Report Format :

MER-7P

Lump Sum / I.B.V. (\$)

1800

Survey Fee:

Transportation

S + P.C. 74

1/10/19

Others

1

TOTAL

220

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 29 July 2019 4:13 PM
To: Ryder Auto workshop
Cc: LKK Auto Appraisers (assignments@lkkauto.com)
Subject: RE: pre repair inspection: your vehicle gbc6784c / our vehile: pc1876c / accident: 26.7.19 sn1m9d203514

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Ryder Auto workshop [mailto:ryderautoworkshop@gmail.com]

Sent: Monday, 29 July, 2019 4:10 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: pre repair inspection: your vehicle gbc6784c / our vehile: pc1876c / accident: 26.7.19 sn1m9d203514

Dear Boon Sen,

Kindly assign Mr. Adrian Ling.

Thank you.

Best regards
June

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19, 02-22 AutoHub @ Kaki Bukit, Singapore 417921
Tel : 67418277 Fax: 67468277

Ryder HV Pte Ltd

5 Tuas Ave 3 BS Logistics Hub Singapore 639405

On Mon, Jul 29, 2019 at 3:34 PM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Rasul (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Wednesday, 25 September, 2019 10:20 AM
To: Ryder Auto workshop
Subject: RE: PC1876C AFTER PAINT

Hi Orson,

As spoken, finalised amount is \$ 1800 / 4 days lump sum
Kindly confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Rasul (LKKAUTO)
Sent: Tuesday, 24 September, 2019 10:07 AM
To: Ryder Auto workshop
Subject: RE: PC1876C AFTER PAINT

Hi Orson,

Refer to attachment
Finalised amount is \$ 1,700 / 4 days lump sum
Kindly confirm


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Ryder Auto workshop [<mailto:ryderautoworkshop@gmail.com>]
Sent: Tuesday, 24 September, 2019 9:40 AM
To: Rasul (LKKAUTO)
Subject: Re: PC1876C AFTER PAINT

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19 / 22 AutoHub @ Kaki Bukit, Singapore 417921
Tel : 67418277 Fax: 67468277

Ryder HV Pte Ltd

5 Tuas Ave 3 BS Logistics Hub Singapore 639405
Fax: 64815390



87781999
24/7

Mobil 1

On Tue, Sep 24, 2019 at 9:01 AM Rasul (LKKAuto) <Rasul@lkkauto.com> wrote:

Hi Orson,

Do you keep photos to support it?


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Ryder Auto workshop [mailto:ryderautoworkshop@gmail.com]

Sent: Monday, 23 September, 2019 6:26 PM

To: Rasul (LKKAuto)

Subject: Re: PC1876C AFTER PAINT

Dear Rasul,

The side mirror is located above the bonnet of your client vehicle. it is not low at all. Also kindly note that DOA was 26/7/2019 and date of survey was 2/9/2019. Approximately 1 month interval which explained the rust.. Kindly assist to finalize.

Thank you

Rgds

Orson

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19 / 22 AutoHub @ Kaki Bukit, Singapore 417921

Tel : 67418277 Fax: 67468277

Ryder HV Pte Ltd

5 Tuas Ave 3 BS Logistics Hub Singapore 639405

Fax: 64815390



87781999

Mobil 1

On Mon, Sep 23, 2019 at 5:58 PM Rasul (LKKAuto) <Rasul@lkkauto.com> wrote:

The pick-up front portion is low

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth. Print only when necessary.

From: Ryder Auto workshop [mailto:ryderautoworkshop@gmail.com]

Sent: Monday, 23 September, 2019 5:57 PM

To: Rasul (LKKAuto)

Subject: Re: PC1876C AFTER PAINT

Dear Rasul,

It is the side mirror of Nissan Navara which cause the damage.

Rgds

Orson

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19 / 22 AutoHub @ Kaki Bukit, Singapore 417921

Tel : 67418277 Fax: 67468277

Ryder HV Pte Ltd

5 Tuas Ave 3 BS Logistics Hub Singapore 639405

Fax: 64815390



87781999

24/7

Mobil 1

On Mon, Sep 23, 2019 at 5:53 PM Rasul (LKKAuto) <Rasul@lkkauto.com> wrote:

Hi Arson,

The front corner panel damage is not consistent to the accident. OI vehicle make and model is Nissan Navara. It's a pick-up. From my point of view,

Unlikely the corner panel damage due to accident. It was old damage and the part was also got the rust on it.

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth. Print only when necessary.

From: Ryder Auto workshop [<mailto:ryderautoworkshop@gmail.com>]

Sent: Monday, 9 September, 2019 1:14 PM

To: Rasul (LKKAuto)

Subject: PC1876C AFTER PAINT

Dear Rasul,

Kindly view attached after paint and finalize soonest.

Rgds

Orson

Ryder Auto Pte Ltd


2 Kaki Bukit Ave 2, #02-19, 02-22 AutoHub @ Kaki Bukit, Singapore 417921

Tel : 67418277 Fax: 67468277

Ryder HV Pte Ltd

5 Tuas Ave 3 BS Logistics Hub Singapore 639405

Fax: 64815390

 **BOE SENG**
(Heavy vehicles, engine repairs)

 **Authorized Workshop**
Authorized Repairing Centre

AL 8778 1999
24 hr roadside net

Mobil 

biSAFE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	105M
Vehicle Details	
Vehicle No.:	PC1876C
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE H/ROOF 3.0 AT
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	1KD2288240
Chassis No.:	JTFST22PX00016655
Maximum Power Output:	-
Open Market Value:	\$37,122.00
Original Registration Date:	22 May 2013
First Registration Date:	22 May 2013
Transfer Count:	1
Actual ARF Paid:	\$1,857.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 May 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$56,011.00
COE Rebate Amount:	\$20,823.00
Total Rebate Amount:	\$20,823.00

The information contained herein is correct as at 02 Sep 2019

OK

43,000
20,823

22,177

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/07/2019 13:06
Date Of Accident	26/07/2019 16:50
Exact Location Of Accident	SLIP ROAD OF TUAS ROAD TOWARDS PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC6784S
Insured/Policyholder	
Name Of Registered Owner	M/S HONGRONG ENGINEERING PTE LTD
Co Reg No	199105717Z
Email Address	HRE0119@YAHOO.COM
Mobile Phone No	
Alternative Phone No	OFFICE-65544718
Vehicle Particulars	
Manufacturer	NISSAN
Model	NAVARA 2.5L S/CAB MT ABS D/AIRBAG TURBO
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1420781905
Cover Note Number	

Driver

Name of Driver	KWOK SOON TING (GUO SHUNTING)
NRIC No	S9019251E
Date Of Birth	03/06/1990
Occupation	OUTDOOR
Date Of Driving Pass	06/07/2015
Driving Experience	4 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83821186
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 202B PUNGGOL FIELD
	#16-248
Postcode	822202
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC1876C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	YUSOPE KHAN SURATTEE
NRIC/Passport Number	S0869592Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	KWOK SOON TING (GUO SHUNTING)
------	-------------------------------

Approximate Age	29
Injuries Sustain	NECK AND BACK PAIN
Injured person in which vehicle?	GBC6784S
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 202B PUNGGOL FIELD #16-248
Postcode	822202

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

HONGRONG ENGINEERING PTE LTD

6, SIN MING ROAD
#01-19, SIN MING PLAZA, TOWER 2
SINGAPORE 575585
TEL: 6554 4718 FAX: 6452 3803

Policyholder's Signature
Date & Time:

29 JUL 2019
(7:06 AM)

Driver's Signature
(If driver is not the policyholder)
Date & Time:

29 JUL 2019
(7:06 AM)

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sub: 40833A



中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

MOTOR COMMERCIAL VEHICLE

CERTIFICATE OF INSURANCE
Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

AN0070A
Cov. Type: C
PLM 330247

ORIGINAL

CERTIFICATE No.

DMCVSN1420781905

Engine No : YD255186507

Chassis No: MMTACUD40A0600391

1. Index Mark and Registration
Number of Vehicle

GRC67845

AutoSafe

2. Name of Policy Holder

M/S HONGRONG ENGINEERING PTE LTD

3. Effective date of the Commencement of
Insurance for the purposes of the Regulations, 23 July 2019
Ordinance or Enactment

Excess Sect 1 S\$500.00

EX ON WINDSCREEN S\$100.00

4. Date of Expiry of Insurance

22 July 2020

5. Persons or Classes of Persons entitled to drive*

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use:

(1) Use in connection with the Policyholder's business.

(2) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.

(3) Use for social, domestic or pleasure purposes.

The Policy does not cover:

(1) Use for hire or reward or racing, pace-making, reliability trial or speed testing.

(2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

HIRE PURCHASE CO. : MAYBANK AS HP OWNER

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By:

Authorised Officer

Authorised Signatory

China Taiping Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200208384E)
3 Anson Road #16-00 Springleaf Tower Singapore 079909

6389 6111

6222 1033

www.sg.cntaiping.com

REPUBLIC OF SINGAPORE
IDENTITY CARD NO S9019251E



Name
KWOK SOON TING
(GUO SHUNTING)
郭 頌 庭
Race
CHINESE
Date of birth
03-06-1990 Sex
M
Country of birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number S9019251E

KWOK SOON TING
GUO SHUNTING

Birth Date: 03 JUN 1990
Valid Until: 06 JUL 2015



NRIC No: S9019251E



Date of issue
10-06-2005

Address
APT BLK 2020 PONGGOL FIELD
#15-248
SINGAPORE 822202

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

EFFECTIVE DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 06 Jul 2015



NP 425A

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

PC1876C Pg 1/1

Veh # : PC1876C Model : TOYOTA HIACE H/ROOF (22/5/2013)
 Date Of Accident: 26/7/19 3P : GBC6784S (CHINA TAIPING)
 Location : PIONEER ROAD

1235.25
 1600.00
 2235.25
 202
 1788.20
 413-1800

S/n	Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$	
		<u>List Items</u>				
1	1 pc	Front bumper <i>de-</i>			1,196.20	545
2	10 pcs	Front bumper clips <i>pc-</i>			120.00	50
3	1 pc	Front bumper n/s corner clips <i>? X sc</i>		1647	76.40	X
4	1 pc	Front n/s head-lamp <i>sc-</i>		259	1,109.30	598
5	1 pc	Front n/s corner panel <i>bt-</i>		1235.25	612.00	264
6	1 pc	Front n/s step garnish <i>at-</i>			215.00	190
		Sub-Total			3,328.90	
		After -25%			2,496.68	
		<u>Labour</u>				
1		To remove and replace front damage parts		400	600.00	
2		To spray painting.		600	700.00	
		Sub-Total		1000	1,300.00	
		Total			3,796.68	
		After -20%			3,037.34	

Chan

Chan San Choon
 Director
 DipEng, AAE MIMI, MSAE(Aust)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Rame
 4p 90010068

4 days

w/s

02/09/19 @ 1120

Resurvey after repair

3/9/19

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19013340/R1QF3N2

Date: 01/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN14207819055	
Claimant Vehicle No :	PC1876C	Insured Vehicle No :	GBC6784S	
Date of Loss:	26/07/2019	Nature of Claim:	TP	Claim No: SNM19D203514C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC1876C	Engine No:	1KD2288240
Make & Model:	TOYOTA HIACE, 3.0 (A)	Chassis No:	JTFST22PX00016655
Reg. Date:	22/05/2013 (Man. Year: 2013)	Odometer:	503422 km
Colour:	Grey		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Goodride 6 mm	Rear Left Side:	Goodride 6 mm
Front Right Side:	Goodride 6 mm	Rear Right Side:	Goodride 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,496.67	1,235.25	1,261.42	50.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	1,000.00	300.00	23.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,796.67	2,235.25	1,561.42	41.13
Approved Total (Overridden) (\$\$)		1,800.00		
Nett Amount (\$\$)	3,796.67	1,800.00	1,996.67	52.59

INSPECTION

Date of Assignment:	03/09/2019	
Date Inspected:	02/09/2019 Inspected At:	Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit Singapore 417921
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 30 Sep 2019)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC1876C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,196.20 FL	*545.00 FL
2	10		*FRONT BUMPER CLIPS	Necessary	120.00 FL	*50.00 FL
3	1		*FRONT BUMPER N/S CORNER CLIPS	Serviceable	76.40 FL	*- FL
4	1		*FRONT N/S HEAD-LAMP	Scratched	1,109.30 FL	*598.00 FL
5	1		*FRONT N/S CORNER PANEL	Bent	612.00 FL	*264.00 FL
6	1		*FRONT N/S STEP GARNISH	Cut	215.00 FL	*190.00 FL
					Sub Total (\$\$)	3,328.90 1,647.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	832.23 411.75
					Total Parts (\$\$)	2,496.67 1,235.25

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE FRONT DAMAGE PARTS	New	600.00	400.00
2	TO SPRAY PAINTING	New	700.00	600.00
Gross Labour Cost (S\$)			1,300.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >