

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd
3 Anson Road 51 Ubi Ave 1 #01-25
#16-00 Springleaf Tower Paya Ubi Industrial Park
Singapore 079909 Singapore 408933

Attn: Chong Boon Sen Date: 31 Jul 2019

Preliminary Advice

Vehicle No	: SLB7895K	Accident Date	: 26/07/2019
Make	: MERCEDES-BENZ A180	Policy No.	: DMPCSN1825701800
Assignment Date	: 30/07/2019	Excess	: S\$0.00
Date of Inspection	: 30/07/2019	Est. Duration of Repair	: 3 days
Inspection At	: CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,872.38
Revised Amount	:S\$	4,228.55
Check Items (Estimated)	:S\$	4,009.59
Total	:S\$	8,238.14
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	88,000.00
COE / PARF Rebate	:S\$	43,583.00
Salvage Value	:S\$	
Margin for Repair	:S\$	44,417.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :