

123456789

ASS. REC. BY:

REF:

CS/CTI19013348/Kqd3<sup>m2</sup>

Special Instruction:

Surveyor: Kenneth  
Mehmen

ASSIGNMENT (Office)

From (Person): Tan Kah leong of CTI

Date/Time: 30/7/19②

Estimated Cost: Bill to:

OD/IT/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMM6816B

Insured: SKV 7949X

at Workshop m/s MBM Wheelpower

Tel: 6262 8888

of 160 Sin Ming Drive #06-02

Policy No: DMPCSN30967118022

Claim No: SNM19D203440C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 21/07/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:28am 30/7/19

Person Contacted: Cressundsen

Vehicle IN/OUT

Date/Time	Action/Instruction
	Estimated /
	SMM6816B - X
	SKV 7949X - X
	Kenneth confirmed final fig \$2072.54. (Red \$ 5717.72, 73%)

ASS. REC. BY:

REF:

CT11

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.:

Yes or No

Lum Sum:

1-B1 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMN 8816B

Yr Regn:

07.19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Pro

c.c

1496

Colour:

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

657

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

G137

1087426

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/85R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

21/7/19

D.O.I.

30/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

OPC

RECEIVED 13 AUG 2019

Date/Time, File Pass to?

☐

: Prell. Report

1) 13/8 10:00 AM

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

MER-TP

Lump Sum / I.B.I. (\$

2072.54

220

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jul 2019		30 Jul 2019 09:37 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

Main Claimant:

Vehicle Reg. No.:

Claim Type:

Vehicle Reg. No. (Insured):

Repairer:

Handling Insurer:

Claimant's Insurer:

Adjuster:

NOR LINDA BINTE MOHAMAD ALI, ID: S7245693I

SMM6816B

TP / SNM19D203440C02

SKV7949X

MBM Wheelpower Pte Ltd (HQ) 160 Sin Ming Drive #06-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6262 8888

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]

HL Assurance Pte Ltd (HQ) - Tel: 69226030

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/08/2019]

Date of Loss:

Policy/Cover Note No.:

Policy No. (Claimant):

Excess:

21/07/2019 18:00 - :59

DMPCSN30961118022

MP310554

S\$750.00

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>  
**Sent:** Tuesday, 30 July 2019 9:34 AM  
**To:** cassandra.chua@mbmwheelpower.com.sg; assignments  
**Cc:** 'danny.ong'  
**Subject:** RE: OUR REF: SNM19D203440/TANKL - FW: Liability Status - Accident involving SMM 6816 B & SKV 7949 X (China Taiping) DOA 21/07/2019

### WITHOUT PREJUDICE

Dear Cassandra,

We refer to your email of 29.07.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

**Tan Kah Leong**

Assistant Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6193 | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** cassandra.chua@mbmwheelpower.com.sg [mailto:cassandra.chua@mbmwheelpower.com.sg]  
**Sent:** Monday, 29 July, 2019 12:34 PM  
**To:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>  
**Cc:** 'danny.ong' <danny.ong@mbmwheelpower.com.sg>  
**Subject:** RE: OUR REF: SNM19D203440/TANKL - FW: Liability Status - Accident involving SMM 6816 B & SKV 7949 X (China Taiping) DOA 21/07/2019


Dear all,

We would like to select Kenneth Kong from LKK as the appointed surveyor for the said vehicle today.

Vehicle already in.

Thank you.

Best Regards,  
Cassandra Chua | Claims Advisor



T 6262 8888 | F 6250 9015 | M 8686 5188  
Email: [cassandra.chua@mbmwheelpower.com.sg](mailto:cassandra.chua@mbmwheelpower.com.sg)  
**MBM Wheelpower PTE. LTD.**  
160 Sin Ming Drive • #06-02  
Sin Ming Autocity • Singapore 575722  
[www.mbmwheelpower.com.sg](http://www.mbmwheelpower.com.sg)

---

**From:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>  
**Sent:** Thursday, 25 July 2019 2:22 PM  
**To:** Tan Kah Leong <[KahLeong.Tan@sg.cntaiping.com](mailto:KahLeong.Tan@sg.cntaiping.com)>; Alfred Toh <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>; [cassandra.chua@mbmwheelpower.com.sg](mailto:cassandra.chua@mbmwheelpower.com.sg)  
**Subject:** OUR REF: SNM19D203440/TANKL - FW: Liability Status - Accident involving SMM 6816 B & SKV 7949 X (China Taiping) DOA 21/07/2019

Dear Kah Leong,

Please conduct PRS for SMM6816B.

Note : officer in charge – Kah Leong 63896193.

Thanks,  
shumin

---

**From:** [cassandra.chua@mbmwheelpower.com.sg](mailto:cassandra.chua@mbmwheelpower.com.sg) [<mailto:cassandra.chua@mbmwheelpower.com.sg>]  
**Sent:** Thursday, July 25, 2019 10:29 AM  
**To:** Claims Dept of CTI  
**Cc:** 'Danny Ong '  
**Subject:** Liability Status - Accident involving SMM 6816 B & SKV 7949 X (China Taiping) DOA 21/07/2019


Dear All,

Refer to attached.

Kindly advise liability status for my client's vehicle, SMM 6816 B.

Thank you.

Best Regards,  
Cassandra Chua | Claims Advisor



T 6262 8888 | F 6250 9015 | M 8686 5188  
Email: [cassandra.chua@mbmwheelpower.com.sg](mailto:cassandra.chua@mbmwheelpower.com.sg)  
**MBM Wheelpower PTE. LTD.**  
160 Sin Ming Drive • #06-02  
Sin Ming Autocity • Singapore 575722  
[www.mbmwheelpower.com.sg](http://www.mbmwheelpower.com.sg)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

--

This message has been scanned for viruses and dangerous content by  
QUAPE SPAM Protection, and is believed to be clean.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/07/2019 15:54
Date Of Accident	21/07/2019 18:25
Exact Location Of Accident	JUNCTION BTW JURONG WEST AVE 4 & STREET 75
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMM6816B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NOR LINDA BINTE MOHAMAD ALI
NRIC No	S7245693I
Email Address	IRONZDER@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96194065
Alternative Phone No	OFFICE-96194065

### Vehicle Particulars

Manufacturer	HONDA
Model	FREED HYBRID-1.5 G (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	HL ASSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MP310554
Cover Note Number	

### Driver

Name of Driver	MUHAMMAD IRSYAD BIN REDZUAN
NRIC No	S9646206I
Date Of Birth	17/12/1996
Occupation	INDOOR
Date Of Driving Pass	07/12/2016
Driving Experience	2 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96789932
Fax Number	
Contact Number	
Email Address	IRONZDER@GMAIL.COM

Address	APT BLK 218D BOON LAY AVE #13-307
Postcode	644218
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : PASSENGER GENDER: : MALE
Passenger 2	NAME: : PASSENGER GENDER: : MALE
Passenger 3	NAME: : PASSENGER GENDER: : FEMALE
Passenger 4	NAME: : PASSENGER GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Same As Sketch Plan

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKV7949X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR



Name of Driver	PHUA SIANG LING
NRIC/Passport Number	S6925304J
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


#### DETAILS OF INJURED PERSON 1

Name	NOR LINDA BINTE MOHAMAD ALI
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SMM6816B
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

#### DETAILS OF INJURED PERSON 2

Name	MUHAMMAD IRSYAD BIN REDZUAN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SMM6816B
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

SKETCH PLAN



A: SMM 6816B  
B: SKV 7949X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 21<sup>st</sup> of July 2019, at about 1825 hrs. I was stationary along Jurong West Ave 4, waiting for the turn arrow to St 75. All of a sudden, I felt an impact from the rear. I realized the vehicle SKV 7949X hit onto the rear portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# MBM WHEELPOWER PTE. LTD.

YOUR REF.: SKV 7949 X

OUR REF.: SMM 6816 B

mbm wheelpower

TO: CHINA TAIPING

CC: MOTOR CLAIMS DEPARTMENT

FAX:

DATE: 27/7/2019

FROM: CASSANDRA

FAX: 6452 5333

CONTACT: 8686 5188

MAKE & MODEL: HONDA FREED

CHASSIS NO.: GB71087426

ENGINE NO.: LEB5625460

YEAR MADE: 2019

ACCIDENT DATE: 21 July 2019

ESTIMATE FOR VEHICLE NO.: SMM 6816 B

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE	
1	TAILGATE		1	\$ 1207.90	1,489.20 ✓
2	TAILGATE WEATHERSTRIP		1	\$	232.80 X
3	REAR WINDSCREEN MOULDING		1	\$	100.48 ✓
4	TAILGATE LAMP RH		1	\$	595.20 X
5	TAILGATE LAMP LH		1	\$	595.20 X
6	TAILGATE "H" LOGO		1	\$ 50.25	84.00 ✓
7	TAILGATE CHROME MOULDING		1	\$	275.20 X
8	TAILGATE "FREED" EMBLEM		1	\$ 48.20	90.48 ✓
9	TAILGATE "HYBRID" EMBLEM		1	\$ 65.10	105.60 ✓
10	TAILGATE INNER TRIM		1	\$	458.80 X
11	REAR BUMPER		1	\$	1,122.00 X
12	REAR BUMPER CLIP		10	\$	80.00 X
13	REAR BUMPER REFLECTOR RH		1	\$	130.48 X
14	REAR BUMPER REFLECTOR LH		1	\$	130.48 X
15	END PANEL		1	\$	704.80 X
16	END PANEL TOP GARNISH		1	\$	155.60 X
TOTAL:				\$	6,350.32
LESS 20%:				\$	(1,270.06)
PARTS TOTAL:				\$	5,080.26

Not Authorised

Resurvey Required

3 days  
KK Auto Consultants hence notify  
of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

SPECIAL NETT

BODY SEALANT

WINDSCREEN SEALANT

REAR NUMBER PLATE WITH HOLDER

REVERSE SENSOR (1 SET)

nn	1	\$	nn	80.00	X
nn	1	\$	40sn	150.00	
	1	\$	45sn	80.00	
	1	\$	sn	300.00	X

LABOUR

TO REMOVE, REFIT &amp; REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD &amp; STRAIGHTEN ON THE AFFECTED PARTS

TO CHECK &amp; RECONNECT ALL NECESSARY WIRING

TO APPLY ANTI RUST COATING

TO REMOVE &amp; REFIT REAR WINDSCREEN

TO REMOVE &amp; INSTALL REVERSE SENSOR

TO SPRAY PAINT ON THE AFFECTED AREAS

		\$	200	700.00	
		\$	20 15l	120.00	
		\$	30l	250.00	
		\$	120l	150.00	
		\$	nn	80.00	X
		\$	440l	800.00	
TOTAL:		\$		7,790.26	
7% GST:		\$		545.32	
GRAND TOTAL:		\$		8,335.57	

Kg

## MBM WHEELPOWER PTE. LTD.

YOUR REF.: SKV 7949 X

OUR REF.: SMM 6816 B



TO: CHINA TAIPING

CC: MOTOR CLAIMS DEPARTMENT

FAX:

DATE: 27/7/2019

FROM: CASSANDRA

FAX: 6452 5333

CONTACT: 8686 5188

MAKE &amp; MODEL: HONDA FREED

CHASSIS NO.: GB71087426

ENGINE NO.: LEB5625460

YEAR MADE: 2019

ACCIDENT DATE: 21 July 2019

FINALISED ESTIMATE FOR VEHICLE NO.: SMM 6816 B

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	TAILGATE <i>1207.90</i>		1	\$ 1,489.20
2	REAR WINDSCREEN MOULDING		1	\$ 100.48
3	TAILGATE "H" LOGO <i>50.25</i>		1	\$ 84.00
4	TAILGATE "FREED" EMBLEM <i>48.20</i>		1	\$ 90.48
5	TAILGATE "HYBRID" EMBLEM <i>65.10</i>		1	\$ 105.60
TOTAL:				\$ 1,869.76
LESS 20%:				\$ (373.95)
PARTS TOTAL:				\$ 1,495.81

SPECIAL NETT

WINDSCREEN SEALANT	1	\$ 40.00
REAR NUMBER PLATE WITH HOLDER	1	\$ 45.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS	\$ 200.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$ 120.00
TO APPLY ANTI RUST COATING	\$ 30.00
TO REMOVE & REFIT REAR WINDSCREEN	\$ 120.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$ 440.00
TOTAL:	\$ 2,490.81
7% GST:	\$ 174.36
GRAND TOTAL:	\$ 2,665.16

PART BY PART: \$ *2072.54* 2,490.81

BEFORE GST

03 REPAIR DAYS

MBM WHEELPOWER PTE. LTD.  
 160 SIN MING DRIVE, #06-02  
 SIN MING ALTCITY  
 16262 8888 6452 5333  
 COMPANY REG. NO.: 200204110W

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119013348/KQD3N2

Date: 13/08/2019

## REFERENCE

<b>Handling Insurer:</b>	China Taiping Insurance (Singapore) Pte. Ltd.	<b>Policy No:</b>	DMPCSN30961118022	
<b>Claimant Vehicle No :</b>	SMM6816B	<b>Insured Vehicle No :</b>	SKV7949X	
<b>Date of Loss:</b>	21/07/2019	<b>Nature of Claim:</b>	TP	<b>Claim No:</b> SNM19D203440C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

<b>Reg No:</b>	SMM6816B	<b>Engine No:</b>	LEB5625460
<b>Make &amp; Model:</b>	HONDA FREED HYBRID, 1.5 G (A)	<b>Chassis No:</b>	GB71087426
<b>Reg. Date:</b>	09/07/2019 (Man. Year: 2019)	<b>Odometer:</b>	657 km
<b>Colour:</b>	Metallic Blue		
<b>Engine Capacity:</b>	1496 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (\$\$):</b>	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

<b>General Condition:</b>		<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	Yes	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>	

## CONDITION OF TYRES

<b>Front Tyre Size:</b>	185/65R15	<b>Rear Tyre Size:</b>	185/65R15
<b>Front Left Side:</b>	Yokohama 9 mm	<b>Rear Left Side:</b>	Yokohama 9 mm
<b>Front Right Side:</b>	Yokohama 9 mm	<b>Rear Right Side:</b>	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,690.26	1,262.54	4,427.72	77.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	810.00	1,290.00	61.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>7,790.26</b>	<b>2,072.54</b>	<b>5,717.72</b>	<b>73.40</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>545.32</b>	<b>145.08</b>	<b>400.24</b>	<b>73.40</b>
<b>Nett Amount (\$\$)</b>	<b>8,335.58</b>	<b>2,217.62</b>	<b>6,117.96</b>	<b>73.40</b>

## INSPECTION

<b>Date of Assignment:</b>	30/07/2019	
<b>Date Inspected:</b>	30/07/2019	<b>Inspected At:</b> MBM Wheelpower Pte Ltd (HQ) 160 Sin Ming Drive #06-02, Sin Ming AutoCity Singapore 575722

**Estimated Period of Repair:** 3.0 days**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 13 Aug 2019)
<b>Parts:</b>	M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMM6816B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,489.20 FL	*1,207.90 FL
2	1		*TAILGATE WEATHERSTRIP	Serviceable	232.80 FL	*- FL
3	1		*REAR WINDSCREEN MOULDING	Necessary	100.48 FL	*100.48 FL
4	1		*TAILGATE LAMP RH	Serviceable	595.20 FL	*- FL
5	1		*TAILGATE LAMP LH	Serviceable	595.20 FL	*- FL
6	1		*TAILGATE H LOGO	Necessary	84.00 FL	*50.25 FL
7	1		*TAILGATE CHROME MOULDING	Serviceable	275.20 FL	*- FL
8	1		*TAILGATE FREED EMBLEM	Necessary	90.48 FL	*48.20 FL
9	1		*TAILGATE HYBRID EMBLEM	Necessary	105.60 FL	*65.10 FL
10	1		*TAILGATE INNER TRIM	Serviceable	458.80 FL	*- FL
11	1		*REAR BUMPER	Repair	1,122.00 FL	*- FL
12	10		*REAR BUMPER CLIP	Not Necessary	80.00 FL	*- FL
13	1		*REAR BUMPER REFLECTOR RH	Serviceable	130.48 FL	*- FL
14	1		*REAR BUMPER REFLECTOR LH	Serviceable	130.48 FL	*- FL
15	1		*END PANEL	Repair	704.80 FL	*- FL
16	1		*END PANEL TOP GARNISH	Serviceable	155.60 FL	*- FL
17	1		*BODY SEALANT	Not Necessary	80.00 FS	*- FS
18	1		*WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS
19	1		*REAR NUMBER PLATE WITH HOLDER	Necessary	80.00 FS	*45.00 FS
20	1		*SET REVERSE SENSOR	Serviceable	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,960.32</b>	<b>1,556.93</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>1,270.06</b>	<b>294.39</b>
<b>Total Parts (\$\$)</b>	<b>5,690.26</b>	<b>1,262.54</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,REFIT & REPAIR AFFECTED DAMAGED PARTS,INCLUDING TO KNOCK-OUT,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	700.00	200.00
2	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	120.00	20.00
3	TO APPLY ANTI RUST COATING	New	250.00	30.00
4	TO REMOVE & REFIT REAR WINDSCREEN	New	150.00	120.00
5	TO REMOVE & INSTALL REVERSE SENSOR	New	80.00	0.00
6	TO SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	440.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,100.00</b>	<b>810.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >