

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SML5328E
Accident Date : 27-Jul-2019

Our Ref : 219123 (AIG) / CHAN

LIM YEW SHENG
11 SELETAR ROAD
#01-53
Singapore 807016

No. : 06025

Date : 29-Jul-2019

PAGE : 1

*Not Withain
C/Lip 8?
Runny After Paint*

ESTIMATED COST OF REPAIR FOR NISSAN QASHQAI 1.2 DIG SLD5646R

1 pc Rear o/s door		By 1,104.80 n ✓
2 pcs Rear o/s door frame tape	@ S\$ 29.90	nn 59.80 n ✓
1 pc Rear o/s fender arch garnish		Red/Car 483.00 n ✓
8 pcs Rr o/s fender arch clip	@ S\$ 3.80	nn 30.40 n ✓
1 pc Rear o/s door rubber		nn 165.40 n X

1,843.40
Less 10% : 184.34

1,659.06

To putty and spray replaced parts

700.00 *450*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

600.00 *300*

To check and adjust wheel alignment

nn 65.00 X

Total : S\$ 3,024.06

Singapore Dollars Three Thousand and Twenty Four
and Cents Six Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: