

Esteeem Performance Pte Ltd
385 Sin Ming Drive, Vicom
Vehicle Inspection Centre
(575718)

Claim Reference: SLU8911R
Assessment number: 011930
Version: 1810
Date calculated: 29/07/2019 5:25 PM

Full Report
Registration: SLS7534M
Printed: 29/07/2019 5:26 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AIG Asia Pacific Insurance Pte Ltd
Printed by:	Carmen SG	Currency:	SGD
Claim Reference:	SLU8911R	Date of Incident:	27/07/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	PRIUS IV
Sub Model:	BASE MODEL
Model Sheet Number:	70 P5 01
Registration:	SLS7534M
VIN number:	
Odometer:	
Model Specs	
TWO COAT METALLIC	

Not Notified
Resurvey After Paint
1-2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom
Vehicle Inspection Centre
(575718)

Claim Reference: SLU8911R
Assessment number: 011930
Version: 1810
Date calculated: 29/07/2019 5:25 PM

Full Report
Registration: SLS7534M
Printed: 29/07/2019 5:26 PM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
B420	RENEW REAR BUMPER INCLUDES: REAR BUMPER AND REQUIRED ATTACHED PARTS R + R		12.0	60.00
1001	R&R REVERSE SENSOR REMOVE&REFIT			120.00*
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		1.20	12.0	60.00
Fixed Rate				120.00
Total of Labour				180.00

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom
Vehicle Inspection Centre
(575718)

Claim Reference: SLU8911R
 Assessment number: 011930
 Version: 1810
 Date calculated: 29/07/2019 5:25 PM

Full Report
 Registration: SLS7534M
 Printed: 29/07/2019 5:26 PM

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	REAR BUMPER NEW PART PAINT K1R	13.0

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	63.96

Labour Cost - Paint

	Factor	Hrs	WU	Price SGD
	50.00 SGD/h		13.0	
	Time Paint		9.0	45.00
	Preparation Comp. Work Plastic	0.90	9.0	45.00
Total	10 WU/h	2.20	22.0	110.00

Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	63.96
Material-constant Plastic	16.20
Total	80.16

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
2583	REAR BUMPER	52159 47913		✓	497.50 ✓
2622	RIGHT RETAINER	90467 09237		✓	112.70 ✓
2636	R/R BUMPER CORNER	52565 47900		✓	149.70 ✓
1000	REAR BUMP CLIP	REAR BUMP CLIP		✓	40.00 ✓
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				799.90
u: Used parts	Subtotal Discount(+30.00%)				-239.97
	Total				559.93

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom
Vehicle Inspection Centre
(575718)

Claim Reference: SLU8911R
Assessment number: 011930
Version: 1810

Date calculated: 29/07/2019 5:25 PM

Full Report
Registration: SLS7534M
Printed: 29/07/2019 5:26 PM

Final Calculation

	SGD	SGD
Parts	799.90	
Total Discount(+30.00%)	-239.97	
Total Parts		559.93
Labour Time Base 10 WU/h		
Total 12.0 WU X 50.00 SGD/h	60.00	
Fixed Rate	120.00	
Total of Labour		180.00
Paint Work Time Base 10 WU/h		
Labour Cost 22.0 WU X 50.00 SGD/h	110.00	
Material Cost	80.16	
Total Paint Including Material		190.16
Repair Cost Excludes GST		930.09
GST (+7.0%)		65.11
Repair Cost Included GST		995.20

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS