

ASS. REC. BY:

REF: CS/CT1 196133601 Kyf3

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Tan Kah Leong of C11

Date/Time: 30.7.19 2.50pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PA 9737D

Insured: SKW 51482

at Workshop m/s Serde You motor

Tel: 9239 3188

of BIK 5033 AMK Industrial Park 2 #01-265

Policy No:

Claim No: SWM19D703494

Sum Insured:

Excess:

Make of Veh:

D.O.A. 24.7.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

mp1

2/8/19 @ 10.30am

H.O.D. Endorsement:

Date/Time: 30.7.19 3.09pm

Person Contacted: Elaine

Vehicle IN / OUT

Date/Time Action/Instruction (✓) Estimate

PA 9737D-X

SKW 51482-X

11/9 21pm @ 3000 email & call (Red \$2233.00, 42%)

ASS. REC. BY:

REF: CTI

ASSIGNMENT

From:

Date:

2/8/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PA 9737 D

at Workshop m/s

of BIK 5033, Amk Ind. Park 2 #01-265

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

10:30am (waiting)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Imp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

PA 97370

Yr Regn:

05, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hijer

C.C.

6692

Colour:

Multi Colour

A/C: Insured / Std / NI / NA

Sp. Reading

281654

T/Radio: Insured / Std / NI / NA

Eng/No:

LKLRIFSTXAB 53549

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

Double Coin

Finnaz 11R 22.5 x 246 (01)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

66

mm

L/Bal.

5

mm

L/Bal.

66

mm

D.O.A.

24/7/19

D.O.I.

218/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Workshop ask whether can direct settle.

RECEIVED 11 SEP 2019

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

11/9/19 - Typist

Days Of Repair: 2

Resurvey No. of Trip:

Add Fee:



Site Insp. (\$



Interview (\$



Tech. Inve (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others:

TOTAL

220

Report Format:

Lump Sum / T.B.E. (\$

\$3000/-

Catherine Chong (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Tuesday, 30 July, 2019 2:50 PM
To: Iris Lim; assignments
Cc: serveyou5033
Subject: RE: OUR REF: SNM19D203494-SKW5148Z-TKL - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

WITHOUT PREJUDICE

Dear Iris,

We refer to your email of 30.07.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Iris Lim [mailto:iris@hoh.com.sg]
Sent: Tuesday, 30 July, 2019 12:26 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Cc: serveyou5033 <serveyou5033@gmail.com>
Subject: RE: OUR REF: SNM19D203494-SKW5148Z-TKL - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

Dear Kah Leong (Urgent)

We refer to your following email.

Our client's workshop would like to use Kenneth Kong to conduct a pre-repair survey of the damage to our client's vehicle.

Kindly make the necessary arrangement. Thank you.

Regards
Iris Lim
Secretary
Hoh Law Corporation
Advocates & Solicitors
209 New Upper Changi Road
#04-631 Singapore 460209
DID: (65) 6244 5756
Fax: (65) 6244 3052
E-mail: iris@hoh.com.sg

Disclaimer: This message is privileged and confidential and is intended solely for the named recipient. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is strictly prohibited. If this e-mail has reached you in error, please delete the e-mail immediately and inform us of the error by sending an e-mail to iris@hoh.com.sg. Though internet communications cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost or infected with viruses, we have scanned this message to minimise the possibility of corruption

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Tuesday, 30 July 2019 9:15 AM
To: Iris Lim <iris@hoh.com.sg>
Subject: RE: OUR REF: SNM19D203494-SKW5148Z-TKL - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

Without Prejudice

Dear Iris,

We refer to your email dated 29 July 2019.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
LOW SAR HUEI
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
HONG FOOK CHOY
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Monday, 29 July, 2019 4:35 PM

To: Iris Lim <iris@hoh.com.sg>; Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: OUR REF: SNM19D203494-SKW5148Z-TKL - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

Dear Kah Leong,

Please conduct PRS for PA9737D.

Note : Officer in charge is Kah Leong 63896193.

Thanks,
shumin

From: Iris Lim [<mailto:iris@hoh.com.sg>]

Sent: Monday, 29 July, 2019 2:01 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: serveyou5033 <serveyou5033@gmail.com>

Subject: NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

Dear Sirs (VERY URGENT) (ACCIDENT INVOLVING PA9737D AND SKW5148Z ALONG SUNGEI TENGAH ROAD SLIP ROAD TO KJE ON 24 JULY 2019)

We refer to the above matter.

We act for the owner of PA9737D, M/s A&S Transit Pte Ltd who has appointed the undermentioned workshop to repair their vehicle no. PA9737D.

Please be informed that the said vehicle can be inspected at:

M/s Serve You Motor Service
Blk 5033 Ang Mo Kio Industrial Park 2
#01-265
Singapore 569536
Contact person: Ms Elaine Chia's handphone no. 9239 3188/ 6481 5652/6481 0555

If you fail to conduct the pre-repair inspection within the next (2) working days excluding Saturday, Sunday or Public Holidays, our client shall instruct the above workshop to commence repairs thereafter without further reference to you.

Regards

Iris Lim
Secretary
Hoh Law Corporation
Advocates & Solicitors
209 New Upper Changi Road
#04-631 Singapore 460209
DID: (65) 6244 5756
Fax: (65) 6244 3052
E-mail: iris@hoh.com.sg

Disclaimer: This message is privileged and confidential and is intended solely for the named recipient. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is strictly prohibited. If this e-mail has reached you in error, please delete the e-mail immediately and inform us of the error by sending an e-mail to iris@hoh.com.sg. Though internet communications cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost or infected with viruses, we have scanned this message to minimise the possibility of corruption.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	917G

Vehicle Details

Vehicle No.:	PA9737D
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Jul 2019
Vehicle Make:	HIGER
Vehicle Model:	KLQ6109Q 6.7L MT ABS TURBO
Primary Colour:	Blue
Manufacturing Year:	2010
Engine No.:	ISBE430021927003
Chassis No.:	LKLR1FSJXAB535491
Maximum Power Output:	-
Open Market Value:	\$86,487.00
Original Registration Date:	18 May 2010
First Registration Date:	18 May 2010
Transfer Count:	1
Actual ARF Paid:	\$4,325.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	17 May 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$23,501.00
COE Rebate Amount:	\$1,902.00
Total Rebate Amount:	\$1,902.00

The information contained herein is correct as at 25 Jul 2019

OK

SERVE YOU MOTOR SERVICE

BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2
#01-265, SINGAPORE 569536
TEL. NO: 64810555 / FAX NO. 64831654
E-MAIL: serveyou5033@gmail.com

INS: CHINA TAIPING INSURANCE SINGAPORE PTE LTD
COMPANY: A&S TRANSIT PTE LTD

Registration no. : PA 9737 D / HIGER KLQ6109Q

Date : 31-Jul-19

Quotation No. : CM190714

Date of accident: 24.07.2019

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

1	1	Rear bumper	\$2,380.00 ✓
2	2	Rear bumper bracket	\$280 each \$560.00 ✗
3	2	Rear bumper fog lamp	\$288 each \$576.00 ✓
4	2	Rear number plate lamp	\$118 each \$236.00 ✓
5	1	Rear number plate	\$50.00 25in ✓
6	1	Rear exhaust tail pipe	\$284.00 ✓
7	1	Rear cover inner lock	\$284.00 ✗

\$4,370.00

Less 10%

\$437.00

\$3,933.00

for 1st Rear Bumper Sticker - \$280 = 180in
LABOUR & MISC CHARGES

1	To dismantle / renew front accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$800.00 350in
2	Supply spray paint material and necessary items to respray on accident damaged portion	\$500.00 300in

TOTAL

\$1,300.00

Total Parts and Labour Cost of Repair

\$5,233.00

*Not Authorised
1/1 Imp & 2900h 3000
Repair After Paint*

2/8/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey the car after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19013360/KTF3N2

Date: 13/09/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3029711903
Claimant Vehicle No :	PA9737D	Insured Vehicle No :	SKW5148Z
Date of Loss:	24/07/2019	Nature of Claim:	TP
		Claim No:	SNM19D203494-SKW5148Z-TKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PA9737D	Engine No:	ISBE430021927003
Make & Model:	HIGER KLQ6109Q, 6.7 D ABS TURBO (M)	Chassis No:	LKLR1FSJXAB535491
Reg. Date:	18/05/2010 (Man. Year: 2010)	Odometer:	281654 km
Colour:	Multi-colour		
Engine Capacity:	6692 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	11R22.5X16	Rear Tyre Size:	11R22.5X16 (D)
Front Left Side:	Double Coin 5 mm	Rear Left Side:	Firenza 6/6 mm
Front Right Side:	Double Coin 5 mm	Rear Right Side:	Firenza 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,213.00	3,074.20	1,138.80	27.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	650.00	650.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,513.00	3,724.20	1,788.80	32.45
Approved Total (Overridden) (\$\$)		3,000.00		
Nett Amount (\$\$)	5,513.00	3,000.00	2,513.00	45.58

INSPECTION

Date of Assignment:	31/07/2019	
Date Inspected:	02/08/2019	Inspected At:
		Serve You Motor Service (HQ)
		BLOCK 5033 ANG MO KIO
		INDUSTRIAL PARK 2 #01-265
		Singapore 569536

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Sep 2019)	
Parts:	N/A	HIGER KLQ6109Q 6.7 D ABS TURBO (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PA9737D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	2,380.00 FL	*2,380.00 FL
2	2		*REAR BUMPER BRACKET	Repair	560.00 FL	*- FL
3	1		*REAR BUMPER FOG LAMP	N/s Cracked	576.00 FL	*288.00 FL
4	2		*REAR NUMBER PLATE LAMP	Cracked	236.00 FL	*236.00 FL
5	1		*REAR EXHAUST TAIL PIPE	Dented	284.00 FL	*284.00 FL
6	1		*REAR COVER INNER LOCK	Repair	284.00 FL	*- FL
7	1		*REAR NUMBER PLATE	Cracked	45.00 FS	*25.00 FS
8	1		*SET REAR BUMPER STICKER	Necessary	280.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,645.00	3,393.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	432.00	318.80
Total Parts (\$\$)	4,213.00	3,074.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW FRONT ACCIDENT DAMAGED PORTION.TO PANEL BEATING,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	800.00	350.00
2	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY ON ACCIDENT DAMAGED PORTION	New	500.00	300.00
Gross Labour Cost (\$\$)			1,300.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >