



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
Ms NG SAN SAN APT BLK 771 BEDOK RESERVOIR VIEW #16-155 SINGAPORE 470771 Contact No Mobile: 90074422	Cust No/Name	/Ms NG SAN SAN
	Reg No/Reg Date	SLV9472D / 24/01/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AJH001636
	Engine No	3A92UGR4884
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	29/07/2019/ 10:29	TLC	442 / CocoLu	43089			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1100 1650.00
RENEW REAR BUMPER, BOOTLID, REPAIR REAR END PANEL								840. 1680.00
E PNT98000								60.00
SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL								220.00
E PNT88000								50.00
REMOVE & INSTALL PARKING SENSOR								80.00
M SUNDRY								40.00
SUPPLY PARKING SENSOR								200.00
M SUNDRY								30.00
SUPPLY REAR NUMBER PLATE WITH FRAME								20.00
M SUNDRY								740.00
APPLY RESEAL REAR NUMBER PLATE FROM LTA								27.00
M SUNDRY								27.00
APPLY SEALANT FOR ACCIDENT PORTION								216.00
A 54900099								155.00
CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM								688.00
A 54900099								201.00
CHECK WIRING & ELECTRICAL SYSTEM								201.00
M SUNDRY								21.00
Sundry								45.00
M FACE,RR BUMPER								65.00
M BRACKET,RR BUMPER,RH								
M BRACKET,RR BUMPER,LH								
M LATCH,TRUNK LID								
M WEATHERSTRIP,TRUNK LID								
M PANEL,TRUNK LID								
M HINGE,TRUNK LID,RH								
M HINGE,TRUNK LID,LH								
M MARK,ATTRAGE								
M MARK,THREE-DIA								
M TRIM,RR END								

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Tanglim 97495749

SURVEYOR SIGNATURE: [Signature]

DATE: 15/8/19 2 1145

KKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Tan Jiah 97495749SURVEYOR SIGNATURE: [Signature]DATE: 15/8/19 2 11:45

Confirm & accepted by

REMARKS: Repairing before paint.sur@kkkauto.com4-5 days7% GST on **Nett 6416.00****Total Payable****6,416.00****449.12****6,865.12**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.