

Kp

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

India International Insurance Pte Ltd

64 Cecil St #04/#05

IOB Building

Singapore 049711

Attn: Accident Claim Department

Date :

27.07.2019

Vehicle No :

GBD 2727 D

Veh Make/Model :

Toyota

YOM :

Hiace

Chassis No :

JTFHT02P300147540

Date of Accident :

25.07.2019

Not Authorised
611 Sg & 3800
5 days, Recovery After Repair

No	Qty	Description	Amount \$
		List Items:-	
1	1	Rear tail gate	\$ 1,974.60 ✓
2	2	Rear tail gate hinge	\$ 190.28 X
3	1	Rear tail gate lock	\$ 298.60 ✓
4	1	Rear tail inner compartment/Trim board	\$ 425.17 X
5	1	Rear tail gate logo	\$ 65.00 ✓
6	1	Rear tail gate garnish panel (with key lock)	\$ 372.14 X
7	1	Rear tail gate lock striker	\$ 132.90 ✓
8	1	Rear weatherstripe	\$ 427.80 X
9	1	Rear bumper <i>539.00</i>	\$ 585.90 ✓
10	2	Rear bumper side bracket	\$ 144.32 X
11	1	Rear bumper bracket	\$ 220.00 X
12	10	Rear bumper clips	\$ 40.00 ✓
13	1	Rear end panel (Inner)	\$ 912.89 X
14	1	Rear end panel (Outer) <i>566.10</i>	\$ 725.14 2 ✓
15	6	Rear end panel garnish clips	\$ 30.00 X
16	1	Rear end panel garnish/Top cover	\$ 198.86 X
17	1	Rear LH side end panel	\$ 335.75 X
18	2	Rear LH small cover (under lamp)	\$ 317.60 X
19	2	Rear lamp <i>426.80</i>	\$ 853.60 4 ✓
20	2	Rear LH lamp clips	\$ 16.00 ✓
21	Set	LH & RH Inner fender compartment clips	\$ 80.00 X
22	1	Rear floor panel	\$ 880.60 X
23	1	Step panel bumper	\$ 208.00 X
24	Set	Rear tail gate windscreen moulding	\$ 150.00 X
25	1		\$ -
26	1		\$ -
27	1		\$ -
28	1		\$ -
29	1		\$ -
30	1		\$ -
Total - List Item			\$ 9,585.15
Less 25%			\$ (2,396.29)
Total			\$ 7,188.86

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

India International Insurance Pte Ltd

64 Cecil St #04/#05

IOB Building

Singapore 049711

Attn: Accident Claim Department

Date : 27.07.2019

Vehicle No : GBD 2727 D

Veh Make/Model : Toyota

YOM : Hiace

Chassis No : JTFHT02P300147540

Date of Accident : 25.07.2019

No	Qty	Description	Amount \$
		Balance c/f	
		Special Nett Items:-	
1	1	Car plate number	\$ 50.00
2	1	Rear tail gate windscreen sealant	\$ 100.00
3	1	70 KM/H Sticker	\$ 10.00
4	Set	Rear tail gate inner compartment clips	\$ 60.00
5	1	Reverse sensor	\$ 280.00
6	1	8 Pax sticker	\$ 10.00
7	1	Rear tail gate "TOYOTA" logo sticker	\$ 98.00
8	1	Rear tail gate "HIACE" logo sticker	\$ 101.00
		Total - SN Item	\$ 709.00
		Less 10%	\$ 638.10
		Labour Charges:-	
1		Spray painting on all affected area.	\$ 800.00
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 1,000.00
3		To apply anti rust treatment.	\$ 120.00
4		To check wiring system & light.	\$ 100.00
5		To check & adjust wheel alignment.	\$ 100.00
6		To remove and replace reverse sensor.	\$ 120.00
7		To remove / Refix tail gate windscreen to new tail gate	\$ 180.00
8		To remove / Refix inner compartment to facilitate repair	\$ 280.00
9		To remove / Refix replace tail gate inner trim board, mechemism (etc)...	\$ 150.00
10		To check water leaking	\$ 120.00
		Total - L/C	\$ 2,970.00
		Sub-Total	\$ 10,796.96
		7% GST	\$ 755.78
		Total	\$ 11,552.74

LEK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: