

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

India International Insurance Pte Ltd

64 Cecil St #04/#05

IOB Building

Singapore 049711

Attn: Accident Claim Department

Date : 27.07.2019

Vehicle No : GBD 2727 D

Veh Make/Model : Toyota

YOM : Hiace

Chassis No : JTFHT02P300147540

Date of Accident : 25.07.2019

Not Authorised
61 Syg & ?
4-5 days, Repair After Rain

No	Qty	Description	Amount \$
		List Items:-	
1	1	Rear tail gate	\$ <i>R</i> 1,974.60 ✓
2	2	Rear tail gate hinge	\$ <i>R</i> 190.28 X
3	1	Rear tail gate lock	\$ <i>R</i> 298.60 ✓
4	1	Rear tail inner compartment/Trim board	\$ <i>R</i> 425.17 X
5	1	Rear tail gate logo	\$ <i>R</i> 65.00 ✓
6	1	Rear tail gate garnish panel (with key lock)	\$ <i>R</i> 372.14 X
7	1	Rear tail gate lock striker	\$ <i>R</i> 132.90 X
8	1	Rear weatherstripe	\$ <i>R</i> 427.80 X
9	1	Rear bumper	\$ <i>R</i> 585.90 ✓
10	2	Rear bumper side bracket	\$ <i>R</i> 144.32 X
11	1	Rear bumper bracket	\$ 220.00 ✓
12	10	Rear bumper clips	\$ <i>R</i> 40.00 ✓
13	1	Rear end panel (Inner)	\$ 912.89 ✓
14	1	Rear end panel (Outer)	\$ 725.14 ✓
15	6	Rear end panel garnish clips	\$ <i>RR</i> 30.00 X
16	1	Rear end panel garnish/Top cover	\$ <i>NSP</i> 198.86 X
17	1	Rear LH side end panel	\$ <i>R</i> 335.75 X
18	2	Rear LH small cover (under lamp)	\$ <i>R</i> 317.60 X
19	2	Rear lamp	\$ <i>NSP</i> 853.60 ✓
20	2	Rear LH lamp clips	\$ <i>RR</i> 16.00 ✓
21	Set	LH & RH Inner fender compartment clips	\$ <i>RR</i> 80.00 X
22	1	Rear floor panel	\$ <i>R</i> 880.60 X
23	1	Step panel bumper	\$ <i>R</i> 208.00 X
24	Set	Rear tail gate windscreen moulding	\$ <i>RR RR</i> 150.00 X
25	1		\$ -
26	1		\$ -
27	1		\$ -
28	1		\$ -
29	1		\$ -
30	1		\$ -
Total - List Item			\$ 9,585.15
Less 25%			\$ (2,396.29)
Total			\$ 7,188.86

