## **Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

Vehicle No.:

Chassis No.:

Vehicle Make:

**SMM 4030P** 

Not Norhard Renory Ble paint

			OB
SMI	N/II //	1111	. IIV

JTDKB3FU603083530

TOYOTA

PRIUS

		Vehicle Model:	PRIUS	
		Date of Accident :	29.6.2019	
		Third Party Insurer :	AIG	
		Date of Registration :	27.6.2019	
		PART		LIST
1	1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	Sz 583.30
2	1	PANEL SUB-ASSY, REAR DOOR, RH	\$	N 1,258.30
3	1	REINFORCE SUB-ASSY, ROCKER, OUTER RH	\$	572.10
4	1	REINFORCEMENT SUB-ASSY, ROCKER PANEL, RH	\$	A 336.60
5	1	BOARD SUB-ASSY, REAR DOOR TRIM, RH	\$	Sa 546.10
6	1	PANEL, QUARTER WHEEL HOUSE, OUTER RH	\$	N 290.50
7	1	REAR FENDER RH	\$	<b>1</b> 817.50
8	1	REAR FENDER LINER	\$	Sh 137.30
9	1	REAR BUMPER	\$	1 458.60 V
10	1	REAR BUMPER RE-INFORCEMENT	\$	1 318.80 X
11	1	REAR BUMPER TOWING COVER	\$	Ju 14.70
12	1	REAR BUMPER UNDER COVER (BLACK)	\$	552.60
13	1	REAR BUMPER SIDE RETAINER RH	\$	Sa 112.70
14	1	TAILLAMP LOWER RH	\$	JL 548.40
15	1	TAILLAMP UPPER RH	\$	557.90
16	1	REAR BUMPER SIDE RH	\$	Su 232.00
17	1	COVER, REAR COMBINATION LAMP, RH	\$	Sa 54.70
18	1	REAR TAILGATE	\$	N 1,547.27)
		TOTA	L \$	8,939.37
		259	% \$	2,234.84
			\$	6,704.53
		Special Nett		
1	1	REAR DOOR STICKER '6555-3333'	\$	~~ 80.00 X
2	1	REAR RIGHT WHEEL RIM	\$	Ph 1,570.55 X
3	1	REAR RIGHT WHEEL RIM COVER	\$	∫ <sub>4</sub> 175.80 ×
4	1SET	PARKING AID	\$	5m 700.00 €
4	IJLI	I ANNINO AID	+	

## **Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

## **SMM 4030P**

5	1SET	REAR BUMPER CLIP	\$ Na 22.00
6	1	REAR BUMPER PROTECTOR	\$ ~ 100.00
7	2	REAR WINDSCREEN SEALANT	\$ NA 80.00
8	1	WINDSCREEN MOULDING	\$ 100.00
9	1	REAR WINDSCREEN INNER SPONGE SEAL	\$ 100.00
10	1	REAR TAILGATE TOYOTA LOGO	\$ Nn 47.00 }X
11	1	REAR TAILGATE WORDING 'PRIUS'	\$ مد 52.90
12	1	REAR TAILGATE WORDING 'HYBRID'	\$ مم <sub>53.50</sub>
13	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$ Na 80.00
14	1	REAR TAILGATE STICKER '6555-3333'	\$ An 80.00
		TOTAL	\$ 3,241.75
		TOTAL PARTS	\$ 9,946.28
		LABOUR	
		Putty And Spray Painting Of The Affected Portion.	\$ 4,500.00 4401
		To transfer of Tailgate fittings, attachments and perform water seepage test.	\$ Nr 170.00 X
		To transfer of Rear Door fittings, attachments and	4
		perform water seepage test.	\$ 170.00 \$
		To transfer of tire, rim and on wheel balancing.	\$ n~ 170.00 X
		To check steering geometry and computer wheel	
		alignment	\$ 12 220.00 X
		To Check Electrical Lighting Concerned.	\$ ma 170.00 X
		To reinstall rear bumper parking sensor.	\$ ~~ 170.00 X
		Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts,	
		Adjust And Realign The Same	\$ NA 4,500.00 X

## Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

**SMM 4030P** 

	2day,
(PART-BY-PART) Repair Days	15 DAYS
Over All Total	\$ 22,216.28
TOTAL	\$ 12,270.00
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$ ~~ <sub>380.00</sub> X
To apply paint protection system (PPS) maintain and enhancement	\$ 11 380.00 X
To Rust-Proofing Of The Affected Areas.	\$ nn 170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$ Na 170.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$ ~~ 380.00 ⊀
To apply paint protection system (PPS) maintain and enhancement	\$ れっ 380.00 🗶
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$ nn 170.00 X
To transfer of Rear Fender fittings, attachments and perform water seepage test.	\$ NA 170.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature: