



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE FRANCE PTE. LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

Company Reg No. 200609327M  
GST Reg No. MR-8500111-X

## ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
Ong Peiqi Jean (wang Peiqi Jea	Cust No/Name /Ong Peiqi Jean (Wang Peiqi Jean
Blk 950 Hougang St 91	Reg No/Reg Date SLD6199H*FS5/ 20/06/2016
#05-318	Date In/Mileage / 0
Singapore 530950	Chassis No VF73DBHZTFJ864897
Contact No Mobile: 98303353	Engine No 10JBHD3028023
	Make/Model CIT/C4P 1.6 BLUEHDI EAT6 SEDUCTION
	Colour/Trim PYM / 8MF

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	27/07/2019/ 11:30	QUA	265 / AndreChow	14592

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PORTION ON REAR BUMPER, REPAIR END PANEL				600 1200.00
E PNT88000 REMOE AND INSTALL REVERSE PARKING SENSORS				80 150.00
E PNT98000 RESpray ACCIDENT DAMAGED PORTION ON REAR BUMPER, REAR END PANEL				420 840.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				50 100.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓ 300.00
M SUNDRY SUNDRIES				20 50.00
M REAR BUMPER	1.00	952.00	0.00	de 952.00
M BUMPER SKIRT	1.00	331.00	0.00	cut 331.00
M BRACKET SET	1.00	107.00	0.00	? 107.00
M BRACKET SET	1.00	61.00	0.00	? 61.00
M BRACKET	1.00	152.00	0.00	? 152.00
M LOW RR PAN FIX	1.00	170.00	0.00	? 170.00

SURVEYOR NAME: Tan Jhi 97495449

SURVEYOR SIGNATURE: [Signature]

DATE: 5/8/19 03pm WP

REMARKS: Resurvey before paint  
sure 11kants.com 03 days

Confirm &amp; accepted by

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp surveyed and is subject to final approval from Insurance Company

Parts	1,773.00
Labour	2,590.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	50.00
<b>Total (w/o GST)</b>	<b>4,413.00</b>

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.