

REPAIR ESTIMATE*

VEHICLE NO : SHC 8795B

DATE 29/7/2019

MAKE :

MODEL : HYUNDAI i40

CBE 445)

LC

LKE kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille ✓			\$ 1,110.10	
	Radiator Grille H Emblem ✓			\$ 39.50	
	Front Bumper Cover x repair			\$ 1,052.20	
	Front Bumper Sponge x			\$ 99.20	
	Front Bumper Reinforcement x			\$ 402.10	
	Front Bumper Grille (LH/RH) x		\$ 41.60	\$ 83.20	
	Front Bumper Bracket Top (LH/RH) x		\$ 22.40	\$ 44.80	
	Front Bumper Bracket (LH/RH) x		\$ 24.60	\$ 49.20	
	SUB TOTAL			\$ 2,880.30	
	LESS 20% 256			\$ 576.06	
	DISCOUNTED TOTAL			\$ 2,304.24	
	Front Number Plate ✓			\$ 25.00	Nett
	Front No Plate Trim Cover x			\$ 30.00	Nett
				\$ 55.00	
	Labour Charge				
	Panel Beating			\$ 400.00 200	
	Spray Painting Charge			\$ 300.00 200	
	TOTAL LABOUR			\$ 700.00	
	ESTIMATE TOTAL			\$ 3,059.24	
<p> <i>Ka hui clay</i> <i>29/7/19 1235</i> <i>204</i> <i>U/S</i> <i>At the Repair shop</i> </p>					
<p> LKK Auto Care the following are the conditions of the estimate: • To be used for repair only • To be used for repair only • Parts and labour is on a "cash" basis • Third party liability is on a "cash" basis • No claim to be made against the insurance company • Supplemental work must be done by the insurance company • Subject to the terms and conditions of the insurance company Acknowledged by Repairer Signature: Date: </p>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					